

Version #	Date of Publication	Internal reference	Description	
SV 1.70	08/2021	PEP0646226R	Fixed channel input value frozen when high EMC disturbance injected in specific condition	



7/29/2021	Date of Publication	Internal reference	Description			
SV1.60	01/2021	PEP0590525R	Optimized the 4 status LEDs (RUN, ERR, I/O, DL) blinking fast mechanism. Under a rare condition, when the inconsistence of data in RAM occurs and could not be recovered autonomously, this issue will be indicated by module healthy bit and 4 status LEDs blinking fast.			

2/5 29-Jul-21 Internal



Version #	Date of Publication	Internal reference	Description							
SV1.50	04/2020	PEP0555714R	Below is the acquisit explanation: BMX AMI Acquisition cycle time when below the slew rate threshold (T) (2) Acquisition cycle time when above the slew rate threshold Input signal slew rate thr Note: (1) SV1.4 was only available for (2) T is the acquisition cycle time acquisition time when above to (3) For SV1.0 the AMI04** chains and the chain acquisition time when above to (3) For SV1.0 the AMI04** chains are acquisition time when above to (3) For SV1.0 the AMI04** chains are acquisition time when above to (3) For SV1.0 the AMI04** chains are acquisition time when above to (3) For SV1.0 the AMI04** chains are acquisition time when above to (3) For SV1.0 the AMI04** chains are acquisition time when above to (3) For SV1.0 the AMI04** chains are acquisition time when above to (3) For SV1.0 the AMI04** chains are acquisition time when above to (3) For SV1.0 the AMI04** chains are acquisition time when above the acquisition time when acquisition t	channels) Fast (periodic acquisition for the declared channels used) AMI0410 (T at normal or fast) AMI0800/0810 (T at normal or fast) eshold (unit: mV/ms or mA/ms)	SV1.0 Value drift (3) Value frozen (4) 23. cold, it might be collation of thresholer range or over	SV1.1 1 ms T x 2 ms T x 2 ms 84 mV T	SV1.2 5 ms (/ 9 ms (/ s+1 ms x num T x 2 ms 8+(Tx2) ms or 0.05	SV1.3 AMI04**) AMI08**) AMI08**) AMI08** AMI08** AMI08** AMI08** T x 2 ms 8+(Tx2) ms 1537 mA T	SV1.4 (1) used NA 16+(Tx2) ms 400 mV T	SV1.5 16+(Tx2) ms 16+(Tx2) ms 16+(Tx2) ms 16 mA T
		PEP0473117R	Fixed that deviation exceeds specification in user manual (0.15%FS) when any channel sees fast change input (such as 1Hz sine) signal							

3/5 29-Jul-21 Internal



Version #	Date of Publication	Internal reference	Description	
SV1.30	06/2018	PEP0446999R	Optimized the timing interrupt management coding to eliminate the weakness in the firmware, which could potentially lead to 4 status LEDs (RUN, ERR, I/O, DL) blinking fast.	



Version #	Date of Publication	Internal reference	Description	
SV 1.20	05/2014	PEP0249277R	Fixed that input value deviation and the input channels occur frozen without warning signal from PLC.	