

EcoStruxure Machine Expert V2.2

Release Notes

12/2023

RN0000000035.19



Legal Information

The information provided in this document contains general descriptions, technical characteristics and/or recommendations related to products/solutions.

This document is not intended as a substitute for a detailed study or operational and site-specific development or schematic plan. It is not to be used for determining suitability or reliability of the products/solutions for specific user applications. It is the duty of any such user to perform or have any professional expert of its choice (integrator, specifier or the like) perform the appropriate and comprehensive risk analysis, evaluation and testing of the products/solutions with respect to the relevant specific application or use thereof.

The Schneider Electric brand and any trademarks of Schneider Electric SE and its subsidiaries referred to in this document are the property of Schneider Electric SE or its subsidiaries. All other brands may be trademarks of their respective owner.

This document and its content are protected under applicable copyright laws and provided for informative use only. No part of this document may be reproduced or transmitted in any form or by any means (electronic, mechanical, photocopying, recording, or otherwise), for any purpose, without the prior written permission of Schneider Electric.

Schneider Electric does not grant any right or license for commercial use of the document or its content, except for a non-exclusive and personal license to consult it on an "as is" basis.

Schneider Electric reserves the right to make changes or updates with respect to or in the content of this document or the format thereof, at any time without notice.

To the extent permitted by applicable law, no responsibility or liability is assumed by Schneider Electric and its subsidiaries for any errors or omissions in the informational content of this document, as well as any non-intended use or misuse of the content thereof.

Table of Contents

Safety Information.....	9
About the Book.....	10
Product Information V2.2.....	12
Product Information	12
Installation Instructions	14
Hardware/Firmware Information V2.2.....	16
Hardware/Firmware Information.....	16
New Features.....	17
Mitigated Anomalies	20
Known Operational Anomalies.....	22
Library Information V2.2.....	24
Library Information.....	24
New Features.....	27
New Features - Examples	29
Mitigated Anomalies	30
Software Information V2.2	32
Software Information.....	32
New Features EcoStruxure Machine Expert.....	34
New Features EcoStruxure Machine Expert - Safety	35
Compatibility EcoStruxure Machine Expert - Safety	36
Mitigated Anomalies	37
Known Operational Anomalies.....	43
Additional Information	44
Cybersecurity Best Practices	44
Updating Projects (Libraries)	44
DTM Connection With TMSES4 Module	44
TLS Versions.....	44
Release Notes History	45
EcoStruxure Machine Expert V1.1	45
Hardware/Firmware Information.....	45
New Features	46
Mitigated Anomalies.....	51
Library Information	53
New Features	55
Mitigated Anomalies.....	60
Software Information	61
New Features for Machine Expert Installer and Online Help	61
New Features EcoStruxure Machine Expert.....	62
New Features for EcoStruxure Machine Expert - Safety	64
Compatibility EcoStruxure Machine Expert	65
Compatibility EcoStruxure Machine Expert - Safety	69
Mitigated Anomalies.....	71
Known Operational Anomalies	79
Documentation - Mitigated Anomalies	82
EcoStruxure Machine Expert V1.1 SP1	82
Hardware/Firmware Information.....	82

Mitigated Anomalies	83
Known Operational Anomalies	85
Library Information	88
Mitigated Anomalies	90
Known Operational Anomalies	90
Software Information	91
Compatibility EcoStruxure Machine Expert	91
Mitigated Anomalies	91
Known Operational Anomalies	92
Documentation - Mitigated Anomalies	93
Documentation - Known Operational Anomalies	94
EcoStruxure Machine Expert V1.2	95
Hardware/Firmware Information	95
New Features	96
Mitigated Anomalies	100
Known Operational Anomalies	102
Library Information	104
New Features	106
Mitigated Anomalies	107
Known Operational Anomalies	107
Software Information	107
New Features for Machine Expert Installer	108
New Features EcoStruxure Machine Expert	108
New Features for EcoStruxure Machine Expert - Safety	109
Compatibility EcoStruxure Machine Expert	110
Compatibility EcoStruxure Machine Expert - Safety	110
Mitigated Anomalies	111
Known Operational Anomalies	112
Documentation - Mitigated Anomalies	113
Documentation - Known Operational Anomalies	114
EcoStruxure Machine Expert V1.2.1	114
Hardware/Firmware information	114
EcoStruxure Machine Expert V1.2.2	115
Hardware/Firmware information	115
Software Information	116
EcoStruxure Machine Expert V1.2.3	117
Hardware/Firmware Information	117
Library Information	119
Software Information	120
EcoStruxure Machine Expert V1.2.4	122
Hardware/Firmware Information	122
Library Information	125
Software Information	126
EcoStruxure Machine Expert V1.2.5	127
Hardware/Firmware Information	127
Library Information	130
Software Information	130
EcoStruxure Machine Expert V1.2.6	132
Hardware/Firmware Information	132
Library Information	133
Software Information	134

EcoStruxure Machine Expert V2.0	135
Hardware/Firmware Information	135
New Features	136
Mitigated Anomalies	140
Known Operational Anomalies	145
Library Information	147
New Features	148
Mitigated Anomalies	151
Known Operational Anomalies	152
Software Information	153
New Features Schneider Electric Software Installer	153
New Features EcoStruxure Machine Expert	153
New Features EcoStruxure Machine Expert - Safety	158
Compatibility EcoStruxure Machine Expert	158
Compatibility EcoStruxure Machine Expert - Safety	159
Mitigated Anomalies	160
Known Operational Anomalies	164
Additional Ethernet Port for PacDrive LMC Control	166
Sercos Improvements (Sercos Robustness) for PacDrive LMC Control	170
EcoStruxure Machine Expert V2.0.0.1	172
Hardware/Firmware Information	172
Mitigated Anomalies	172
Known Operational Anomalies	172
Library Information	172
Software Information	172
EcoStruxure Machine Expert V2.0.1	172
Hardware/Firmware Information	172
New Features	173
Mitigated Anomalies	174
Known Operational Anomalies	175
Library Information	177
New Features	178
Mitigated Anomalies	180
Known Operational Anomalies	181
Software Information	182
New Features EcoStruxure Machine Expert	182
New Features EcoStruxure Machine Expert - Safety	182
Compatibility EcoStruxure Machine Expert - Safety	183
Mitigated Anomalies	183
Known Operational Anomalies	185
EcoStruxure Machine Expert V2.0.2	186
Hardware/Firmware Information	186
New Features	186
Mitigated Anomalies	187
Known Operational Anomalies	189
Library Information	191
New Features	192
Mitigated Anomalies	194
Known Operational Anomalies	194
Software Information	195

New Features EcoStruxure Machine Expert	195
Compatibility EcoStruxure Machine Expert - Safety	197
Mitigated Anomalies	198
Known Operational Anomalies	199
EcoStruxure Machine Expert V2.0.2.1	199
Hardware/Firmware Information	199
Mitigated Anomalies	200
Library Information	200
Software Information	201
Mitigated Anomalies	201
Known Operational Anomalies	201
EcoStruxure Machine Expert V2.0.3	202
Hardware/Firmware Information	202
New Features	202
Mitigated Anomalies	203
Known Operational Anomalies	205
Library Information	206
New Features	206
Mitigated Anomalies	208
Known Operational Anomalies	209
Software Information	209
New Features EcoStruxure Machine Expert	209
Mitigated Anomalies	210
Known Operational Anomalies	211
Additional Information - C2C for Lexium™ MC12 multi carrier	212
EcoStruxure Machine Expert V2.0.3.1	214
Hardware/Firmware Information	214
Mitigated Anomalies	214
Library Information	215
New Features	215
Known Operational Anomalies	215
Software Information	215
EcoStruxure Machine Expert V2.1	216
Hardware/Firmware Information	216
New Features	217
Mitigated Anomalies	219
Known Operational Anomalies	221
Library Information	224
New Features	226
New Features - Examples	228
New Features - Function Templates	229
Mitigated Anomalies	230
Known Operational Anomalies	231
Software Information	231
New Features EcoStruxure Machine Expert	232
New Features EcoStruxure Machine Expert - Safety	233
Compatibility EcoStruxure Machine Expert - Safety	234
Mitigated Anomalies	236
Known Operational Anomalies	237
EcoStruxure Machine Expert V2.1.1	240
Hardware/Firmware Information	240

New Features	241
Mitigated Anomalies.....	241
Known Operational Anomalies	243
Library Information	244
New Features	245
New Features - Examples.....	245
Mitigated Anomalies.....	245
Known Operational Anomalies	245
Software Information	246
Known Operational Anomalies	246
EcoStruxure Machine Expert V2.1.2.....	246
Hardware/Firmware Information	246
Mitigated Anomalies.....	247
Known Operational Anomalies	247
Library Information	247
New Features	248
Mitigated Anomalies.....	248
Known Operational Anomalies	248
Software Information	248
Index	249

Safety Information

Important Information

Read these instructions carefully, and look at the equipment to become familiar with the device before trying to install, operate, service, or maintain it. The following special messages may appear throughout this documentation or on the equipment to warn of potential hazards or to call attention to information that clarifies or simplifies a procedure.



The addition of this symbol to a “Danger” or “Warning” safety label indicates that an electrical hazard exists which will result in personal injury if the instructions are not followed.



This is the safety alert symbol. It is used to alert you to potential personal injury hazards. Obey all safety messages that follow this symbol to avoid possible injury or death.

DANGER

DANGER indicates a hazardous situation which, if not avoided, **will result in** death or serious injury.

WARNING

WARNING indicates a hazardous situation which, if not avoided, **could result in** death or serious injury.

CAUTION

CAUTION indicates a hazardous situation which, if not avoided, **could result in** minor or moderate injury.

NOTICE

NOTICE is used to address practices not related to physical injury.

Please Note

Electrical equipment should be installed, operated, serviced, and maintained only by qualified personnel. No responsibility is assumed by Schneider Electric for any consequences arising out of the use of this material.

A qualified person is one who has skills and knowledge related to the construction and operation of electrical equipment and its installation, and has received safety training to recognize and avoid the hazards involved.

About the Book

Document Scope

This document contains important information about the delivery of the product EcoStruxure Machine Expert V2.2, and the history of previous Release Notes. Read the complete document before you use the product or products that are described in here.

Validity Note

The information in this Release Notes document is applicable only for EcoStruxure Machine Expert compatible products.

This document has been updated for the release of EcoStruxure™ Machine Expert V2.2.

Available Languages of this Document

This document is available in these languages:

- English (RN0000000035)
- French (RN0000000036)
- German (RN0000000037)
- Italian (RN0000000038)
- Spanish (RN0000000039)
- Chinese (RN0000000040)

Related Documents

Document title	Reference
Cybersecurity Best Practices	CS-Best-Practices-2019-340
Cybersecurity Guidelines for EcoStruxure Machine Expert, Modicon and PacDrive Controllers and Associated Equipment	EIO0000004242
Schneider Electric Software Installer - User Guide	EIO0000002848 (ENG); EIO0000002849 (FRE); EIO0000002850 (GER); EIO0000002852 (SPA); EIO0000002851 (ITA); EIO0000002853 (CHS)
EcoStruxure Machine Expert Compatibility and Migration User Guide	EIO0000002842 (ENG); EIO0000002843 (FRE); EIO0000002844 (GER); EIO0000002846 (SPA); EIO0000002845 (ITA); EIO0000002847 (CHS)

To find documents online, visit the Schneider Electric download center (www.se.com/ww/en/download/).

Information on Non-Inclusive or Insensitive Terminology

As a responsible, inclusive company, Schneider Electric is constantly updating its communications and products that contain non-inclusive or insensitive terminology. However, despite these efforts, our content may still contain terms that are deemed inappropriate by some customers.

Trademarks

QR Code is a registered trademark of DENSO WAVE INCORPORATED in Japan and other countries.

Product Information V2.2

Product Information

Overview

EcoStruxure Machine Expert

EcoStruxure Machine Expert is a unique software solution for developing, configuring, and commissioning the entire machine in a single software environment, including logic, motion control, HMI, and related network automation functions.

NOTE: If you are using templates and examples which are not updated with the update of EcoStruxure Machine Expert V2.2, you may be presented the **Update Project** dialog. If you are opening an example or template for the first time, you should update to have the correct and corresponding libraries and other necessary support.

EcoStruxure Machine Expert - Safety

EcoStruxure Machine Expert - Safety is a component of EcoStruxure Machine Expert. It is an engineering tool used to develop safety-related applications for the Safety Logic Controller TM5CSLC•00FS.

Integrity of Your Software

To verify the integrity of your software, you have to ensure the internet connection before starting the software for the first time.

EcoStruxure Machine Expert - Installation Note

In our efforts of continuous improvement, major releases such as EcoStruxure Machine Expert V1.1 or EcoStruxure Machine Expert V1.2 may have some minor releases thereafter to improve quality, add minor features or add hardware that may not have been available at the time of the major release. Major releases are installed as separate instances on your PC. Minor releases will update the existing installed version on your machine to which they belong. For example, EcoStruxure Machine Expert V2.2 provides a full installation of the software and related system components.

Contrast this to a PC that has EcoStruxure Machine Expert V1.1 (or V2.0.●) installed as you install, for example, EcoStruxure Machine Expert V2.2. In this case, EcoStruxure Machine Expert V2.2 will be installed as a complete and separate instance to EcoStruxure Machine Expert V1.1 (or any of its minor releases like, for example, EcoStruxure Machine Expert V1.1 SP1).

NOTE: For full use of EcoStruxure Machine Expert V2.2 beyond the trial period, you must have a V2.0 license. For more information, see section Licensing Information, page 15.

NOTE: In case of an existing SoMachine/SoMachine Motion installation, for shared components like the Controller Assistant, verify whether the latest SoMachine Configuration Manager is installed. Consider the SESU (Schneider Electric Software Update) notifications or visit <https://www.se.com/ww/en/download/document/SoMachineConfigurationManager/>.

Product Identification

Reference	Description
Schneider Electric Software Installer	V22.23.33501
EcoStruxure Machine Expert	V2.2
EcoStruxure Machine Expert - Safety	V2.2.105.8356
Safety Plugin (SafeLogger, Safety Offline Help)	V22.0.109.61107 (Installer and Technical Information)

NOTE: You can see the installed software versions in the Schneider Electric Software Installer or in the **Help > Technical Information** dialog box of EcoStruxure Machine Expert Logic Builder.

Release History

Version	Release Date	Description
V1.1	July 2019	EcoStruxure Machine Expert V1.1
V1.1 SP1	November 2019	EcoStruxure Machine Expert V1.1 SP1
V1.2	December 2019	EcoStruxure Machine Expert V1.2
V1.2.1	February 2020	EcoStruxure Machine Expert V1.2.1
V1.2.2	March 2020	EcoStruxure Machine Expert V1.2.2
V1.2.3	May 2020	EcoStruxure Machine Expert V1.2.3
V1.2.4	August 2020	EcoStruxure Machine Expert V1.2.4
V1.2.5	September 2020	EcoStruxure Machine Expert V1.2.5
V1.2.6	October 2020	EcoStruxure Machine Expert V1.2.6
V2.0	April 2021	EcoStruxure Machine Expert V2.0
V2.0.0.1	July 2021	EcoStruxure Machine Expert V2.0.0.1
V2.0.1	September 2021	EcoStruxure Machine Expert V2.0.1
V2.0.2	January 2022	EcoStruxure Machine Expert V2.0.2
V2.0.2.1	February 2022	EcoStruxure Machine Expert V2.0.2.1
V2.0.3	June 2022	EcoStruxure Machine Expert V2.0.3
V2.0.3.1	August 2022	EcoStruxure Machine Expert V2.0.3.1
V2.1	December 2022	EcoStruxure Machine Expert V2.1
V2.1.1	June 2023	EcoStruxure Machine Expert V2.1.1
V2.1.2	September 2023	EcoStruxure Machine Expert V2.1.2
V2.2	December 2023	EcoStruxure Machine Expert V2.2

System Requirements

EcoStruxure Machine Expert can be installed on a personal computer with the following hardware:

- Processor Core 2 Duo or greater
- RAM Memory 4 GB minimum, 8 GB recommended or greater
- Hard disk 8 GB for typical and 15 GB for full software installation
- Display 1280 x 1024 resolution or greater
- Mouse or compatible pointing device
- USB interface
- Internet access

EcoStruxure Machine Expert can be installed on the following operating system:

- Microsoft Windows 10 (64 Bit)
- Microsoft Windows 11 (64 Bit)

NOTE: Some components still support 32 Bit operating systems (see the following table).

Software	Supported OS
EcoStruxure Machine Expert	64 Bit
EcoStruxure Machine Expert - Safety	32 Bit & 64 Bit
Schneider Electric Software Installer	32 Bit & 64 Bit
SQL gateway	32 Bit & 64 Bit
Gateway	32 Bit & 64 Bit
Device Assistant	32 Bit & 64 Bit
Diagnostics	32 Bit & 64 Bit
Controller Assistant	32 Bit & 64 Bit
Motion Sizer	32 Bit & 64 Bit

Microsoft.NET Framework

EcoStruxure Machine Expert requires the .NET Framework 4.7.2. Therefore, it is required to have a current Windows version on your system. If a previous version is found on your current Windows version, EcoStruxure Machine Expert will install the required version.

The DTM installation requires the Microsoft.NET Framework 3.5 Service Pack 1 with the latest updates.

This package is not installed with Windows 10. An internet connection is required to install Microsoft.NET Framework 3.5.

For information on how to install it, refer to <https://docs.microsoft.com/en-us/dotnet/framework/install/dotnet-35-windows-10>.

Installation Instructions

Overview

The Schneider Electric Software Installer is used for configuring and installing the EcoStruxure Machine Expert software. For information on the installation procedure, refer to the [Schneider Electric Software Installer User Guide](#).

Limitations on USB Driver Installation for M241/M251 Controllers

In some cases, this driver installation is incomplete. The controller is shown with a yellow triangle in the **Device Manager**.

You can solve this issue by manually installing the USB driver for the marked device. The driver is available in the following directories:

- *C:\Program Files (x86)\Schneider Electric\EcoStruxure Machine Expert\Tools\Gateway\Driver\USB PLC Driver\Win7_x64 for x64 systems*
- *C:\Program Files (x86)\Schneider Electric\EcoStruxure Machine Expert\Tools\Gateway\Driver\USB PLC Driver\Win7_x86 for x86 systems*

Limitations on EcoStruxure Machine Expert - Safety Installation

Installing the Safety component via Schneider Electric Software Installer requires at minimum to select and install one available controller (Modicon or PacDrive) component to get a full usable system environment (refer to *Schneider Electric Software Installer User Guide*).

Ensure that during the installation of EcoStruxure Machine Expert - Safety, no instance of a previously installed legacy version of SoSafe programmable V2.x is running.

Installation of CodeMeter

The third-party tool CodeMeter is installed to allow for licensing of selected dongle-protected CODESYS add-ons. In order to take advantage of the latest cybersecurity bug fixes and enhancements, you must update the third-party tool CodeMeter. Go to <https://www.wibu.com/support/user/user-software.html> and install the latest patch.

Licensing Information

For EcoStruxure Machine Expert V2.2 there are no new licenses required. A valid license from EcoStruxure Machine Expert V2.0 can be used. A valid V2.0 license allows you to use also EcoStruxure Machine Expert V1.1 and V1.2 installations on the system.

For further information, refer to the *Schneider Electric Software Installer Online help*.

Hardware/Firmware Information V2.2

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M241	5.2.11.18
M251	5.2.11.18
M262	5.2.8.12
TMSES4	1.0.0.21
TM3BCCO	2.1.50.2
TM3BCEIP	2.4.0.3
TM3BCSL	2.1.50.2
TM3•HSC202•	2.0
TM3DI8	2.0
TM3DI8G	2.0
TM3DI16	2.0
TM3DI16G	2.0
TM3DI16K	2.0
TM3DI32K	2.0
TM3DM8R	2.0
TM3DM8RG	2.0
TM3DM24R	2.0
TM3DM24RG	2.0
TM3DQ8••	2.0
TM3DQ16••	2.0
TM3DQ32••	2.0
TM5NEIP1 / TM5NEIP1K	3.12
TM5NS31	2.81
LXM32••••M2 / LXM32S•••N4	• Drive firmware: V1.12.2 • Sercos3 interface firmware: V1.12.02
LXM52••••C••••	1.54.29.0
ILM••••••••••	1.54.26.0
LXM62••••C••••	• 1.64.11.0 for hardware revision RS1• • 1.54.27.0 for hardware revision RS0•
LXM62••••D••••	• 1.64.11.0 for hardware revision RS1• • 1.54.27.0 for hardware revision RS0•
LXM62••••E••••	1.54.27.0
LXM62••••F••••	1.54.27.0
LXM62••••G••••	1.64.11.0
LMC Eco	1.76.14.1
LMC Pro	1.76.14.1
LMC Pro2	1.76.14.1
ATV340S	• Drive firmware: V1.4IE09_B06 • Sercos3 interface firmware: A1.2IE01_B00

Description	Safety-related Firmware Version
LXM62....E.....	1.2.5.0 SLCv1 1.3.3.0 SLCv2
LXM62....F.....	1.2.5.0 SLCv1 1.3.3.0 SLCv2
VW3E702200000 safety option module	1.2.5.0 SLCv1 1.3.3.0 SLCv2
TM5CSLC100FS	2.59
TM5CSLC200FS	2.59
TM5CSLC300FS	3.07
TM5CSLC400FS	3.07
BWU2984 SWID	134253
BWU2984 Safe CPU A	135115
BWU2984 Safe CPU B	135116
BWUASI5ASI3	- V 199415 BWU3861 SWID (FW) - V 199143 BWU3861 Safe CPU A (FW) - V 199144 BWU3861 Safe CPU B (FW)
ASIMON360	3.2.6.7 / V5.1.7.10

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

New Features

M241/M251

- Support of CODESYS V3.5 SP19.
- Support of modifying and fixing addresses for TM3 bus coupler and TM3 I/O module.
- New function to manage user rights from the WebVisualization.
- Support of Security Policy and Message Security for OPC UA server.
- Support of signing and encrypting boot applications.
- Support of TM3BCEIP Modbus TCP / EtherNet/IP IO mapping status.

M262

- The number of Modbus TCP server connections has been increased to a maximum of 30 clients. It is a good practice to allocate at least 40% of the CPU load and to use a maximum of 100 ms cycle time for the task managing *FB_ModbusTcpServer* in order to enable 30 connections.
- A new set of function blocks is available to manage axis homing from Modicon M262 Motion controllers:
 - *FB_HomingDigitalInput*: Homing method based on standard digital input.
 - *FB_HomingTouchProbe*: Homing method based on a Touchprobe input in LXM32S.
 - *FB_HomingTorque*: Homing method based to targeted torque applied to servomotor shaft (blocking shaft).
- New master offset and subordinate offset inputs in the *MC_CamIn* function block.
- New *FC_CAMBounds* allowing to calculate the maximum and minimum values to position, velocity and acceleration for subordinate axis, based on the CAM table, maximum velocity and maximum acceleration of the subordinate axis.

PacDrive LMC Control

Storage devices connected to PacDrive LMC controllers, such as memory cards (CF or SD cards) or USB keys, are automatically mounted to the system.

Starting with EcoStruxure Machine Expert V2.2, the path to the memory storages is named according to the following schema:

``/msd<Device><Partition>``

Where ``<Device>`` is replaced by a number per device (for example, ``0`` for the first found device, ``16`` for the second device, and so on), and `<Partition>` is replaced by a single character for each partition (for example, ``a`` for the first partition of the device, ``b`` for the second partition, and so on).

Example:

The third partition of the second found device, for example, a USB key, is mounted to ``/msd16c``.

NOTE: For compatibility reasons, the partition containing the operation system ("boot partition") is renamed to ``ide0:``.

PacDrive LMC Controls & I/Os

OPC UA Method Call - Client

Allows you to exchange data with the OPC UA protocol using the Method Call mechanism.

Stack size for the IEC tasks has been increased to 128 KB

- In previous versions the stack size was 64 KB
- This improvement has been implemented to resolve compiler messages indicating potential stack overflows in an application.

Profinet IO Interrupt Mode Enable/Disable

A new mechanism allows you to enable or disable the IO update triggered by the Profinet Interrupt mode.

The following new interfaces have been added:

- *IF_Direction*
- *IF_DriveOverload*
- *IF_EncIn*
- *IF_EncIn_Incremental*
- *IF_EncIn_Incremental_TM5*
- *IF_EncIn_SinCos*
- *IF_EncOut*
- *IF_EncOut_BT4Enc1*
- *IF_EncOut_TM5*
- *IF_ErrorDeceleration*
- *IF_InObject*
- *IF_Mechanic_DSM*
- *IF_MotorIdentification*
- *IF_PowerSupplyCurrent*
- *IF_PowerSupplyModes*
- *IF_SercDrive*
- *IF_SercosDiagnosticNumber*
- *IF_SercosMaster*
- *IF_State*
- *IF_Touchprobe2_CaptureCount*
- *IF_Touchprobe2_SensorDelay*
- *IF_Touchprobe2_ShaftDelay*
- *IF_VoltageFeedForwardMode*

New user interface disable hardware watchdog has been added to the Profibus master object.

New control loop parameters are available per carrier (*CarrierControlLoop*).

For further information, refer to the *Lexium™ MC multi carrier Device Objects and Parameters Guide*.

Fast Device Replacement (FDR) is supported for Lexium™ MC multi carrier segments.

TM5CSLC300FS / TM5CSLC400FS

- Cybersecurity improvements.
- Quality improvements (see mitigated anomalies).
- New safety-related firmware version.
 - Re-qualification of the customer application is required if a firmware version before 3.07 is used.

TM5NS31

- Cybersecurity improvements.
- Quality improvements for the FDR (Fast Device Replacement) of the safety-related I/O system.
- TM5 firmware upgrade to V2.81.

Mitigated Anomalies

M241/M251

ID	Description
M2X1-1008	The value <i>i_udiRX_MessagesError</i> now starts at 0 after a download or a reset.
M2X1-1017	The Modbus SL IOScanner no longer disconnects if the timeout value is less than 1 second.
M2X1-1055 M2X1-1056	The memory resource for user rights and WebVisualization has been optimized.
M2X1-1078	The post configuration file is no longer supported by controllers. Use the security settings of the OPC UA server.
M2X1-1133	The Modbus TCP IP address can be modified by the function block <i>ChangeIPaddress</i> .
M2X1-1179	In the OPC UA Symbol Configuration view, arrays of TIME and WSTRING were accessible even if they were not supported.
M2X1-1212	A maximum of eight fast TCP connections are now supported.
M2X1-1606	The status of the Modbus TCP bus coupler icon when no TM3 modules are connected has been corrected.
M2X1-228	Boolean values of the M2xx Web server can now be monitored in Oscilloscope .
M2X1-238	The values of monitored variables are now updated when the list is refreshed.
M2X1-290	In case of an incorrect Modbus Write multiple registers request, the exception code 0x03 now has a higher precedence than exception code 0x02.
M2X1-834	The icon status for CanOpen in the Devices tree has been corrected.
M2X1-879	The log file content can now be visualized on the WebVisualization without size limits.

M241/M251/M262, PacDrive LMC Control, HMISCU

ID	Description
CVE-2022-4224, CVE-2022-4304, CVE-2022-4450, CVE-2022-47380, CVE-2022-47381, CVE-2022-47382, CVE-2022-47383, CVE-2022-47384, CVE-2022-47385, CVE-2022-47386, CVE-2022-47387, CVE-2022-47388, CVE-2022-47389, CVE-2022-47390, CVE-2022-47391, CVE-2022-47392, CVE-2022-47393, CVE-2023-0215, CVE-2023-0286, CVE-2023-3662, CVE-2023-3663, CVE-2023-37545, CVE-2023-37546, CVE-2023-37547, CVE-2023-37548, CVE-2023-37549, CVE-2023-37550, CVE-2023-37551, CVE-2023-37552, CVE-2023-37553, CVE-2023-37554, CVE-2023-37555, CVE-2023-37556, CVE-2023-37557, CVE-2023-37558, CVE-2023-37559	The following security vulnerabilities have been addressed in this release.

M262

ID	Description
DFPLAT-10099 / PEP1055607R	Using Machine Assistant on a Sercos scanner/devices was corrupting the controller DHCP table, creating duplicate IP addresses.
M262-14225 / PEP1055321R	When a Modicon M262 controller communicated using the ASCII protocol at 115200 bps, it took a long time to switch to receive mode and some messages were lost.
M262-15272	Using an OPC UA client it was not possible to write in Array of standard data types.
M262-16117	A Modicon M262 controller could stop responding while using <i>FB_getLabel</i> to read a label from an SD card.
M262-18063	The status displayed in the views Ethernet_1 , Diagnostic and SercosMaster was different in case all devices connected to Eth1 lost connection.
M262-18241 / PEP1069340R	The WebVisualization stopped responding in HTTP with some Internet Browser versions.
M262-19382 / PEP1062423R	When trends were used in WebVisualizations, the error message <i>Some kind of disk I/O error occurred. Check disk space</i> could be displayed after some time.
M262-9412 / PEP1062428R	In trend recording, the maximum storage size configured for trend files is now considered.
MSOLCTRL-3384	The <i>MC_Stop</i> outputs are not set according to the PLCopen definition.
MSOLCTRL-3975	When the MC_Home process was aborted with MC_Stop , a jump occurred on axis or an error was detected on the drive.
MSOLCTRL-4629	The execution of <i>MC_Reset.Done</i> did not completely comply to the PLCopen definition.
MSOLCTRL-4924	In certain situations, the drive could go to run and the axis changed the status to disable.

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-2910	<i>PositionBehaviorOfMasterAndSlave</i> could have different behavior in C2C.
LMCFW-4132	A disabled Profinet device could update the input values.
LMCFW-5826	Incorrect messages were detected in the Profinet controller object.
LMCFW-7299	The SafeLogger station ID had an incorrect name.
LMCFW-7309	The PacDrive LMC controller as OPC UA client applying <i>SE_OPC.UA_Browse</i> could browse the application but not the server items.
LMCFW-7327	The PacDrive diagnostic message <i>8507 Sercos write cycle overflow</i> was issued on an LMC902.
LMCFW-7363	The input data of the Profinet module could be moved after an online change.
LMCFW-7389	A <i>Missing Application.crc on controller</i> message was displayed when connecting a USB device to a PacDrive LMC controller.
LMCFW-7414	Excessive cycle overrun was detected with a <i>DeleteMonitoredItemsRequest</i> in OPC UA.
LMCFW-7452	The EtherNet/IP hardware watchdog exceeded <i>CIFX_ResetW</i> .
LMCFW-7457	The device name of USB devices did not follow the nomenclature described in the online help.
LMCFW-7506	The <i>Application.app</i> was renamed to <i>Application.err</i> after reboot.
LMCFW-7534	An <i>8902 Software error (page fault)</i> was detected after switching off the main switch.
LMCFW-7607	The data type <i>NamespaceIndexes</i> for structures was incorrectly displayed when using OPC UA.
LMCFW-7608	An available load drop was detected in the PacDrive LMC during FTP access.
LMCFW-7633	An unexpected behavior was detected when the parameter <i>PowerSupplyMonitoring</i> was deactivated.

Safety System

ID	Description
SSP50-10052	The TM5CSLC300FS/400FS entered safe state when the memory key was removed during the SK-COPY function triggered by the <i>SLCRemoteController</i> interface.
SSP50-10188	The Fast Device Replacement (FDR) firmware update for safety I/O modules was not possible for modules that were placed behind a missing or dummy module type in a bus coupler I/O island.

Known Operational Anomalies

M241/M251

ID	Description
DFSI-19887	A firmware download to a V2.1 and earlier versions requires the new Controller Assistant V22.0.7.0.
M2X1-1320	The <i>CodesysLateConf.cfg</i> file is not accessible via the file system.
M2X1-1874	TM4 Profibus modules might become unresponsive after a reset cold/warm during data exchange. Workaround: Perform a power cycle to resolve the issue.
M2X1-1894	Certain features (such as Web server, Filezilla) might not work when the application processor load is high. Workaround: To reduce the processor load, increase the cycle time.
M2X1-1904	Certain applications might have a higher processor load utilization after upgrading to V2.2. Workaround: To reduce the processor load, increase the cycle time.

M262

ID	Description
M262-18238 / PEP1087143R	An IP address conflict with a TMS bus occurs when using the IP address range 192.168.2.0 for Ethernet interfaces. Workaround: Use IP addresses for Ethernet interfaces in a different TMS bus IP address range.
M262-20971	Certain applications might have a higher processor load utilization after upgrading to V2.2. Workaround: To reduce the processor load, increase the cycle time.

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-7670	<i>CAA_File.GetPos</i> can intermittently lead to the error <i>HANDLE_INVALID</i> being detected when opening files simultaneously.
LMCFW-7678	Loading the boot application can be unsuccessful due to retain memory area.
LMCFW-7693	The controller may become unresponsive as long as an asynchronous task with <i>CmpAsyncMgr</i> is running.
LMCFW-7705	Access and symbol rights cannot be restored from a backup.
LMCFW-7706	After an unsuccessful transfer of an image with symbol rights, the PacDrive LMC controller may not restart automatically.
DFBOC-2360 / LMCFW-7709	A transfer backup with Controller Assistant is not possible.
LMCFW-7735	A delay during the first login and an overload each 24 hours (during Key Pair generation) might be detected.
LMCFW-7749	Due to the OpenSSL update, the SecurityPolicy - Aes256-Sha256-RsaPss used for OPC UA communication, may not be operable. Workaround: Use another SecurityPolicy.

Safety System

ID	Description
SSP50-10958	The minimum values of the safety-related <i>Ton/Toff</i> filter time are related to the I/O module cycle time. This information is not provided in the user guide. Filter times below the I/O module cycle time will have no effect. Users switching from firmware 305 to the latest firmware 333 can be impacted because the legacy firmware 305 on some modules due to different internal timing could filter out shorter pulses on inputs on some input module variants. Workarounds / adaptations: Keep for the moment firmware 305 (old firmware of the EcoStruxure Machine Expert V2.0 release) for machines that are already in the field. There is no compatibility issue if a machine was already certified OK with firmware 305. - However, it is proposed to update in future to the EcoStruxure Machine Expert latest version in case a V2.1 or V2.2 is planned to be used. - And in case some instabilities are observed by unintended triggers of safety-related functions if pulses are used. (the filter is not active and it may or may not function). In case you want to update an existing machine or to build a new machine, do the following: - Adjust the filter setting according to the I/O module cycle time and evaluate the impact to the safety-related function reaction time in this path. - With a response time impact < 1 ms (I/O module cycle time 800 µs) there should be no real impact on a real safety-related chain or alternatively. - Verify if the way of installation or the safety integrity level required allows to not use pulse diagnostic on these inputs.

Library Information V2.2

Library Information

Version Identification

Description	Version
ApplicationLogger	1.1.7.0
AsyncManager	1.0.8.0
AutoTune	1.3.16.0
CertificateHandling	1.2.1.0
CNCExtension	1.0.7.0
CollisionDetection	1.0.1.0
CommonMotionInterface	1.4.4.0
CommonMotionTypes	1.0.3.0
CommonPouTypes	1.1.3.0
CommonToolbox	1.2.5.0
ControlLoopLibrary	1.0.0.0
CrankModule	1.4.3.0
Diagnostic Dictionary	1.0.5.0
DigitalTwinCommunication	1.2.1.0
EMailHandling	2.1.4.0
EtherNetIP Explicit Messaging	1.2.0.0
EtherNetIP Remote Adapter	1.2.0.0
Explicit Messaging LMC	1.0.2.0
Explicit Messaging M262	1.0.2.0
FastSampling	1.0.2.0
FeatureNotSupported	2.0.1.0
FileFormatUtility	1.6.1.0
FtpRemoteFileHandling	1.4.8.0
GeoMath	1.0.1.0
GMC Independent Altivar	1.4.0.0
GMC Independent Base	1.4.0.0
GMC Independent Base Device	1.5.3.0
GMC Independent CANopen	1.3.0.0
GMC Independent EtherNetIP	1.5.1.0
GMC Independent Interfaces	1.4.0.0
GMC Independent Lexium	1.3.0.0
GMC Independent ModbusTCP	1.4.0.0
GMC Independent PLCopen MC	1.4.0.0
Hoisting	5.0.5.0
HttpHandling	1.3.6.0
IoLinkHandling	1.2.6.0
IoTCloudCommunication	1.0.9.0

Description	Version
Lexium 28	1.6.2.0
LexiumCobotCommunication	1.0.1.0
M262Diagnostics	1.1.0.0
MachineAssistantServices	1.0.6.0
Mathematics	1.0.4.0
ModbusHandling	1.1.4.0
MotionApplicationFunctionBlocks	1.2.5.0
MqttHandling	2.3.0.0
Multicarrier	1.3.7.0
MulticarrierStation	1.2.0.0
OpcUaHandling	2.3.0.0
PackML	1.4.3.0
PD_AxisModule	1.7.1.0
PD_ETest	1.6.0.0
PD_GlobalDiagnostics	1.6.0.0
PD_MultiBelt	1.7.2.0
PD_MultiBeltModule	1.7.2.0
PD_PacDriveLib	1.11.2.0
PD_SmartInfeed	1.5.0.0
PD_SmartInfeedModule	1.6.0.0
PD_SoMotionGenerator	1.9.4.0
PD_Template	1.9.0.0
PLCCommunication	1.0.5.0
PLCopen MC part 1	2.19.1.0
PreventaSupport	1.1.8.0
ProxyCommunicationSupport	1.0.6.0
Robotic	3.6.9.0
RoboticModule	2.18.3.0
SchneiderElectricRobotics	2.14.2.0
SchneiderElectricRobotics Parameters	2.18.1.0
SchneiderElectricRobotics Toolbox	1.7.5.0
Sercos3PlcOpenMc	1.4.1.0
SercosCommunication	1.3.0.0
SercosCommunicationLMC	1.0.2.0
SercosCommunicationM262	1.0.2.0
SercosDriveUtility	1.2.2.0
SercosIpClient	1.0.5.0
SlcRemoteController	1.4.4.0
SnmpManager	1.3.4.0
SqlRemoteAccess	2.0.11.0
TcpUdpCommunication	2.3.0.0
TeSys Library	3.1.0.0
TeSys_island	2.0.6.0
TimeSync	1.1.7.0

Description	Version
Toolbox	3.1.0.0
TransportSystemCommunication	1.1.1.0
TwidoEmulationSupport	1.2.7.0
Unwinder	1.5.0.0
UnwinderModule	1.3.0.0
UserMotorTypePlate	1.5.0.0
UserTorqueFeedForward	1.4.0.0
XpsuSupport	1.0.7.0

Version Identification Smart Templates

Description	Version
SMT_ESME_Axis	2.2.5.0
SMT_ESME_Camera	2.3.5.0
SMT_ESME_Conveyor	2.4.2.0
SMT_ESME_Robot Cartesian	1.1.5.0
SMT_ESME_Robot P-Series	2.6.0.0
SMT_ESME_Robot T-Series	2.5.0.0
SMT_ESME_RobotCell	2.0.3.0
SMT_ESME_Sensor	1.3.2.0

Version Identification Template Libraries

Description	Version
Altivar Device Templates	5.2.4.0
CANopen Device Modules	5.2.5.0
Communication Functions	1.3.9.0
EtherNet/IP Device Modules	5.2.16.0
Hardwired Device Modules	5.2.1.0
ModbusSL Device Modules	5.2.3.0
ModbusTCP Device Modules	5.2.3.0
Sercos Device Modules	1.1.5.0

New Features

CommonToolbox

- A new function block *FB_HeatingControl2* for temperature control is available. It provides the following improvements compared to the existing *FB_HeatingControl*:
 - Improved and faster auto-tuning function.
 - Improved control behavior.
 - Advanced diagnostics based on the temperature sensor signal.
- *FB_HeatingControl*: The lower limit of the PWM (Pulse-Width Modulation) time period has been modified to improve the control quality based on a faster regulation.
- The values of the properties of the function block *FB_RuntimeMeasurement* can be monitored in a watch window in online mode.
- The new function *FC_MultiConcat2* supports a composite string with a length of 320 characters as return value.

DigitalTwinCommunication

- The *ET_EntityOffset* is used for SmartVisu entity ID input.
- Support of multi carrier in SmartVisu of EcoStruxure Machine Expert Twin V2.0: The variable *udiUnivocalId* has been added to *ST_TrackConfig* and *ST_CarrierConfig*.

EmailHandling

The maximum length of the username and the password inside the credentials structure has been increased to 255 characters.

LexiumCobotCommunication

This new library provides function blocks to establish a TCP connection to a Lexium Cobot Controller and to interact with it by sending commands or retrieving feedback data to 255 characters.

ModbusHandling

- New features of the function block *FB_ModbusTcpServer*:
 - The number of permissible client connections is configurable in the range of 1...30.
 - A link-down state of the bound interface is detected and a diagnostic message is indicated. After a link-down state was detected, up to 3 attempts for reopening the server are performed.
- The configuration of allowed IP addresses for incoming client connections is supported. Incoming connections from clients with an IP address which is not allowed are refused.
- The configuration of access rules to specify the allowed memory areas for connected clients is supported. If a client sends a request for accessing a non permitted memory address, the exception code *Illegal Data Address* is sent as response.

- The property *GetConnectedClients()* is provided, allowing to retrieve the IP address and the port of each connected client.

MotionApplicationFunctionBlocks

The new function block *RotaryKnife* is provided.

Multicarrier

- A new move command (*ifMoveGapControl.StartAntislosh*) for antislosh on straight segments has been added.
- *TrackCalibration*: Calibration of a single segment and of open tracks is now supported.

PackML

- The new function block *FB_UnitModeManager2* is available which facilitates the *UnitMode* handling according to the PackML standard.
- The new function block *FB_StateModelHandlerBase* is available which facilitates the implementation of the control logic for each state of a state model.
- The structures *ST_Status*, *ST_Command*, and *ST_Administration* are updated according to the implementation guide ANSI/ISA TR88.00.02-2022.
- The new visualization *FR_DynStateModel_2022* is available that supports the state model as described in ANSI/ISA TR88.00.02-2022.

Robotic and RoboticModule

Interfaces to support tools and additional components have been integrated.

SchneiderElectricRobotics

The calibration procedure has been improved. A vibration that could occur on the axes during calibration has been removed.

SchneiderElectricRobotics Toolbox

Properties *raetConveyorList*, *raetRobotList*, *raetTargetGeneratorList*, *raetTargetTypeList*, *raetTrackingSystemList* have been added to *IF_EntitiesHandler*.

IrMaxObstacleHeight has been added to *ST_TrackingConstraints*.

For *FB_TargetsHandler*:

- The behavior in case of rollover has been improved.
- *EvaluateSlotTarget()* has been improved.

SnmpManager

The function block *FB_SnmpManager* supports the protocol version v3 with authentication and encryption for exchanged data messages.

The new function block *FB_UserManagement* is provided for storing the user credentials that are used by the *FB_SnmpManager*.

New Features - Examples

Multi Robot Example

The new Multi Robot example implements a pick and place line with a configurable number of delta robots and conveyors. The Multi Robot project is aligned to the graphical RobotCell configuration provided by Smart Template. Configuration adaptations like the number of robots, conveyors or the geometrical arrangement can be performed via Smart Template. The Multi Robot project example supports the SmartVisu functionality in EcoStruxure Machine Expert Twin. The line can be visualized in EcoStruxure Machine Expert Twin instantly by importing it from the controller. Smart Template has been enhanced alongside the Multi Robot project and provides an integrated 3D view of a robot cell to facilitate configuration. Colors can be defined in Smart Template which are reflected in EcoStruxure Machine Expert Twin to ease verification of the configured pick and place process implemented by the Multi Robot example.

PackML Example

The example has been updated to support the new function blocks *FB_UnitModeManager2* and *FB_StateModelHandlerBase* provided by the PackML library.

OPC UA Handling Example

The example is updated to support the device based user management for the visualization. Additionally, it provides a custom login dialog box for the web visualization.

Mitigated Anomalies

ID	Description
DFBOC-1065 / IECLIB-2944	CommonToolbox and PD_PacDriveLib: The return value of <i>FC_LrealToString</i> is now properly rounded.
DFBOC-1381 / IECLIB-16863	PD_MultiBeltModule: If a write to axis encoder was executed on a MultiBelt train in case an error had been detected, it could happen that the error message did not indicate the reason and displayed a general <i>UnexpectedFeedback</i> message instead.
DFBOC-1404 / IECLIB-17092	PD_MultiBeltModule: The home flag of MultiBelt trains was reset on entering the service operation mode. The home flag had to be set inside the service operation mode again.
DFBOC-2097 / IECLIB-24625	PD_MultiBeltModule: It is now possible to trigger a command of type <i>WarmStart</i> to the MultiBelt, when the module before has left operation mode Automatic due to a detected collision error.
DFBOC-2232 / IECLIB-26023	PD_MultiBelt: If the parameter <i>IrTrainDistance</i> of an indexed station was defined differently to the <i>IrTrainDistance</i> parameter of the station ahead and the train movement was blocked by the train ahead, a possible error because of a backward movement of the train is now prevented.
DFBOC-2284 / IECLIB-27617	CrankModule: The visualization has been modified so that all labels (texts) are displayed properly. The moving lines have been replaced by rectangles.
DFBOC-2389 / IECLIB-27320	FileFormatUtility - <i>FB_JsonUtilities</i> : The <i>Select</i> method compares the name of JSON items completely to select the correct item.
DFBOC-2464 / IECLIB-27926	PD_AxisModule: <i>FC_EtDiagExtToString</i> returns the correct string for <i>ET_DiagExt</i> . <i>UserCamHasBeenDeleted</i> .
DFBOC-2502 / IECLIB-28094	PD_PacDriveLib: The function blocks <i>FB_AsciiReader</i> and <i>FB_AsciiWriter</i> abort the execution with a corresponding diagnostic message if the parameter <i>i_dwBufferAdr</i> is not assigned.
DFBOC-2504 / IECLIB-28093	PD_PacDriveLib: The function blocks <i>FB_BinaryReader</i> and <i>FB_BinaryWriter</i> abort the execution with a corresponding diagnostic message if the parameter <i>i_dwBufferAdr</i> is not assigned.
DFBOC-2514 / IECLIB-28135	GMC Independent CANopen: The shift factor is now read after power is enabled for Lexium devices.
DFBOC-2520 / IECLIB-28162 IECLIB-28192	FileFormatUtility: A timeout has been implemented in case the maximum number of file accesses are reached and a meaningful diagnostic message is returned if the timeout occurs.
DFBOC-2526 / IECLIB-28176	Multicarrier: A <i>StopWithEmergencyParameter</i> can no longer be overwritten by another 'normal' <i>Stop</i> command.
DFBOC-2567 / IECLIB-28242	MqttHandling: The disabling process of <i>FB_MqttHandling</i> is not affected by toggling the <i>i_xEnable</i> input and completes the function block clean up correctly.
DFBOC-2589 / IECLIB-28555	Multicarrier Example: WebVisualization now functions as designed.
DFBOC-2626 / IECLIB-29172	GMC Independent CANopen: Mapping regarding positive Limit Switch for drives of type Lexium SD328A now functions as designed.
DFBOC-2650 / IECLIB-30296	SqlRemoteAccess: Processing fragmented messages received from the SQL Gateway is supported.
DFBOC-2693 / IECLIB-30898	PD_PacDriveLib: The output <i>q_xInWsWindow</i> of <i>FB_MultiCam</i> in warm start mode <i>New/StoredCamShowCamPosition</i> is now set according to the other modes.
DFBOC-2694 / IECLIB-30504	Multicarrier: <i>FB_CrashPrevention</i> now functions as designed for disabled and reenabled carriers.
DFBOC-2713 / IECLIB-31268	MqttHandling: A publish message will not have the identifier 0.
DFBOC-2723 / IECLIB-31303	Multicarrier: <i>MoveGapControl</i> functions as designed if <i>CurveCompensation</i> from <i>CarrierInFront</i> is started in the curve.
DFBOC-2743 / IECLIB-27927 IECLIB-28207, IECLIB-28208, IECLIB-28209, IECLIB-28210, IECLIB-28211, IECLIB-28212, IECLIB-30508, IECLIB-31291	CrankModule, PD_GlobalDiagnostics, PD_SoMotionGenerator, PD_PacDriveLib, Unwinder, PD_Template, UserMotorTypePlate and UserTorqueFeedForward: The functions <i>FC_EtDiagToString</i> and <i>FC_EtDiagExtToString</i> provide a meaningful result in case the input <i>i_etDiag</i> or <i>i_etDiagExt</i> is undefined.
IECLIB-2449	PD_MultiBeltModule: The output <i>q_xCrash</i> of the Multibelt interface did not turn TRUE when a collision was detected.
IECLIB-2450	PD_MultiBeltModule: Unnecessary <i>ProductIgnored</i> exception with reaction 4 has been removed. It was triggered only if another exception with <i>errorreaction</i> 1, 2 or 3 was already active.
IECLIB-27139	TcpUdpCommunication: <i>FB_TcpServer/ FB_TcpServer2</i> : When the method <i>Close</i> is called, all clients are disconnected.
IECLIB-27160	XpsuSupport: The tolerance for cycle time verification that caused an intermittent error message on M262 was increased.

ID	Description
IECLIB-27289	CNCExtension: The version of the referenced library PLCopen MC Part1 is compatible with EcoStruxure Machine Expert V2.2.
IECLIB-27377	MotionApplicationFunctionBlocks: The start mode <i>ContinueWithOffsetCurve</i> has been modified. The function blocks <i>FlyingShear</i> and <i>RotaryKnife</i> return an error if the master is inside and the slave outside the synchronous phase.
IECLIB-27583	PD_PacDriveLib: Set correct enumeration value for the output <i>q_etDiagExt</i> if the <i>FB_PropController</i> was disabled (<i>i_xEnable</i> = FALSE).
IECLIB-27619	PD_MultiBeltModule: Meaningful error messages are provided, instead of <i>Unexpected Feedback</i> .
IECLIB-27657	CrankModule Example: The visualization for <i>Crank_left</i> and <i>Crank_right</i> has been aligned with the correct scaling according to the visualization from the library.
IECLIB-28134	MulticarrierStation: - For standard stations and closed tracks, the position checks of wait position and process position now functions as designed for all station positions. - Standard stations now function as designed if the station position is equal to the track length.
IECLIB-28144	PD_SoMotionGenerator: Acceleration and deceleration calculation has been improved if a new positioning command is set during the acceleration and the deceleration phase.
IECLIB-28186	Multicarrier: The method <i>SetExplicitlyLowerJerk</i> reports an error if <i>setJerk</i> > <i>MaxAbsJerkEmergency</i> . The method <i>SetMotionParameter</i> reports an error if <i>setJerk</i> = 0 and if <i>setJerk</i> GCL.IrMinAbsJerk.
IECLIB-28218	Multicarrier: The method <i>SetExplicitlyLowerJerk</i> is applied after the method <i>SetMotionJoggingParameter</i> .
IECLIB-28224	Multicarrier: <i>MoveGapControl</i> : <i>RefMinGap</i> is now considered correctly if two carriers are moving against each other with relative movement.
IECLIB-28522	OpcUaHandling: The legacy version of the library, OpcUaHandling V1.0.13.0, is removed from the delivery.
IECLIB-2855	Multicarrier Example: You can now add a WebVisualization without an error being detected if you enable the option Activate property handling in all element properties in the Project Settings .
IECLIB-30381	CommonPouTypes: The state machine of the function block <i>FB_ExecuteAbort</i> now functions as designed. The method <i>Aborting</i> is called when the function block <i>FB_ExecuteAbort</i> is executed and <i>i_xAbort</i> is already TRUE.
IECLIB-30458	Multicarrier Example: The OPC UA server can be stopped and then writes only one entry about the task monitoring in the Message logger.
IECLIB-30459	Multicarrier Example: The <i>FC_OpcUaSetAccessType</i> is used for OPC UA fast access.
IECLIB-30490	CommonToolbox: Values starting with '0.' are now converted by the function <i>FC_LrealToString</i> .
IECLIB-30505	PD_PacDriveLib: Values starting with '0.' are now converted correctly by the function <i>FC_LrealToString</i> .
IECLIB-30507	PD_SmartInfeedModule: The function <i>FC_EtDiagExtToString</i> supports conversion of <i>ET_DiagExt</i> , <i>MotionActiveVelLimitRange</i> , <i>ET_DiagExt.SensorOutInvalid</i> , <i>ET_DiagExt.AddSensorOutInvalid</i> , and <i>ET_DiagExt.TargetSensorOutInvalid</i> to String.
IECLIB-30509	PD_MultiBelt: The function <i>FC_EtDiagExtToString</i> supports the conversion of <i>ET_DiagExt</i> , <i>MoveOutOfCrashDistanceNotPossible</i> to String.
IECLIB-30659	TcpUdpCommunication - <i>FB_TcpServer</i> / <i>FB_TcpServer2</i> : The socket option <i>ReuseAddress</i> functions as designed. Precondition is that the option is set before the server is open.
IECLIB-31264	TcpUdpCommunication: The TLS protocol version 1.1 is discontinued due to cybersecurity reasons. An appropriate diagnostic result is returned by the TCP server and client.
IECLIB-31275	Multicarrier: <i>TrackCalibration.StartCalibration</i> no longer reports a <i>SercosWriteError</i> in case of virtual segments.
IECLIB-31316	Multicarrier Example - OPC UA server: The firewall is active and only the OPC UA port is open.
METWIN-1726	DigitalTwinCommunication: The default value of <i>udiTimeoutTwin</i> for SmartVisu has been changed from 100 to 1000.
SSP50-10163	SlcRemoteController: The memory key commands <i>CopySafeKeyStart</i> and <i>CopySafeKeyContinue</i> could not be executed via the SlcRemoteController library if used with the TM5CSLC300FS/400FS.

Software Information V2.2

Software Information

Version Identification

Description	Version
Schneider Electric Software Installer	22.23.33501
EcoStruxure Machine Expert Twin	2.0.0.0
Diagnostics	22.0.6.0
Controller Assistant	22.0.11.0
Device Assistant	22.0.5.0
DiffViewer	22.0.15.0
Gateway	22.0.0.0
Launcher	22.0.15.0
NetManage Server	22.0.6.0
OPCServer	3.5.19.40
SVN	4.4.0.0
Logic Builder ⁽¹⁾	2.2.0.0
Vijeo-Designer	6.3.0.1007
Codesys	V3.5 SP19 Patch4 HF1
SQL Gateway	2.2.0.0
Motion Sizer	4.3.2.0
(1) If you are using a virtual machine, the download of the online help operates correctly only if the option Accelerate 3D graphics is deactivated in the VM settings.	

Version Identification of DTMs

Description	Version
Advantys OTB	11.1.0.0
ATV320	1.4.1.0
ATV340	3.2.3.0
ATV6xx	3.3.1.0
ATV9xx	3.3.3.0
Harmony XB5R	1.0.41
Lexium 28 A	1.6.8.0
Lexium 28 S	1.6.13.0
Lexium 32 A	1.20.402
Lexium 32 C	1.20.402
Lexium 32 i	1.20.402
Lexium 32 M-S	1.20.402
Modbus Serial Communication	2.6.12
Modbus TCP Communication	2.6.12
TeSys island	2.2.1.0
TeSysT	2.14.1.0
TeSysU	2.8.0.0
TM5-7 CANopen Interface	1.1.8
TM5-7 Expansion Module	1.1.8

Version Identification of SQL Server

Description	Version
MySQL	8.0.30 - Workbench 8.0
Oracle	- Oracle Database 18c Express Edition Release 18 – Version: 18.4.0.0.0 - SQL Plus – 18.4.0.0.0 - OracleXE213_Win64 (21c) sqldeveloper-22.2.0.173.2018-x64
MS SQL Server	- MS SQL Server 2019 Express/ 15.0.2101.7 (x64) - SQL Management Studio 18.12.1
SQLite	- Sqlite3 - 3.37.2 - sqlite-tools-win32-x86-3.39.02.00

New Features EcoStruxure Machine Expert

Project Menu

Two new commands have been added to the **Project** menu:

- **Direct Address Summary:** Displays a list of connected controllers where direct addresses are configured.
- **Remove any Direct Address set:** Allows you to remove the direct addresses configured for the selected device and the related subdevices.

CODESYS Git

CODESYS Git from the CODESYS store is now supported by the Schneider Electric Software Installer. EcoStruxure Machine Expert is now able to directly store source code in a Git repository (local or global).

Motion Sizer

The Motion Sizer contains an updated motor database for SH3 motors. The torque and current values have changed significantly to become more realistic.

With this update it can happen that motor-drive-combinations that were valid in previous versions are now reported as invalid. This can be the case especially for motor-drive-combinations that were close to the limits of the product bundle.

SH3070 motors that were used in earlier versions of Motion Sizer can now become unassigned due to new reference numbers which now include the encoder type instead of the placeholder that was used in previous versions. In that case, select the motor after a recalculation and reassign it to the axis.

Compared diagrams are specified.

AutoScale is available for complete display of diagrams.

Two buttons have been added to collapse and expand the tree structure.

General Improvement

- **CFC**
 - Space optimization by displaying variable names without prefix in input / output assignments
 - Dark theme
 - Re-arrangement of pins in FFB boxes by drag and drop
- **Library Manager**
 - All CODESYS libraries are now signed
 - **Summary** button to display all libraries referencing a specific library
 - Reworked **Parameter List** (new central editor for edition of all parameters; export / import / reset)
- **Project Compare**
 - Allow comparison of two arbitrary objects
 - Additional third window available for improved merging; possibility to edit modifications in the text
- **Watch list**
 - Allows a structured display of inherited variables of a function block.

- Datatypes
 - Support of LDATE, LTOD, LDT, LTIME within visualization, alarm management, recipe management
- ST
 - Specific display of non-compiled code (depending on "defined" pragma)
- SVN
 - Improved online help for SVN Python scripting
- IEC
 - UTF-8 support for STRINGS (using compiler setting)
 - VAR_GENERIC_CONSTANT (customizable function blocks by using constant declaration)
 - Partial access to bit fields (for example, "variable.%B0" or ".%W1",...)
- Device user management
 - Accessible from the IEC application (by using the CmpUserMgr library)
- Visualization
 - XYChart element: displays localized texts for axis labeling
 - Trend element: simplified configuration
 - New *OnValueChanged* event in several visual elements
 - Configuration of maximum visualization clients
 - Tabs element: dynamic visibility of tabs by using IEC variable
 - New format specifier for display of date / time including time zone / offset or UTC
 - Possibility to localize **Login** dialog box
- **Import PLCOpen XML**
 - Configurable conflict handling for imported items (replace, rename, skip)
- **Communication settings**
 - **Device Security Settings** dialog box with list of device settings
- **Code Analysis** metrics
 - Go to cross reference for instances of **Code Analysis** metrics
 - Function blocks (and other) instances from libraries to be listed for **Code Analysis** metrics
 - Number of FC calls for Code Analysis metrics
- Switching visualization text input type during runtime

New Features EcoStruxure Machine Expert - Safety

Starting EcoStruxure Machine Expert - Safety V2.2, in addition to the legacy BWU2984 ASi-3 gateway, the new generation of compatible ASi-5/ASi-3 gateways of Bihl & Wiedemann (B+W) are supported in the LMCx architectures and related EcoStruxure Machine Expert engineering software.

In addition, this release provides:

- Windows 11 compatibility support
- Updated EcoStruxure Machine Expert - Safety offline/online help (such as ASi Integration Guide)
- Cybersecurity and quality improvements

For further information about the new system features, refer to the updated hardware and software documentation.

For additional Bihl & Wiedemann (B+W) information on Schneider Electric-compatible ASi-Gateways refer to [Schneider Electric Drives - Bihl+Wiedemann GmbH](#) (bihl-wiedemann.de).

Compatibility EcoStruxure Machine Expert - Safety

Project Updates

ASi-5/ASi-3 Generic Gateway / Legacy ASi-3 BWU2984

Existing projects that use the legacy ASi-3 BWU2984 gateway of Bihl & Wiedemann (B+W) can be used after project update in EcoStruxure Machine Expert V2.2 without modification. Legacy implementation and behavior has not been modified.

The new supported ASi-5/ASi-3 generic gateway BWUASI5ASI3 (for example, BWU3861) is integrated in general in the same way as the legacy BWU2984. The major difference is the extension of the safe data interface from 8 Byte to 12 Byte capacity due to enhanced ASi-5 capabilities. This allows for migration of existing legacy applications to this new generation of Sercos safety ASi-5/ASi-3 compatible gateways. However, the ASi-5/ASi-3 gateway devices are only supported by TM5CSLC300FS / TM5CSLC400FS system architectures. Migrate to the latest safety-related controllers, that were launched with EcoStruxure Machine Expert V2.1, to use these gateways and adjust and test their applications according the safety-related process.

Overview of the validated EcoStruxure Machine Expert - Safety version with the appropriate safety-related firmware.

Device	Safety-related firmware version for EcoStruxure Machine Expert - Safety version								
	1.1 / 1.2	1.2.2	2.0	2.0.1	2.0.2 / 2.0.3	2.1 / 2.1.x		2.2	
						SLCv1	SLCv2	SLCv1	SLCv2
TM5CSLC100FS	2.52	2.53	2.56	2.57	2.58	2.59	-	2.59	-
TM5CSLC200FS	2.52	2.53	2.56	2.57	2.58	2.59	-	2.59	-
TM5CSLC300FS	-	-	-	-	-	-	3.05	-	3.07
TM5CSLC400FS	-	-	-	-	-	-	3.05	-	3.07
TM5SAI4AFS	322	322	322	322	322	322	334	322	334
TM5SDC1FS	302	302	302	302	302	302	335	302	335
TM5SDI20DFS	305	305	305	305	305	305	333	305	333
TM5SDI2DFS	305	305	305	305	305	305	333	305	333
TM5SDI4DFS	305	305	305	305	305	305	333	305	333
TM5SDM4DTRFS	305	305	305	305	305	305	333	305	333
TM5SDM8TBFS	305	305	305	305	305	305	333	305	333
TM5SDO2DTRFS	300	300	300	300	300	300	333	300	333
TM5SDO2TAFS	280	280	280	280	280	280	333	280	333
TM5SDO2TFS	280	280	280	280	280	280	333	280	333
TM5SDO4TAFS	280	280	280	280	280	280	333	280	333
TM5SDO4TFS	280	280	280	280	280	280	333	280	333
TM5SDO6TBFS	295	295	295	295	295	295	333	295	333
TM5SPS10FS	320	320	332	332	332	332	333	332	333
TM5STI4ATCFS	322	322	322	322	322	322	334	322	334
TM7SDI8DFS	305	305	305	305	305	305	333	305	333
TM7SDM12DTFS	305	305	305	305	305	305	333	305	333

Mitigated Anomalies

EcoStruxure Machine Expert

ID	Description
CVE-2022-4046, CVE-2022-47378, CVE-2022-47379, CVE-2022-47380, CVE-2022-47381, CVE-2022-47382, CVE-2022-47383, CVE-2022-47384, CVE-2022-47385, CVE-2022-47386, CVE-2022-47387, CVE-2022-47388, CVE-2022-47389, CVE-2022-47390, CVE-2022-47391, CVE-2022-47392, CVE-2022-47393, CVE-2023-28355, CVE-2023-3662, CVE-2023-3663, CVE-2023-3669, CVE-2023-3670, CVE-2023-37545, CVE-2023-37546, CVE-2023-37547, CVE-2023-37548, CVE-2023-37549, CVE-2023-37550, CVE-2023-37551, CVE-2023-37552, CVE-2023-37553, CVE-2023-37554, CVE-2023-37555, CVE-2023-37556, CVE-2023-37557, CVE-2023-37558, CVE-2023-37559	Specific cybersecurity vulnerabilities are mitigated.
DFBOC-2718 / DFSI-20189	Project update was unsuccessful for SVN projects without connection to the server.
DFBOC-2635 / DFSI-19760	PD_PacDriveLib error messages in the user library were not removable.

ID	Description
DFBOC-1061 / CDSYS-557	Replace all function only renamed the first object found in the selection of an CFC (Continuous Function Chart).
DFBOC-1233 / CDSYS-751	Direct addresses of variables in the symbol configuration export file were incorrect.
DFBOC-1238 / CDSYS-858	The display of the I/O mapping for EDS files was not refreshed correctly.
DFBOC-1239 / CDSYS-753	The compiler did not display the compiler error message <i>C0224 Call Recursion: SR_Recursive -> SR_Recursive</i> for programs called within methods or actions. For compatibility reasons, recursive calls are now issued as compiler alert messages.
DFBOC-1307 / CDSYS-800	Time base axis of Trace in offline mode was set to hours if resolution μ s was selected.
DFBOC-1343 / CDSYS-845	Watch view: An incorrect icon was displayed for function block properties during smart coding.
DFBOC-1350 / CDSYS-854	Incorrect behavior when extending a library function block method containing an input of type Array with maximum size defined by a library constant.
DFBOC-1367 / CDSYS-868	The Input Assistant started with the focus on the Categories tab.
DFBOC-1446 / CDSYS-1051	Opening the tree inside the Library Manager led to a resize of the EcoStruxure Machine Expert window when the DPI setting of the screen was not set to 100%.
DFBOC-1521 / CDSYS-943	If you used a generic EDS (Electronic Data Sheet) for an EtherNet/IP device, the connection was changed to the default connection when you selected another tab of the same device or you selected another device.
DFBOC-1532 / CDSYS-948	Integrated visualization: Modifications on the property <i>Absolute Movement</i> had no effect on the visualization element Line .
DFBOC-1542 / CDSYS-951	Monitoring of expression results within a POU implemented LD or FBD language were unavailable.
DFBOC-1563 / CDSYS-964	Smart Coding: A variable was prefixed with the GVL name, even if the GVL did not contain the pragma <code>{attribute 'qualified_only'}</code> .
DFBOC-1571 / CDSYS-967	The <code>EnumType</code> led to compilation errors when using such a variable in <code>Var PERSISTENT RETAIN</code> and executing the Add all Instance Paths command.
DFBOC-1626 / CDSYS-988	An SFC jump in a macro of an SFC POU caused an exception when opening the SFC editor for a special Sequential Function Chart.
DFBOC-1650 / CDSYS-1011	The Input Assistant did not display an instance for the method call in the FBD editor.
DFBOC-1659 / CDSYS-1022	The property <i>invisible</i> of the visualization element Meter did not operate correctly.
DFBOC-1713 / CDSYS-1046	LD editor: Copy and paste operations of box elements onto horizontal links of parallel branches did not lead to the desired result.
DFBOC-1744 / CDSYS-1069	If a connection between two blocks in CFC had been linked to <code>EN</code> of the second block, you could not delete the line by clicking on the line itself to select it.
DFBOC-1804 / CDSYS-1107	The compiler error <i>Identifier 'genvInput' not defined</i> was detected when a dialog box was opened from a table in a web visualization.
DFBOC-1848 / CDSYS-1121	A misleading precompile error C0201 was displayed when a project was opened in a new EcoStruxure Machine Expert instance. (Use case: An array is based on a GPL (Global Parameter List) constant and is connected to a <code>VAR_IN_OUT</code> of a function block.) The precompile error disappeared after a Build .
DFBOC-1849 / CDSYS-1122	A direct address could be modified with the command Find & Replace .
DFBOC-1863 / CDSYS-1124	An issue occurred with SVN when using Save current values to recipe in the Persistent Variables editor.
DFBOC-1865 / CDSYS-1125	The display issues in the German version of the Trace configuration no longer exist.
DFBOC-1894 / CDSYS-1140	An unexpected precompile error was detected while defining an array area with constants from an enumeration.
DFBOC-1907 / CDSYS-1146	The cursor position was lost in the Project comparison view after committing accepted changes.
DFBOC-1949 / CDSYS-1154	With some projects, the flow control did not operate correctly.
DFBOC-1977 / CDSYS-1157	The LD editor drawing was incomplete (incomplete horizontal link) due to the variable length.
DFBOC-1978 / CDSYS-1158	After a contact placed in a complex LD network after a closed parallel branch had been deleted, the network could no longer be displayed.
DFBOC-1979 / CDSYS-812	SmartCoding: The namespace of a variable was added in FBD/LD editors even so the corresponding option had been deactivated.

ID	Description
DFBOC-1994 / CDSYS-1166	The visualization was set to offline mode if the cursor had been moved to a specific button in the visualization.
DFBOC-2049 / CDSYS-1184	Visualizations referenced from a library were not found.
DFBOC-2080 / CDSYS-1187	Using an XYChart in a visualization led to error messages.
DFBOC-2081 / CDSYS-1188	It was not possible to save recipes containing REAL, LREAL variables without having provided a value for the variables.
DFBOC-2094 / CDSYS-1191	Modified variable names (Chinese) of I/O Mapping became " _".
DFBOC-2095 / CDSYS-1190	The function XSIZEOF could not be used in FBD (Function Block Diagram).
DFBOC-2106 / CDSYS-1195	Differences were displayed in the Project Compare tree for CFC POU's with Auto Data Flow Mode activated although no differences existed.
DFBOC-2136 / CDSYS-1015	Compile errors related to the usage of the library IoDrvModbusSerial were generated after a Convert device from TM241CEC24T to TM241CEC24R had been performed.
DFBOC-2142 / CDSYS-1211	Recipe Manager : An element of a STRUCT declared as an ENUM type that came from a library could not be added to a recipe definition.
DFBOC-2150 / DFSI-17458	Integrity verification was displayed when <i>VisualStudio.Diagnostics.ServiceModelSink.dll</i> was detected.
DFBOC-2163 / CDSYS-1225	Adding modules to a Profinet device took a long time.
DFBOC-2164 / CDSYS-1226	Changing the communication parameters of a Profinet device could take several seconds.
DFBOC-2170 / DFSI-17417	Adding a Profinet device for the first time could take several seconds in case of a large device repository after the installation of many third-party devices.
DFBOC-2185 / CDSYS-1232	It was not possible to add methods from several unit conversion function blocks to CFC or FBD/LD by using the Input Assistant .
DFBOC-2197 / CDSYS-1237	Differences were displayed in the Project Compare tree for CFC POU's and Visualization Manager although no differences existed.
DFBOC-2204 / DFPLAT-2324	A space character was missing in the Build menu (PostConfiguration).
DFBOC-2206 / CDSYS-1245	In the German user interface, some strings were truncated in the Search and Project Compare dialog boxes when specific DPI screen settings had been set.
DFBOC-2235 / DFSI-17845	Compiler error C0136 <i>Ambiguous use of name</i> was generated when adding a CAM diagram named <i>BravoModule</i> if a corresponding POU with the name <i>SR_BravoModule</i> existed (as in the template project).
DFBOC-2239 / CDSYS-1259	The Import PLCOpenXML... command no longer allows importing a Sercos module from another parent device when executed from the main menu.
DFBOC-2240 / DFSI-17844	Controller Assistant: Downgrading PacDrive LMC firmware from V2.0.* to V1.2 could lead to incorrect timing.
DFBOC-2250 / DFPLAT-2368	Using a CONSTANT as upper bound of arrays in NVL (Network Variable Lists) led to the exception <i>Could not find any recognizable digits</i> .
DFBOC-2251 / CDSYS-1266	Modifying SDO parameters and switching to other editors could take several seconds.
DFBOC-2265 / CDSYS-1270	The Visualization dialog box did not display correctly (without background color) depending on the position configured.
DFBOC-2266 / CDSYS-1269	The Visualization was not displayed due to automatic font size reduction and anisotropic scaling (settings in the Visualization Manager).
DFBOC-2267 / DFSI-17877	The example in the online help for compiler defines was incorrect.
DFBOC-2282 / CDSYS-1252	The IO-Link Parameter tab saved an incorrect parameter value to the project.
DFBOC-2290 / CDSYS-1279	Since library version 3.5.16.0, the method <i>RecipeManCommands.GetRecipeValues</i> returned only one value of the request.
DFBOC-2294 / CDSYS-1280	An issue was detected with the EcoStruxure Machine Expert find functionality online (for large GVLs).
DFBOC-2296 / DFSI-18273	ModbusTCP_Slave is now part of the chapter <i>Libraries Overview</i> in the online help.
DFBOC-2304 / CDSYS-1284	Incorrect execution of LD logic - FB (inside of nested parallel branches) was executed even if the resulting condition had been FALSE.
DFBOC-2309 / DFSI-18300	Diagnostics: Parameters for PacDriveM controller were incorrectly displayed.
DFBOC-2318 / CDSYS-1286	Implicit LRange checks now function as designed.

ID	Description
DFBOC-2320 / CDSYS-1250	Trace editor: A variable/parameter name was overlapping trace cursor values (depending on the column sizes configured in the Trace tree).
DFBOC-2328 / SSP50-9075	EcoStruxure Machine Expert - Safety - About dialog box: A permanent instead of a temporary license was displayed.
DFBOC-2333 / CDSYS-781	An unhandled exception was detected while canceling a connection credentials dialog box in a complex use case.
DFBOC-2337 / DFSI-18369	External tools: New configured tools disappeared after closing/opening EcoStruxure Machine Expert.
DFBOC-2347 / CDSYS-1294	An unhandled exception EcoStruxure Machine Expert occurred during login to a controller in exception when the Call Stack view was opened.
DFBOC-2352 / DFSI-18414	The list of attribute pragmas was incomplete in the online help.
DFBOC-2365 / CDSYS-1301	The <code>Region</code> pragma cursor was indented further to the right after each time Enter was pressed.
DFBOC-2366 / DFSI-18465	Validity Note in the online help was not consistent for Device Assistant.
DFBOC-2369 / DFPLAT-9809	M2xx compile error message was displayed due to incomplete addressing <code>%I*</code> .
DFBOC-2382 / CDSYS-1305	The German names of the buttons at the IO-link Parameter tab were not displayed correctly.
DFBOC-2384 / DFSI-18513	The temporary file <code>-dialogowner</code> was not deleted after executing the command Create Image and Transfer it to the Controller .
DFBOC-2385 / CDSYS-1306	Floating point format definition did not function for Combo Box in the visualization.
DFBOC-2401 / DFSI-18899	Dependent on the selection in the Devices tree , a POU with incorrect content was generated while adding POUs for implicit check by using Python script.
DFBOC-2412 / CDSYS-1314	The online values of the IO-Link Parameter tab were not displayed in italic font after selecting Restore values .
DFBOC-2414 / SSP50-10750	After deleting all Sercos devices, the projects became corrupt.
DFBOC-2422 / CDSYS-1320	In the SFC editor, an unintended change of a transition name occurred (while clicking in the SFC editor and switching to other editors).
DFBOC-2423 / CDSYS-1321	Project compare with SFC-POU: Hidden differences in the properties of a transition led to an exception in the Logic Builder.
DFBOC-2424 / CDSYS-1322	Modification of the EtherCat configuration led to compile and/or precompile errors being detected.
DFBOC-2439 / CDSYS-1327	Versions of sublibraries were updated together with the top-level library when the version of the latter was modified in the Placeholders dialog box of the Library Manager .
DFBOC-2449 / DFSI-18915	It was not possible to create and transfer images to the controller after repair of an installation.
DFBOC-2457 / DFSI-18983	It was not possible to change the device (node) name when EcoStruxure Machine Expert or Controller Assistant had been started with administrator rights.
DFBOC-2459 / DFSI-18984	Online help: The description for the property Placeholder (project information) was not available.
DFBOC-2472 / DFSI-18986	Not all example projects for PacDrive were installed by the Schneider Electric Software Installer.
DFBOC-2475 / DFSI-18981	Application Logger: Changing the log level did not function as designed in tree view mode for <i>RobotConfiguration</i> or <i>RoboticRtp</i> .
DFBOC-2486 / CDSYS-1355	<i>SoftMotion</i> library: The function block <code>SMC_Trafo_Tripod_Arm</code> did not provide <i>dA</i> , <i>dB</i> , <i>dC</i> output values when the Z-axis coordinates were given.
DFBOC-2490 / DFSI-19025	Updating the Schneider Electric Software Installer led to issues while trying to customize a previously installed EcoStruxure Machine Expert version.
DFBOC-2493 / DFSI-19051	A silent Installation of EcoStruxure Machine Expert ServiceTools was not possible due to integrity check messages. NOTE: Silent installation is not possible when using the parameter <code>"-help"</code> .
DFBOC-2521 / MSOLSW-3553	Intermediate certificates were unavailable when installing EcoStruxure Machine Expert Tools using the Schneider Electric Software Installer.

ID	Description
DFBOC-2525 / CDSYS-1369	The Logic Builder reported an exception when Blink LED was executed in the Profinet Scan Devices window.
DFBOC-2528 / CDSYS-1368	NVL Variables of extended types were not transmitted.
DFBOC-2540 / DFSI-19144	A project update of libraries caused drives to be locked in SVN.
DFBOC-2554 / DFSI-19170	An error message was displayed when the Device Addressing tab was opened.
DFBOC-2568 / DFSI-19292	The SQL Gateway service status was not correctly displayed by the icon.
DFBOC-2575 / DFSI-19506	The Device Assistant did not translate the type number of the TM5SE4IOL.
DFBOC-2580 / DFSI-19498	The Communication Settings page did not indicate whether a controller supports encrypted communication.
DFBOC-2608 / CDSYS-1431	It was impossible to move variables in the Trace tree view when the trace had been created with SoMachine Motion.
DFBOC-2611 / CDSYS-1423	Synchronization between diagrams (in the graphic view) and variables (in the tree view) was not correct when some of the diagrams / variables were selected as invisible.
DFBOC-2622 / DFSI-19681	The cursor in the cam diagram did not display any values.
DFBOC-2696 / CDSYS-1522	A build-time error was detected and the message <i>Memory corrupted!</i> was displayed (in case of a modification of an initial value in a DUT, used widely in a project).
DFBOC-34 / DFSI-5600	The link to the DHCP server configuration did not work for Modbus TCP devices.
DFBOC-468 / CDSYS-291	No compiler error was displayed for duplicate IO mapping.
DFBOC-513 / CDSYS-54	In the CAM editor the tappet values could be modified in the table. Using this method the value was limited to the <i>SlaveEndPosition</i> which was incorrect.
DFBOC-545 / CDSYS-152	If variables from a library had been declared inside the Global Variable List, errors could occur while compiling the project. The invalid syntax is now reported by the compiler. If the GVL contains no other valid declarations which are referenced in the project, then the detected errors are only reported in precompile.
DFBOC-847 / CDSYS-458	Documentation for CloseDialog2 is now available.
DFBOC-932 / CDSYS-500	The use of an AT declaration for a 32 bit variable (for example, DWORD) inside a Struct, led to an error from the equal check.
DFBOC-945 / CDSYS-870	The Trace editor buffer size for device trace could not be modified. The trace recording time was limited to 01h 11min.
DFPLAT-1947	The import and export mapping as .csv (comma-separated values) file now uses the list separator from the regional settings.
DFPLAT-2368	An Array defined with a non-immediate value as lower or upper limit led to a compilation error.
DFPLAT-9809	Using incomplete addressing variables led to a compilation error.
DFPLAT-10134	Using <i>Write Single Coil</i> on a Modbus Serial IOScanner could lead to a controller exception.

EcoStruxure Machine Expert - Safety

ID	Description
DFBOC-2222 / SSP50-10529	EcoStruxure Machine Expert - Safety did not operate with offline licenses retrieved from the Floating License Server.
DFBOC-2447 / DFSI-18914	Invalid configuration files were detected after a Repair of an installation.

Motion Sizer

ID	Description
DFBOC-1896 / DFMS-2198	Result (Axis) view: Invalid gearbox values were not marked in red.
DFBOC-1991 / DFMS-2201	The Result (Axis) view was not updated after the motion profile had been changed.
DFBOC-2074 / DFMS-2185	The torque for Neugart PLN190 gearbox is now calculated correctly.
DFBOC-2083 / DFMS-2203	Small values were rounded in the Motion Sizer result page.
DFBOC-2092 / DFMS-2205	The LXM28-BCH2 torque-speed curve differed between Motion Sizer and the user guide.
DFBOC-2256 / DFMS-2210	Diagrams were cut in the Motion Sizer PDF print-out.
DFBOC-2405 / DFMS-2230	The units for motion limits were incorrect.
DFBOC-2551 / DFMS-2256	The MH3 - LXM62 combination was not available.
DFBOC-2563 / DFMS-2257	Kinetic friction appeared in standstill.
DFBOC-2616 / DFMS-2262	Motion Sizer lost crank values when switching the motion profile.
DFBOC-2692 / DFMS-2268	The project could not be opened after assigning a LXM32D18M2 and a LXM32U45M2 to the same power circuit.
DFBOC-2699 / DFMS-2282	In the diagram comparison, the diagram name was not visible.
DFBOC-620 / DFMS-1942	SH3 140 motors were not provided in the motor database.
DFBOC-783 / DFMS-2219	Motion Sizer online help: The <i>Load Diagrams</i> chapter has been updated regarding torque calculation.

Known Operational Anomalies

EcoStruxure Machine Expert

ID	Description
CDSYS-1507	Compile errors about the image pool (unknown type) are detected in combination with the Robotic library in the global (pool) Library Manager and a web visualization for a PacDrive application. Workaround: Manually adjust the CommonMotion resolution from CommonMotionPcrt to CommonMotionPacDrive via the Placeholders dialog box of the global Library Manager .
DFBOC-2239 / CDSYS-1511	The Import PLCopenXML... command allows importing a Sercos module from another parent device which should not be allowed when executed from the contextual menu.
DFBOC-2269 / CDSYS-1272	An incorrect alert message is displayed when you click the initialization value of a complex variable.
DFBOC-2293 / DFPLAT-4485	An SFC online change is not possible in combination with an HMI.
DFBOC-2334 / CDSYS-1287	An error is detected while importing users and groups when the filename contains German special characters (umlauts).
DFBOC-2345 / CDSYS-1293	<i>OPCConfig.exe</i> : User and password are not saved in the .ini file , when the .ini file is from a previous installation. Workaround: Re-enter the user name and password and re-save the file.
DFBOC-2364 / CDSYS-1300	Smart coding does not function as designed for the namespace of libraries when these are shadowed by identically named enumeration values. Workaround: Rename the conflicting enumeration value or the library namespace.
DFBOC-2368 / CDSYS-1309	<i>MaxStackSize</i> is not verified for ETEST objects.
DFBOC-2427 / CDSYS-1323	A delay occurs in very large enumeration declarations if the option Highlight symbols is activated in the Tools > Options > Smart Coding dialog box.
DFBOC-2539 / CDSYS-1380	The SVN commit window displays the locked files of other users.
DFBOC-2647 / CDSYS-1448	Variables are deleted from the Symbol Configuration when the types of these variables are adjusted in the Symbol Configuration .
DFBOC-2673 / DFSI-19897	EcoStruxure Machine Expert does not renew a route to a DTM device when the IP address of the controller has changed.
DFBOC-2686 / CDSYS-1495	An incorrect behavior occurs when executing methods without I/O in Ladder Diagram.
DFBOC-2700 / CDSYS-1505	The Find command does not function on enumerations with text list support.
DFBOC-2719 / CDSYS-1516	The OPC DA server randomly stops operating.

EcoStruxure Machine Expert Twin

ID	Description
DFBOC-2321 / METWIN-1139	EcoStruxure Machine Expert Twin does not accept a floating license.
DFBOC-2353 / METWIN-924	Auto Connect does not function as designed in EcoStruxure Machine Expert Twin for OPC UA connections.

Motion Sizer

ID	Description
DFBOC-2697 / DFMS-2281	Incorrect marking in the Torque over Time diagram.

Additional Information

Cybersecurity Best Practices

Schneider Electric has incorporated cybersecurity best practices and solutions in our products.

NOTE:

To help keep your Schneider Electric products secure and protected, it is in your best interest that you implement the cybersecurity best practices as indicated in the following documents:

- *Cybersecurity Best Practices* provided on the [Schneider Electric website](#)
- Cybersecurity Guidelines for EcoStruxure Machine Expert, Modicon and PacDrive Controllers and Associated Equipment - EIO0000004242

Updating Projects (Libraries)

- A library profile is no longer considered.
 - The libraries become unbound placeholders.
 - It takes the latest available version of a library.
- Manually set placeholder resolutions will be updated by the project to the most recent library version if the manually set (old) library version is not installed.

DTM Connection With TMSES4 Module

In some scenarios, depending on the configuration of your local network interfaces, the mechanism to set the route to the device using the TMSES4 module does not function properly. You can verify the resulting route settings by executing the `route print` command in the Windows console. The gateway entry of the device IP you attempt to connect should point to the TMSES4 IP address with a local interface that is able to reach the TMSES4.

In case of permanent connection issues, try to connect to the controller directly.

TLS Versions

Starting with EcoStruxure Machine Expert V2.2, due to the lack of support for present cryptographic algorithms and mechanisms, the TLS (Transport Layer Security) versions prior V1.2 are not supported.

Release Notes History

EcoStruxure Machine Expert V1.1

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M241	5.0.7.20
M251	5.0.7.20
M262	5.0.2.1
TMSES4	1.0.0.8
TM3BCEIP	1.2.1.1
TM3•HSC202•	2.0
TM3DI16	2.0
TM3DI16G	2.0
TM3DI16K	2.0
TM5NS31	2.74
LXM32S•••M2 drive	1.06.03
LXM32S•••M2 Sercos	1.08.04
LXM32S•••N4 drive	1.06.03
LXM32S•••N4 Sercos	1.08.04
LXM52••••C••••	1.54.26.0
ILM••••••••••	1.54.26.0
LXM62••••C••••	• 1.60.0.0 for hardware revision RS1• • 1.54.27.0 for hardware revision RS0•
LXM62••••D••••	• 1.60.0.0 for hardware revision RS1• • 1.54.27.0 for hardware revision RS0•
LXM62••••E••••	1.54.27.0
LXM62••••F••••	1.54.27.0
LXM62••••G••••	1.60.1.0
LMC Eco	1.60.3.3
LMC Pro	1.60.3.3
LMC Pro2	1.60.3.3

Description	Safety-Related Firmware Version
LXM62••••E••••	1.2.4.0
LXM62••~F••~•	1.2.4.0
VW3E702200000 safety option module	1.2.4.0
TM5CSLC100FS	2.52
TM5CSLC200FS	2.52
BWU2984 SWID	134253
BWU2984 Safe CPU A	135115
BWU2984 Safe CPU B	135116
ASIMON360	3.2.6.7

Safety-Related Products

Additional information on the Safety Option Module VW3E702200000 for Lexium 62 ILM:

Lexium ILM070, ILM100 and ILM140 motors must have a certain hardware revision of the electronic unit and a new FPGA (field-programmable gate array) to be compatible with the Safety Option Module for Lexium 62 ILM.

The new revision is included in Lexium ILM motors with the following S/N and DOM:

- ILM070: S/N $\geq$ 2506064503 (DOM $\geq$ 11.09.2015)
- ILM100: S/N $\geq$ 2506058831 (DOM $\geq$ 18.08.2015)
- ILM140: S/N $\geq$ 2506059644 (DOM $\geq$ 21.08.2015)
- New FPGA version: CB0013_D010_0109_00_04

When using earlier versions of the Lexium ILM, the Safety Option Module is not recognized, and the drive does not start.

For PacDrive architectures the AS-i/Sercos III Safety Gateway BWU2984 is integrated. For more information, refer to the AS-i/Sercos III Safety Gateway BWU2984 for Embedded Safety System - Bihl+Wiedemann Integration Guide.

Performance and System Limitations of New TM5CSLC•00FS Firmware Version

The new TM5CSLC•00FS firmware version delivered with EcoStruxure Machine Expert V1.1 has some performance improvements in relation to previous TM5CSLC•00FS firmware versions.

The total number of safety axis and safety I/Os in a system depends on several factors such as, for example, Sercos cycle time, activated/simulated devices, configured devices in the architecture, and local device configurations using additional IDNs, local I/Os on drives, etc. When the system limit is reached, a C1D C30F 0109 hex is triggered.

The supported axis in a system running on the edge of device limitations can vary between boot up by ± 1 . Therefore, it is a good practice to stay two axis away from the detected system limit.

For more information on performance refer to System Limitations (see Embedded Safety for M262, Integration Guide).

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

New Features

M241/M251

- Support of CoDeSys V3.5 SP12
- Default login/password changed when user rights are not activated.
- User right management adapted to CoDeSys V3.5 SP12
- Support of TM3BCEIP TM3 EtherNet/IP bus coupler for distributed I/O architectures
- Behavior of outputs in STOP mode: default value applies after application download, controller power cycle, reset cold/warm
- Behavior of outputs during the transitions from RUN to STOP, and from RUN to EXCEPTION also sets default output values
- Support of TM3DI16/G and TM3DI16K renewal modules (latch and filter functions are only configurable with modules of software version 2 or greater).

- Support of `FC_GetFreeDiskSpace`, `FC_GetLabel`, `FC_GetTotalDiskSpace`
- Extended Motion Function Blocks to allow the configuration of 4 *JerkRatio* parameter settings.

M262

Modicon M262 Logic/Motion Controller offer is made for performance - demanding machines.

- M262 controllers are ready for IIoT, (MQTT, AMQP, OPC UA, TLS,...) and combine logic, motion and safety-related control applications:
 - TM262L: for the logic control of multiple input and output configurations
 - TM262M: for the motion control of up to 16 synchronized axes
In combination with a TM5CSLC•00FS for safety-related control applications up to SIL3.
- Modicon M262 Logic/Motion Controller embed 4 fast digital inputs and 4 fast digital outputs, connected to the controller with the use of screw terminals on the front face of controllers.
- Modicon M262 Logic/Motion Controllers (TM262M•••) embed an encoder input (SSI or incremental).
- Modicon M262 Logic/Motion Controllers can be combined with Modicon TM3, Modicon TM5, and Modicon TM7 offers using Sercos III, EtherNet/IP and CANopen bus couplers.
- Modicon M262 Logic/Motion Controllers have a Dual Core processor:
 - Core 1: is dedicated exclusively to managing program tasks and offers the maximum resources for real-time execution of the application code.
 - Core 2: is dedicated to executing communication tasks, which then have no further impact on the application execution performance.
- Performance:
 - 256 MByte RAM memory
 - 128 MByte Flash memory
 - 3-5 ns/ instruction
- A slot for an industrial memory card is available on the front face of the controllers:
 - SD-card up to 2 GB, or
 - SDHC-card up to 32 GB
- A QR-code, printed on the front face of the controllers and Smart Communication modules, provides a link to the Schneider Electric maintenance page of the product.
- A TMS bus port allows the connection of Smart Communication modules, assembled by simple interlocking on the left-hand side of the controllers.
- A TM3 bus port allows the connection of TM3 expansion modules, assembled by simple interlocking on the right-hand side of the controllers.

PacDrive LMC Controls

- Watchdog supervision during I/O-update:
 - Watchdog was deactivated during the cyclic execution when I/Os were updated. Now the watchdog stays active during I/O-updates.
 - If a given limit for I/O updates is exceeded, a watchdog is triggered.

- PROFINET:
 - The consumer and provider statuses (CS and PS) are now available in the application. The provider status appears in the tab **PNIO Module I/O Mapping**.

NOTE: Verify the direct call of % addresses in your application. The preferred solution to access the % addresses in your application is to map variables to all the % addresses.

Accessories TMS

The TM262 Logic/Motion Controllers allows to connect 3 TMS communication modules.

TM3 EtherNet/IP Bus Coupler

TM3 EtherNet/IP Bus Coupler is a distributed architecture solution, which enables the creation of distributed islands of industrial TM3 I/Os managed by a master controller M241, M251 or M262 via Ethernet fieldbus.

New features:

- The TM3 EtherNet/IP bus coupler supports TM3 and TM2 I/O modules:
 - Up to 14 TM3 I/O modules
 - Up to 7 TM2 I/O modules
 - Up to 7 TM2 I/Os mixed with TM3
- The TM3 EtherNet/IP bus coupler has an embedded webserver which supports:
 - User rights management
 - BOOTIP, DHCP, fixed IP-configuration
 - Bus coupler firmware update
- The TM3 EtherNet/IP bus coupler has an embedded switch with isolated RJ45 ports to support daisy chaining and ring topologies (RSTP/SNMP).
- The TM3 EtherNet/IP bus coupler provides cyber security protection features supporting Achilles level 1.

Limitations:

- Latch feature is not supported for TM3DI16, TM3DI16G, TM3DI16K.
- TM3 expert I/O are not supported.
- Only single user can modify the firmware update or write values through embedded webserver.
- The maximum number of TM3 I/O modules will be validated by software and may result in a lower number, depending on the number of analog I/O modules used.

TM3 Expert I/O

The TM262 Logic/Motion Controller supports 4 types of high speed counting modules:

- TM3XFHSC202
- TM3XFHSC202G
- TM3XHSC202
- TM3XHSC202G

These modules are connected on the right side of the controller and allow management of 2 counting channels with / without reflex output.

TM3XFHSX202 / TM3XFHSX202G can be configured to raise events in the controller to manage fast actions.

The firmware of the I/O module can be updated by the controller.

Limitations:

The TM3XFHSC202 / TM3XFHSC202G and TM3XHSC202 / TM3XHSC202G high speed counting modules are not supported by M241/M251 logic controllers nor the TM3 EtherNet/IP bus coupler

TM3 Standard I/O

New hardware revision for TM3DI16, TM3DI16G, TM3DI16K.

These new TM3 I/O modules are supported by M241, M251, M262 and TM3 EtherNet/IP bus coupler and support new features:

- Configurable input filter
 - The input acquisition time filter can be adjusted to allow fast input signals (0.3 - 12 msec).
- Input latch function
 - The input latch function allows to capture input signals with short durations and memorize the state till the next controller task execution.
 - This feature is not supported by the TM3 EtherNet/IP bus coupler.
- Firmware upgrade
 - The firmware of the I/O-module can be updated by the controller.

LXM32S Servo drives

The Lexium 32 product family consists of various servo drive models that cover different application areas. Together with Lexium BMH servo motors or Lexium BSH servo motors, as well as a comprehensive portfolio of options and accessories, the drives are suited to implement compact, high-performance drive solutions for a wide range of power requirements.

New features:

- Sercos module firmware update with Device Assistant
- Diagnostic object S-0-0390 can be mapped to the realtime data, showing C1D / C2D with corresponding error number
- IP-settings coming from Sercos become valid without powercycle
- DS402 statusword P-0-3027.0.2 can be mapped to the real-time data.
- Support of ProfileTorque mode with target value via parameter
- Support of PTI/PTO Torque mode
- Support of index pulse with SinCos1Vpp as machine encoder
- Controlled ramp down when drive will be disabled
- Locate device function by commissioning the SoMove configuration software
- SIN/COS values are traceable
- Error class for error A344 can be defined when using machine encoder for position control.

LXM32S Firmware Version Requirements

The LXM32S firmware is not automatically updated from M262. Therefore, the following firmware version requirements must be met:

- Drive firmware: V1.06.03 or later
- Sercos module firmware: V1.08.04 or later

If the firmware does not meet these requirements, it must be updated. For performing the firmware update, please contact your local Schneider Electric representative.

Lexium 62 Standard Plus and Advanced Plus System Integration

- System integration of the LXM62 Standard Plus and Advanced plus drive within the basic object Lexium LXM62 Drive.
- New configuration tab **Feature Configuration** to select the **DeviceVariant** within the drive object.

DeviceVariant for Lexium 62:

DeviceVariant type	Description
Standard	Standard Lexium 62 functions are available. No additional user functions.
Standard Plus	Additional Standard Plus user functions are supported.
Advanced Plus	Additional Advanced Plus user functions are supported.
Application defined	• Selection of the available user functions. • Possibility to create a generic project. • Configuration of the device variant type via IEC before the Sercos phase-up check.

During Sercos phase-up, PacDrive LMC Pro, PacDrive LMC Pro2 and PacDrive LMC Eco verifies if the configuration matches with the connected physical devices.

User functions

The new concept allows you to select the new drive-specific features with EcoStruxure Machine Expert inside the **Lexium LXM62 Drive** object. After selecting the **DeviceVariant** type in the **Feature Configuration** tab, the supported user functions are visible in the user interface and can be activated with the check box or using the IEC application. After the activation of a user function, the corresponding parameters appear in the parameter editor and can be used in the IEC application.

Supported features of LXM62 Standard Plus:

Feature	Description
Brake check functions (new system interface library functions)	- FC_BrakeCheckGetState(...) - FC_BrakeCheckSet(...) Verify whether the coupled brake is able to hold its specified torque.
Encoderless velocity control	- Support of BMP servo motors without encoder - Open-loop control for low velocity. The current is pre-defined by the drive and displayed by the object parameter <i>StartingRefCurrent</i>. You can adjust it with object parameter <i>UserStartingRefCurrent</i>. - Closed-loop position control for high velocity. The required velocity for the closed-loop control is displayed by the object parameter <i>MinimalOperatingVelocity</i>.
Torque limitation	Two new modes available: acceleration-dependent torque limitation and mechanical overload protection. - Both configurations allow to limit the torque on load side. - The functionality is enabled and switched with the object parameter <i>TorqueLimitationMode</i>. - The torque levels are set by the user with two object parameters <i>AccelerationTorqueLimit</i> and <i>DecelerationTorqueLimit</i>. - In mechanical overload protection mode, the motor is switched to torque free, when the adjusted torque is exceeded on the load side. It can be filtered to adjust the sensitivity. - In acceleration-dependent torque limitation mode, the torque on the load side is limited.

Supported features of LXM62 Advanced Plus:

- All features for LXM62 Standard Plus
- Incremental Encoder Output
Encoder signal reflection of motor encoder or machine encoder.
- Machine Encoder Input
The Machine Encoder Input is only used for the position control in the drives control loop.

Supported features of the *UserMotorTypePlate* library:

- FB_InitMachineEncoder*
POU to initialize the machine encoder type plate for LXM62 Advanced Plus.

Fast Device Replacement

- Support of the new Lexium LXM62 Drive Standard Plus and Advanced Plus with fast device replacement.
- A message logger entry is added if the configuration and physical device do not match.

Lexium ILM62 Integrated Servo Drives

Multiaxis integrated servo drives from 0.31 to 1.91 kW for automation solutions based on PacDrive 3.

Mitigated Anomalies

PacDrive LMC Controls & I/Os

ID	Description
OEM00069352 / LMC FW-1153	For the TM5 modules TM5SE1IC20005 and TM5SE1MISC20005, the counter data type is corrected (DWORD).
OEM00069411 / IECLIB-1547	Functions returning a large amount of data (for example, with an ARRAY[0..1023] OF STRING[255]) triggered a watchdog error message.

ID	Description
OEM00070481	After a project download, the EtherNet/IP scanner started with the diagnostic message: <i>Module not found</i> .
OEM00071401 / LMC FW-1985	TM5CSLCx00FS (Safety Logic Controller) did not start if the SLC was the first device in the Sercos ring.
OEM00071989	A <i>Not enough memory on device</i> exception detected in a Logic Motion Controller during download triggered a watchdog error message.
OEM00074169	An OPC UA server detected a <i>page fault</i> in the Logic Motion Controller when an OPC UA client initialized an OPC UA item with the value <i>OPC_Quality_BadWaitingForInitialData</i> .
OEM00076495 / LMC FW-1184	The internal function <i>TranslateBrowsePathsToNodeIds</i> of the OPC UA server terminated with an error and returned the diagnostic code <i>BadNoMatch</i> during a client request.

Lexium52 / 62 / 62 ILM

ID	Description
OEM00055840	Lexium 62 Double Drive with two different <i>InverterEnable</i> : A rising edge on the <i>InverterEnable</i> input for drive B caused a peak current in drive A. The diagnostic message <i>8107 Overcurrent</i> was displayed and a jerk was detected in drive A.
OEM00074423	A new Lexium 62 firmware was successfully updated with a legacy Device Assistant . Nevertheless, the drive did not operate after the update. No diagnostic message was displayed.

M241/M251

ID	Description
OEM00060178	Different versions of the IoDrvModbusSerial library were added to the Library Manager when using the Modbus IO Scanner with different controllers.
OEM00063394	After disconnecting the CANbus connection of a J1939_ECU device, the device in the Devices tree was still displayed in green color and the status of the J1939_ECU device was still displayed as running.
OEM00066740	The Task Configuration > Monitor tab displayed more tasks than the number of tasks that had been configured.
OEM00068203	The Input Assistant did not provide instances of the HSCSimple counter.
OEM00068334	Configuring fast outputs (pulse generators) for an M241 controller caused a shutdown of the programming software.
OEM00069524	The Relocation Table editor allowed to assign variables outside of the dynamic memory area (read and write).
OEM00069581	Relocation Table : Downloading an application was possible even though the relocation table provided invalid values.
OEM00071569	The NetManage tool provided incorrect information when connected to an M241 controller by a TM4ES4 Ethernet communication module.
OEM00073294	Using a PTO (Pulse Train Output) with an M241 controller configured in homing mode <i>ShortReference_Reversal</i> did not operate correctly. The movement did not end as intended.
OEM00075330	FDR (Fast Device Replacement) service authentication is successful now when IP mode is set to DHCP.
OEM00072090	Using the Modbus TCP IO Scanner , the inputs no longer keep the former values after an application download.
OEM00076970	EtherNet/IP Scanner is more stable now after an online change (no timeout).
OEM00077608	The file system is no longer corrupted after multiple manually executed HTTP requests with long URL addresses.
OEM00077471	Using the <i>FB_ControlClone</i> (to control cloning of a M241 controller) is possible now when the user rights are activated.

ID	Description
OEM00072657	X-Frame-Options header is now protected against clickjacking (user interface redress attack).
PEP0502989R	Communication with Festo motor controller CMMO/CMMP devices can be established now.
PEP0310789R / PLAT-239	The Modbus TCP connection timeout is adjusted now.
PEP0351007R / PLAT-337	The Ethernet connection is interrupted no longer when receiving Modbus TCP requests not written correctly.
PEP0439107R	The communication between the Controller Assistant and an M241 controller is possible now when connecting to the second ETH2 network interface.
PEP0408448R	Misleading error log messages in the M241 controller log file are removed.
PEP0428747R	The status of the homing function block is correct now when using homing mode 20.
PEP0444388R	Loading/storing of data parameters table in the webserver is improved.

Library Information

Version Identification

Description	Version
ApplicationLogger	1.1.2.0
AsyncManager	1.0.5.0
AutoTune	1.3.14.0
Booster Pumping	5.0.0.5
CommonMotionTypes	1.0.1.0
CrankModule	1.3.4.0
EMailHandling	2.0.4.0
EtherNetIP Explicit Messaging	1.1.7.0
EtherNetIP Remote Adapter	1.0.10.0
FileFormatUtility	1.2.6.0
FtpRemoteFileHandling	1.2.3.0
GMC Independent Altivar	1.2.4.0
GMC Independent Lexium	1.1.7.0
GMC Independent PLCopen	1.2.3.0
HttpHandling	1.0.11.0
M262 Encoder	1.0.0.2
M262 PLCSystem	1.0.0.19
M262Diagnostics	1.0.1.0
MotionInterface	1.0.69.5509
MqttHandling	2.0.6.0
PackML	1.2.3.0
PD_AxisModule	1.6.2.0
PD_EDesignAxisModule	2.3.2.0
PD_EdesignCore	2.2.6.0
PD_EdesignCrankModule	1.5.2.0
PD_ETest	1.3.6.0

Description	Version
PD_GlobalDiagnostics	1.3.1.0
PD_MultiBelt	1.4.2.0
PD_MultibeltModule	1.4.1.0
PD_PacDriveLib	1.8.7.0
PD_SmartInfeed	1.4.3.0
PD_SmartInfeedModule	1.3.1.0
PD_SoMotionGenerator	1.5.1.0
PD_Template	1.6.1.0
PLCopen MC part 1	1.0.69.5509
PreventaSupport	1.1.1.0
Robotic	2.12.1.0
RoboticModule	2.8.0.0
SchneiderElectricRobotics	2.8.0.0
SchneiderElectricRobotics Parameters	2.9.0.0
SchneiderElectricRobotics Toolbox	1.2.0.0
SercosCommunication	1.0.1.0
SercosDriveUtility	1.1.1.0
SercosMaster	1.0.69.5509
SlcRemoteController	1.3.6.0
SnmpManager	1.2.1.0
SqlRemoteAccess	1.1.2.0
TcpUdpCommunication	2.0.11.0
TeSys island	1.1.0.0
TimeSync	1.1.2.0
Toolbox	3.2.1.0
TwidoEmulationsupport	1.2.2.0
Unwinder	1.2.2.0
UnwinderModule	1.1.0.0
UserMotorTypePlate	1.3.9.0
UserTorqueFeedForward	1.1.2.0

Version Identification Safety Libraries

Description	Version
EnableSwitch_SE_SF	V0.99 from 10/28/15
PLCopen_SF	V1.00 from 09/14/07
Preventa_SafeMotion	V0100.0100 from 02/08/16

New Features

ApplicationLogger

The controller related dependencies are deleted. The library is now also working on M2•• controllers.

AsyncManager

Offers the functionality to call time-intensive jobs asynchronously to help prevent cycle time overruns without the need to create additional tasks separately.

CommonMotionTypes

This library supports common motion data types independent of the controller platform.

EmailHandling

- The function block `FB_SendEmail` provides parameters for recipients of type CC and BCC.
- Improved online modification behavior:
 - All function blocks in the library can detect an online modification of the application.
In the event of a detected online modification while the function block is in progress, all input parameters of type REFERENCE TO and POINTER TO are updated.
 - New global variable `SE_Email.GCL.G_xOnlineChangeAllowed` indicates if an online modification can be performed in executed function blocks out of the EmailHandling library.

FileFormatUtility

- Added function block `FB_CreateJsonFormattedString` which is used to facilitate the creation of a text STRING in JavaScript Object Notation (JSON) format.
- Added function block `FB_WriteFile` which is used to write or append content into a new or existing file on the file system of the controller.
- Improved online change behavior:
 - All function blocks in the library can detect an online modification of the application.
In the event of a detected online modification while the function block is in progress, all input parameters of type REFERENCE TO and POINTER TO are updated.
 - New global variable `FFU.GCL.G_xOnlineChangeAllowed` indicates if an online modification can be performed in executed function blocks out of the FileFormatUtility library.

GMC Independent Altivar

- Support for ATV32 and ATV71 are removed.

- Improvement of the function blocks `SetDriveRamp_ATV` and `SetFrequencyRange_ATV`: Errors resulting from write requests inside the function block abort subsequent write commands and will no longer cause communication deadlock.

GMC Independent Lexium

- Integration of LXM32 and ILX CANopen drives.
- Improvement of the function blocks `SetDriveRamp_LXM` and `SetDriveRamp_ILX`: Errors resulting from write requests inside the function block abort subsequent write commands and will no longer cause communication deadlock.
- Integration of Lexium SD328A (CANopen).

GMC Independent PLCopen

`ET_DeviceType` to use this Enum together with the `AxisRefBase` to identify the added axis type.

HttpHandling


New library providing HTTP client with GET and POST commands.

Library EnableSwitch_SE_SF

The safety-related `SF_EnableSwitch` function block evaluates the signals of a manually actuated three-stage enable switch (in accordance with EN 60204) to identify its switching stage and direction.

Library PLCopen_SF

The safety-related functions or function blocks described within this library are solely intended for creating safety-related code for suitable Safety Logic Controllers using EcoStruxure Machine Expert - Safety software. You can only combine your safety-relevant tasks within the safety-related control system if the tasks are integrated into the execution process in a correct and functionally safe manner as defined in the applicable standards.



Library Preventa_SafeMotion

The safety-related `SF_SafeMotionControl` function block acts as an interface between the Safety Logic Controller and the Safety Module (option module) which is the safety-related component of the ILM62 or LXM62 standard drive.

M262Diagnostics

Library added to gather system information on the M262 controller application and the configured devices in it.

M262 Encoder

Library added to support standard encoder input service for M262 controller.

M262 PLCSystem

Library added to provide read & write services for M262 controller.

MachineAssistantServices

Library added to provide functionality to discover Ethernet devices connected to the controller and to perform commands to detected devices.

MotionInterface

Library added to affect low level access for motion control for M262M•5 controllers.

MqttHandling

- Library added to provide the MQTT client functionality to exchange data with other devices over the network through an MQTT message server.
- Includes feature to establish an encrypted connection to a TCP server.

PackML

- Library is updated to support the ANSI/ISA TR88.00.02-2015.
 - Two new POU's, FC_SetWarning and FC_GetDateTimeAsArray, are provided accordingly.
 - Five new frame visualizations, FR_StateDisabled, FR_AlarmSingleLine, FR_AlarmHistorySingleLine, FR_DateTimeDisplay and FR_Warning, are provided accordingly.
- The variable GPL.Gc_uiNumberOfMaterials has been removed.
- The background colors for offline mode in the provided visualizations corresponds now to the color which becomes effective in online mode.
- FB_ModeManager:
 - In the event of a detected error during execution (`q_xError = TRUE`) the output `q_xError` is reset.
 - The values of the inputs `i_diUnitMode` and `i_diStateCurrent` are verified only upon a rising edge of `i_xUnitModeChangeRequest`.
 - A rising edge of the inputs `i_xUnitModeChangeRequest` and `i_xModeChangeDone` is detected only if output `q_xReady` is TRUE.
 - Upon a falling edge of the input `i_xUnitModeChangeRequest`, a detected error during latest execution is reset. A restart of the function block is no longer required.

PD_PacDriveLib

The PacDriveLib Homing functions and function blocks are prepared for use with MachineEncoder. If the MachineEncoder is active, then the EncoderPosition from the MachineEncoder is used for homing.

PLCopen MC part 1

Library added to provide motion control according to PLCopen Motion Control Part 1 v2.0 (formerly parts 1 and 2) for M262M•5 controller.

PreventaSupport

Library added to support diagnostic and maintenance tasks for Preventa safety-related modules.

Robotic

Library added to provide a collection of POU's for controlling robot kinematics.

The following kinematics can be controlled:

- Triaxial delta robot - IF_RobotConfiguration.Delta3Ax
- Triaxial cartesian robot - IF_RobotConfiguration.Cartesian3Ax
- Biaxial cartesian robot - IF_RobotConfiguration.Cartesian2Ax
- Biaxial delta robot - IF_RobotConfiguration.Delta2Ax
- Biaxial articulated robot - IF_RobotConfiguration.Articulated2Ax
- Four axial SCARA robot - IF_RobotConfiguration.Scara4Ax
- Up to triaxial user-defined robot - IF_RobotConfiguration.User3Ax

Motion interpolation in order to move to a point in two or three-dimensional space:

- Linear interpolation - IF_RobotMotion.MoveL
- Circular interpolation - IF_RobotMotion.MoveC
- Spline interpolation - IF_RobotMotion.MoveS
- Joint interpolation - IF_RobotMotion.MoveJ

RoboticModule

Library added containing the equipment module for the default PacDrive 3 template and auxiliary functions. It includes the functionality of the Robotic library.

- The interfaces of the provided equipment module enable an integration into the default PacDrive 3 template.
- RoboticModule provides the operation modes Auto, Homing, Manual and BrakeRelease.

SchneiderElectricRobotics

Library added containing function blocks to parametrize a Schneider Electric robot.

SchneiderElectricRobotics Parameters

Library added containing the parameters for a Schneider Electric robot.

SchneiderElectricRobotics Toolbox

Library added to provide provides structures, functions and function blocks for the following purposes:

- Read the protocol of a camera.
- Send data, for example, to simulate the protocol of a camera.
- Generate random Cartesian poses.
- Parameterize and generate a list of targets.

SercosDriveUtility

Library added to read and write drive configurations using the Sercos III fieldbus network.

SercosMaster

Library added to provide low level access to the Sercos master for M262M•5 controllers.

SlcRemoteController

- The command `ET_UserCommand.SetSafeKeyPassword` added for the function block `FB_RemoteController`, to allow setting or modifying the password on the `SafeKey`.

Execute this command to set a password before downloading the application using the function block `FB_DownloadApplication`.

- The library is compatible with M262 by substitution of `PacDriveLib` dependency with generic `AsyncManager`.

TcpUdpCommunication

- Fix of an anomaly in buffer handling on receiving messages with fill level greater than 65535 bytes.
- Corrected behavior: In case of an interruption of the connection while sending or receiving data, the property `State` indicates `ShutDown` and the property `Result` indicates `ClosedByPeer`.
- The property `IsReadable` is reset if the connection is interrupted.
- The function block `FB_TcpClient` provides the property `SocketOpt_CustomPort` which is used to specify the port used by the client for the next connection.
- The function block `FB_TcpServer` provides the property `SocketOpt_LingerEnabled`. This property is used to enable or disable the socket option `Linger` influencing the behavior on closing a connection.
- The processing of methods is no longer influenced by online monitoring of certain properties at the same time.
- The library offers functionality to establish TLS encrypted TCP connections.

TeSys Island

- Library added to provide function blocks to develop applications for TeSys island.

- The function blocks manage the digital functional object known as Avatar by:
 - controlling Avatars.
 - reading diagnostic information from Avatars.
 - reading energy data from Avatars.
 - reading asset data from individual modules of TeSys island.

UserMotorTypePlate

The function block `FB_InitMachineEncoder` is included to initialize the machine encoder with a typeplate (the machine encoder object is available on Lexium 62 Advanced Plus).

Examples

New example projects:

- XML file handling example
- CSV file handling example
- Email handling example
- MQTT example using JSON format
- Machine Advisor communication example

Updated example projects:

- PackML example updated according to the library update
- RTC TimeZone example with SNTP client
- SLC remote controller example

New function template:

- HTTP client

Mitigated Anomalies

Libraries

ID	Description
OEM00052518 / IECLIB-1631	<i>MTP.FB_MotorDataRead</i> : Improved diagnostic message if no type plate is stored in the drive.
OEM00071708 / IECLIB-1551	PacDriveLib library: After disabling the function blocks <i>FB_HomeForce</i> and <i>FB_HomeTorque</i> , all outputs are reset.
OEM00071904 / IECLIB-1349	MultiBelt Library: The parameter <i>xLeaveStation</i> of <i>ST_Station</i> is now compatible with indexed stations.
OEM00075161 / IECLIB-1771	SmartInfeed library: After <i>SI.FB_Infeed.i_xStart := FALSE</i> , the state machine is now finished correctly. To achieve this, a new GPL parameter was added: <i>Gc_IrMasterMotionActiveVelLimit</i> Internal velocity limit parameter to verify in <i>FB_Infeed</i> if the master of the <i>InfeedBelt</i> is in motion.
OEM00060445 / IECLIB-1348	TcpUdpCommunication library: You can access the properties of the <i>FB_TcpServer</i> function block from different tasks. The <i>InputOutOfRange</i> message is no longer reported.
OEM00069263 / IECLIB-957	EmailHandling library: By setting <i>GVL.Gc_udiMaxNumberOfAttachmentPaths</i> to a value greater than one, the function block can receive more than one email.
OEM00064768 / IECLIB-404	GMC Independent Altivar library and GMC Independent Lexium library: You can use now <i>ET_DeviceType</i> together with <i>AxisRefBase</i> to identify an added axis type.

ID	Description
OEM00043940	IoDrvModbusSerial library: It is now possible to write a single register and to initialize a server.
IECLIB-1708	GMC Independent Altivar library: Active movements of Altivar drives are stopped now if the application is set to stop.

Software Information

Version Identification

Description	Version
Machine Expert Installer	11.19.16801
Diagnostics	18.0.10.0
Controller Assistant	18.0.10.0
Device Assistant	18.0.10.0
DiffViewer	18.0.10.0
Gateway	18.0.10.0
Launcher	18.0.10.0
OPCServer	3.5.12.70
SoftSPS	3.5.12.80
SVN	4.2.4.0
Logic Builder ⁽¹⁾	1.1
Vijeo-Designer	6.2.8.1016
CoDeSys	V3.5 SP12 Patch8 HF1
SQL Gateway	18.0.1.0
Motion Sizer	4.1.0.0
(1) If using a virtual machine, the download of the online help operates correctly only if the option Accelerate 3D graphics is deactivated in the VM settings.	

New Features for Machine Expert Installer and Online Help

Machine Expert Installer

The Machine Expert Installer provides an intuitive user interface to perform an online installation. During installation phase, you can select required sets which will be automatically downloaded and installed.

You can also use the Machine Expert Installer to customize an existing installation of the EcoStruxure Machine Expert product.

Online Help

With EcoStruxure Machine Expert, the online help is published as HTML5 help only on a Web server. You can download a local copy of the online help using Machine Expert Installer.

Known restrictions on different browsers used with the HTML5 help:

Browser and Version	Restriction	Workaround
Internet Explorer V11	Poor graphic / display quality	–

Browser and Version	Restriction	Workaround
	If the HTML5 help is located on a local PC, then: - Contents are blocked. - Help pages cannot be opened. NOTE: When the HTML5 help is located on the Web, the restrictions do not exist.	1. Open the Internet Explorer and go to Tools -> Internet Options. 2. Click the Advanced tab and scroll down to the Security section. 3. Enable the check box Allow active content to run in files on My computer.
Chrome V63	If the HTML5 help is located on a local PC, then: - Printing subtopics is not supported. - Changing the topic language is not supported. NOTE: When the HTML5 help is located on the Web, the restrictions do not exist.	–
Edge V40	If the HTML5 help is located on a local PC, then: The contextual help opens only the individual topic, but not the HTML5 GUI. NOTE: When the HTML5 help is located on the Web, the restrictions do not exist.	–

New Features EcoStruxure Machine Expert

Project Update

- Project update categories are separated in single pages.
- Overview page summarizes the update actions: sufficient in most cases.
- Details for update of different parts of the system in separate tabs.
- Update of visualization styles added.
- Detailed information on library update enhanced by presenting the updated list of libraries.
- Display of progress status added.

NOTE: When you update a SoMachine project which contains solution libraries (Pumping, Packaging, Hoisting) to EcoStruxure Machine Expert, the solution libraries will not be updated. You have to replace the Pumping library manually by the Booster Pumping library. Hoisting and Packaging libraries are not supported by EcoStruxure Machine Expert V1.1.

Functional View

- A view has been introduced to group the project objects by logical machine units.
- These groups can be saved and re-used in other projects.

Smart Template

The Smart Template has been conceptually redesigned to open the framework beyond Robotics functionality.

The benefits of the revised version of Smart Template are:

- You can start to program with a default project and can add smart template functionality afterwards. Robotics projects can now be under SVN control and support folder structures.
- Can be used for more than one controller in a project. Smart Template functions or modules can be added to several controllers in a project.
- Supported SVN-functionality. Smart Template modules are handled in SVN (commit, update...) like any other POU in the system. Sub-elements (configuration, methods, ...) are considered appropriately.
- Smart Template is open for new IEC-frameworks. The modules are self-describing and no longer limited to a specific infrastructure like PacDrive Template. Basically any IEC-environment can be used from zero to maximum.

Supported Features:

- **Modules** view
Smart Template module instances can be added in an own view called **Modules**.
- **Add module / Add object**
Modules can be added using the **Add module** dialog providing more information and flexibility in terms of versioning, etc. Currently the following modules and objects are usable:
 - Camera module
 - Camera configuration
 - Module interface
 - Method
 - Action
 - Transition
 - Notes
- **Module manager**
 - Key element to manage several modules, their version and their referenced libraries.
 - Modules can be updated as easy as libraries.
 - The user code, the user configuration and the resolved library version are used to generate the code for smart template
- **Camera Module**
 - Supports the known functionality to connect vision systems - generic cameras and specific for Cognex cameras.
 - Online views allow to see the camera status, the position of products identified.

Migration Strategy of Smart Template

As the old Robotics for SmartTemplate-Framework is not supported any longer, the code and configuration has to be transferred to a new **Standard** project.

1. Create a new empty project in EcoStruxure Machine Expert.
2. Copy and paste the source code.
3. Add the modules to the new project via **Add module** and adapt the configuration according to the old project.

Code Analysis

Code Analysis add-on was improved and stabilized.

- New metrics (cyclomatic complexity)
- Compile messages as part of the convention results output.

- Analysis of libraries (POU-space analysis) is supported now.
- User interface and scripting API for machine advisor code analysis connection to upload snapshots and queries

ETEST

ETEST improves the usability and the handling of integration in Continuous Integration systems, especially when working with big and/or long running test projects.

- Optional test case methods
 - The ETEST standard methods (**Prepare, Execute, Finalize, CleanUp**) are optional for test cases and test resources
- Test duration
 - The test results view shows the duration of each executed test case.
 - The exported result file contains the start, end time and duration of each test case.
- Test progress:
 - The result of each test case will be printed to the shell console, if executed via scripting.
 - You always know which tests are already finished in long-running test-series.

Diagnostics

- Diagnostics supports the Safe Logger for safety-related devices.
- Support for Lexium 62 Standard Plus and Advanced Plus.

Controller Assistant

Support for Lexium 62 Standard Plus and Advanced Plus.

Device Assistant

Support for Lexium 62 Standard Plus and Advanced Plus.

New Features for EcoStruxure Machine Expert - Safety

Overview

- EcoStruxure Machine Expert - Safety component distribution / installation using Machine Expert Installer together with the EcoStruxure Machine Expert components (Install new Software (Online) (see Schneider Electric Software Installer, User Guide)).
- Floating licenses: New license type for EcoStruxure Machine Expert - Safety and BWU2984 AS-i safety gateway available.
- Embedded Safety integration into TM262M• controller architectures. (TM5CSLCx00FS, TM5/TM7 Safety I/Os).
- Online Help:
 - HTML 5
 - Online help (safety and non-safety parts)
 - Offline help (safety)

- Support of context-sensitive help in EcoStruxure Machine Expert - Safety.
- Integration of latest help and documentation content.
- Update to EcoStruxure Machine Expert product changes.
- Fixed documentation issues of previous versions.
- Lexium 62 with new hardware revision is supported (no change on safety functionality).
- Updated EULA (End User License Agreement)

Compatibility EcoStruxure Machine Expert

Overview

EcoStruxure Machine Expert can be installed in parallel to other Schneider Electric software products, such as SoMachine and SoMachine Motion.

For general information on compatibility of EcoStruxure Machine Expert, refer to the Compatibility and Migration Guide (see EcoStruxure Machine Expert Compatibility and Migration, User Guide).

Behavior Modifications in EcoStruxure Machine Expert compared to SoMachine / SoMachine Motion Versions

NOTE: For a list of compiler versions included in EcoStruxure Machine Expert, SoMachine and SoMachine Motion versions indicated in the following table, refer to the Compatibility and Migration Guide appendices (see EcoStruxure Machine Expert Compatibility and Migration, User Guide).

ID	Description
OEM00071037	Firewall: The file name Firewall is case sensitive. Only a default firewall file, named FirewallDefault.cmd , is recognized.
OEM00071000 / SI-5249	I/O Mapping: Modified behavior of Default Value . If the compiler version is EcoStruxure Machine Expert V1.1 or later: You can edit this field only, when mapping an input/output to a new created variable. When mapping to an existing variable, the initialization value of the variable is used as the default value. Selecting a compiler version earlier than EcoStruxure Machine Expert V1.1, the default values can also be edited and are applied in case of mapping to an existing variable or to no variable. When importing projects from SoMachine / SoMachine Motion, default values are still imported for the cases above, but are not visible and not applied, as long as the compiler version is $\geq$ EcoStruxure Machine Expert V1.1. See also OEM00072811.
OEM00071094 / CDSYS-72	Trace: Multi-selection of variables in the Trace Record part of the Trace Configuration dialog is not supported.
OEM00071748 / CDSYS-82	Tabular Declaration: The number of variables in online mode is limited to 1000.
OEM00071929 / CDSYS-83	Online Change: Adding a library opens the Online Change dialog, even if nothing was used out of this library. After confirming this dialog, the message Code has not changed. No online change necessary is generated.
OEM00072060 / CDSYS-84	Auto-Declare: Using a statement like <i>IF Var_0 OR Var_1 THEN</i> triggers an auto-declaration proposal of INT instead of BOOL.
OEM00072474 / CDSYS-100	SVN: After checking out a project from SVN and closing the project, an entry is created in the Recent files menu, even though the corresponding file has not been saved. Selecting this entry will fail to open the project with an error message.
OEM00072745	Compiler: Bool is not supported as a base type in enumerations and causes a compiler error message. Only Integer data types are supported.

ID	Description
OEM00072811 / CDSYS-105	I/O Mapping: Reset Mapping does not delete default values. Reset Mapping deletes the variables in the I/O Mapping. If a Default variable was associated with such a deleted variable, this is no longer shown and applied. However, creating a new variable for the same I/O will bring back the old Default value. Note, that you can only modify the Default value, when you have created a new variable first. See also OEM00071000.
OEM00073255 / CDSYS-119	Find: The Find command is associated to the shortcut Ctrl+F. The shortcut only works, when an editor window is open.
OEM00073314 / CDSYS-120	FBD: If the FBD option Connect boxes with straight lines is selected, connection lines (links) between function blocks may overlap.
OEM00074431 / CDSYS-139	Auto-Declare Using a statement like <code>ptVar := ADR(var) ;</code>, where <code>ptVar</code> is declared a <code>POINTER TO INT</code>, will lead to an auto-declaration proposal of <code>POINTER TO INT</code> for <code>var</code>, instead of <code>INT</code>.
OEM00074574 / CDSYS-141	Auto-Declare: Using a statement like <code>GVL.toto := bool_1 ;</code>, where <code>bool_1</code> is declared as <code>BOOL</code> and <code>GVL</code> is the name of a <code>GVL</code>, causes an autodeclaration proposal of <code>INT</code> for <code>toto</code> instead of <code>BOOL</code>.
OEM00074609 / SI-4762	Reset Cold/ Reset Warm: Breakpoints that were activated before executing the commands are still active after the execution of the command. (In SoMachine / SoMachine Motion they were deactivated).
OEM00074647 / CDSYS-143	Auto-Declare: Using Auto-Declare from a POU will not offer an already existent <code>PersistentVars</code> as object, except if selecting in the following order: PERSISTANT and RETAIN followed by VAR_GLOBAL as scope.
OEM00074787	SysTimeRtc: The actual behavior of functions <code>SysTimeRtcConvertHighResToLocal</code>, <code>SysTimeRtcConvertLocalToHighRes</code>, <code>SysTimeRtcConvertUtcToLocal</code> and <code>SysTimeRtcConvertLocalToUtc</code> is compliant to the defined <code>TimezoneInformation</code> (struct) definition of member <code><iBias></code> (which itself is based on Windows Definition), where <code>UTC = localtime + bias</code>. Therefore, the bias for eastern longitude is negative and the bias for western longitude is positive.
OEM00076496	Project Compare: New menu command "Project - Commit t accepted changes. The command is also available as toolbar button and allows to commit already accepted differences from the project comparison to the current project. Thus, you are no longer limited to committing differences accepted in one compare view only. Instead you can determine the time and extent of the Commit.
OEM00076869 / CDSYS-197	Project Export/Import: After exporting modules, when importing the modules are reordered alphabetically by module name.
OEM00071445 / CDSYS-76	ProfiNetIO-Controller (Master): New parameters on the General tab: I/O provider/ consumer status. Parameter Application stop > Substitute values : When the user stops the application, the provider state is set to BAD. The slaves then set the inputs and outputs to predefined substitute values. For more details refer to the Online Help.
OEM00074786	SFC - Init step: For the compiler version of EcoStruxure Machine Expert V1.1 or later the <code>Init</code> step counts from the program start moment (not from the system start moment. Additionally, triggering <code>SFCInit</code> or <code>SFCReset</code> flag resets the <code>Init</code> step time to zero.
SP12CDS-57549	Compiler, I/O Mapping: Task deployment for function blocks used in initial values. For the compiler version of EcoStruxure Machine Expert V1.1 or later: only these tasks will be used as update task for function block instances with I/Os, in which an access to the I/Os can be detected, or in which the instance is called directly. This behavior may lead to a smaller number of output updates. For example, if a function block instance is declared in a program, but there is no direct call of this instance, there will be no update in the task in which the program is called. Direct call means, that calls via interface are not considered. You can manually edit the tasks in which to update I/Os in the I/O configuration.
SP12CDS-56915	Compiler: A Bit-located Bool variable assigned to a <code>REFERENCE TO BOOL</code> variable generates a compiler error.

ID	Description
	For the compiler version of EcoStruxure Machine Expert V1.1 or later, a compiler error is generated when assigning a BOOL variable located on a bit address to a <code>REFERENCE TO BOOL</code> variable. Workaround: assign the bit located variable to a Boolean variable first and assign the latter to the <code>REFERENCE</code> variable.
SP12CDS-59141	Compiler: Unexpected online change related to the usage of the <code>PersistentVars</code> object with attributes. For the compiler version of EcoStruxure Machine Expert V1.1 or later, the order of attributes in a <code>PersistentVars</code> list object is always fix (sorted lexically). Opening projects without update, that contain a compiler version earlier than EcoStruxure Machine Expert V1.1 and attempting to login may request an online change in the above-mentioned case. Project Archive: Sending a project archive via mail directly from the Save Archive dialog is not supported in EcoStruxure Machine Expert V1.1 (64-bit) due to MAPI limitations.
SP11CDS-35119	Trace: flexible assignment of variables to diagrams. EcoStruxure Machine Expertsupports configuring one or more diagrams within the trace and displaying one or more variables, allowing a flexible arrangement of these variables within the diagrams. All diagrams share the same time axis, but the appearance including the Y-axis can be configured separately for each diagram. Download and Upload diagram configurations to the PLC and Save and load diagram configurations in the trace.csv format are not supported. When opening projects containing Single-/Multichannel traces, they will be displayed in an equivalent way. The former menu command Multichannel (changing the view only) was replaced by two new commands Convert to Single/Multi Channel, which modify the configuration accordingly.
SP11CDS-52137	Compiler: Compiler Error message for libraries with invalid namespace. For the compiler version of EcoStruxure Machine Expert V1.1 or later, a compiler error will be generated for library namespaces that are not valid identifiers according to IEC 61131-3.
SP11CDS-47465	Runtime: Default values: STOP to STOP over Reset behaves differently than RUN to STOP over Reset. Default values for direct addressed outputs are set, if application is in stop, and a reset is executed. Previously, the direct addressed outputs were not reset in this scenario.
SP10P10CDS-50882	ScriptEngine: IronPython behavior regarding reading files. Within IronPython, Byte Order Marks (BOM) at the start of files are not implicitly skipped any more, which may lead to a different behavior of scripts parsing files, for example using the <code>ConfigParser</code> module. Open these files using <code>codecs.open()</code>.
SP10CDS-43667	Compiler: Initialization (order) of DUT structures For the compiler version of SoMachine Motion V4.4 or later, the initialization order of arrays of Data Unit Types.. Example: <pre>arr : ARRAY [0..1] OF DUT := [(a := 1), (a := 2)];") is: FOR i := 0 TO 1 DO arr[i].FB_Init; END_FOR arr[0].a := 1; arr[1].a := 2;</pre> Where the order for compiler version < V4.4 Motion was: <pre>arr[0].FB_Init(); arr[0].a := 1; arr[1].FB_Init(); arr[1].a := 2;</pre> Additionally, if a DUT variable is initialized by assigning another variable, as in: <pre>xx : DUT := yy;</pre> with compiler version SoMachine Motion V4.4 or later, there will also be a <code>FB_Init</code> call in this case.
SP10CDS-47295	Compiler: C0405 multiple assignments to interfaces variables not allowed. For compiler versions of SoMachine Motion V4.4 or later, a compiler error is generated for constructs like:

ID	Description
	<code>itfVar1 := itfVar2 := 0;</code>
SP10CDS-49943	Symbol Configuration: Properties with monitoring type variable . For the compiler version of SoMachine Motion V4.4 or later, properties with monitoring type variable are exported read-only in the Symbol Configuration.
SP10CDS-49852	Project User Management: Settings: New hash format for passwords. Hashes for user passwords can now be stored with a new format, which supports salt and a new hash algorithm, improving the security of a password against guessing and brute-force. The password hash of a user is converted with the first login after the setting was changed. The project loses its backward compatibility with the conversion to the new password hashes. You can convert the new password hashes back by disabling the setting and re-login of every user, which logged in during the time the setting was enabled. Another option is to set a new password for every user (that logged in while the setting was enabled).
SP10CDS-49093	Online Change: Programming system with .Net 4.6 Framework. In projects using Webvisualization it might not be possible to login without an Online Change, if the project contains an Imagepool object, referencing the same image more than once.
SP10CDS-25116	Gateway, RTS: <code>NodeName</code> limitation to 50 characters: The <code>NodeName</code> of controllers (as displayed in the Communication Settings dialog) is now limited to 50 wide-char characters (including NULL termination). If a controller with a longer node name is updated to a SoMachine Motion V4.4 version or later, the node name is cut to this limit. Clients like PLCHandler or OPC Server cannot connect when using the old, longer <code>NodeName</code> . In this case, you need to update the connection parameters of the affected clients and/or rename your controller.
SP9CDS-47453 / OEM00061201	Online Change: Handle out of memory exception For compiler versions of SoMachine Motion V4.4 or later, in the case of memory outage during online change, a compiler error C0398 will be generated.
SP9CDS-46022	Compiler: AT declaration in <code>VAR_TEMP</code> , <code>VAR_IN_OUT</code> and <code>VAR CONSTANT</code> . For compiler versions of SoMachine Motion V4.4 or later, a compiler error C0392 is generated if an AT declaration is used inside one of the following blocks: <code>VAR_TEMP</code> , <code>VAR_IN_OUT</code> and <code>VAR CONSTANT</code> .
SP9CDS-45977	Compiler: Assignment of function block outputs to interfaces. For compiler versions of SoMachine Motion V4.4 or later, the assignment is not supported, a type mismatch error is reported for the following case: <code>fbUser(fbOut => iMain);</code>
SP9CDS-43812	Compiler: <code>__ISVALIDREF</code> returns TRUE for check of interface instance with value zero. <code>__ISVALIDREF</code> is a special operator that can now only be used for checking references. A compiler error gets generated in case <code>__ISVALIDREF</code> is used with any other type than REFERENCE types. Interfaces and pointers can be checked via <code>interf <> 0, pointer <> 0</code> .
SP9CDS-44576	Compiler / Online Change: AT declarations If an address is moved from one variable to another variable, an online change will not be possible; a compiler error will be generated. Example: <code>var1 : BYTE; -> var1 AT %MB0 : BYTE;</code> <code>var2 AT %MB0 : BYTE; var2 : BYTE;</code>
SP9CDS-45776	Compiler: Array with length 0. For compiler versions of SoMachine Motion V4.4 or later, a compiler error will be generated for arrays like: <code>arr[0..unsigned_const-1]</code> , if the <code>unsigned_const</code> is 0. The upper limit is evaluated as an unsigned operation and would result in a too large number for any signed array limit. Use a signed constant instead, or cast the constant to a signed type:

ID	Description
	<code>arr[0..TO_INT(unsigned_const)-1]</code>
SP9CDS-45575	Compiler: PRIVATE, PROTECTED not allowed for FB_Init, FB_Exit, FB_ReInit. For compiler versions of SoMachine Motion V4.4, a compiler error will be generated, if an FB_Init, FB_Exit or FB_ReInit method is declared as PRIVATE or PROTECTED.
SP9CDS-45684	Compiler: Writing to %I* input variables. For compiler versions of SoMachine Motion V4.4, a compiler error will be generated, when writing to variables located at %I* addresses
SP9CDS-383	Compiler: FB_Exit is called to destroy local instances. For compiler versions of SoMachine Motion V4.4, FB_EXIT is now called for instances allocated on the stack before the owning scope returns. A warning informs you about the changed semantics in these cases. In order to suppress the warning, decorate the POU declaring the local instance with the warning disable macro for warning code C0394 (<code>{warning disable C0394}</code>).

NOTE: If you are extracting a project archive in EcoStruxure Machine Expert that has been created with SoMachine or SoMachine Motion, and **Options** are selected in the **Extract Project Archive** dialog box, your EcoStruxure Machine Expert installation may be altered and it may appear the devices are missing.

⚠ CAUTION

INOPERABLE EQUIPMENT

When you extract a project archive that has been created with a different programming software, deselect the **Options** check box in the **Extract Project Archive** dialog box.

Failure to follow these instructions can result in injury or equipment damage.

To restore your EcoStruxure Machine Expert installation, execute the **Tools > Options** command and select the **Directories (Devices, Libraries,...)** option. From the **Directories (Devices, Libraries,...)** dialog box, click the **Reset repository locations** button and the devices are restored.

NOTE:

- If a SoMachine or SoMachine Motion project with HMIs is loaded, it may occur that Vijeo-Designer must be started by the update. In this case, it may occur that Vijeo-Designer is only started in the background.
Vijeo-Designer must be opened manually to continue the update.
- If a SoMachine or SoMachine Motion project with obsolete HMIs is loaded, it may occur that Vijeo-Designer is started and you are prompted to enter a reference number.
If the reference number is not available, click **No** and the device is updated automatically to a preprogrammed type.
- If a SoMachine or SoMachine Motion project with obsolete HMIs (with control) is loaded, the HMI is converted in Vijeo-Designer to a supported HMI.

Compatibility EcoStruxure Machine Expert - Safety

Overview

Former SoSafe Programmable versions cannot be started from EcoStruxure Machine Expert environment anymore and can only be installed and used if the related SoMachine Motion version is installed.

However, the former SoSafe Programmable projects - starting from V2.1 - can be imported, re-used, and updated in EcoStruxure Machine Expert - Safety V1.1.

In almost all cases, the update works without impact on the overall safety application and the resulting project CRC (cyclic redundant checksum) value stays the same and there is no recertification needed.

However, EcoStruxure Machine Expert - Safety with this release does not support reusing a project built on EcoStruxure Machine Expert - Safety with LMCx01 system to EcoStruxure Machine Expert - Safety with M262 system or vice-versa.

Identified Incompatible Project Updates

The CRC of the safety project done before SoSafe Programmable V2.21 is changed if the old project contains the following safety devices:

- TM5SAI4AFS
- TM5STI4ATCFS

In this case, the safety project must be compiled again and downloaded to the TM5CSLCx00FS and the related safety function must be validated and recertified.

It is still possible to install former SoSafe Programmable versions in parallel to EcoStruxure Machine Expert - Safety as long the compatible SoMachine Motion package is available on the PC. Thus, you can maintain old projects using previous compatible engineering tool chains.

Overview of the validated safety-related software with the appropriate safety-related firmware.

Device	Safety-related firmware version for SoSafe Programmable version				
	1.0	2.0	2.1	2.2	2.21 ⁽¹⁾
TM5CSLC100FS	1.10	2.36	2.41	2.44	2.47
TM5CSLC200FS	1.10	2.36	2.41	2.44	2.47
TM5SAI4AFS	–	–	302	302	322
TM5SDC1FS	–	–	302	302	302
TM5SDI20DFS	–	–	301	305	305
TM5SDI2DFS	281	281	301	305	305
TM5SDI4DFS	281	281	301	305	305
TM5SDM4DTRFS	281	281	301	305	305
TM5SDM8TBFS	–	–	301	305	305
TM5SDO2DTRFS	–	–	300	300	300
TM5SDO2TAFS	280	280	280	280	280
TM5SDO2TFS	280	280	280	280	280
TM5SDO4TAFS	280	280	280	280	280
TM5SDO4TFS	280	280	280	280	280
TM5SDO6TBFS	–	295	295	295	295
TM5SPS10FS	–	–	320	320	320
TM5STI4ATCFS	–	–	–	–	322
TM7SDI8DFS	–	–	301	305	305
TM7SDM12DTFS	280	280	301	305	305
(1) EcoStruxure Machine Expert - Safety V1.1 is compatible with the same component versions as SoSafe Programmable V2.21.					

Mitigated Anomalies

Machine Expert Installer

ID	Description
OEM00073838	SoMachine Motion installation on a Windows system with Turkish language is operational.

Online Help

ID	Description
OEM00060935	Missing information on the safety-related characteristics of the Safe Logic Controller TM5CSLCx00FS and the TM5/TM7 I/O safety-related modules added in the Online Help.
OEM00067912	Missing information on the safety-related parameters in the configuration window of safety-related drives added in the Online Help.
OEM00069590	In the German Online Help, the links of the chapters <i>Lexium 62 Single/Double Drive Embedded Safety</i> and <i>Lexium 62 ILM Safety Option Module</i> are operational.
OEM00069710	In the Online Help, the link to the <i>PacDrive TM5/TM7 Safety System Planning and Installation Guide</i> is operational.
OEM00070505 OEM00070510	In the Online Help, the description of some LED indicators of the TM5CSLCx00FS is present. The following was enhanced: • Missing module detected. • Boot phase. • Debug state (RUN, STOP, HALT).
OEM00070844	In the Online Help, the parameter information on the encoder resolution of motors (<i>EncoderResolutionRotary</i>) is present.
OEM00071262	In the Online Help, the description for the TM5CSLCx00FS cycle time parameter provides sufficient information.

EcoStruxure Machine Expert

ID	Description
OEM00055804	In simulation mode, you can assign the application to the same node name as the Soft PLC. The Vijeo-Designer Simulation Runtime on the same Windows PC will connect to the simulated PLC.
OEM00061672	The diagnostic message <i>Program name or function block instance expected instead of IoMgr...</i> no longer is displayed at the first login or after the Update > Build > Generate code procedure.
OEM00067034 / SI-5218	When converting an M251 controller to an M241 controller, the modules of an Ethernet OTB slave are no longer arranged in reverse order.
OEM00067403 / SI-3320	In online mode, the parameters for Modbus TCP servers can no longer be edited or modified.
OEM00068030 / SI-1116	It is now possible to install Sercos III EtherCAT bridge devices without losing parameters in the device description.
OEM00070178 / SI-1069	McAfee security analysis no longer incorrectly declares the <i>Clean_all.exe</i> files as Trojans.
OEM00071130 / SI-5252	In the Add Device dialog box, the iPC Series is now available.
OEM00071816 / SI-5259	The <i>SiteManagerEmbedded.exe</i> file (used for Vijeo-Designer) is available in the <i>Tools</i> folder.

ID	Description
OEM00062595 / MS-1605	Motion Sizer: In the Device selection dialog, the Inertia ratio column can be sorted.
OEM00006868	Smart Coding no longer displays incorrect icons for POU's or actions in the SFC (Sequential Function Chart) editor.
OEM00010333	GlobalImagePool : After embedding an image into a project, the image has become part of the project and the referenced file is no longer needed. The embedded image without referenced file is no longer displayed in red.
OEM00012125	Source Download : If you execute the Source Download command, your project is no longer automatically saved without first prompting you to confirm.
OEM00016215	Variable declaration: The declaration of variables in the tabular declaration editor no longer automatically adds an additional pair of keywords (<i>VAR</i> , <i>END_VAR</i>) to the textual declaration editor.
OEM00019426	For Visualization elements, user-defined colors are retained.
OEM00022360 OEM00033901	The size of project files no longer increase over time due to precompile and auxiliary files for shared strings.
OEM00025211	When there is no memory space available on the file system of the controller, the <i>Create boot application</i> application command can not be executed successfully, but no message is displayed indicating the reason. Workaround: The message can be created by the function <i>CAL_SysFileWrite</i> with the return value <i>ERR_DISK_FULL</i> .
OEM00026350	Behavior of outputs for <i>STOPPED</i> state (from Addendum SoM V3.1): All outputs initially assume their configured state (Keep current values or Set all outputs to default). The subsequent state of the outputs depends on the value of the Update IO while in stop setting, or the state dictated by output forcing if used and on commands received from remote devices. NOTE : The initial assumption of state of the outputs is for the equivalent of one controller cycle. After this, the subsequent state takes effect. For detailed information, refer to the <i>Programming Guide</i> specific to your controller, chapter <i>Controller States Description</i> .
OEM00027910	Opening the preview of project documentation no longer leads to overflow of GDI (Graphics Device Interface) objects.
OEM00028990	When function <i>DirList</i> out of the CAA File library was used to read files and folders from the controller file system the first file/folder is no longer missing.
OEM00030446	When the Tools > Options dialog box was closed with the X button, the settings are no longer saved (as if the OK button was clicked).
OEM00030618	Variable declaration: The order of the variables copied from one GVL to another GVL is correct.
OEM00031906	CANopen, DTM: If the CANopen option Block SDO, DTM and NMT access while application is running is set, after the application is running and subsequently stopped, the DTM (Device Type Manager) can be synchronized.
OEM00035324	Case sensitive renaming a POU is possible.
OEM00035704	In online mode, you can no longer add a POU to the MAST task by drag-and-drop in the Device Editor .
OEM00035785	Library Manager > Add Library > Placeholder : Placeholders defined in the library profile (like for the Standard•• library) are present in the placeholder list.
OEM00037183	Addressing bits in variables: Compiler error message is now generated indicating that bit access is only possible on integer variables.
OEM00038122	A cut-and-paste operation is now possible for a POU in an application if a device with the same name exists.
OEM00038656	When adding a POU to the MAST task by using the contextual menu, the entered comment is now taken into account.
OEM00038866	Creating an <i>ARRAY OF BOOL</i> located on a bit address, Build > Generate Code no longer generates an internal error message.
OEM00039266	Adding an FB (function block) to an LD (Ladder Diagram) no longer results in an undefined FB when clicking outside the FB edit dialog box instead of confirming the name with the Enter key.

ID	Description
OEM00041670	Downloading a project which included a visualization trace for which a DWORD variable was specified in the Load trace from a file > FileName property, no longer cause connection issues.
OEM00041917	If you used the 3S CanOpenStack library in your project, a build error is no longer generated when using a POU named <i>START</i> or <i>STOP</i> .
OEM00042160	If you disconnect an Ethernet cable from a device for a short time and reconnected it, is now recognized that the device was reconnected.
OEM00042331	The %I and %Q addresses of a project are organized during code generation. Less time is required to manage a large number of %I/%Q addresses existing in a project, when the option Always update variables is activated.
OEM00042591	The correct message is now displayed when trying to connect to a device with an incompatible firmware version.
OEM00042732	Symbol Configuration: The symbols from Symbol Configuration can now be exported to Vijeo-Designer after a second modification.
OEM00043711	When outputs have default values configured and are driven by an external task and the external task has not been executed at least once, the default values are now not applied when the controller mode changes from RUN to STOP.
OEM00043954	WebVisualization: The configured background color is now used for the complete website.
OEM00044255	In EcoStruxure Machine Expert Logic Builder under Project > Project Settings > Security > Enable project file encryption > Password , you are no longer prompted for the present password and the new password if the security settings have never been enabled. You are now asked only for the new password.
OEM00044349	WebVisualization: The controller no longer transitions to STOP mode when you open a tab of the WebVisualization.
OEM00044785	WebVisualization: Connecting to WebVisualization with a tablet or a smartphone now consistently returns the addressed page.
OEM00044844	CAA_File.library: The function <i>FILE.DirList</i> now provides information about the file size and date when <i>xDone=TRUE</i> and the directory is empty.
OEM00045192	Resolution of a DTM (Device Type Manager) communication issue now allows FDT (Field Device Tool) information to be saved.
OEM00045337	SysDir Library: <i>CreateFolderTransfer</i> now calls <i>CAL_SysDirClose</i> when the directory is invalid.
OEM00045442	The Symbol Configuration object can now be used/configured for a Turkish localization.
OEM00045474	Symbols created with the Symbol Configuration editor can now be shared with the Vijeo-Designer after upgrading the programming software.
OEM00045495	When you cancel the closing of a project, the message: <i>Could not save project. Object reference not set to an instance of an object.</i> is no longer presented and you can login to the controller.
OEM00045521	An unhandled exception no longer occurs during Project > Export when changing the message categories.
OEM00046210	Variables of large POUs in a CFC program can now be monitored online.
OEM00046215	If you attach two addresses to one contact/coil, a build error message is displayed.
OEM00046286	In the communication elements list of the Add Device dialog box, one version is now displayed for the Modbus devices.
OEM00046718	The message <i>Assertion Failed</i> is no longer displayed during the build process when you use a function of the Conveying library or the Conveying Templates library and afterwards remove the libraries from the project.
OEM00046780	A runtime system shutdown during operation no longer occurs when using a large number of network adapters.
OEM00046838	Toolbar and toolbox no longer disappear while using drag-and-drop of elements/operators in an undocked POU editor.
OEM00047072	Elements of an <i>ARRAY [x..y] OF STRUCT</i> can now be read by Vijeo-Designer.

ID	Description
OEM00047248	In EcoStruxure Machine Expert Logic Builder under Tools > Options > International Settings , the option to select English as language appears now only once in the list.
OEM00047320	Online with an extensive WebVisualization: you can now run an additional stand-alone visualization in parallel.
OEM00047399	In the Tools tree and the Applications tree, the green (+) button is now visible when the width of the Tools tree or the Applications tree is small.
OEM00047586	In the GUI of the programming software, some French translations are no longer missing and French characters are now displayed correctly.
OEM00047786	If you now reduce the size of the Visualization Manager dialog box, buttons are displayed proportionally, and can now be read.
OEM00047962	If you now delete an operator or function block from the LD or FBD editor, and attempt to drag-and-drop another, different element, the correct element will appear as opposed to the element which was deleted.
OEM00048174	The Modbus channel dialog of the Modbus I/O scanner is now translated to Italian.
OEM00048226	The removing of the CANopen connection cable from an Altivar drive (ATV61/ATV71) is now detected.
OEM00048337	<i>SysSockGetRecvSizeUdp</i> now returns <i>ERR_FAILED</i> if a timeout occurs.
OEM00048341	In the Project > Project Settings dialog box, some Italian words were not translated.
OEM00048342	The Tools > Library Repository dialog is now translated to Italian.
OEM00048605	When clicking the Export groups for global visualization button in the Visualization Manager > User Management > Groups tab), the error message <i>Unhandled exception</i> is no longer displayed.
OEM00049190 / PLAT-109	In the GUI of the programming software, there is no longer some Chinese translations missing.
OEM00049405	By converting an XBTGC HMI Controller to an HMISCU Controller, the build error message <i>Out of code memory</i> is no longer displayed.
OEM00049576	The operating modes Circular and Stop when full for the log file of the data log manager now operate correctly. The entries are added at the correct position and the log file is not limited to a fixed size.
OEM00050567	When you add a Visualization to a project and perform an Undo and then a Redo , the navigators (Devices tree, Applications tree, ...) of the programming software now continue to operate correctly.
OEM00050997	DTM dialog message boxes now display the correct icons.
OEM00051067	Index variable values are now displayed correctly when the index variable is of type UINT.
OEM00051333	WebVisualization: When you modified the WebVisualization property Best Fit from Use specified client size to Best fit in online mode , this modification is now taken into account.
OEM00051955	Lexium 23 (LXM23) drive: It is no longer necessary to execute the <i>MC_Reset</i> function block twice to bring the status (PLCopen) from <i>ErrorStop</i> to <i>StandStill</i> when a limit switch (AI14, AI15) is released.
OEM00052042	WebVisualization: The displayed content is now more consistent depending on the browser or smartphone used.
OEM00052458	Performance has been improved when opening a project which includes a CANbus network.
OEM00052907	Now you can close the editor of drive DTMs which control and run a motor, or go offline before the motor is stopped.
OEM00053685	NVL (Network Variables List): During creation of an NVL receiver list, it is now possible to add NVL senders to NVL receiver lists.
OEM00053715	The FDT (Field Device Tool) frame application now verifies whether a DTM (Device Type Manager) is in state <i>Configured</i> before executing import/export and copy/paste operations.
OEM00053859	The time to perform the Build > Clean All command is now more consistent across projects.

ID	Description
OEM00053917 / IECLIB-1423	Unsupported libraries are no longer delivered in the Category: Test Versions .
OEM00054730	Configuring the hotkeys in the VisualizationManager window now operates correctly.
OEM00055008	It is now possible to import a device to a connector which is configured with the attribute <i>explicit=true</i> .
OEM00055516	In a project which contains the Lexium 32i library and the Lexium 28 library, the structured view in the Input Assistant now displays the correct sorting of the function blocks.
OEM00055707	You can now attach several Groups to the same position in your visualization, select the groups, and move them to a new position without an error message being displayed.
OEM00057166	Using the Input Assistant in a visualization no longer causes a shutdown of the programming software.
OEM00057461	When a contact or a coil was added to an LD network and you attempt to attach a variable, the Input Assistant now proposes a BOOL instead of an INT.
OEM00057572	When using Project > Compare , a null reference exception message is no longer displayed and the compare feature operates.
OEM00057670	The attempt to edit the HMI Application object of a Vijeo-Designer device while the Cross Reference List is open no longer causes a shutdown of the programming software.
OEM00058078	If you select several function blocks in an FBD (Function Block Diagram) and delete them, all of them are now deleted.
OEM00058877 / IECLIB-1006	For a PGN (Parameter Group Number) inserted into a J1939_ECU device (CANbus), all the parameter values are now sent.
OEM00059249	The attempt to open Project > Project Information , no longer results in the errant display of the message: <i>Object reference not set to an instance of an object</i> .
OEM00059361	After importing an EDS file (device description), the Hardware Catalog is now updated and the added device is available.
OEM00059847	WebVisualization: When you modify the WebVisualization settings, the settings are now taken into account for download.
OEM00059965	After deleting the first TX Signal of a J1939_ECU device (CANbus), the I/O mapping of the associated PGN (Parameter Group Number) is now correct.
OEM00060184	SVN: Modifications on a CANopen node in the first instance of a project are recognized by SVN and are now also taken into account for the second instance of the project.
OEM00060617 / IECLIB-1006	After saving and reopening a project, the I/O Mapping tab of a J1939_ECU device now displays the Unit column for the TX/RX signals.
OEM00060712	SVN: The time stamps now displayed by SVN provide the local time of the computer running the programming software.
OEM00061003	Replacing an element in an LD network by drag-and-drop from the ToolBox now operates correctly.
OEM00061075	Devices can now be added, copied and pasted, and then deleted from a project without provoking an error message when you execute the Build command.
OEM00061639	SVN: Modifications on the first instance of a project are now taken into account by SVN for the second instance of the project.
OEM00062014	After executing the Convert Device command, a GVL (Global Variable List) is no longer missing in the project.
OEM00062211	Using Project > Export , the prompt to overwrite the already existing project now appears only once.
OEM00062593	Trying to log in to a controller no longer results in an internal error message displayed and the need to execute the Clean all command in order to log in.
OEM00063335	After disconnecting the CANbus connection of a J1939_ECU device, all devices in the Devices tree now display the appropriate color and the status of the J1939_ECU device is now displayed correctly.
OEM00063354	The status LEDs (CAN_R , CAN_E) of the J1939_ECU device are no longer turned off in all operating modes.

ID	Description
OEM00063414	SVN: Under Project Settings > Security > Enable project file encryption > Password , you can add a password to your project. After checking in the project to SVN and checking it out again, the password is now retained.
OEM00063623	SVN: After checking out a project from SVN, save the project and then reopen it again, objects are now highlighted or not as is appropriate.
OEM00063640	In a Ladder Diagram, inserting a function block into a parallel contact branch is now possible.
OEM00063811	SVN: After checking out a project from SVN, the time stamps are now synchronized with the working copy.
OEM00065365	Using the Input Assistant to attach a global variable out of the TcpUdpCommunication library to an application, the name space is now only added once (<i>TCPUDP.GVL.G_stDefault</i>).
OEM00065836	Unforce and Restore all Selected Values now affects %QX0.0 outputs.
OEM00065955	Performance was improved when mapping variables to bits using Modbus TCP servers.
OEM00066218	In connected mode, the tooltip of a variable with mapping to %IX is now correct.
OEM00066295	Variable address mapping can now be deleted in the table view of the declaration section.
OEM00066930	IntelliSense now operates for actions.
OEM00067143	SVN: Performance improvement when calculating the <i>SVN_Version_INFO</i> .
OEM00067152	AS-i Sercos Gateway: During an update procedure, the configured non-safety-related submodules are no longer replaced by default modules.
OEM00067216 / IECLIB-670	Clicking the Ignore button to the error message <i>Out of global data memory</i> no longer causes a shutdown of the programming software when logging in to a controller.
OEM00067283	After performing multiple online changes on a project with an HMISCU Controller, the connection to the controller is no longer interrupted.
OEM00067382	PLCopenXML import: Importing files (Sercos slaves) exported from projects created with earlier software versions is improved.
OEM00067384	PLCopenXML import: Importing files (controllers) exported from projects created with earlier software versions is improved.
OEM00067452	Whenever a Source Upload (after an upload and download of Users and Groups) is performed, a user login is no longer displayed.
OEM00067621	VisualizationManager > User Management : After deleting a RemoteTargetVisualization or a WebVisualization , a build error message is no longer displayed when activating the user rights.
OEM00067743	An incorrect declaration of the initial value of an INT variable no longer causes a shutdown of the programming software.
OEM00067888	Using the Cut command in an FBD (Function Block Diagram) no longer causes a shutdown of the programming software.
OEM00067935	Modifications in the Recipe Manager are now managed correctly during Online Change .
OEM00068130	SVN: Each server polling no longer increases the number of available updates.
OEM00068211	SVN: Server polling now updates the locked-by-other-user icon.
OEM00068219	In an FBD (Function Block Diagram), it is now possible to search for a variable used in an Execute box.
OEM00068229	Symbol Configuration : Modifying the access rights of an object in the Symbol Configuration Editor no longer causes a shutdown of the programming software.
OEM00068383	SVN: Including external objects (<i>svn.include_external(URL)</i>) is now compatible with Python scripting.
OEM00068449	OPC DA (Open Platform Communications Data Access): The communication between OPC clients and the OPC server of controllers no longer stops after one of the OPC clients sends a request for one or more variables of a <Controller> PLCSystem library.
OEM00068458 / IECLIB-1446	Running a Trend Recording and starting and stopping the application no longer results in a watchdog exception.

ID	Description
OEM00068537 / CDSYS-50	Symbol Configuration: The variable list of the Symbol Configuration Editor is now updated correctly.
OEM00068562 / CDSYS-51	The Diff Viewer no longer displays misleading information on unmodified objects.
OEM00068649 / CDSYS-52	In the Diff Viewer , it is now possible to accept the detected modifications with the related button. The new command Project > Commit accepted changes , was added. This command is also available as a button in the toolbar.
OEM00068767	Auto Declare no longer proposes a Type without namespace.
OEM00068847	Program simulation is now possible when a POU contains ARRAY variables and where a variable and an arithmetic operator are used for addressing the ARRAY (Example: <code>slider[slr_index+1]:=55</code>).
OEM00068853	Python Scripting: Setting a new value via <code>IScriptDriverInfo.always_update_variables</code> now operates correctly.
OEM00068954	PLCopenXML import: Some objects, such as <code>SoftMotionGeneralAxisPool</code> , can now be imported.
OEM00068970	PLCopenXML import: Some objects, such as <code>PowerDistribution</code> , <code>DM72F0</code> , <code>DM72F1</code> , and <code>TM5_Manager</code> , can now be imported.
OEM00069258	SVN: A CANbus device is no longer erroneously highlighted as modified.
OEM00069291 / SI-1107	SVN: Each instance of the application now independently updates the parameter values without first being closed.
OEM00069359	In an LD (Ladder Diagram), inserting a function block into a contact branch no longer causes an incorrect diagram.
OEM00069424 / SI-656	It no longer takes long time to close a project while View > Hardware Catalog > Devices & Modules was open.
OEM00069603	Updating the programming software to the latest version: During update, implicit tasks (related to modules) are no longer added to the application when they are already available in the application.
OEM00069634	PLCopenXML import: All importable objects can now be imported.
OEM00069976	Tables in Visualization objects have been made more stable.
OEM00070615	When sending a UDP packet of size 0 to destination port 1740, the communication with the controller is no longer stopped.
OEM00071356	PLCopenXML import: After an import and an export, an output of <code>SR_Main</code> is no longer missing.
OEM00071386	Cross References (locations where variables are used within a project) now operates without generating spurious error messages.
OEM00071389	Using Auto declare for commands in an FBD network no longer cause an unhandled exception.
OEM00071445 / CDSYS-76	PROFINET I/Os are now updated when the application program is stopped.
OEM00071842	Dynamically created recipes are now loaded during download.
OEM00071886	It is now possible to edit parameter lists of libraries in the Library Manager of the POUs tree.
OEM00072172	If an edge detection is used at an output of an object in FBD, this edge detection is now retained after PLCopenXML export and PLCopenXML import of the POU.
OEM00072392	Using Auto declare for an Execute box in an FBD network no longer causes an unhandled exception.
OEM00072417	Using Refactoring > Rename (project-wide renaming of object names and variable names) no longer results in the message: <i>Index was outside the bounds of the array</i> .
OEM00072810	If you select a visualization style that differs from the default, the programming software no longer requests an online change at login after the programming software has been closed and reopened.
OEM00073327	Copy-and-paste of variables in the trace configuration, no longer causes an unhandled exception.

ID	Description
OEM00073465	SVN: The time it takes to update a function block to the latest revision of SVN has been improved.
OEM00073690 / SI-2292	The default resolution of the following placeholders is now correct: <i>SysSocket2</i> , <i>CmpTls</i> , <i>CmpX509Cert</i> .
OEM00074493	As the compile process consumes a large amount of memory size, a download or online change is now performed after the compile process has been finished.
OEM00074646	A Clean all operation led to a peak in memory usage and kept the automatic memory management from collecting garbage memory.
OEM00074872	Access to the filesystem no longer negatively influences the real-time behavior of the system.
OEM00075100 / SI-3324	Comparing different versions of a project is now improved.
OEM00075449	PLCopenXML import: After a PLCopenXML export and subsequent import, an additional output (<i>Out1</i>) is no longer added to an action.
OEM00075456	PLCopenXML import: If a function (FC) with assignment but without variable is exported, the assignment is no longer lost after import.
OEM00075518	Go To Definition command: The command now operates correctly for enumerations in the online view.
OEM00075789	Selecting a variable in the Trace Configuration dialog no longer "freezes" the application.
OEM00075950	Python Scripting: <i>ScriptDriverInfo.driver_info</i> now operates correctly for fieldbus devices.
OEM00069264 / SI-3430	SVN: Reverting project modifications on a controller now operates correctly.
OEM00075591	Opening a SoMachine Motion V4.41 project with EcoStruxure Machine Expert, the correct visualization profile is used now.
OEM00070437 / SSP50-4194	Tying to export the SafeLogger messages to a storage device (for example, an USB device) that does not provide enough memory space, no longer causes a shutdown of the programming software.
OEM00070681 / SI-2262	In the Dependency View of the Code Analysis Manager , the German translation is corrected for specific objects.
OEM00071201	The French and German localization of the User Management dialog (Visualization Manager) has been adapted to the English version.
OEM00072358 / SI-2490	The Vijeo-Designer no longer shuts down with HMI Connection Mode > IP Address (Fast TCP) .
OEM00072397 / LMC FW-1000	The Controller Assistant now loads the firmware of drives. Thus, FDR (Fast Device Replacement) may now operate for drives.
OEM00073151 / SI-2037	SVN: There is now an option to revert a complete project to a specific revision.
OEM00073371 / SI-2254	Firmware update with the Controller Assistant: The Sercos device firmware version dialog was improved. Now the Sercos files from the selected firmware version are used.
OEM00073417 / SI-2466	The programming software no longer shuts down after opening and closing a project several times.
OEM00075268	An unhandled exception is no longer caused by copying and pasting a variable inside the trace configuration.
OEM00075412	Graphics added to the WebVisualization in the programming software are now displayed in the web browser.
OEM00075624 / SI-3446	<i>CheckLRangeSigned</i> and <i>CheckLRangeUnsigned</i> (<i>CheckLibs</i> = POU for implicit checks) now trigger a reaction on PacDrive controller.
OEM00074309 / LMC FW-1154	If you modify the Logic Motion Controller settings or the fieldbus device settings, the fieldbus now continues to operate after a program download.
OEM00075265 / LMC FW-1468	The CanL2 communication now operates even after performing several project downloads.
OEM00070192	NetManager Server service no longer causes communication traffic issues. The automatic refresh behavior was modified.

ID	Description
OEM00076105	Using the Project > Convert Device command to convert the Magelis GTUX HMIG3X device to an HMIG2U device, the screen resolution is now adapted correctly.
OEM00074658 / SI-3196	DTM - TM5/TM7: Using an *.eds file for a TM5/TM7 island without activating the Create all SDOs check box no longer results in an incorrect I/O mapping.

EcoStruxure Machine Expert - Safety

ID	Description
OEM00063913 / LMC FW-577	Applications with an LMC Pro2 controller and many safety-related devices no longer have safety-related axes reporting incorrect reference values which lead to Sercos issues and system shutdown.
OEM00070603 / LMC FW-1973	Phase-up of Sercos with the largest possible safety-related application and a specific device sequence is now possible.
OEM00068174 / SSP50-6797	STO (Safe Torque Off) is stabilized and a communication error is no longer detected.
OEM00069176	A web-based installation of the EcoStruxure Machine Expert - Safety is now available.
OEM00071263	In the Online Help, the description for the TM5CSLCX00FS cycle time has been enhanced and more detailed information is provided.
OEM00072267	In the SafeLogger, a safety-related message is not displayed if the TM5CSLCX00FS is not in operational state due to an incorrect encoder resolution.

Known Operational Anomalies

Limitations for the Release of TM262M••

- Disabling of Safety slices is not supported.
- There are restrictions on the simulation feature of devices in some use cases for machine options.
- The Safety Logic Controller will switch to SafeOS state SAFERUN in case Sercos state NRT is active. This is normal behavior and is used to debug the Safety Logic Controller application in case no TM262M is connected.
- Validation of file name is not performed when a new application file is saved in the local directory: If a file with the same name is in a folder and the user confirms to save in dialog, then the existing file is overwritten without further notification to the user.

Limitations for the Release of TM262••

The minimum required firmware version is 5.0.2.1. If the product has an earlier firmware version, firmware update is mandatory. Update can be executed via SD-card or the Controller Assistant.

Limitations for the Release of PacDrive Controllers

Validation of file name is not performed when a new application file is saved in the local directory. If a file with the same name is in a folder and the user confirms to save in the dialog, then the existing file is overwritten without further notification to the user.

Immediate Addressing

EcoStruxure Machine Expert allows you to program instructions using either a direct or indirect method of parameter usage. The direct method is called Immediate Addressing where you use direct address of a parameter, such as %IWx or %QWx for example. The indirect method is called Symbolic Addressing where you first define symbols for these same parameters, and then use the symbols in association with your program instructions.

Both methods are valid and acceptable, but Symbolic Addressing offers distinct advantages, especially if you later make modifications to your configuration. When you configure I/O and other devices for your application, EcoStruxure Machine Expert automatically allocates and assigns the immediate addresses. Afterward, if you add or delete I/O or other devices from your configuration, EcoStruxure Machine Expert will account for any changes to the configuration by reallocating and reassigning the immediate addresses. This necessarily will change the assignments from what they had once been from the point of the change(s) in the configuration.

If you have already created all or part of your program using immediate addresses, you will need to account for this change in any program instructions, function blocks, etc., by modifying all the immediate addresses that have been reassigned. However, if you use symbols in place of immediate addresses in your program, this action is unnecessary. Symbols are automatically updated with their new immediate address associations provided that they are attached to the address in the I/O Mapping dialog of the corresponding Device Editor, and not simply an 'AT' declaration in the program itself.

WARNING

UNINTENDED EQUIPMENT OPERATION

Inspect and modify as necessary any immediate I/O addresses used in the application after modifying the configuration.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

NOTE: Systematically use symbols while programming to help avoid extensive program modifications and limit the possibility of programming anomalies once a program configuration has been modified by adding or deleting I/O or other devices.

EcoStruxure Machine Expert - Safety

ID	Description
OEM00060343 / SSP50-6783	In the SafeLogger you can read that the status of an input/output of a safety-related module has changed. Detailed information on the reason can be decoded out of the additional <i>info0</i> and <i>info1</i> information. (Refer to the SafeLogger User Guide).
OEM00060774	The communication state between the Safe Logic Controller TM5CSLCx00FS and a drive is not indicated by a message in the SafeLogger: Under certain conditions, a drive is treated as a non-working drive but this is not recognized by the SafeLogger or by the drive. You have to restart the Safe Logic Controller TM5CSLCx00FS to recover.
OEM00068735 / SSP50-6800	If you set the <i>MaxDataTransportTime</i> and <i>CommunicationWatchdog</i> parameters to significantly greater values than proposed by the calculator (for example, 6500 ms), this can result in an unstable system because these parameters influence the timeouts and restart timing of the safety-related system. In this case, the <i>ModuleOK</i> status for some safety-related modules is not reached or is unstable. Use the values calculated by the Response Time Calculator . Do not increase the parameters by more than factor two.
OEM00068980 / SSP50-6805	If you set the value for <i>MinDataTransportTime</i> to a value less than the value calculated by the Response Time Calculator , a build error message may be displayed. The <i>MinDataTransportTime</i> must be set to the calculated value.

ID	Description
OEM00069079	System limitation on number of drives with 1 ms Sercos time setting: With TM5CSLCx00FS firmware version 2.47 and earlier, up to 22 safety-related drives can be handled with 1 ms Sercos time setting. The maximum number of slaves depends on different factors: • The number of physical connected devices. • The configured additional real-time parameters. • The data exchanged between LMC and TM5CSLCx00FS. • The number of additional safety-related devices (I/O modules, safety-related gateways...). Workaround: When the error message <i>C1D 0x010A</i> is displayed, the system limit is reached. In this case, the system must be optimized on the influencing factors. Another possibility to increase the number of supported safety-related drives is to split the machine into several modules, with each one having a TM5CSLCx00FS and an LMC inside.
OEM00069082 / SSP50-6808	TM5CSLCx00FS displays the internal error message <i>BF86</i>: This occurs when <i>SafeModuleOK</i> parameter is not used in all safety-related modules in the system. Workaround: Use the <i>SafeModuleOK</i> parameter in all safety-related modules.
OEM00070294 / SSP50-6812	The channel of a safety-related module goes to FALSE if an unsuitable cycle time value is configured: The <i>CycleTime</i> value must be greater than the processing time for the safety-related application. If the <i>CycleTime</i> parameter value is less than or too close to the processing time, a cycle time violation may occur. The cycle time configured for TM5CSLCx00FS must be an integer multiple of the Sercos cycle time. You must configure an appropriate TM5CSLCx00FS cycle time: • Set a greater cycle time value for the TM5CSLCx00FS. • Download and run the safety-related application. • Open the SafePLC control dialog and click the info button: The present processing time is displayed. • Set the TM5CSLCx00FS cycle time to a value $\geq$ processing time + 1 ms.
OEM00070390	No information could be found for the SafeLogger entry <i>0x9406</i>. This entry indicates a cross communication issue in the network processing engine.
OEM00070466 / SSP50-4192	When the <i>MaxDataTransportTime</i> value is set to a value that is too small, the <i>TM5CSLCx00FS</i> does not change its status to RUN. Workaround: Use the value from the Response Time Calculator. If this value does not work, increase the <i>MaxDataTransportTime/CommunicationWatchdog</i> in small steps up to a maximum of two times the calculated value.
OEM00070475	TM5CSLCx00FS does not change its status to RUN and stays in <i>PreOp</i> mode. Possible reasons: • For one or more drives, the safety-related parameters are not valid. • <i>OutputActiveSet</i> value is missing. • <i>AutoRun</i> is not activated. • Safety response time relevant parameters are not set to appropriate values.
OEM00070493 / SSP50-6817	Sporadically, safety-related modules do not go to operational state: After the restart of an LMC (Logic Motion Controller), the TM5CSLCx00FS goes to operational state but the safety-related modules stay in pre-operational state. Workaround: Restart the entire system.
OEM00071897 / SSP50-6831	In the SafeLogger, some issues are displayed as non-safety-related messages, whereas they should be safety-related messages. Known issues: • <i>0x9414 Cross communication error</i> • <i>0x960B Internal error cross communication</i> • <i>0xD126 Execution differences processes</i> • <i>0x8609 Supply voltage error</i> Use the latest firmware versions for the safety-related components in your system.
OEM00077282 / SSP50-6867	In one special tested system configuration, running with 1 ms Sercos cycle time the state of <i>SafeModuleOK</i> parameter of one safety-related module changes from

ID	Description
	TRUE to FALSE. This does not occur with 2 ms and 4 ms as Sercos cycle time in the same configuration. Workaround: Use 2 ms or 4 ms as Sercos cycle time if applicable for your application or slightly adjust the safety-related timing parameters (for example <i>maxDataTransportTime</i>).
OEM00052480	Support of special characters (German umlauts) in variable names in ST: An error is detected if a special character is entered as part of the naming of a variable in EcoStruxure Machine Expert - Safety. It is not possible to ignore or cancel this exception. The program must be terminated by the windows task manager. After restarting EcoStruxure Machine Expert - Safety, the special character can be deleted. Workaround: Do not use special characters in variable names.
OEM00073379 / SSP50-6844	TM5CSLCx00FS stays in boot state after MXCHG confirmation for drives: TM5CSLCx00FS indicates MXCHG after the drive has been replaced. To confirm drive replacement, MXCHG ask for confirmation twice. After the second MXCHG confirmation, TM5CSLCx00FS reboot its-self and stays in bootphase (FIL leds light) until it is physically restarted. Workaround: Switch off and on the control voltage.
OEM00070117 / SSP50-6811	Number of possible safety-related axes varies between ring and line topology.
OEM00077251 / SSP50-6866	TM5 modules switch <i>SafeChannelOK</i> state to FALSE during Sercos ring break.

Documentation - Mitigated Anomalies

Documentation

ID	Description
OEM00061702	In the German Online Help, the section headers of some TM5/TM7 safety-related modules are now translated.
OEM00061925	Some information on using SELV/PELV for TM5 safety-related modules is no longer missing in the Online Help.
OEM00062559	In the Online Help, the SVN icons are now documented.
OEM00063454	In the Online Help, the description for <i>ErrorState_2</i> and <i>ModuleOK</i> of the TM5SDM8DTS module is no longer missing.
OEM00065214	Multiple download: An information was added to the Online Help to deselect the Start all applications after download option to help prevent the targeted controllers from restarting in the <i>RUNNING</i> state.
OEM00072124	Hanging and Pulling Loads (<i>Lexium 52 drive - Product manual</i>): A misleading reference to Lexium 62 variants E/F was removed.

EcoStruxure Machine Expert V1.1 SP1

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M241	5.0.7.23
M251	5.0.7.23
M262	5.0.3.2
TMSES4	1.0.0.8
TM3BCEIP	1.2.1.1

Description	Firmware Version
TM3•HSC202•	2.0
TM3DI16	2.0
TM3DI16G	2.0
TM3DI16K	2.0
TM5NS31	2.74
LXM32S•••M2 drive	1.06.03
LXM32S•••M2 Sercos	1.08.04
LXM32S•••N4 drive	1.06.03
LXM32S•••N4 Sercos	1.08.04
LXM52••••C••••	1.54.26.0
ILM••••••••••	1.54.26.0
LXM62••••C••••	1.60.0.0 for hardware revision RS1• 1.54.27.0 for hardware revision RS0•
LXM62••••D••••	1.60.0.0 for hardware revision RS1• 1.54.27.0 for hardware revision RS0•
LXM62••••E••••	1.54.27.0
LXM62••••F••••	1.54.27.0
LXM62••••G••••	1.60.1.0
LMC Eco	1.61.0.1
LMC Pro	1.61.0.1
LMC Pro2	1.61.0.1

Description	Safety-Related Firmware Version
LXM62••••E••••	1.2.4.0
LXM62••~F••••	1.2.4.0
VW3E702200000 safety option module	1.2.4.0
TM5CSLC100FS	2.52
TM5CSLC200FS	2.52
BWU2984 SWID	134253
BWU2984 Safe CPU A	135115
BWU2984 Safe CPU B	135116
ASIMON360	3.2.6.7

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

Mitigated Anomalies

PacDrive LMC Controls & I/Os

ID	Description
OEM00078652 / OEM00077643 / LMC FW-1524	The function <code>SystemInterface.FC_DrvEncSetPosition</code> cannot write the encoder position of an ILM.

M241/M251

ID	Description
OEM00076481	Crafted HTTP request on web visualization could lead to information leakage or unintended controller behavior.
OEM00078382	Missing input validation in Web interface.
OEM00078535	Crafted HTTP request on web visualization could lead to unintended controller behavior.
PEP0536708R	ASCII frames dropped when serial connection was configured with low baudrate and disturbances were applied on the line.

M262

ID	Description
OEM00078089	After several hundred of 'Reset Cold', an error could appear. Internal error was detected on the controller, the ERR LED fast flashing and the application removed.
OEM00078072	Some controller tasks were stopped without information (no error detected) in debug mode.
OEM00078057	SSI encoder: Value was temporarily outdated (each 20 ms) - same value during two SSI cycle times.
OEM00077980	M262: Unintended stop of operation under specific denial of service, causing internal error on controller with the ERR LED fast flashing and the application removed.
OEM00077977	When the connection was interrupted during the transfer phase download FTP over TLS, the controller task stopped without information (no error message).
OEM00077909	If a TMSES4 was configured and available, approximately every 6 s the serial communication was interrupted for approximately 3 s.
OEM00077889	When access to variables not available in the controller was requested through Machine Expert Protocol, an internal error was detected on the controller with 'Led ERR Fast flashing' and the application was removed.
OEM00076813	No hardware fallback if the controller was non-responsive after a watchdog Hardware timeout (1.6 s).
OEM00074451	After one week of operation, the controller time was ahead of local time (approximately 4 s).

M262 - Motion

ID	Description
MK-833	Lexium 32S <i>CaptureEdge</i> (Cap1, Cap2, and Cap3) offline parameter value was not applied after download.
MK-817	Controller task suspended after a reset of the encoder error.
MK-804	The Sercos service channel stopped operating after several hours.
MK-790	Unstable SSI encoder movement of Position/Vel/Acc.
MK-778	Safety Logic Controller integration - parameter editor: The information about which function blocks to use was incorrect.
MK-767	An axis with <i>CustomJob</i> without master could not be master for another axis.
MK-764	<i>MC_Power</i> error did not reset properly in some special cases.
MK-734	It was not possible to reach Sercos phase 4 when Sercos bus coupler TM5NS31 with safety slices was set to simulated working mode.
MK-699	<i>xIsHomed</i> flag was not reset properly on encoder axis.
MK-631	Improved performance while performing Sercos phase up.

ID	Description
MK-249	SLC.OutputActiveSet offline parameter value was not applied after download.
MK-223	Sercos master DesiredPhase offline parameter value was not applied after download.

Known Operational Anomalies

PacDrive LMC Controls & I/Os

ID	Description
OEM00054944	It is not possible to establish an EtherNet/IP connection when the EtherNet/IP device (ATV32/IL•) is connected directly to the controller. Workaround: You must add a switch between the controller and the EtherNet/IP device.
OEM00070704 / LMCFW-1976	If EcoStruxure Machine Expert and previous SoMachine Motion versions are installed in parallel on the local PC, the Controller Assistant provides a firmware version for selection that does not match.
OEM00076369 / SI-3444	Modifications are detected for persistent variables, although the persistent variables were not modified. This occurs if a 128 Mb Compact Flash (CF) memory card is used.
OEM00076650 / LMCFW-2023	Too many fieldbus participants with too much data can lead to the following error message: <i>EtherCAT Master: Download busconfiguration to NetX....</i>

Lexium 52 / 62 / 62 ILM

ID	Description
OEM00063956	ILM motor: If the Kendrion brake is used, the voltage value for the holding brake is set to the minimum value required by the brake. This minimum value is monitored. Deviations during measuring can cause malfunctions of the brake. NOTE: See important hazard message after the table.
OEM00065793	If you use a Lexium 62 drive (LXM62) in open-loop control and set <i>RefVelocity</i> = 0, a current value is displayed in the monitoring trace diagram, even though no current value was expected in open-loop control.
OEM00069062 / SSP50-7128	Diagnostic code 8123 is reported for one of the axes at standstill: An application containing a master axis with a Cam and other axes at standstill reports the diagnostic code 8123 when testing under specific conditions.
OEM00069830	A Sercos run-up with a double-line topology is not possible for Lexium 62 drives.
OEM00070988	The Lexium 52 drive does not boot after firmware update (version 1.54.10 -> 1.54.23).
OEM00072092	Your application contains a Lexium 62/ILM 62 drive with safety-related modules (LXM62/ILM62 Safety Module). If you reboot the Sercos network, the diagnostic message <i>8169 Sercos Slave comm. disturbance detected</i> is displayed in the message logger.
OEM00073627	Using an MH3 motor with a Sinus/Cosinus encoder connected to a Lexium 52/62 drive triggers the diagnostic message <i>8908 Unintended motor operation detected</i> .
OEM00074275	Lexium 62 Plus: After online modification of parameters and then a phase down and phase up in a different topology, modification of parameters of type ES is no longer possible.
OEM00075885	Lexium 62 Plus: Flashing of state LED during device identification on single drives and advanced drives is slower (2 Hz) than on double drives.
OEM00077378 (OE-M00073129)	Lexium 62 Plus: A sequence of Sercos topology modifications may lead to a Sercos error message.

ID	Description
–	Lexium 62 Plus: The diagnostic message <i>8503 Service service channel error detected</i> is triggered at phase up if one of the following parameters is configured as a real-time parameter: <i>UserDefinedStopJerk</i> , <i>UserDefinedStopDeceleration</i> , <i>TrackingDeviationLimit</i> .
–	Lexium 62 Plus: Firmware update using the device assistant inside virtual machines may not update all drives. Repeated updates may be required.
–	Lexium 62 Plus: Writing the motor type plate for sensorless motors into advanced drives (variant G) triggers an error message, that type plate has not been written. Nevertheless the type plate is available after a reboot of the drive.
–	Lexium 62 Plus: Machine encoder data is not actualized after change of encoder and reinitialization. A power cycle is required.
OEM00078751	If Lexium 62 Advanced is configured to use machine encoder and no machine encoder is connected, no diagnostics message is triggered.
OEM00078419	For asynchronous motors used in combination with Lexium 52 / Lexium 62, the sign of the current value does not match with the direction of the motor.
OEM00078784	Changing the filter time in combination with torque limitation triggers a Sercos parameter channel error.

⚠ WARNING

UNINTENDED EQUIPMENT OPERATION

- Verify that movements without braking effect cannot cause injuries or equipment damage.
- Verify the function of the holding brake at regular intervals.
- Do not use the holding brake as a service brake.
- Do not use the holding brake for safety-related purposes.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

M241/M251

ID	Description
OEM00074655 / PLAT-524	M241/M251: The Online > Multiple Download command is not performed correctly for Modicon M241 / M251 Logic Controllers: When an application with two controllers has been modified and the Multiple Download command is executed, the application is not downloaded to one of the controllers. Workaround: Execute the Build > Clean All command before executing the Online > Multiple Download command.
OEM00074733 / PLAT-525	The default values of cartridge outputs are not applied in the same way during RUN->STOP and RUN->RESET WARM transitions.
OEM00072286 / PLAT-490	Default values remain enabled during RUN->STOP transition even if removed from the application.
OEM00077925 / PLAT-563	During migration of an application from SoMachine V4.3 (with user rights enabled) to EcoStruxure Machine Expert, the user rights are not automatically converted before being downloaded to controller. You cannot log in into the controller. Workaround: Use a script stored on the SD card executing the command <i>delete /usr/*</i> or performing a firmware update from the SD card.

M262

ID	Description
OEM00077150 / IECLIB-2031	TcpUdpCommunication library: At first startup after firmware update, the certificate store is not ready. An application that includes TLS communication needs a second startup.
OEM00071051	Tasks of type Freewheeling must have a minimum cycle time of 3 ms.
OEM00073787	WebVisualization with trace objects significantly increases the processor load.
OEM00074101	The Sercos master does not provide network configuration parameters for Sercos slaves (IP address, subnet mask, gateway).
OEM00074841	SSL connection is noticeably slow if client has chosen a cipher suite that uses DHE/ECDHE key exchange.
OEM00075485	Adding a TM5NS31 and I/O modules to a Sercos network impacts the M262 cycle task.
OEM00075670	WebVisualization: SelfAwareness variables cannot be used directly inside a WebVisualization.
OEM00076315	The diagnostic structures of PLCSystem/PLCSystemBase library (for example <i>PLC_R</i>) cannot be accessed directly from external monitoring devices through the Symbol Configuration . They first must be copied to local variables.
OEM00076939	All nodes in a ring topology need to support RSTP (rapid spanning tree protocol).
OEM00076940	EtherNet/IP Scanner: A "stateful" firewall keeps in its memory the connections flow. If such a firewall is defined, the EtherNet/IP traffic from slaves sending their assemblies in multicast may be blocked. So this firewall mode must not be used in this case.
OEM00077157	OTB devices may not respect the scanner RPI (Requested Packet Interval) when TM3 analog modules are configured.
OEM00077199	After transferring an application using an SD card, a TM3XHSC module may restart with an error message. A power cycle restores the correct operation.
OEM00077280	Using the <i>PLCO.MC_TouchProbe</i> with an invalid argument for <i>ifTrigger</i> is not managed as expected.
OEM00077663	If a firmware update using an SD card completes with a steady yellow SD card LED, repeat the firmware update operation.
OEM00077713	When you are modifying the user rights, ensure that no external equipment are trying to access M262 variables with former credentials.
OEM00077807	TM3 bus cycle time must not be set to a value greater than 200 ms when TM3XHSC modules are configured.
OEM00077830	<i>NbOfIncs</i> and <i>NbOfUnits</i> values must be $< 2,147,483,647$ (2^{31}), else the capture is invalid.
OEM00077839	The boot time of a controller increases when the number of files increases.
OEM00077915 / BOC-304	The PWR LED turns to red when the internal temperature is $> 80^{\circ}$ (instead of $> 100^{\circ}$).
OEM00076745	If EcoStruxure Machine Expert is running in a Virtual Machine (VMware), M262-USB may conflict with the VMware: • USB communication is inoperable. • The controller is not discovered in: <i>My Controller/Communication setting</i>. Install EcoStruxure Machine Expert directly on the PC or use Ethernet for PC connection to the controller.
OEM00077894	If SoMachine V4.3 or an earlier version was installed on the computer, the IP address used by the PC is not correct. Thus, the USB communication is not operational. Workaround: You have to select the network interface SE RNDIS PSX M262 connection under <i>Control Panel/Network and Internet/Network and Sharing Center</i> and set the IP address manually to 192.168.200.2.
OEM00077911	An M262 is not discovered by USB and cannot be connected to EcoStruxure Machine Expert. Workaround: You have to restart the USB by the gateway. Select the gateway tray application and restart the gateway.
OEM00077737	When unplugging and plugging an M262 cable (Eth2-RJ45), there was Modbus IO-scanner application loss on the ATV340.

M262 - Motion

ID	Description
MK-823	When working with 16 LXM32S and 23 TM5 BC and 1 SLC with multiple MC_CamIn running on all LXM32S, and when using a MAST task at 5 ms, the controller reports an overload of the task. Workaround: When working with big configurations, ensure that you use a proper cycle time for your controller task by verifying the load of your task during commissioning. Also, configure a Watchdog on your task to ensure that there is no overload during run time.
MK-835	MC_TouchProbe reports no error when the drive is disconnected. When you execute an MC_TouchProbe on an LXM32S and you disconnect the drive, the function block does not report an error. The output Busy stays active. Workaround: Make sure to cancel the running MC_TouchProbe using MC_AbortTrigger.
MK-847	Starting MC_CamIn with non-connected SSI-encoder as master results in the ErrorID: Unexpected Feedback. Workaround: If starting an MC_CamIn with an SSI-encoder as master, and this SSI-encoder is not connected to the M262, the ErrorId reported is Unexpected Feedback when it should be MasterDataInvalid.

HMISCU Controllers

ID	Description
OEM00077527 / SI-4094	The EcoStruxure Machine Expert Logic Builder command Refactoring > Rename is not available for HMISCU controllers. You must rename HMISCU controllers manually without the Refactoring feature.

Library Information

Version Identification

Description	Version
ApplicationLogger	1.1.2.0
AsyncManager	1.0.5.0
AutoTune	1.3.14.0
Booster Pumping	5.0.0.5
CommonMotionTypes	1.0.1.0
CrankModule	1.3.4.0
EmailHandling	2.0.4.0
EtherNetIP Explicit Messaging	1.1.7.0
EtherNetIP Remote Adapter	1.0.10.0
FileFormatUtility	1.2.6.0
FtpRemoteFileHandling	1.2.4.0
GMC Independent Altivar	1.2.4.0
GMC Independent Lexium	1.1.7.0
GMC Independent PLCopen	1.2.3.0
HttpHandling	1.0.11.0
M262 Encoder	1.0.0.2
M262 PLCSystem	1.0.0.19

Description	Version
M262Diagnostics	1.0.1.0
MotionInterface	1.1.75.12
MqttHandling	2.0.6.0
PackML	1.2.3.0
PD_AxisModule	1.6.2.0
PD_EDesignAxisModule	2.3.2.0
PD_EdesignCore	2.2.6.0
PD_EdesignCrankModule	1.5.2.0
PD_ETest	1.3.6.0
PD_GlobalDiagnostics	1.3.1.0
PD_MultiBelt	1.4.3.0
PD_MultibeltModule	1.4.1.0
PD_PacDriveLib	1.8.7.0
PD_SmartInfeed	1.4.3.0
PD_SmartInfeedModule	1.3.1.0
PD_SoMotionGenerator	1.5.1.0
PD_Template	1.6.1.0
PLCopen MC part 1	1.1.69.12
PreventaSupport	1.1.1.0
Robotic	2.12.1.0
RoboticModule	2.8.0.0
SchneiderElectricRobotics	2.8.0.0
SchneiderElectricRobotics Parameters	2.9.0.0
SchneiderElectricRobotics Toolbox	1.2.0.0
SercosCommunication	1.0.1.0
SercosDriveUtility	1.1.1.0
SercosMaster	1.1.75.12
SlcRemoteController	1.3.6.0
SnmpManager	1.2.1.0
SqlRemoteAccess	1.1.2.0
TcpUdpCommunication	2.0.11.0
TeSys island	1.1.0.0
TimeSync	1.1.2.0
Toolbox	3.0.1.0
TwidoEmulationsupport	1.2.2.0
Unwinder	1.2.3.0
UnwinderModule	1.1.0.0
UserMotorTypePlate	1.3.9.0
UserTorqueFeedForward	1.1.2.0

Version Identification Safety Libraries

Description	Version
EnableSwitch_SE_SF	V0.99 from 10/28/15
PLCopen_SF	V1.00 from 09/14/07
Preventa_SafeMotion	V0100.0100 from 02/08/16

Mitigated Anomalies

Libraries

ID	Description
OEM00077455 / IECLIB-2072	<i>FB_FtpClient</i> : Communication interruption during file transfer is now detected.

Known Operational Anomalies

Libraries

ID	Description
OEM00056474 / IECLIB-94	AxisModule library: The command <i>ET_Cmd.StartTrigWaitInPos</i> is sent to the <i>FB_AxisModule</i> to perform a positioning while the command is active, the input <i>iq_diCmd</i> is overwritten by the value 0. In this situation, the <i>FB_AxisModule</i> triggers the diagnostic message <i>UnexpectedProgramBehavior (DiagExt = UnknownCase)</i>. Workaround: Re-enable the function block to quit the diagnostic message.
OEM00072319 / IECLIB-1966	SmartInfeed library: Using the <i>ET_TargetGeneratorMode.External</i> in combination with the <i>FB_VelocityRatioAlgorithm</i> and defining an invalid target position triggers a <i>page fault</i> exception.
OEM00073262 / IECLIB-2427	MultiBelt library: If the start station is defined as a <i>PassBy</i> station, the second train remains in arriving state (<i>ET_TrainState.Arriving</i>).
OEM00073263 / IECLIB-2428	MultiBelt/MultiBeltModule library: Under certain conditions, after stop and warmstart of a <i>MultiBelt</i> module, the <i>ET_DiagExt</i> message <i>TrainMovesBackward</i> is displayed.
OEM00074810 / IECLIB-1739	Unwinder library, precontrol movement by an external master (bobbin radius changes): The <i>Setpos</i> value for this movement is incorrect if <i>DRV_WinderRight.Direction = left</i> .
OEM00075899 / IECLIB-2444	MultiBelt/MultiBeltModule library: The <i>q_xHomeOk</i> bit of all trains is set to TRUE in homing mode <i>HomeOnTp</i> , even if the homing procedure was stopped due to missing <i>TouchProbe</i> signals.
OEM00076350 / IECLIB-1883	Unwinder/UnwinderModule library: A basic load is required when the unwinder is empty. The basic load value is replaced by the calculated value but the calculated value should be added to the basic load value.
OEM00076417 / IECLIB-2448	MultiBelt/MultiBeltModule library: Under certain conditions, a train starts moving backwards after a coldstart, but is stopped immediately. An error message is displayed.
OEM00074744 / LMCFW-2010	SystemInterface library: Calling the <i>FC_TPEdge</i> triggers the diagnostic message <i>8902 Software error (page fault)</i> in the RTP (Real Time Process) task, and the controller displays a hardware watchdog message.
OEM00077150 / IECLIB-2031	TcpUdpCommunication library: At first startup after firmware update, the certificate store is not ready. An application that includes TLS communication needs a second startup.
OEM00078797	Writing a nameplate by use of <i>FB_InitMachineEncoder</i> results in high tracking deviation. Workaround: Restart Sercos bus after the nameplate is written.

ID	Description
OEM00078768 / IEC LIB-2231	Leaving multibelt OpMode and restarting to automatic mode by executing a warm start may trigger a page fault.
OEM00078541 / ROB-94	Robotic: The EcoStruxure Machine Expert installation does not include the library ARMIO.

Software Information

Version Identification

Description	Version
Machine Expert Installer	11.19.16801
Diagnostics	18.1.1.0
Controller Assistant	18.1.1.0
Device Assistant	18.1.1.0
DiffViewer	18.1.1.0
Gateway	18.1.1.0
Launcher	18.1.1.0
OPCServer	3.5.12.70
SoftSPS	3.5.12.80
SVN	4.2.4.0
Logic Builder ⁽¹⁾	1.1
Vijeo-Designer	6.2.8.4008
CoDeSys	V3.5 SP12 Patch8 HF2
SQL Gateway	18.0.1.0
Motion Sizer	4.1.0.0
(1) If using a virtual machine, the download of the online help operates correctly only if the option Accelerate 3D graphics is deactivated in the VM settings.	

Compatibility EcoStruxure Machine Expert

Overview

EcoStruxure Machine Expert can be installed in parallel to other Schneider Electric software products, such as SoMachine and SoMachine Motion.

For general information on compatibility of EcoStruxure Machine Expert, refer to the Compatibility and Migration Guide (see EcoStruxure Machine Expert Compatibility and Migration, User Guide).

EcoStruxure Machine Expert V1.1 SP1 updates the existing EcoStruxure Machine Expert V1.1 installation.

Mitigated Anomalies

Controller Assistant

ID	Description
OEM00078093 / SI-4431	The command line from the Controller Assistant did not support a command to list the available Sercos slave versions.

EcoStruxure Machine Expert

ID	Description
OEM00078173 / TES-152	EcoStruxure Machine Expert did not stop monitoring from variables in online mode even if the variable was not visible. In some cases, this caused high memory load and slow down of online monitoring in specific or huge projects.
OEM00078040 / OEM00077799 / LMCFW-1302 / SI-4379	If Execute program was selected as the behavior for outputs in Stop mode and an exception occurred in the controller (e.g. a division by 0), the communication between EcoStruxure Machine Expert and the controller stopped if the POU's for implicit checks were active in the project and a new Application download was executed.
OEM00078036 / OEM00077749 / TES-152	In the event of some specific or huge projects it could happen that EcoStruxure Machine Expert froze periodically every few minutes. In these cases the used RAM from the EcoStruxure Machine Expert went from 6 GB to 4 GB.
OEM00077971 / OEM00077799 / SI-4379	The communication between EcoStruxure Machine Expert and the controller stopped with an error detected in <code>GlobalInit</code> if the function block input was assigned via direct addressing (AT%).
OEM00077962 / OEM00077791 / TES-152	In big projects expanding an array in online mode (watchlist, declaration editor) EcoStruxure Machine Expert could freeze for up to 10 seconds.
OEM00077833 / TES-152	It was not possible to execute an online change after modifying a variable of an FBD program which contains structs, arrays, etc.
OEM00076607 / OEM00077711 / TES-152	When modifying the trace configuration (insertion, deletion, display / hiding) of variables, the cursor went to the beginning of the configuration.
OEM00075276 / CDSYS-256	When a trace was shown in Logic Builder, the values were not displayed properly and the next value on the left-hand side was displayed. It was necessary to select the variable itself to see the exact value from the cursor.
OEM00077734 / OEM00074209 / PLAT-98	When using direct addressing in the EcoStruxure Machine Expert project, an advisory message was displayed everytime you performed a build (F11) of the project. This dialog box had to be confirmed by pressing Alt + F.
OEM00078553 / SI-4555	The sub-objects (Methods, Properties, ...) were locked in SVN when the parent object (POU) was modified.
OEM00078290 / SI-4457	The project update changed the offline parameter value of <code>ControlMode</code> .
SI-4261	Sometimes an unhandled exception occurred (...HWND...) in combination with DTMs.
SI-4514	EcoStruxure Machine Expert shell did sporadically not work with controllers in simulation mode (unsuccessful login).
SI-4652 / OEM00078509	EcoStruxure Machine Expert opened the SLC Remote Controller example instead of the Quick Motion Programming.
OEM00077162 / SI-3909	A CSV export did not contain all data in case of a 2-dimensional array of DUT.
OEM00078358 / SI-4571	<code>LibDoc</code> scripting transformation is not working
IECLIB-2187	Function Template for <code>HttpClient</code> has been implemented

Known Operational Anomalies

EcoStruxure Machine Expert

ID	Description
OEM00064709 / MS-1900	Motion Sizer: The torque/speed curve of the SH205/30360 with an external fan is calculated incorrectly.
OEM00067341 / MS-1898	Motion Sizer: The performance of the Motion Sizer with large projects is slow while entering axis names and descriptions (slow refreshing).

ID	Description
OEM00072759 / MS-1910	Motion Sizer: It is not possible to add Lexium 62 ILM drives of different sizes to the same connection module. The rounding operation for the cycle time does not provide suitable values.
OEM00069953 / BOC-550	To display different comments for libraries you can enter the key <i>LibDocContent</i> . Using <i>LibDocContent</i> with <i>DocsOnly</i> or <i>CommentsAndDocs</i> , the same results are displayed.
OEM00073945 / BOC-547	Accessing a variable name of the TM5 module I/O mapping is not possible with Python scripting using an ARRAY.
OEM00075351 / BOC-544	You log in to a project (FBD code) and put the focus on a network (which is not the last one) in an action/program. If you log out and log in again, the focus will be on the last network in the action/program. The same behavior is shown up, if you switch between two actions.
OEM00063214 / BOC-90	TCP socket communication is delayed sporadically when the programming software is connected to the controller.
SI-3439	While converting a device during Update Project , you may be asked to delete internal data of persistent variable lists. Depending on the number of devices to be converted, this question may occur several times. Confirming it will avoid asking again for devices of the same controller.
SI-3971	When you convert a controller, for example, an M262L20 to an M262M35, the module configuration of the TM5/TM7 interface is not converted and is no longer available after conversion. Workaround: 1. Export and remove the TM5_Interface before the conversion. 2. Start the conversion. 3. Import the TM5_Interface after the conversion.
SI-3727	For ATV-DTM with activated control panel, the Disconnect command does not have any effect when the motor accelerates (ACC), turns constantly (RUN) or decelerates (DEC). To stop the motor, press the Stop button. Nevertheless, the control panel is not updated and still displays the state that was active before. You can execute the Online > Logout command, but this may have the effect that EcoStruxure Machine Expert is being closed.
OEM00076442 / SI-3505	Context sensitive help (F1) is not available for POU's declared with namespace.
–	If you are using a Virtual Machine (VM) you must deactivate the option Accelerate 3D graphics in the VM settings before downloading the online help.
SI-4244	ATV340: The DTM is not available.

EcoStruxure Machine Expert - Safety

ID	Description
OEM00078801	Exchanging data between an M262 controller and an SLC is not operable if not both directions are configured. Workaround: Configure at least one exchange data in both directions, then the data exchange becomes operable.

Documentation - Mitigated Anomalies

Documentation

The online help is updated with the following documentation:

- M262 Diagnostics Library Guide
- M262 Logic/Motion Controller - Programming Guide
- M262 Logic/Motion Controller - Hardware Guide
- TM3 Expert Modules - Hardware Guide

- TMS Expansion Modules - Hardware Guide

ID	Description
OEM00077576 / BOC-276	M262 documentation of cloning procedure wrongly said that the ERR Led flashes at the end of successful cloning procedure.
OEM00077931 / BOC-288	Incorrect encoder transmission speed list and default value in M262 documentation.
OEM00077981 / BOC-291	M262 documentation must inform that the network name modification is applied at next power ON.
OEM00077984 / BOC-292	M262 industrial plug and work documentation did not include the information that the locate button must be used to well identify the target device.
OEM00077991	M262 documentation did not include an explanation on how to remove user rights using a script with command format .
OEM00078056 / BOC-297	M262 Programming Guide: Incorrect link to Modicon M262 Logic/Motion Controller Sercos Configuration.
OEM00078083 / BOC-298	TM3 Expert I/O Modules Hardware Guide: Incorrect description of LEDs state when a TM3X•HSC• module is not configured.
OEM00078297 / BOC-305	M262 Programming Guide contained several minor incorrect descriptions.
OEM00078298 / BOC-306	Incorrect ISO standard reference for CAN characteristics of the TMSCO1 module.
OEM00072944 / BOC-199	M262 documentation did not contain the information that Reset origin command makes the web visu files erased.

Documentation - Known Operational Anomalies

Documentation

ID	Description
OEM00032469	Detailed information required for WD (watchdog) of the logic motion controller LMC •01. Documentation needs to be enhanced.
OEM00045026	Some dimension values provided by the hardware guides and the CAD files on the Schneider Electric homepage are slightly different for LXM 52 drives, LXM 62 drives and LMC Eco Motion Controllers. Documentation needs to be enhanced.
OEM00058892	In the Online Help, the chapter <i>TM5 / TM7 System - Load Breaking (TM5/TM7 System Planning and Installation Guide)</i> needs to be enhanced.
OEM00071212	The Online Help for the TM5SEAI5G module (<i>Modicon TM5, Expansion Modules Configuration, Programming Guide</i>) provided incorrect ranges for the analog input register.
OEM00076210 / BOC-243	The information on the TM5SPS1 power supply module needs to be enhanced in the Online Help.
OEM00077834	Lexium 62 Plus: The encoder output frequency is limited to 1 MHz, interpolation factor is set to 16 increment cycles per Sinus/Cosinus period of the analog encoder.
—	PLCopen MC part 1: The following text and warning need to be added to the library documentation. If the position value of the master leaves the defined cam position range, the cam signals that the end of the cam profile has been reached. This implies that a buffered job is activated, regardless of whether the master has left the cam position range in a positive or a negative direction. The master can also leave the cam position range as a result of jitter if the master is at a standstill at a position sufficiently close to the positive or negative limit of the cam position range. See important safety information at the end of this table.
—	PLCopen MC part 1: A hazard message needs to be added to the library documentation. See important safety information at the end of this table.

ID	Description
OEM00077826 / BOC-285	Remove in the online help the statement that for the <code>AccelerationTorqueLimit</code> and <code>DecelerationTorqueLimit</code> parameters the value zero deactivates the torque limit.
OEM00078341 / BOC-315	Maximum number of files in the Message Logger must be documented.

⚠ WARNING

UNINTENDED EQUIPMENT OPERATION

Implement all measures required to ensure that a job is only buffered if a sufficient distance from the position value to the end of the cam position range can be respected.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

⚠ WARNING

UNINTENDED EQUIPMENT OPERATION

Implement a filter for the master velocity and acceleration if you have an axis that follows a feedback axis master.

Failure to follow these instructions can result in death, serious injury, or equipment damage.

EcoStruxure Machine Expert V1.2

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M241	5.0.8.4
M251	5.0.8.4
M262	5.0.4.7
TMSES4	1.0.0.8
TM3BCEIP	1.3.1.2
TM3BCSL	1.0.15.11
TM3•HSC202•	2.0
TM3DI16	2.0
TM3DI16G	2.0
TM3DI16K	2.0
TM5NEIP1	1.07
TM5NS31	2.74
LXM32S•••M2 drive	V1.10.01
LXM32S•••M2 Sercos	V1.10.03
LXM32S•••N4 drive	V1.10.01
LXM32S•••N4 Sercos	V1.10.03
LXM52•••••C•••••	1.54.26.0
ILM••••••••••••••••	1.54.26.0

Description	Firmware Version
LXM62••••C•••••	1.62.07.0 for hardware revision RS1• 1.54.27.0 for hardware revision RS0•
LXM62••••D•••••	1.62.07.0 for hardware revision RS1• 1.54.27.0 for hardware revision RS0•
LXM62••••E•••••	1.54.27.0
LXM62••••F•••••	1.54.27.0
LXM62••••G•••••	1.62.07.0
LMC Eco	V1.62.05.07
LMC Pro	V1.62.05.07
LMC Pro2	V1.62.05.07
ATV340S	- Drive firmware: OPAL_V1.4IE09_B06 - Copla firmware: Sercos3_A1.2IE01_B00

Description	Safety-Related Firmware Version
LXM62••••E•••••	1.2.4.0
LXM62••••F•••••	1.2.4.0
VW3E702200000 safety option module	1.2.4.0
TM5CSLC100FS	2.52
TM5CSLC200FS	2.52
BWU2984 SWID	134253
BWU2984 Safe CPU A	135115
BWU2984 Safe CPU B	135116
ASIMON360	3.2.6.7

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

New Features

TM3 EtherNet/IP Bus Coupler

For TM3BCEIP use firmware V1.3.1.2 and later versions.

TM3 Serial Line Bus Coupler

TM3 Serial Line Bus Coupler is a distributed architecture solution. It allows you to create distributed islands of industrial TM3 I/O modules managed by a master controller M241, M251, or M262 via Modbus Serial Line fieldbus.

New features:

- Support of TM3 and TM2 I/O modules:
 - Up to 14 TM3 I/O modules.
 - Up to 7 TM2 I/O modules.
 - Up to 7 TM2 I/O modules mixed with TM3 I/O modules.
- Embedded webserver supporting:
 - User rights management
 - Bus coupler maintenance such as speed configuration, firmware upgrade, and diagnostics logs.
 - Island I/O monitoring and control.

- Isolated RJ45 ports to support daisy chaining.

Limitations:

- The latch feature is not supported by TM3DI16, TM3DI16G, TM3DI16K.
- TM3 expert I/O modules are not supported.
- Only a single user can modify the firmware update or write values through the embedded webserver.
- The number of TM3 I/O modules is validated by the software. Depending on the number of analog I/O and/or safety modules used, the maximum number of TM3 I/O modules allowed may be reduced.
- Slave addresses are valid from 1...127.

TM5 EtherNet/IP Bus Coupler

TM5 EtherNet/IP Bus Coupler is a distributed architecture solution. It allows you to create distributed islands of industrial TM5/TM7 I/O modules managed by a master controller M241, M251, M262, or LMC controllers via Ethernet fieldbus.

New features:

- Support of TM5 and TM7 I/O modules.
- Embedded webserver supporting:
 - User rights management
 - DHCP, fixed IP configuration
 - Bus coupler firmware update
- Embedded switch with isolated RJ45 ports to support daisy chaining.
- ODVA (Open DeviceNet Vendors Association) certification

Limitations:

The following TM5 / TM7 modules are not supported:

- All TM5/TM7 safety I/O modules.
- TM5SE1RS2 RS232 Serial interface module
- TM5SE1MISC20005 Encoder output module
- TM5SDM8DTS 4DI/4DO Timestamp module

Plug&Work (Machine Assistant)

- PW2-4 Machine Instance Name: The controller name can be modified from the Machine Assistant. The IP address of the controller can be modified from the Machine Assistant.
- PW2-13 One Cable: You can create temporary routes to devices under another interface from the Machine Assistant.
- PW2-33 Bonjour Service: The M262 controller can be discovered using Apple devices.

PacDrive LMC Eco/PacDrive LMC Pro/Pro2 Cybersecurity Implementation

In PacDrive LMC Eco/PacDrive LMC Pro/Pro2 controllers IP forwarding is disabled using firewall settings.

NOTE: To help keep your Schneider Electric products secure and protected, it is in your best interest that you implement the cybersecurity best practices as indicated in the *Cybersecurity Best Practices* document provided on the Schneider Electric website.

PacDrive LMC Eco/PacDrive LMC Pro/Pro2 - ATV340S

It is a good practice not to connect more than the following number of ATV340S to the PacDrive LMC controllers:

PacDrive LMC controller	Maximum number of ATV340S
PacDrive LMC Eco	15
PacDrive LMC Pro/Pro2	25

M241 / M251 Logic Controllers

Support for the new TM3 high-speed counter modules:

- TM3XHSC202
- TM3XHSC202G

M262 Motion Controllers

- Encoder enhancements:
 - New object for LXM32S onboard PTI (Pulse Train In) encoder to be used as feedback axis with motion function blocks.
 - New object for LXM32S encoder option module (analog and digital) to be used as feedback axis with motion function blocks.
 - Filter parameter available for the encoder objects.
 - *DeadTimeCompensation* parameter available for the encoder objects.
- New object for direct support of ATV340S.

–	M262-15			M262-25			M262-35		
Sercos cycle time	1 ms	2 ms	4 ms	1 ms	2 ms	4 ms	1 ms	2 ms	4 ms
Total maximum number of Sercos devices allowed	8	16	16	12	16	24	16	24	40
Number maximum devices: TM5NS31 (TM5 range), TM5CSLCx00 safety controller, third-party devices	4	12	12	8	8	16	8	8	24
Number maximum devices: LXM32S, ATV340S	4	4	4	4	8	8	8	16	16

M262 Cybersecurity Implementation

In order to meet cybersecurity requirements, the Modicon M262 Logic/Motion Controller has been designed in accordance with the standard IEC 62443. As this standard constantly evolves, the Modicon M262 Logic/Motion Controller is compliant with a part of the 2019 standard.

To be compliant with the standard, the following modifications are implemented by default on the Modicon M262 Logic/Motion Controller:

Dialog box / Issue	Default setting / Solution
MyController > Ethernet Services > IP Routing	IP forwarding is disabled.
MyController > Ethernet _1 or MyController > Ethernet _2	Only the secured protocol is active.
The first access by webserver / FTP is denied.	Modify the default user name and password by using EcoStruxure Machine Expert.

For further information, refer to the *Cybersecurity Information for User Rights Management* chapter.

NOTE: To help keep your Schneider Electric products secure and protected, it is in your best interest that you implement the cybersecurity best practices as indicated in the *Cybersecurity Best Practices* document provided on the Schneider Electric website.

M262: TMSES4 Support

The capability to manage three TMSES4 modules on the left bus is embedded in version 5.0.4.7 of the following M262 platforms:

- M262L20MESE8T
- M262M25MESS8T
- M262M35MESS8T
- M262L10MESE8T
- M262M15MESS8T

NOTE: A maximum of three Ethernet or CANopen TMS modules is supported.


Examples:

- 2 TMSES4 modules and 1 TMSCO1 module
- 3 TMSES4 modules
- A maximum of one TMSCO1 module is supported.

M262: Single Wiring Coexistence (SWC) Architecture

In addition to real-time and safety-related data exchanged via Sercos, Sercos allows to transmit other Ethernet protocols, such as EtherNet/IP and TCP/IP in parallel.

The SWC architecture allows you to manage Sercos devices and EtherNet/IP or TCP/IP devices via a single cable.



An additional gateway is not required. Configuration is performed in EcoStruxure Machine Expert. Place the Ethernet device after the last Sercos device. The last Sercos device is used as a gateway. It must provide two Sercos connectors.

Considerations:

- Connect the Ethernet devices after the last Sercos device.
- Connect a LXM32S or ATV340S as last device on the Sercos bus.

- Connect a maximum of six Ethernet devices.
- Ethernet communication is operational when the Sercos bus is in phase 4.

NOTE: It is a good practice to stop the Ethernet communication when the Sercos bus is not in phase 4. To stop the EIP / TCP scanner, use the function blocks in the IEC application.

M262 Modifying the Default IP Address of the USB Port

By default, the IP address of the USB port is 192.168.200.1. Customers expressed the need to alter this address as it may conflict with their internal addressing schemes for existing Ethernet industrial networks. You are now able to change this address in the case that this IP address conflicts with the existing network configuration by modifying the address through the post configuration functions. Contact your local Schneider Electric service representative for more information on this expert topic.

Lexium 62 Servo Drives

Support of SH3 servo motors with Hiperface DSL-encoder and OneMotorCable connectivity.

Mitigated Anomalies

HMISCU Controllers

ID	Description
OEM00046432	HMISCU controller Panels: Sporadically, the communication between the HMI and the controller was interrupted without displaying an error message. You had to restart the HMISCU to re-establish the communication.

M241/M251 Controllers

ID	Description
OEM00072152 / PLAT-488	The termination of Modbus TCP connections was not handled correctly when the controller was acting as a Modbus TCP client.
OEM00077994 / PLAT-567	Using fast output operations in first application MAST cycle sometimes resulted in an exception.
OEM00070503 / PLAT-466	Sporadically, an error on a Modbus TCP IO scanner channel was not detected when the last one was not in error state.
PEP0541743R	Ethernet frames smaller than 60 bytes were not null byte padded.
PEP0545408R / BOC-350	Default range for M251 Ethernet port 1 and M241 TM4ES4 IP address has been changed to 10.11.x.y (x and y 5th and 6th bytes of interface MAC address) with a mask of 255.255.0.0.
OEM00074965	M251: Reading the <i>PLC_R</i> structure via the Symbol Configuration triggered a system watchdog error message.
OEM00075411 / PLAT-536	M251MESC: For Modicon M251MESC Logic Controllers, the cloning operation to an empty SD memory card (and other scripts like upload and download) did not operate.
OEM00078373 / PLAT-574	Insufficient session ID length in cookie.
OEM00078372 / PLAT-573	Sensitive information stored in cookie.
OEM00078369 / PLAT-572	Session password was transmitted in clear text.

ID	Description
OEM00078368 / PLAT-571	Webserver was vulnerable to cross-site request forgery attack.
PLAT-597	Entering incorrect credentials in the webserver was leading to a controller exception.

LXM32S

ID	Description
SER-VO00002939 / SERVO-251	The device MAC address was incorrectly displayed when read over the associated Sercos parameter.
SER-VO00002905	Position capture was not working when trigger was configured to record it on both signal edges.

Lexium 32

ID	Description
MK-733	Using the LXM32S did not map more than 6 additional IDNs to the cyclic data. NOTE: Lexium32S TouchProbe is counted as 4 IDNs and diagnostic message S-0-0390 is counted as 2 IDNs.

M262

ID	Description
OEM00076809	M262 Motion Controllers did not support the EtherNet/IP Scanner if used on the same port as the Sercos devices.
OEM00073473	TM5NS31 required the firmware version 2.74 or greater.
OEM00072876 / BOC-302	NVL/GVL (Network Variable List/Global Variable List) only worked if an Ethernet cable was plugged in the Ethernet port 1.
OEM00074106	TM5NS31 scan time on the TM5 bus was only taken into account after the next power cycle of TM5NS31.
OEM00076657	M262: When a network scan was performed, the EtherNet/IP connection to the Modicon M262 Logic/Motion Controller was sporadically disconnected without any message indicating the loss of connection.
OEM00076721	M262: If a Modicon M262 Logic/Motion Controller was connected via a USB interface, a restart was required to allow a connection to the controller after a network scan had been performed.
OEM00077207	M262: If an M262 was used as an EtherNet/IP Scanner and as an EtherNet/IP Adapter simultaneously, some devices could be temporarily disconnected.
OEM00077940	When OPC UA was configured in the application, the application had to be downloaded using the menu command Online > Login (instead of the menu command Online > Download).
M262- 4336	An anomaly was reported with the delivery of the Firmware V1.1 SP1 - V5.0.3.2. After every 24 days of consecutive operation of the controller, the controller would reboot automatically and restart as if without an application loaded. The issue, now resolved, required a work-around of cycling controller power prior to the expiration of the 24 day period.

PacDrive LMC Controls & I/Os

ID	Description
OEM00072576 / LMCFW-916	Both EtherNet/IP adapters are now operational when C2C master is enabled by default.
OEM00078575 / LMCFW-2076	C2C sometimes reported <code>sync failed</code> in combination with safety and a large number of Sercos slaves.

Known Operational Anomalies

ATV340S

ID	Description
GE-DEC00240596	When using PacDrive LMC Pro2 and ring topology, ring healing performed after the Sercos ring has been broken can result in the Sercos communication phase switching to phase 11 (error detected). Workaround: To be able to switch to phase 4, perform a <code>DiagQuit</code> .
GE-DEC00266016	In case ring healing is performed after the Sercos ring has been broken, the connection between the EtherNet/IP slaves and the master can be interrupted for a few seconds (communication state No Connection).

Lexium 32

ID	Description
SER-VO00002953 / SERVO-258	Sporadically, the drive advisory code is delayed from one Sercos cycle. The entry in the device logger displays <code>0x0000</code> instead of the drive advisory code.
SER-VO00002913 / SERVO-229	Sporadically, reading/writing manufacturer-specific parameters via SVC (Service Channel) leads to a timeout (error <code>0x7016</code>). NOTE: The issue is solved with Sercos3 module hardware having FPGA firmware V1.20.

Lexium 52 / 62 / 62 ILM

ID	Description
SERVOD-261	Lexium 62 Plus: If a download is not executed successfully and another attempt is performed by executing a firmware update, a misleading error message is displayed.
LMCFW-1616	Lexium 62 Plus: A parameter has been renamed in function <code>FC_BrakeCheckSet</code> .
SERVOD-163	Lexium 62 Plus: LEDs indicate that an error has been detected in communication phase CP0. Use case with Lexium BMP synchronous motor: Motor type plate to be configured in LXM62 drive.
SERVOD-147	Lexium 62 Plus: It is not possible to modify parameters of type <i>ES</i> . After an online change of the parameters, phase down and phase up is performed in different topology.
SERVOD-152	Lexium 62 Plus: Sporadic error is detected during phase up <code>0x2000B</code> : Phase up is not executed and machine operation is not possible.
LMCFW-1817	Lexium 62 Plus: Sercos phase up is not possible if devices are addressed with Identification mode = Application type .

M241/M251

ID	Description
OEM00079046	When a TM3 HSC is be used together with TM2 modules, the system performances are impacted. When a Freewheeling task is defined, the task duration is increased. When the Cyclic mode is active, increase the MAST cycle time. Otherwise, a CPU load exception can occur. It is a good practice to configure a minimum MAST cycle time of 30 ms (or more), depending on the application size.
OEM00079107	On connecting using Connection mode = IP Address, the user is prompted to enter the credentials. Workaround: 1. Use the Connection mode = IP address via NAT (Remote TCP). 2. Enter the controller IP address into the NAT Address field. 3. Click the Refresh button. 4. Double-click the controller from the controller list to establish a connection.
OEM00070134 / PLAT-459	Sporadic loss of controller IP address when power cycling the controller.

M262

ID	Description
OEM00079151	Webvisualizaton: Each refresh of variable manages a communication access if the user rights are validated, a password will be requested for these actions. Username and password are requested each time a page refresh / online change/ application download is performed by the webvisualizaton.
OEM00076931	In case an SLCx00 or TM5NS31 is the last Sercos device in the SWC architecture, the PhaseUp may be not possible.
OEM00079179 / PLAT-588	The content of the object type ARRAY read for an <i>ETH_R</i> structure is not correct when displayed on an HMI. Workaround: Copy the value to an intermediate variable (not accessing <i>ETH_R</i> directly).
OEM00079052 / PLAT-585	The content of elements (<i>i_byFirmVersion</i>, <i>i_byFirmVersion</i>) in the <i>PLC_R</i> data structure is not correct when displayed on an HMI. Workaround: Copy the value to an intermediate variable (not accessing <i>PLC_R</i> structure elements directly).
OEM00079223	An error is detected when rebooting projects with 4 KB retain variables.
SI-4694	The download may be unsuccessful and the message <i>TLS_IO_Communication</i> is displayed. Workaround: Deselect the option Encrypted Communication in the Communication Settings tab in controller selection mode of the EcoStruxure Machine Expert Logic Builder.

M262 - Motion

NOTE: The Modicon M262 Logic/Motion Controller does not support Advanced Message Queuing Protocol (AMQP).

TM3 Bus Coupler Serial Line TM3BCSL

ID	Description
OEM00078558	When bus ownership is held by the webserver, the controller is blocked from retaking bus ownership but there is no notification of the reason in EcoStruxure Machine Expert. Workaround: Make sure that the bus ownership is released by the webserver before restarting operation between the controller and the TM3BCSL.
OEM00079152	In EcoStruxure Machine Expert, setting the Monitoring Timeout of the TM3BCSL to 0 also effectively prevents the webserver from taking bus ownership. There is no notification of this reason on the webserver. Workaround: Configure a Monitoring Timeout value that is appropriate for the intended system behavior.
OEM00078760	In EcoStruxure Machine Expert, you can manage a maximum of 10 TM3 safety-related modules on the same TM3 bus, either behind the M262 or the bus coupler.

Library Information

Version Identification

Description	Version
ApplicationLogger	1.1.2.0
AsyncManager	1.0.5.0
AutoTune	1.3.14.0
Booster Pumping	5.0.0.5
CommonMotionTypes	1.0.1.0
CrankModule	1.3.4.0
EMailHandling	2.0.4.0
EtherNet/IP Explicit Messaging	1.1.8.0
EtherNet/IP Remote Adapter	1.0.10.0
FileFormatUtility	1.3.5.0
FtpRemoteFileHandling	1.3.0.0
GMC Independent Altivar	1.2.4.0
GMC Independent Lexium	1.1.7.0
GMC Independent PLCopen	1.2.3.0
Hoisting	5.0.0.1
HttpHandling	1.1.4.0
M262 Encoder	1.0.3.2
M262 PLCSystem	1.0.0.19
M262Diagnostics	V1.0.3.0
MotionInterface	1.1.75.21
MqttHandling	2.0.8.0
PackML	1.2.3.0
PD_AxisModule	1.6.2.0
PD_EDesignAxisModule	2.3.2.0
PD_EdesignCore	2.2.6.0
PD_EdesignCrankModule	1.5.2.0

Description	Version
PD_ETest	1.4.1.0
PD_GlobalDiagnostics	1.3.1.0
PD_MultiBelt	1.4.4.0
PD_MultibeltModule	1.4.1.0
PD_PacDriveLib	1.9.3.0
PD_SmartInfeed	1.4.4.0
PD_SmartInfeedModule	1.3.1.0
PD_SoMotionGenerator	1.5.1.0
PD_Template	1.6.1.0
PLCopen MC part 1	1.2.77.21
PreventaSupport	1.1.1.0
Robotic	2.14.0.0
RoboticModule	2.10.0.0
RoboticsAutoTune	2.0.0.0
SchneiderElectricRobotics	2.10.0.0
SchneiderElectricRobotics Parameters	2.11.0.0
SchneiderElectricRobotics Toolbox	1.5.0.0
SercosCommunication	1.0.1.0
SercosDriveUtility	1.1.1.0
SercosMaster	1.2.79.21
SlcRemoteController	1.3.6.0
SnmpManager	1.2.1.0
SqlRemoteAccess	2.0.1.0
TcpUdpCommunication	2.0.15.0
TeSys island	1.1.0.0
TimeSync	1.1.2.0
Toolbox	3.0.1.0
TwidoEmulationsupport	1.2.2.0
Unwinder	1.2.4.0
UnwinderModule	1.1.0.0
UserMotorTypePlate	1.3.9.0
UserTorqueFeedForward	1.2.2.0

Version Identification Safety Libraries

Description	Version
EnableSwitch_SE_SF	V0.99 from 10/28/15
PLCopen_SF	V1.00 from 09/14/07
Preventa_SafeMotion	V0100.0100 from 02/08/16

New Features

HttpHandling

New methods available:

- *Put*
- *Head*
- *Delete*

FileFormatUtility

The new function block *FB_XmlItemsUtility* provides a comprehensive set of utilities to get information from the data or to modify them. In addition, it is provided to create a complete new data set.

FtpRemoteFileHandling

The FTP client functionality supports asynchronous execution.

SqlRemoteAccess

The new function block *FB_SqlDbRequest* is used for secured/unsecured communication between the library and the SQL Gateway.

NOTE: Secured communication is only supported by M262 controllers.

TcpUdpCommunication

- The new method *SockOpt_EnableKeepAliveExtended* is used to configure the keep alive for TCP client and server to help detect communication interruption on M262 controllers.
- The *Close* procedure is processed in *Closing* state also by calling the method *State*.

RoboticsAutoTune

The RoboticsAutoTune library allows you to tune the Schneider Electric P-Series robot.

Hoisting

New function block *HoistDutyRating* collects run time data and calculates the actual mechanical class corresponding to the usage. This data can be used to identify whether the crane is being used according to its specification.

New function block *AdvancedPositionSync* can synchronize multiple linear axes with identical or different motors, gears, and encoders. The block can retain information about positions of synchronized axes and their synchronization status when the machine is switched off.

New function block *OperatingAreaRestrictionIC* helps to prevent a physical contact between the suspended load and obstacles located within the operating area of the crane. The restricted areas are defined in Cartesian coordinates. The function block supports definition of polygonal restricted areas.

Mitigated Anomalies

Libraries

ID	Description
OEM00078224 / IECLIB-2142	When disabling the MultiBelt in certain situations, a Set position command on the axis of a train was executed during the warm start. This resulted in an offset of the mechanical position of the train.
OEM00077558 / OEM00077938 / IECLIB-2121	SmartInfeed: During the correction movement of a SeriesBelt, an unintended error with <i>q_etDiag = Unexpected program behavior</i> , <i>q_etDiagExt = UnknownFeedback</i> , and <i>q_sMsg = 'NoJobWhileAxisMoving'</i> could be triggered.
OEM00071749 / IECLIB-2312	<i>PDL.FB_HomeAbs</i> and <i>PDL.FB_HomeSetPos</i> work correctly if a fraction of <i>UserPeriod</i> and <i>EncoderPeriod</i> cannot be represented exactly as a binary break.
OEM00073767 / IECLIB-2326	TcpUdpCommunication library: Method <i>SockOpt_EnableKeepAliveExtended</i> to configure the keep alive for the TCP client and server to detect communication interruption on the M262 controller.
OEM00067842 / IECLIB-2163	UserTorqueFeedForward: The function block <i>FB_TorqueFeedForwardConfigured</i> works correctly in case the SLC is on the first Sercos topology address.
OEM00077914 / PLAT-102	TcpUdpCommunication library: If more than one secured (Transport Layer Security) TCP server was active at the same time, a system watchdog could occur due to a higher system load. Therefore, only one instance of a secured (TLS) TCP server was allowed to be active.
–	Hoisting library: Function block <i>GrabControl</i> : Corrected close speed calculation during closing on stack. Calibration status information is kept in the status output even if the function block is disabled. Torque scaling is active even in disabled (cable change) state.

Known Operational Anomalies

Libraries

No known operational anomalies detected for EcoStruxure Machine Expert V1.2.

Software Information

Version Identification

Description	Version
Machine Expert Installer	12.20.01401
Diagnostics	19.0.11.0
Controller Assistant	19.0.11.0
Device Assistant	19.0.11.0
DiffViewer	19.0.11.0
Gateway	19.0.11.0
Launcher	19.0.11.0
OPCServer	3.5.12.83
SoftSPS	3.5.12.80
SVN	4.2.5.0
Logic Builder ⁽¹⁾	1.2
Vijeo-Designer	6.2.9.1008
CoDeSys	V3.5 SP12 Patch8 HF3

Description	Version
SQL Gateway	1.2.0.0
Motion Sizer	4.2.0.0
(1) If using a virtual machine, the download of the online help operates correctly only if the option Accelerate 3D graphics is deactivated in the VM settings.	

New Features for Machine Expert Installer

Machine Expert Installer

- Reduced Machine Expert Installer size.
- Faster installation.
- New improved user interface.
- Online help can be downloaded during standard installation.
- Select installation path.
- Improved offline medium.

New Features EcoStruxure Machine Expert

Motion Design Object

- New graphical interface to parametrize an axis.
- Displays the actual state of the axis.
- Support for M262.

SQL Gateway

- New with secured communication.
- Permitted clients (whitelist for controllers).

Cybersecurity Improvement

- Username and password for the controller mandatory.
- Controller Assistant, Diagnostic, and EcoStruxure Machine Expert extended user rights operations.

NOTE: To help keep your Schneider Electric products secure and protected, it is in your best interest that you implement the cybersecurity best practices as indicated in the *Cybersecurity Best Practices* document provided on the Schneider Electric website.

Code Analysis

- New Metric FBD Halstead Complexity (difficulty, length, max, consistency, average).

Python

- New functions, such as online change memory, user rights management.

New Project Dialog

- Search by controller or by example.

Browse Cross References

The contextual menu of a selected structured variable (`myVar.Elem`) now contains two commands below the **Browse** command:

- **Browse > Cross References** `<myVar.Elem>`: Searches for all usages of the variable instance. (This is the existing command that is also executed by default when selecting a variable when the **Cross Reference** dialog box is open.
- **Browse > Cross References** `<DUT.Elem>`: Searches for all usages of `<DUT.Elem>`, where `Elem` is the subelement of the structured type DUT of the variable `myVar`.

New Features for EcoStruxure Machine Expert - Safety

Overview

- **Machine Safety Set** selection in Machine Expert Installer now automatically installs the components needed to program safety-related applications.
- Support for LXM62 Standard Plus Safety drives in PacDrive systems.
- Enhancements performed on the safety-related user guides and the help management. Updated offline safety-related help.
- Diagnostic: Safe logger time stamp harmonization in accordance with IEC format.
- Cybersecurity feature support improved (user management, licensing, IP forwarding). Also refer to the hints below and to the chapter *Cybersecurity Information for User Rights Management*.
- Quality improvements.

NOTE: To help keep your Schneider Electric products secure and protected, it is in your best interest that you implement the cybersecurity best practices as indicated in the *Cybersecurity Best Practices* document provided on the Schneider Electric website.

Cybersecurity Information for Safety-Related Use Cases

User management activation on standard controllers (non-safety-related controllers) sometimes needs/requests login credentials also for some safety-related use cases.

With the new M262 default setting for IP forwarding (disabled) and the new LMC default setting for firewall management, a connection to the SLC (Safety Logic Controller) can no longer be established without dedicated user interactivity.

To establish a connection to an SLC during a commissioning phase by using the EcoStruxure Machine Expert - Safety programming tool, for example, for application download, the IP forwarding/firewall have to be configured accordingly on the related standard controller. Refer to the PacDrive LMC Eco, PacDrive LMC Pro/Pro2, M262 Programming Guides for further information.

In general, it is a good practice to disable IP forwarding / enable firewall on standard controllers for the machine operation phase.

The *SLCremotelibrary* functions for SLC control are not impacted by the enhanced cybersecurity mechanisms.

Compatibility EcoStruxure Machine Expert

Overview

EcoStruxure Machine Expert V1.2 can be installed in parallel to EcoStruxure Machine Expert V1.1 or V1.1SP1.

EcoStruxure Machine Expert can be installed in parallel to other Schneider Electric software products, such as SoMachine and SoMachine Motion.

For general information on compatibility of EcoStruxure Machine Expert, refer to the Compatibility and Migration Guide (see EcoStruxure Machine Expert Compatibility and Migration, User Guide).

Compatibility EcoStruxure Machine Expert - Safety

Overview

Former SoSafe Programmable versions cannot be started from EcoStruxure Machine Expert environment anymore and can only be installed and used if the related SoMachine Motion version is installed.

However, the former SoSafe Programmable projects - starting from V2.1 - can be imported, re-used, and updated in EcoStruxure Machine Expert - Safety V1.2.

In almost all cases, the update works without impact on the overall safety application and the resulting project CRC (cyclic redundant checksum) value stays the same and there is no recertification needed.

However, EcoStruxure Machine Expert - Safety does not support reusing a project built on EcoStruxure Machine Expert - Safety with LMCx system to EcoStruxure Machine Expert - Safety with M262 system or vice-versa.

Identified Incompatible Project Updates

The CRC of the safety project done before SoSafe Programmable V2.21 is changed if the old project contains the following safety devices:

- TM5SAI4AFS
- TM5STI4ATCFS

In this case, the safety project must be compiled again and downloaded to the TM5CSLCx00FS and the related safety function must be validated and recertified.

It is still possible to install former SoSafe Programmable versions in parallel to EcoStruxure Machine Expert - Safety as long the compatible SoMachine Motion package is available on the PC. Thus, you can maintain old projects using previous compatible engineering tool chains.

Overview of the validated EcoStruxure Machine Expert - Safety version with the appropriate safety-related firmware.

Device	Safety-related firmware version for EcoStruxure Machine Expert - Safety version	
	1.1	1.2
TM5CSLC100FS	2.52	2.52
TM5CSLC200FS	2.52	2.52
TM5SAI4AFS	322	322
TM5SDC1FS	302	302
TM5SDI20DFS	305	305
TM5SDI2DFS	305	305

Device	Safety-related firmware version for EcoStruxure Machine Expert - Safety version	
	1.1	1.2
TM5SDI4DFS	305	305
TM5SDM4DTRFS	305	305
TM5SDM8TBFS	305	305
TM5SDO2DTRFS	300	300
TM5SDO2TAFS	280	280
TM5SDO2TFS	280	280
TM5SDO4TAFS	280	280
TM5SDO4TFS	280	280
TM5SDO6TBFS	295	295
TM5SPS10FS	320	320
TM5STI4ATCFS	322	322
TM7SDI8DFS	305	305
TM7SDM12DTFS	305	305

For a list of safety-related firmware versions for SoSafe Programmable legacy versions, refer to the [Release Notes History](#) chapter, page 69.

Mitigated Anomalies

EcoStruxure Machine Expert

ID	Description
OEM00072313 / SI-4994	Project user management: Drag and drop from navigators of one project to another did not follow cut/copy permissions (of the source project).
OEM00078934 / CDSYS-255	Trace: For the case of a pinned cursor, variable values were not displayed correctly (value of the previous time stamp was displayed) when the cursor was dragged from left to right.
OEM00078819 / CDSYS-252	OPC DA server: For a variable that was registered for data-change callbacks but was deactivated the following occurred: In case of writing the variable followed by activating it, the previous written value was sent to the client before sending the present value. (This use case is only possible for some special OPC DA clients.)
OEM00075185	When you attempted to upload a Harmony ZBRN1 DTM running under Modbus TCP IO Scanner , EcoStruxure Machine Expert was no longer operational.
OEM00077196 / HMI-21	Vijeo-Designer: The communication between an M262 controller and the Vijeo-Designer HMI was interrupted after several days.
OEM00070927 / SI-1087 / SI-1088	Depending on the circumstances, when the project was connected to SVN, it was no longer possible to save (autosave included). The message the process cannot access the file...because it is being used by another process appeared.
OEM00078357 / IECLIB-1707	Control_ATV - Drive moved on if controller was in stop.
OEM00078790 / SI-4745	Machine Expert Installer closed unexpectedly during modification of an existing installation. The modification was not completed.
OEM00078543 / CDSYS-247	When searching for an element of the structure, the <code>CrossReferenceList</code> did not search in the complete project.
OEM00079022	When DTM components are installed, Logic Builder prompted for importing the installed DTMs. Sometimes Logic Builder stopped operating during this import procedure.
SI-5043	Exporting an imported cam diagram resulted in an exception from EcoStruxure Machine Expert. The export was canceled.

ID	Description
OEM00078812 / SI-4732	EcoStruxure Machine Expert stopped operating when modifying the IEC structure of a cam diagram in specific projects.
OEM00078386 / SI-4429	Update Device: It is no longer allowed to update an interface device (such as Ethernet Network, Serial Line) or a protocol manager (such as Industrial Ethernet Manager) into a device of another type.
OEM00076949 / MS-1927	Motion Sizer: When exporting a cam diagram into an .asc file, the starting point was missing. It was added to the end of the points table.
OEM00077970 / PLAT-565	OPC UA Configuration editor: When opening a project where this editor had been open before the project was closed, variables from Global Variables Lists (GVL) were not always displayed consistently.
OEM00062678 SI-605	Issue has been solved with the new feature implemented in Machine Expert Installer allowing to select the installation path.

EcoStruxure Machine Expert - Safety

ID	Description
OEM00078219 / SSP50-4519	For TM7SDI8DFS and TM5SDI20DFS It was not possible to map a variable for <i>SafeTwoChannelOkxxyy</i> channel from EcoStruxure Machine Expert Logic Builder to EcoStruxure Machine Expert - Safety. If the variable was added in Logic Builder, the Safe Configuration Change window was displayed in EcoStruxure Machine Expert - Safety but the variable was not displayed in the parameter grid after the confirmation.
OEM00074304 / SSP50-4508	Project Compare in EcoStruxure Machine Expert - Safety did not display a message when an attempt was made to compare a safety-related with a non-safety-related project.
OEM00078024 / SSP50-4503	Floating license server configuration that was not fully cleaned up caused a long start time (>30 min) of EcoStruxure Machine Expert - Safety.
OEM00066284 / SSP50-6928	The online help did not provide information about the maximum configurable amount of variables for LMC2SLC or SLC2LMC.

Known Operational Anomalies

EcoStruxure Machine Expert

ID	Description
OEM00069862 / MS-1969	Motion Sizer: While displaying a Crank mechanic with Motion Sizer, the position curve is incorrect (different to EcoStruxure Machine Expert). The label of the curve is also incorrect.
OEM00076614 / MS-1967	Motion Sizer: A cam profile (.asc file) exported from Motion Sizer has one cam point less than the exported file from ECAM.
OEM00070100 / MS-1963	Motion Sizer: With special mechanical parameters and a BMH1903P + LXM32xD85N4 bundle, the maximum required motor speed is 2250 rpm. Motion Sizer indicates the incorrect message that the maximum motor limit has been exceeded.
OEM00079146 / MS-1960	Motion Sizer: Input of a negative mechanic parameter for Crank is not possible.
OEM00078318 / MS-1947	Motion Sizer: ILM140 motor and drive type do not match.
OEM00071717 / MS-1946	Motion Sizer: Not possible to select a minimum supply voltage for ILM.
OEM00078190 / MS-1944	Motion Sizer: Torque characteristics are not updated.
OEM00076612 / MS-1943	Motion Sizer: Incorrect jerk is displayed for motion law mod sin .
OEM00071728 / MS-1938	Motion Sizer: Projects that contain a calculated cycle time that is not an INTEGER value cannot be reopened.

ID	Description
OEM00064125 / MS-1902	Motion Sizer: If only Lexium 62 ILM servo drives are included in a power circuit, the limits of the power supply for the maximum DC bus current and the effective DC bus current are not evaluated.
OEM00064415 / MS-1901	Motion Sizer: Power calculations do not consider the limits from the connection module.
–	Motion Sizer: Incorrect motion profile for motion Dwell when the Y values of the startpoint and endpoint are equal and m and k are not zero.
OEM00077539 / MS-1945	Motion Sizer: After creating a new motor, an error exception was detected.
SI-3117	When a library is only referenced by another library, the referenced library is not updated during a project update. Workaround: Execute the automatic update in the Library Manager .
SI-5150	Machine Expert Installer: After an update from EcoStruxure Machine Expert V1.1 to EcoStruxure Machine Expert V1.2, the ATV320 DTM is displayed as not imported and is not available. Workaround: Remove and reinstall the ATV320 DTM by using the Modify Installed Software option of the Machine Expert Installer.
SI-4893	Motion Sizer: When you open the Help > About dialog box, open the system explorer, select a system project, and click Add current project , then an exception can occur in the Motion Sizer.
OEM00078429 / BOC-558	Relocation Table: The Length of ARRAY variables containing structures with elements of type DATE, TIME, DATE_AND_TIME is not correctly displayed.

EcoStruxure Machine Expert - Safety

ID	Description
OEM00079205 / SSP50-6903	The message logger of an M262 controller can be flooded with a lot of messages in case an optional safety-related module configured in the system becomes defective. Workaround: Consult the message logger and replace the defective module that has been identified.
OEM00078271 / SSP50-4523	The TM5SPS10FS module does not differentiate if the user parameter centralcontrol is set to Central or Direct . In both cases you must set the parameter for the output in addition to the safety-related parameter in the SLC to get the output powered.

Documentation - Mitigated Anomalies

Documentation

ID	Description
OEM00077321 / BOC-264	Event Task: A remark was needed that only internal IEC variables and values of onboard touchprobes and digital inputs (controller) are permitted.
SI-4252	The project update with HMI has been changed, as some HMI devices are not supported by Machine Expert.
IECLIB-2162	HttpHandling library guide: An example was needed on how to send an HTTP <code>Get</code> request using the property <code>State</code> as state variable of the state machine.
OEM00074603 / IECLIB-1713	TcpUdpCommunication library guide: An example was needed on how to implement UDPmulticast with <code>FB Method JoinMulticastGroup</code> in the TcpUdpCommunication library.
OEM00078342 / BOC-316	M262 Programming Guide: Incorrect information for Reset origin command. It removes part of the system logs.
OEM00078593	M262 Hardware Guide: Contained a not accurate graphic: the size of M262 controller was different to TM3 size.

ID	Description
OEM00078594	M262 Hardware Guide: Missing link to the TM5 fieldbus interface Hardware Guide.
OEM00078595	M262 Hardware Guide: Incorrect link for SetRTCDrift documentation.
OEM00078598	M262 Hardware Guide: Incomplete description of Run/Stop sources.
OEM00078607	M262 Hardware Guide: Incorrect links to I/O status LEDs.
OEM00078608	M262 Hardware Guide: No description about LED of SL yellow blink.
OEM00078610	M262 Hardware Guide: Incorrect links for Ethernet 1 and Ethernet 2 ports of TM262M15MESS8T/TM262M25MESS8T/TM262M35MESS8T.
OEM00078629	The memory size of M262 was different between Programming Guide and Hardware Guide.
OEM00078630	M262 Programming Guide: Item 4 was not included in Files Transfers in Memory graphic.
OEM00078691 / BOC-327	Missing note on TMSES4 not to interconnect embedded Ethernet port and TMSES4 (or interconnect TMSES4 module).

Documentation - Known Operational Anomalies

Documentation

ID	Description
OEM00079053 / BOC-351	Incorrect module size of the TM3AQ2/TM3AQ2G in the <i>TM3 Analog I/O Modules Hardware Guide</i> : - Incorrect: 14.6 mm - Correct: 18 mm
TM3BC-556	Incorrect graphic in the section <i>Ethernet Port</i> of the <i>TM3 Bus Coupler Hardware Guide</i> : The orientation of the RJ45 plugs must be reverted.

EcoStruxure Machine Expert V1.2.1

Hardware/Firmware information

Version Identification

Description	Firmware Version
TM3BCCO	1.0.16.1

New Features

TM3 CANopen Bus Coupler is a distributed architecture solution. It allows you to create distributed islands of industrial TM3/TM2 I/O modules managed by a master controller M241, M251, or M262 via CANopen fieldbus.

- Support of TM3 and TM2 I/O modules:
 - up to 14 TM3 I/O modules
 - up to 7 TM2 I/O modules
 - up to 7 TM2 I/O modules mixed with TM3 I/O modules

- Embedded webserver supporting:
 - user rights management
 - bus coupler maintenance such as speed configuration, firmware upgrade, and diagnostics logs
 - island I/O monitoring and control
- Isolated RJ45 ports to support daisy chaining

Limitations

- The latch feature is not supported by TM3DI16, TM3DI16G, TM3DI16K.
- TM3 expert I/O modules are not supported.
- Only a single user can modify the firmware update or write values through the embedded webserver.
- HMISCU is not supported as CANopen Master for TM3BCCO.

Known Operational Anomalies

There are no known anomalies with this release.

EcoStruxure Machine Expert V1.2.2

Hardware/Firmware information

Version Identification

Description	Firmware Version
TM5NS31	2.75

Description	Safety-Related Firmware Version
TM5CSLC100FS	2.53
TM5CSLC200FS	2.53

NOTE: The other firmware versions remain as documented in the Release Notes History, page 110.

Quality Improvement for TM5 Sercos Bus Coupler and TM5 Safety Controllers

- TM5 Sercos Bus coupler (TM5NS31)
 - Cybersecurity: Unused Ethernet services are disabled
- TM5 Safety Controllers (TM5CSLC•00)
 - Cybersecurity: Unused Ethernet services are disabled

NOTE: For updating existing TM5NS31 and TM5CSLC•00 devices in your M262 and PacDrive system use the Device Assistant tool as usual. For more information refer to the M262 Embedded Safety - Integration Guide and the M262 Logic/Motion Controller - Programming Guide.

If you are using in PacDrive systems the Fast Device Replacement (FDR) function, then you have to create a new LMC controller flash card with exchanged firmware files with the Controller Assistant tool. Thereby you have new firmware releases for TM5CSLC•00 and/or TM5NS31 available on the controller to execute the FDR function correctly. For more information refer to the LMC Pro Device Objects and Parameters Guide.

Software Information

Version Identification

Description	Firmware Version
Machine Expert Installer	12.20.08301

New Features for EcoStruxure Machine Expert - Safety

The Safety offline help was updated with small corrections and additional translations.

Mitigated Anomalies - Machine Expert Installer

ID	Description
BOC-628 / SI-5608	Connection to Schneider Electric server is not possible in case default system proxy server with credentials (user and password) is configured.

Known Operational Anomalies - EcoStruxure Machine Expert

ID	Description
SI-5692	Working with DTM device editors can cause an error message "Invalid window handle" occurs and the application crashes. This is caused by a combination of Windows .NET Framework and a custom scale factor in Windows Display settings. Workaround: On a Windows 10 PC go to Display settings and click on Turn off customs scaling and sign out. If this does not solve the issue modify the setting Change the size of text, apps and other items to 100%. Sometimes you have to change the Display resolution to a lower size to reach the goal. Then sign out the user if not done before.

EcoStruxure Machine Expert V1.2.3

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M262	5.0.4.75
TM5NEIP1	3.10

New Features

Quality Improvement for TM5 Ethernet/IP Bus Coupler

- Cybersecurity: Unused Ethernet services are disabled.
- Enable/Disable webserver through Machine Expert configuration.

M262 - OPC UA Client


OPC Unified Architecture (OPC UA) is a vendor-independent communication protocol for industrial automation applications.

The client / server OPC UA capability of the following M262 controllers:

- M262L20MESE8T
- M262M25MESS8T
- M262M35MESS8T

The server OPC UA capability of the following M262 controllers:

- M262L10MESE8T
- M262M15MESS8T



OPC UA data exchange is performed using function blocks that are compliant with the PLCopen specification *PLCopen OPC-UA Client for IEC61131-3 version 1.1* and provide the following functions:


- Read/write of multiple items
- Diagnostics

The following function blocks are supported:

- *UA_Connect*
- *UA_ConnectionGetStatus*
- *UA_Disconnect*
- *UA_NamespaceGetIndexList*

- *UA_NodeGetHandleList*
- *UA_NodeGetInformation*
- *UA_NodeReleaseHandleList*
- *UA_ReadList*
- *UA_WriteList*

The graphic provides an example for managing the read/write list:



The table lists the OPC UA performance:

Performance	M262
Number of servers supported	5
Number of clients supported	1
Numbers of variables / connections	5,000
Numbers of variables / connections (total)	15,000

Mitigated Anomalies

M262

ID	Description
OEM00077237	User rights: You were asked twice to enter the default administrator credentials at activation.
OEM00079079	NVL did not start when ETH1 was not exchanging data.
M262-4953	M262 incorrectly displayed the error message "Values cannot be retrieved".

Known Operational Anomalies

M262 - Motion

ID	Description
MK-992	The Scaling library is removed. As a result, customer projects including this library (EcoStruxure Machine Expert V1.1) cannot be converted to EcoStruxure Machine Expert V1.1 SP1 or greater without the error message "Unhandled exception has occurred in your application". Workaround: Either do not convert or copy the application content instead of converting it.
MK-974	While enabling a vertical axis, a small drop of the axis can be observed. This results from the gravity effect on the motor load for the time it takes between requesting the enable and finalizing it.

Library Information

Version Identification

Description	Firmware Version
SqlRemoteAccess	2.0.2.0
TeSys island	2.0.3.0
OpCuaHandling	1.0.13.0

New Features

OpCuaHandling

- New library provides the OPC UA client functionality in order to exchange data with other devices through an independent communication protocol using the server - client model for M262.

TeSys island

- Added new function block supporting the new device avatars:
 - SwitchSILStopWCat3and4
- Added new function blocks supporting the new load avatars:
 - MotorOneDirectionSILStopWCat3and4
 - MotorTwoDirectionsSILStopWCat3and4
 - MotorTwoSpeedsSILStopWCat3and4
 - MotorTwoSpeedsTwoDirectionsSILStopWCat3and4
- Added new function blocks supporting the new application avatars:
 - Pump
 - ConveyorOneDirection
 - ConveyorOneDirectionSILStopWCat1and2
 - ConveyorTwoDirections
 - ConveyorTwoDirectionsSILStopWCat1and2
- Added new function blocks to read and set the system time of the bus coupler:
 - SystemTimeGet
 - SystemTimeSet
- Added new outputs supporting the new process variables of the avatars:
 - MotorOneDirection
 - MotorTwoDirections
 - MotorTwoSpeeds
 - MotorTwoSpeedsTwoDirections
 - MotorYDOneDirection
 - MotorYDTwoDirections

- Changes:
 - Changed the order of the function blocks inputs and outputs.
 - Moved the outputs `q_iMotorTemperature` and `q_usiSILGroup` from the dedicated control function blocks to the `EnhancedStatus` function block.
 - Added the output `q_wPredictiveAlarmsStatus` to the `EnhancedStatus` function block.
 - Added the outputs `q_uiVRMSL1L2`, `q_uiVRMSL2L3` and `q_uiVRMSL3L1` to the `SystemVoltageBasic` function block.
 - Renamed the term safety into SIL (Safety Integrity Level) on the elements of the library.
 - Renamed the term warning in alarm on the elements of the library.
 - Renamed the term error in event on the elements of the library.

Project Example

- Added OPC UA client project example for M262.
- Update of the Machine Advisor project example with management of user rights and secure access to the web visualization server.

Mitigated Anomalies

ID	Description
IECLIB-2556	SqlRemoteAccess: Limitation issue after 9999 read or write execution is solved.

Known Operational Anomalies

ID	Description
M262-5106	Changing the cycle time of a task might cause an exception during download of the application using OPC UA.
M262-5092	Downloading large and complex applications may cause an exception during download of the application.
M262-5080	While rebooting, the controller may detect an error if the cycle time of the application is too low.
M262-5072	Using multiple OPC UA clients and a large number of nodes may result in a long execution time and consequently in a watchdog exception.
M262-4248	OPC UA client: <code>UA_ReadList</code> using a pointer in persistent variables may lead to an exception error. An advisory is already present during the build: "Do not use POINTER in persistent variables, since addresses will change at download."

Software Information

Version Identification

Description	Firmware Version
SQL Gateway	1.2.3.0

New Features

SQL Gateway

- It is possible to protect the configuration/user interface from the Gateway via a password.
- Usability improvement for client certificates: The handling of permitted client certificates has been simplified by showing received but rejected certificates. These rejected certificates can be used to simply add them to the permitted certificates.
- Cybersecurity improvements such as encrypted configuration file.

TeSys island DTM

- Update of avatars with process variable inputs and advanced control modes. See also the section [Library Information](#), page 119.
- Added predictive alarms for avatars.
- Upstream voltage detection is improved.
- Custom avatar configurations can be saved for re-use in individual DTM libraries.
- Factory reset allowed in any system state.
- Dynamic port mapping guide added to ease wiring of digital and analog inputs and outputs.
- Support of PTC binary sensor added.
- Predictive alarms data exchange with EcoStruxure Machine Expert added.

Mitigated Anomalies

EcoStruxure Machine Expert

ID	Description
OEM00076873 / SI-5770	During convert from a M241, the ATV320 DTM was deleted.
BOC-741 / SI-5743	Controller Assistant: Writing image to flash disk was unsuccessful with message "Formatting failed".
SI-5741	SQL Gateway: After importing the configuration, the content of permitted clients lists was not updated.
SI-5736	Import of DTMs may render Machine Expert inoperable.
SI-5718	Controller Assistant reports that a version of Machine Expert is already installed on a clean system after program start.
SI-5717 / BOC-395	Calling online help via F1 button is inoperable when using function block name space.
SI-5716 / SI-3684 / SI-5710	Conversion of ATV32 leads to deletion of I/O mapping.
SI-5715	Controller Assistant: Issue on resetting user rights when writing image to M262.
SI-5713	It is not possible to synchronize more than one cam diagram between Motion Sizer and Machine Expert.
SI-5711 / BOC-36	When using the Chinese character set in the Windows operating system, the button inside the user cyclic data configuration is not visible if the screen size is > 100%.
SI-5708	Device Assistant: Incorrect DSM-FW for LXM62+ is displayed.

EcoStruxure Machine Expert - Safety

ID	Description
SSP50-7148 / BOC-763	For new safety projects created with Machine Expert - Safety V1.2, V1.2.1 and V1.2.2, it is not possible to use POU's with structured text (ST) language. Machine Expert - Safety is closed immediately after inserting a POU for ST programming. Workaround: Projects created with these versions and which use ST in a POU have to be recreated with V1.2.3 to avoid this issue. NOTE: Projects upgraded from any version before V1.2 to the mentioned versions are not impacted and can add and use POU's with structured text without re-creation.

Known Operational Anomalies

EcoStruxure Machine Expert

ID	Description
SI-5714 / BOC-467	CamEditor: Editor view allows to configure an invalid value for the "C" parameter for motion profile ModAccTr or ModSin.

EcoStruxure Machine Expert V1.2.4

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M262	5.0.4.81
TM3BCEIP	2.1.50.2
TM3BCSL	2.0.50.2
TM3BCCO	2.0.50.2
TM3DI8	2.0
TM3DI8G	2.0
TM3DI32K	2.0
TM3DM8R	2.0
TM3DM8RG	2.0
TM3DM24R	2.0
TM3DM24RG	2.0

New Features

Lexium LXM28S

The device LXM28S is available in the **Hardware** catalog. It can be used to control the drive LXM28S.

Modicon TM3 Bus Coupler

- TM3 CANopen Bus Coupler (TM3BCCO) is supported by Harmony SCU HMI Controller.

- Support for the new Modicon TM3 I/O modules with the filter and fallback function:
 - TM3DI8
 - TM3DI8G
 - TM3DI32K
 - TM3DM8R
 - TM3DM8RG
 - TM3DM24R
 - TM3DM24RG

Modicon TM3 Standard I/O

New hardware revisions for TM3DI8, TM3DI8G, TM3DI32K, TM3DM8R, TM3DM8RG, TM3DM24R and TM3DM24RG.

NOTE: The new features are available only with the new firmware provided with EcoStruxure Machine Expert V1.2.4.

These new TM3 I/O modules are supported by M241, M251, M262 and TM3 Bus Couplers, and support new features:

- Configurable input filter
 - The input acquisition time filter can be adjusted to allow fast input signals (0.3 - 12 msec.).
- Input latch function
 - The input latch function allows to capture input signals with short durations and memorize the state till the next controller task execution.
 - This feature is not supported by the TM3 Bus Couplers.
- Output fallback function
 - The output of the TM3 I/O modules will apply fallback values configured by user after an elapsed delay, when the I/O bus is lost.
- Firmware upgrade
 - The firmware of the TM3 I/O modules can be updated by the controller. (New features only configurable with modules of software version 2 or greater.)

M262 - Motion

- Cam slave start mode Absolute
 - Mode Absolute is now available, which can be chosen as an alternative to the already existing slave start modes Relative and RampIn when starting a cam.
 - Mode Absolute starts the new cam directly at the position, velocity and acceleration according to the new cam profile (like Relative/unlike RampIn) and without performing any ramp-in movement (unlike RampIn).
 - Mode Absolute cannot be started on a slave axis configured to modulo. This will result in the error output of MC_CamIn function block being set.
- Interpolated cam (straight/poly5)
 - As an alternative to using segment-defined cam profiles, a cam profile can now also be interpolated between a list of points.
 - Up to 10,000 points are supported. In the case of straight interpolation, these points are Y coordinates, which are equidistant on the X axis. Interpolation between two points is straight (same as straight cam segment law).
 - Alternatively, a 5th degree polynomial interpolation can be used between the given points. In this case, the user also has to input slope and curvature in addition to the corresponding slave position.

- Real-time Task
 - The real-time task is a task for the user application that synchronized with the fieldbus and the internal motion calculation. This task will be scheduled to be executed after motion calculation and data transfer from/to devices. Please ensure that this task is executed immediately by setting its priority to the highest priority (lowest number) in your application.
 - The intended use case is to read inputs or axes positions as soon as they are available, create branch logic based on them, trace, etc.
 - Be aware that it is not intended for Motion function blocks.
 - Be aware that digital outputs set in this task will only be sent to the device after 2 cycles.

Documentation

The online help is updated with the following new documentation:

- How to Configure the Firewall for PacDrive LMC Controllers

Mitigated Anomalies

M262

ID	Description
M262-5074	WebVisualization: Credential page is reloading on an Apple iPad. Allow Apple iPad for WebVisualization.
M262-5218	OPC UA server is able to read the M580 certificate.
M262-5230	OPC UA server: The display name of variables has been modified in order to provide a "Flat" view of the array's structure. The view is modified to show the complete node name of the variable.
M262-5233	M262: The LED is aligned with the state of the output when the default value is requested.

M262 - Motion

ID	Description
MK-939	An unnecessary ramp-in movement no longer occurs, when an MC_CamIn function block is executed with slave start mode RampIn but no ramp-in movement is necessary because the axis already starts in the correct position according to the cam profile definition.
MK-967	Discrete motion jobs no longer finish with the final axis position merely very close to the commanded target position (e.g. 10^{-32} instead of 0.0), but instead with the axis exactly in the target position.
MK-975	Resolved an issue whereas Sercos on M262 Logic controller stops working and the drive displays error B103, or that on a subsequent attempt M262 Logic controller crashes, when executing any Motion Control FB in buffered mode while it is already active.
MK-1005	An unnecessary ramp-in movement, leading to a jump in axis velocity, no longer occurs when an MC_CamIn function block is executed with slave start mode RampIn and buffer mode Aborting, with identically parameterized cam profile as the previously running cam. Linked to MK-939.
MK-1017	A very high velocity and acceleration of the drive shortly before reaching the target, caused by a sudden jump in axis position for one cycle, no longer occurs after MC_MoveAbsolute function block with jerk has been used to abort itself with a new target position further away.
MK-1021	Configuring the axis with a position resolution of 1.0 no longer leads to an unexpected sudden jump from zero velocity to target velocity. Instead the axis now accelerates with the defined ramp, as expected.
MK-1033	The value of an axis stMotionOfMaster.lPosition is no longer set to zero for one cycle when the active cam is changed (buffered or aborted) and the new cam is started with slave start mode RampIn. Instead, this property now shows the expected value.

Known Operational Anomalies

M262

ID	Description
BOC-537	Sercos bus: Unable to disable/enable the TM5 slices of Sercos III via IEC program with the M262 Logic Controller.
BOC-751	Modbus serial: Serial IO scanner sends FC15 while FC05 is configured.
M262-5137	<i>SysTimeRtcSet</i> : After a power OFF the real time clock (RTC) of the controller get lost if it is set by the <i>SysTimeRtcSet</i> function. Workaround: Set the real time clock by the software.

M262 - Motion

ID	Description
MK-1016	Online status of bit <i>InvertDirection</i> is not displayed in the encoder configuration window. The pre-configured value is shown instead.
MK-1048	SLC remote controller shows phase -1 when trying to set Sercos phase to 0 and it shows phase 0 when trying to set Sercos phase to -1.
MK-1073	Real-time task configuration - Watchdog precision cannot be set to microseconds.

Modicon TM3 Bus Coupler

ID	Description
M262-5335	When in a distributed architecture, with TM3BCEIP, if the diagnostic for the analog modules TM3AQ2 and TM3AQ4 is disabled, CPU exception occur , after the download of the application. Workaround: The diagnostic is activated by default - do not change the diagnostic setting for these both modules: TM3AQ2 and TM3AQ4.
-	Always use the value Yes for the variable StatusEnabled in the analog modules, see screenshot below. When it is set to No the values of the analog inputs will make a shift in the read data buffer, causing wrong data value read in the software or controller.



The screenshot shows the 'I/O Configuration' window with the 'Information' tab selected. A tree view on the left shows 'Optional module', 'Inputs', and 'Diagnostic'. Under 'Diagnostic', 'StatusEnabled' is selected. The main table displays the following data:

Parameter	Type	Value	Default Value	Unit	Description
Optional module	Enumeration of BYTE	No	No		
Inputs					
Diagnostic					
StatusEnabled	Enumeration of BYTE	Yes	Yes		

Library Information

Version Identification

Description	Version
CommonMotionInterface	1.4.1.0
CommonToolbox	1.0.1.0
Mathematics	1.0.0.0
PD_PacDriveLib	1.9.4.0

New Features

Project Example

Update of the Safety Logic Controller (SLC) project template for PacDrive 3 to allow connection between EcoStruxure Machine Expert - Safety and TM5CSLC•00FS.

CommonToolbox

The new library provides a collection of additional functions and function blocks:

- **FC_CloseSlcCommunication:** Deactivates the standard port rules for the controller firmware which allow a connection from the programming tool to the TM5CSLC•00FS through the controller.
- **FC_LrealToString:** The function converts any numerical value to a **STRING** with freely defined format.
- **FC_MultiConcat:** The function concatenates the 4 input strings according to their sequence.
- **FC_OpenSlcCommunication:** Activates the required port rules for the controller firmware to allow a connection from the programming tool to the TM5CSLC•00FS through the controller.
- **FB_HeatingControl:** Function block for monitoring and controlling heating systems.
- **FB_RandomGenerator:** This function creates a random number.
- **FB_RuntimeMeasurement:** Runtime measurement of program code.

Mathematics

- **ST_Vector3D:** Represents a Cartesian vector in a three-dimensional space.

Mitigated Anomalies

There are no additional mitigated anomalies with this release.

Known Operational Anomalies

NOTE: If you are using templates and examples which are not updated with the update of EcoStruxure Machine Expert V1.2.4, you may be presented the **Update Project** dialog. If you are opening an example or template for the first time, you should update to have the correct and corresponding libraries and other necessary support.

Software Information

Version Identification

DTMs

Description	Version
Advantys OTB	11.1.0.0
ATV320	1.2.6.0
ATV340	1.7.0.0
ATV6xx	2.5.1.0
ATV9xx	2.2.1.0
Harmony XB5R	1.0.41
Lexium 28 A	1.6.00.07
Lexium 28 S	1.6.12.00

Description	Version
Lexium 32 A	1.20.02.01
Lexium 32 C	1.20.02.01
Lexium 32 i	1.20.02.01
Lexium 32 M-S	1.20.02.01
Modbus Serial Communication DTM	2.6.12
Modbus TCP Communication DTM	2.6.12
TeSys island	2.2.1.0
TeSysT	2.12.0.0
TeSysU	2.8.0.0
TM5-7 CANopen Interface DTM	1.1.8
TM5-7 Expansion Module DTM	1.1.8

New Features

Quality improvement for Lexium 32 DTM

- Cybersecurity: No UMAS transfer for MotionSequenceMode download.

EcoStruxure Machine Expert - Safety

- Safety System communication management improvement. New standard controller firmware handling functions available. For details see chapter Library Information, page 126.

Mitigated Anomalies

DTMs

ID	Description
LXM32DTM-4	Resolution of the issue with the downloading of an old SoMove file into a new LXM32 drive.
190220	TeSys island: Could not select 22 kW power rating from combo box.

Known Operational Anomalies

There are no additional known anomalies with this release.

EcoStruxure Machine Expert V1.2.5

Hardware/Firmware Information

Version Identification

Description	Firmware Version
TM258LD42DT	5.0.4.11
TM258LD42DT4L	5.0.4.11
TM258LF42DT	5.0.4.11
TM258LF42DT4L	5.0.4.11
TM258LF66DT4L	5.0.4.11

Description	Firmware Version
TM258LF42DR	5.0.4.11
LMC058LF42	5.0.4.11
LMC058LF424	5.0.4.11

New Features

Modicon M258 Logic Controllers and Modicon LMC058 Motion Controllers

- Support of Codesys 3.5 SP12
- Migration of a project from SoMachine V4.3 to Machine Expert V1.2.5 (with the limitation of devices in Machine Expert)
- User Right password has to be changed at first login to the controller
- Default administrator password change on first login

Mitigated Anomalies

ID	Description
PLAT-718	M258: High Speed Counter (HSC) in Period Meter Mode with resolution = 0.1 μ s is available.
PLAT-730	M258: Function blocks with the input of type ANY are not generating an internal error anymore.
PLAT-901	M258: Size of Union variables is correctly sized when variables are mapped to a Relocation Table .
BOC-319 / PEP0533758R	Documentation: Maximum frequency of Expert I/O is 200 kHz instead of 100 kHz.
BOC-507 / CDSYS-191 / PLAT-879	LMC058: The Modicon LMC058 Motion controller was stopped during an online change with some projects.
BOC-512 / CDSYS-55 / PLAT-879	M258: We triggered an issue if <code>MC_GearIn.RaionNumerator = 0</code> was used and during this state <code>MC_SetPosition</code> on the Master drive was executed.
BOC-514 / CDSYS-40	LMC058: <code>SMC_Limitdynamics</code> did not limit Z-axis with some G-code files.
BOC-515 / CDSYS-34	LMC058: There was a jump in position on quick stop.
BOC-517 / CDSYS-14	LMC058: <code>SMC_Limitdynamics</code> did not limit the acceleration and deceleration values in some G-code files.
BOC-518 / CDSYS-11	LMC058: Using M-functions inside a G-code file the interpolator output containing the M-function number showed sometimes incorrect values (65533 and 65534).
BOC-519 / CDSYS-8	LMC058: If <code>SMC_Interpolator2Dir</code> was started (<code>set bExecute=TRUE</code>), then the output "busy" of this function block remains FALSE (but should become TRUE).
BOC-520 / CDSYS-6	LMC058: <code>SMC_BlockSearch</code> to restart a aborted CNC G-code file from a specific point did not start correctly in certain situations.
BOC-521 / CDSYS-17 / PLAT-879	LMC058: In a special case of G-code, the ToolCorrection did not work correctly (there occurs a jump on the path and target position was not correct).
BOC-557 / SI-5735	LMC058: Input parameter from <code>MC_GearIn</code> was too small and is changed to DINT and UDINT.
BOC-588 / CDSYS-364	LMC058: CNC decoder did not detect syntax error.
BOC-590 / CDSYS-366	LMC058: <code>MC_GearInpos</code> did not behave correctly when changing the ratio in negative direction. If the ratio was changed from -1/1 to -1/2 then a full turn in opposite direction was executed.

ID	Description
BOC-592 / CDSYS-367	LMC058: When the master was in standstill, MC_GearIn was started correctly, but if then MC_GearOut was started, axis reported an error "Axis not ready for motion".
BOC-594 / CDSYS-368	LMC058: When velocity ramp type of slave axis was set to Quadratic and the MC_GearIn was executed with Jerk=0 (FB input), then the controller stopped with exception.
BOC-597 / CDSYS-370	LMC058: If tappets are defined in a CAM, the CAM application needs about 3 times more CPU power (measured in MotionTask) than the same application without tappets in the CAM. Additionally, when CAM tappets are configured, the MC_CamIn was demonstrating an incorrect behavior after one running CAM cycle.
BOC-599 / CDSYS-371	LMC058: In a LMC058 CNC application, the reset of H-functions by programming "H-2 L-10" did not work.
BOC-913 / PLAT-1090	TM2/TM3: When using a TM2 analog module, it was not possible to edit the minimum/maximum of the scope.
CVE-2019-13532	Security update for CODESYS V3 web server
CVE-2019-13548	Security update for CODESYS V3 web server

Known Operational Anomalies

ID	Description
PLAT-943	LMC058/M258: When migrating a project from SoMachine V4.3 to Machine Expert V1.2.5, default value of input/outputs of TM5 are lost. Default value must be re-affected.
PLAT-958	M258: Embedded, local and remote TM5 on M258/LMC058 cannot be directly duplicated on a TM5 bus coupler.
PLAT-1007	M258: In simulation mode, the icon of Can0 and Can1 is green instead of red. No CAN traffic will be generated.
PLAT-1025	M258: In case of converting a controller application from M258 to M241, the WebVisualization protocol option is reset. Verify the option in your converted application.
PLAT-1089	LMC058/M258: In case of an upgrade from a firmware version older than 4.0.3.6 or 2.0.31.40 having "option bit(s)" activated, the migration to this newer version will deactivate them.
PLAT-1194	LMC058/M258: When using LMC058***S0 (legacy hardware version of LMC058), downloading the application via USB key is not functional. Using Machine Expert solves this anomaly.
PLAT-1217	LMC058/M258: After changing the alarm output configuration and downloading the new configuration, perform a reset warm to ensure the alarm output is correctly set.
PLAT-1229	LMC058/M258: When deleting CAN motion configuration from CAN1 when CAN0 is also configured may lead to spurious error on CAN0 when generating code. Perform a Clean all in order to remove these spurious errors.
SI-6608	LMC058/M258: The SoftMotion version is not automatically updated after an project update from SoMachine to Machine Expert. This leads to missing libraries in some project. Workaround: The SoftMotion version has to be set manually in the Project Settings > SoftMotion .

Library Information

Version Identification

Description	Version
LMC058 Expert IO	1.0.2.3
LMC058 Motion	1.0.2.1
LMC058 PLCSystem	1.0.3.6
M258 Expert IO	1.0.2.3
M258 PLCSystem	1.0.3.6
FtpRemoteFileHandling	1.3.3.0

Mitigated Anomalies

There are no additional mitigated anomalies with this release.

Known Operational Anomalies

ID	Description
IECLIB-2909	FtpRemoteFileHandling: On LMC058 and M258 the LIST command for servers which sends the data in several frames sometimes does not work correctly if the <code>FB_FtbClient</code> was previously connected to another FTP server.

NOTE: If you are using templates and examples which are not updated with the update of EcoStruxure Machine Expert V1.2.5, you may be presented the **Update Project** dialog. If you are opening an example or template for the first time, you should update to have the correct and corresponding libraries and other necessary support.

Software Information

Version Identification

Description	Version
Controller Assistant	19.2.3.0

New Features

Documentation

The online help is updated with the documentation for:

- SoftMotion (the included chapter for Robotics is not valid as EcoStruxure Machine Expert V1.2.5 do not support this feature)
- Modicon LMC058 Motion Controller
- Modicon M258 Logic Controller

Mitigated Anomalies

ID	Description
CVE-2020-11896	Treck IP stack (Ripple 20)
CVE-2020-11898	Treck IP stack (Ripple 20)
CVE-2020-7520	URL redirection to untrusted site
CVE-2020-7523	Modbus serial driver
BOC-310	Documentation: CTS Inversion was described with "Insert CTS (Clear To Send) level" and is corrected with "Invert CTS (Clear To Send) level" in the TM5 Programming Guide.
BOC-311	TM5 Strain Gauge IoDrvTM5SEAISG Library Guide: In the Related Documents table the incorrect part numbers of the TM5 Programming Guide are corrected.
PLAT-704	Translation of the module TM5SDM12DT description is corrected: 8DO 4DO (incorrect) -> 8DI 4DO (correct)
BOC-326 / HMI-45	Documentation: Legacy information about ModbusTCP Slave was visible in the help.
BOC-488 / SI-6501 / SI-5766	TcpUdpCommunication.library was generating spurious compiler warnings.
BOC-586 / CDSYS-362	Online change was triggered after reopen of a project with G-code.
BOC-638 / SI-6365 / SI-5565	Sporadically it was not possible to create an image from the Project menu (Build > Create image...)
BOC-732 / SI-6364 / SI-6597	The retain file was deleted with a compatible update of the LMC image in the controller assistant.
BOC-772 / SI-5809	The Customize menu was deleted with a Logic Builder update or reinstallation.
BOC-777 / SI-6345 / SI-5803	The Controller Assistant is sometimes not able to format the CF card of a PacDrive M controller (Win10).
BOC-782 / SI-5847	Documentation: There was a translation error for QUERYINTERFACE in the Machine Expert Programming Guide.
BOC-799 / SI-6361 / SI-5884	Sometimes the Device tree was deleted after an convert from TM241CE40T to TM251MESE.
BOC-873 / SI-6354 / SI-5944	Machine Expert was losing user-defined repository path information on closing.
BOC-854 / PLAT-981	A call from the method <code>generate_code</code> which has no arguments was generating an error.
BOC-888 / SI-6353 / SI-6106	The Project update dialog was updating the device version unnecessarily.
BOC-902 / ROB-111	Documentation: RoboticAutoTune library help was not included with the application libraries.
BOC-936 / PLAT-1107	The connection path from some EthernetIP.eds files was marked as invalid.
BOC-1029 / IECLIB-2905	Documentation: The variable from the SmartInfeed product generation simulation was <code>xProductLenghtVariance</code> instead of <code>xProductLengthVariation</code> in the Online Help.
SI-6031	Documentation: The firmware function <code>FC_MAreaCommunicationServiceEnable</code> was not documented.
SI-6248	Documentation: The error message 8342 "On/OffPos inverted (On/OffDelay ok?)" was not listed in the online help.

Known Operational Anomalies

ID	Description
BOC-861 / SI-5984	ApplicationLogger: The text size of the Applicationlogger filter is not sufficient to read the complete text.
BOC-945 / SI-6329	Trace editor buffer size for Device Trace cannot be changed. Trace recording time limited to 01h 11min.
BOC-946 / IECLIB-2840	Using the SmartInfeed outside PacDrive templates and using functions/ methods from the IF_Infeed results in a PageFault if AutoRunning is not active, respectively the FB_Infeed is not in the state "Working".
BOC-971 / SI-6376	Smpb file is proposed as supported file, but when opening such a file an error occurs.
BOC-980 / CDSYS-529	Generate code leads to an AssertionFailed exception in some projects using function blocks which use arrays with a variable size.
BOC-982 / IECLIB-2873	Exception 8105 - Encoder Signal out of Range does not reset the flag HomeOk for an axis in the template.
BOC-992 / CDSYS-527	Array online monitoring range does not work properly and allow more than 1000 REFERENCE TO ARRAY elements for online monitoring.
BOC-1000 / SI-6472	The communication parameters of a Profinet device are not displayed correct in the PDI file.
BOC-1002 / SI-6473	Converted an LMC Pro to an LMC Eco, the PLC Settings were changed unintentionally.
BOC-1003 / SI-6474	No messages are shown about changed library version after converting a controller.
BOC-1017 / SI-6542	Device addressing in the popup menu points an incorrect PacDrive controller.
BOC-1072 / CDSYS-552	Smart coding does not work on alias from a library of type ARRAY OF STRUCTURE.
SI-5988	No information at start up when the new installed version/addon contains new Device Type Managers (DTMs).
SI-6029	When using the function Save As Function Template a negative value for a numeric parameter is not possible. The minus is not considered as part of the value.
SI-6125	When using the command Show update dialog it is always shown, that an upgrade for the project version is needed.
SI-6483	Performance issue in CompileMessage convention with some big projects.
SI-6443	Generic Ethernet/IP object is available for PacDrive, but it does not work.
PLAT-991	Reopening a just saved project may lead to non real build errors on serial line. Perform a Clean all in order to remove these spurious errors.

EcoStruxure Machine Expert V1.2.6

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M262	5.0.4.83

Modicon M262 Motion Controller

The Modicon M262 Motion Controller supports the Robotic library. For details see the section Library Information, page 133.

OPC UA Client

NOTE: The OPC UA Client is usable only if the OPC UA Server is enabled. For that, open in Machine Expert the **MyController** window, then **OPC UA Server Configuration > General settings** and select **OPC UA Server** enabled.

Mitigated Anomalies

M262 Motion

ID	Description
MK-1106	Axis jumped on MC_CamIn - rampin - positive or negative direction.

Known Operational Anomalies

M262 Motion

ID	Description
MK-1118	Robotic - Variables of ARRAY OF PDL.ST_Vector3D marked as undefined.
MK-1109	MC_MoveAbsolute - with modulo axis and small ramps.
MK-1097	Negative velocity MC_MoveAdditive.

Library Information

Version Identification

Description	Version
FileFormatUtility	1.4.15.0
FtpRemoteFileHandling	1.3.6.0
Robotic (PacDrive)	2.16.0.0
Robotic (M262)	3.0.3.0
RoboticModule	2.12.0.0
SchneiderElectricRobotics	2.10.0.0
SchneiderElectricRobotics Parameters	2.13.0.0
SchneiderElectricRobotics Toolbox	1.5.0.0
RoboticsAutoTune	2.0.0.0

New Features

FileFormatUtility

Added new function block FB_JsonUtilities supporting the parsing of JSON formatted data.

Robotic

For limitations with M262 refer to the *Robotic Library Guide*.

Mitigated Anomalies

ID	Description
BOC-1122 / IECLIB-3436	FtpRemoteFileHandling required TcpUdpCommunication library V2.0.17.0 which was not available.

Known Operational Anomalies

ID	Description
IECLIB-3417	FileFormatUtility: Precompiler error C0358 occurs if an ENUM ET_JsonValueType is been used for verifying "Type of Selected" property.
BOC-1107 / IECLIB-3420	MC_Power timeout is insufficient when used with an LXM32M with 3rd party motor.
BOC-1117 / IECLIB-3437	The function block MC_Power does not enable the power stage in combination with Lexium_IL*2 drives.
BOC-1118 / IECLIB-3438	Motion Control Library Guide: It is not clearly described which stop ramp is used by the function block MC_Stop.
BOC-1119 / IECLIB-3440	CrankModule Library: The crank module warm start can be executed before the transformation is active.
BOC-1120 / IECLIB-3439	MC_ReadAxisInfo: The outputs LimitSwitchPos and LimitSwitchNeg are not correct when Safe Torque Off (STO) inputs are FALSE.
BOC-1123 / ROB-124	In case of an emergency stop (E-Stop) the use of the variable rstRefOrientationTCP inside of FB_AdditionalTransformationTCP triggers a watchdog.

NOTE: If you are using templates and examples which are not updated with the update of EcoStruxure Machine Expert V1.2.6, you may be presented the **Update Project** dialog. If you are opening an example or template for the first time, you should update to have the correct and corresponding libraries and other necessary support.

Software Information

Mitigated Anomalies

There are no additional mitigated anomalies with this release.

Known Operational Anomalies

ID	Description
BOC-1086 / SI-5669	The functionality of Add function from Template does not take over the used IP address from the template to the device.
BOC-1089	The PreCompiler creates an error if a project with M262M controller is used where the ARRAY OF PLCO.MC_CAM_ID is used in the code.
BOC-1100 / CDS-64615	An application with two function blocks FB_1 and FB_2 where FB_1 has two methods that it provides to FB_2. A call of FB_2 generates the advisory message C0298 "Calculation of stack usage incomplete because of recursive calls: SR_Main () -> FB_2 () -> FB_1.METH_1 () -> FB_1.METH_2 () -> FB_1.METH_2 ()".
BOC-1103 / PLAT-1278	The Download App macro does not contain the command to download the WebVisualization files.
BOC-1109 / SI-4922	Activation of Code Analysis trial is unsuccessful.

EcoStruxure Machine Expert V2.0

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M241	5.1.9.14
M251	5.1.9.14
M262	5.1.5.30
TMSES4	1.0.0.8
TM3DQ8••	2.0
TM3DQ16••	2.0
TM3DQ32••	2.0
TM5NEIP1	3.10
TM5NS31	2.78
LXM32S•••M2 / LXM32S•••N4	- Drive firmware: V1.10.2 - Sercos3 interface firmware: V1.10.7
LXM52••••C•••••	1.54.26.0
ILM••••••••••	1.54.26.0
LXM62••••C•••••	1.64.10.0 for hardware revision RS1• 1.54.27.0 for hardware revision RS0•
LXM62••••D•••••	1.64.10.0 for hardware revision RS1• 1.54.27.0 for hardware revision RS0•
LXM62••••E•••••	1.54.27.0
LXM62••••F•••••	1.54.27.0
LXM62••••G•••••	1.64.10.0
LMC Eco	V1.64.18.26
LMC Pro	V1.64.18.26
LMC Pro2	V1.64.18.26
ATV340S	- Drive firmware: V1.4IE09_B06 - Sercos3 interface firmware: A1.2IE01_B00

Description	Safety-Related Firmware Version
LXM62••••E•••••	1.2.4.0
LXM62••~F••~••	1.2.4.0
VW3E702200000 safety option module	1.2.4.0
TM5CSLC100FS	2.56
TM5CSLC200FS	2.56
BWU2984 SWID	134253
BWU2984 Safe CPU A	135115
BWU2984 Safe CPU B	135116
ASIMON360	3.2.6.7

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

Certificates on the Controller

Certificates on the controller use the real time clock.

NOTE: To create certificates with a valid expiration date, set the real time clock to the present time beforehand.

TM5 EtherNet/IP Bus Coupler

NOTE: The TM5 EtherNet/IP bus coupler is not available for PacDrive controllers with EcoStruxure Machine Expert V2.0. Projects containing this module can be opened with EcoStruxure Machine Expert V2.0 but cannot be compiled.

To compile your project containing the TM5 EtherNet/IP bus coupler, use the original EcoStruxure Machine Expert version you used to create the project.

However, the TM5 EtherNet/IP bus coupler remains compatible with the Modicon M262, M241 and M251.

New Features


M262 OPC UA Client Enhancements

OPC Unified Architecture (OPC UA) is a vendor-independent communication protocol for industrial automation applications.

The client / server OPC UA capability is embedded in version V5.1.5.15 of the following M262 platforms:

- M262L20MESE8T
- M262M25MESS8T
- M262M35MESS8T

The controller can be client and server simultaneously. The OPC UA client functionality is delivered in the *OpcUaHandling* library.



OPC UA data exchange is performed using function blocks that are compliant with the PLCopen specification *PLCopen OPC-UA Client for IEC61131-3* version 1.1 and provide the following functions:

- Read/write of multiple items
- Diagnostics

For the new function blocks, refer to *OpcUaHandling* in the *Library Information* chapter, page 149.

OPC UA Server Enhancements

The OPC Unified Architecture server (OPC UA server) allows the Modicon M262 Logic/Motion Controller to exchange data with the OPC UA clients.

Server and client communicate through sessions.

New OPC UA Server Symbols Configuration

In addition to IEC base data types, the OPC UA server can also expose OPC UA variables from IEC symbols that are composed of the following complex types:

- Arrays and multi-dimensional arrays (limited to three dimensions).
- Structured data types and nested structured data types as long as they are not composed of a UNION field.

Performance OPC UA Client / Server

The table lists the OPC UA performance:

OPC UA Client		OPC UA Server	
Number of servers concurrently	5	Number of client connections concurrently	4
Nodes per client / connection	5,000	Number's variables / connection	5,000
-	-	Number's variables / connection (maximum)	15,000
Minimum refresh time client	Server capability	Performance refresh variable	200 ms...5,000 ms
Subscription Client / Server			
Maximum queue list size per subscribed node	10	-	-
Maximum number of subscriptions	Server capability	Maximum number of subscriptions (server)	100
Variables per subscription	100	-	-
Maximum number of returned browse results with one execution	30	-	-

New Controller

The new controller reference TM262M05MESS8T is added. Modicon M262M05 is the new entry level for synchronized motion application (up to 4 synchronized axes) and embedded safety. For details refer to the catalog.

TM262M35MESS8T Improvement

The maximum number of synchronized axes has been increased from 16 to 24 in 4 ms Sercos cycle time.

Global View of the Axis Number on Sercos

New references and capabilities on the number of Sercos drives and devices are added:

	Sercos cycle	Max Number Sercos drives	Max Number Sercos devices (including Sercos drives)
TM262M05	1ms	4	6
	2ms	4	10
	4ms	4	12
TM262M15	1ms	4	8
	2ms	4	16
	4ms	4	16
TM262M25	1ms	4	12
	2ms	8	16
	4ms	8	24
TM262M35	1ms	8	16
	2ms	16	24
	4ms	24	40

NTP V4.0

NTP V4.0 client/server is available in the M262 references, configuration through configuration screen with EcoStruxure Machine Expert.

Other

- New rules for Cybersecurity embedded.
- New symbol configuration management thanks to the Symbol set.
- New Diagnostic feature embedded.

Modicon M262 Motion Controller

G-Code and CNC Solutions

With M262 M05, M15, M25 and M35 it is possible to create CNC applications with libraries that are compatible to those used in LMC058 and LMC078 applications.

Main features are:

- CNCExtension library (compatible with SM3_CNC)
- Functions for path conversions and compensations
- Full set of interpolation functions
- 3D CNC editor according to DIN 66025 (G-code) for motion planning and representation; with parallel textual and graphical display and DXF import.

CSV - Cyclic Synchronous Velocity

When an application requires that the motor maintains a set speed, even under varying loads, CSV mode is used (position is ignored). Examples of applications that use CSV mode are conveyor tracking, dispensing, and machining processes such as grinding or polishing, where motor load varies but velocity needs to be maintained throughout the process.

Modicon M241/M251 Logic Controllers

- Possibility to configure IP routes in the controller.

- Possibility to configure the KeepAlive time and communication time-out for TCP connections.
- Encrypted communication is available for embedded Webserver (HTTPS) and FTP server (FTPS).

Modicon TM3 Standard I/O

New hardware revisions are available for TM3DQ8••, TM3DIQ16••, and TM3DQ32••.

The new TM3 I/O modules are supported by M241, M251, M262 controllers and TM3 bus couplers. The following new features are configurable with modules of software version V2.0 or later:

- Output fallback function: When the I/O bus connection is lost, user-configurable fallback values are applied to the outputs of the TM3 digital output modules after a delay time period has elapsed.
- Firmware upgrade: The firmware of the TM3 I/O modules can be updated by the controller.

Drives

New Diagnostic Message - The new diagnostic message 8915: *Selected EncoderMode not supported* is triggered if the EncoderMode "Machine encoder is only used for position control / 1" is selected with a linear motor or an asynchronous motor. In this case it replaces the diagnostic message 8503: *Sercos service channel error detected*.

PacDrive LMC Control

Sercos Robustness - Allows you to keep the Sercos network operable even if a non-critical device is in an inoperable state or is removed. For further information, refer to *Sercos Improvements (Sercos Robustness) for PacDrive Control* in the *Additional Information* chapter, page 170.

OPC UA Client - New function blocks based on PLCopen standards are available to establish OPC UA client connections between controllers. For further information, refer to the new features of the OpcUaHandling library, page 149 or to the OpcUaHandling Library Guide.

Additional Ethernet Port - Provides the possibility to have an additional standard Ethernet interface on board. For further information, refer to *Additional Ethernet Port for PacDrive Control* in the *Additional Information* chapter, page 166.

Profinet Topology Editor - New editor to display the network topology, available for the Profinet IO controller.

UTC and Time Zone Information - The LMC PacDrive family supports UTC time and time zone information via IEC interface.

Encrypted Communication - The LMC PacDrive family supports encrypted communication between the controller and the engineering tool EcoStruxure Machine Expert.

M262: Single Wiring Coexistence (SWC) Architecture

The architecture limitation is removed. TM5NS31 and TM5CSLCx00FS can now be the last device in the Sercos segment.

Mitigated Anomalies

Drives

ID	Description
SERVOD-163	The diagnostic message <i>8916: Wrong ControlMode selected</i> is no longer triggered and the status LED of the drive is not flashing red when a motor without encoder was used. This occurred during a drive boot before Sercos reached the phase 4. Workaround with EcoStruxure Machine Expert V1.2: The diagnostic message can be acknowledged.
SERVOD-261	When an update of the drive firmware was started with the Device Assistant while the Sercos was in phase 4, the correct error message is triggered.
SERVOD-283	The parameters <i>GearIn</i> and <i>GearOut</i> now allow for greater maximum values. The limits have been increased from 999999 to 9999999 (from 6 to 7 digits) for both parameters.
SERVOD-309	The diagnostic message <i>8137: Motorless</i> can now be acknowledged.
SERVOD-312	The execution of <i>FB_InitMachineEncoder</i> reset the <i>EncoderMode</i> "Machine encoder is only used for position control / 1" in the drive so it was different to the <i>EncoderMode</i> in the controller configuration. The <i>RefPosition</i> of the drive was adjusted to the position of the <i>MachineEncoder</i> while the position control in the drive was performed with the motor encoder. Typically there is a big position difference between the two encoders. Therefore, the diagnostic message <i>8111: Shutdown due to tracking deviation</i> was triggered when the <i>ControllerEnable</i> was set.
SERVOD-346	When Sercos was in phase 4 in line topology, a LXM62StandardPlus or a LXM62AdvancedPlus was the last device in line and the second port of the controller had been connected with the second port of this drive so that the topology should switch from line to ring, a C1D error was triggered.
SERVOD-350	There was sometimes an inaccurate current value for asynchronous motors in open-loop control because the standstill (<i>RefVelocity</i> = 0) was not detected correctly. In this case the current value was changing without an action in the movement.
SERVOD-409 / SERVOD-435 / LXM62P-1630	New diagnostic messages are triggered with Hiperface DSL encoders: • <i>8171: Encoder communication disturbance detected</i> is a diagnostic message to inform about a disturbance in the encoder communication that does not lead to a shutdown yet. • <i>8175: Extended message for encoder disturbance</i> is triggered after diagnostic message 8171 to show additional data in the drive logger that must be asked from the encoder first. Therefore, this logger entry is delayed. • <i>8176: Encoder connection break</i> is a diagnostic message to show a physical break of the connection to the encoder. • <i>8958: Encoder communication not possible</i> is a diagnostic message triggered when data could not be read from the encoder several times. An error code from the encoder is available as additional data in drive logger. This diagnostic message had only existed for standard Hiperface encoders in the past.
-	When the encoder supply voltage (provided by the drive) is too low during firmware boot, the diagnostic message <i>8185: Internal device error</i> is triggered.
SERVOD-429	The new states <i>16#B5 "ReleaseEncoderlessVelocityControl"</i> and <i>16#C5 "ActiveEncoderlessVelocityControl"</i> have been added for <i>InternalDeviceState</i> . These new states are used in <i>ControlMode "Encoderless velocity closed-loop control / 2"</i> and replaces the states <i>16#B1 "Release the brake for position control"</i> and <i>16#C1 "Active position control"</i> in this case.
-	When a Sercos parameter with the attribute write protected in CP4 was written in Sercos phase 4, the Sercos service channel error with the extension <i>0x7001 Parameter doesn't exist</i> was triggered instead of <i>0x7005 Write protected at time</i> .
SERVOD-452 / SERVOD-491 / SERVOD-503	The diagnostic message <i>8503: Sercos service channel error detected</i> has been replaced by the diagnostic message <i>8916: Wrong ControlMode selected</i> , if <i>EncoderMode</i> of the machine encoder does not match with the selected <i>ControlMode</i> or if an encoder is needed but not available for the selected <i>ControlMode</i> . It is also considered, if a machine encoder is used with <i>ControlMode "open-loop control / 1"</i> or <i>"Encoderless velocity closed-loop control / 2"</i> or with linear or asynchronous motors, because these combinations are not allowed.
SERVOD-469	Identify Device had always been indicated on both axis of a DoubleDrive. The flashing of S3 and State LED was not synchronized.
SERVOD-479	The <i>ControlMode "Encoderless velocity closed-loop control / 2"</i> was not usable on axis B of LXM62StandardPlus DoubleDrive. This mode could be configured but was not operating as required.
-	When an invalid encoder position is detected, the diagnostic message <i>8105: Encoder position invalid</i> or <i>8195: Machine Encoder position invalid</i> is triggered and the position is adjusted again. If, however, an invalid position is again detected while one of these diagnostic messages is still pending, this did not lead to a new position adjustment. Due to this effect the encoder position could differ from the physical position with standard Hiperface encoders. A pending diagnostic message <i>8105: Encoder position invalid</i> could lead to an undetected deviation in the position from the motor encoder and a lost commutation of the motor. The diagnostic message <i>8908: Unintended motor operation detected</i> could be triggered as soon as <i>ControllerEnable</i> has been set.

ID	Description
	A pending diagnostic message 8195: <i>Machine Encoder position invalid</i> no longer leads to an undetected deviation in the position from the machine encoder.
SERVOD-481	Incorrect counter values: infrequently an incorrect counter value was displayed at TouchProbe inputs from drives. The counting itself was not incorrect but the displayed counter value could be incorrect.
SERVOD-509	The number of allowed additional IDN was reduced from 6 to 5 if the Machine Encoder has been used on LXM62AdvancedDrive. The number of additional IDN is now restored to 6.
SERVOD-1699	A drive firmware update with FDR (Fast Device Replacement) could be declined by a timeout in the LMC (visible in the MessageLogger), mainly when it was used with a high amount of axis. The stability of the FDR process is improved by a better response behavior on the drive side.

HMISCU Controllers

ID	Description
CVE-2019-9008	Specific cybersecurity vulnerabilities are mitigated.
CVE-2019-9009	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-10245	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-7052	Specific cybersecurity vulnerabilities are mitigated.

M262

ID	Description
M262-4249	Upon restart the TMS was randomly not taken into account.
M262-4503	In case an SLCx00 or TM5NS31 was the last Sercos device in the SWC architecture, the PhaseUp was sometimes not performed.
M262-4549	When modifying the user rights, you had to ensure that no external equipment made an attempt to access M262 variables with former credentials.
M262-4557	<i>NbOfIncs</i> and <i>NbOfUnits</i> values had to be < 2,147,483,647 (231), otherwise the capture was invalid.
M262-4574	If SoMachine V4.3 or an earlier version was installed on the computer, the IP address used by the PC was not correct. Thus, the USB communication was not operational.
M262-4576	An M262 was not discovered by USB and could not be connected to EcoStruxure Machine Expert.
M262-4655	WebVisualization: Each refresh of variable manages a communication access if the user rights are validated, a password will be requested for these actions. Username and password are requested each time a page refresh / online change / application download is performed by the WebVisualization.
M262-4658	An error was detected when restarting projects with 4 KB retain variables. The download could be unsuccessful and the message <i>TLS_IO_Communication</i> was displayed.
M262-4683	TcpUdpCommunication library: At first startup after firmware update, the certificate store was not ready. An application that included TLS communication needed a second startup.
M262-5224	CANopen: After a few hours LXM32A returned the error code B4000.
M262-5137	<i>SysTimeRtcSet</i> : After a power OFF the real time clock (RTC) of the controller was no longer accessible if it is set by the <i>SysTimeRtcSet</i> function.
M262-5260	OpcUaClient: <i>ServerState</i> = <i>Running</i> while the cable was disconnected.
M262-5350	Crash "SchedException" occurred while downloading via Ethernet.
M262-5376	EtherNet/IP Scanner: Loss of ATV320 connection occurred after a project update.
BOC-1143	TM5NEIP did not start properly. Workaround: Adapt the cycle time in configuration if needed.
CVE-2019-9008	Specific cybersecurity vulnerabilities are mitigated.
CVE-2019-9009	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-10245	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-7052	Specific cybersecurity vulnerabilities are mitigated.

M262 Motion

ID	Description
MK-992	The Scaling library is removed. As a result, customer projects including this library (Machine Expert V1.1) could not be converted to Machine Expert V1.1 SP1 or greater without the error message <i>"Unhandled execution has occurred in your application"</i> . Workaround: Either do not convert or copy the application content instead of converting it.
MK-1155	<i>MC_CamIn</i> had an offset compared to the absolute master position. This offset increased at each execution. This occurred if master start mode was absolute and slave start mode was absolute or ramp-in. This could have led to a jump on the slave axis.

M262 Safety

ID	Description
OEM00076931	In case an SLCx00 or TM5NS31 was the last Sercos device in the SWC architecture, the PhaseUp was often not possible.

M241/M251

ID	Description
CVE-2021-22699	Specific cybersecurity vulnerabilities are mitigated.
CVE-2019-12257, CVE-2019-12255, CVE-2019-12261, CVE-2019-12263, CVE-2019-12258, CVE-2019-12259, CVE-2019-12262, CVE-2019-12264, CVE-2019-12265	Specific cybersecurity vulnerabilities are mitigated.
CVE-2019-9008	Specific cybersecurity vulnerabilities are mitigated.
CVE-2019-9009	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-10245	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-7052	Specific cybersecurity vulnerabilities are mitigated.
M2X1-5	The Upload Recipes From Devices command is functional now.
M2X1-145 / OEM00077297	After > 300 power cycles the controller indicated error states on the Ethernet adapter and the TM3BC_EtherNetIP_3_RemoteAdapter nodes.
M2X1-173	The webserver session was not handled correctly on M241 controllers.
M2X1-190 / OEM00077736	The function block <i>FB_FtpClient</i> block did not detect a communication loss during file transfer.
M2X1-219 / OEM00077779	The application could not be simulated if the function block <i>FB_TesysU</i> was used.
M2X1-236 / OEM00079349	Incorrect boot up IP address on the USB Ethernet interface is resolved.
M2X1-263 / OEM00069074	TM251MESE: After > 200 power cycles, ETH1/ETH2 indicated that the Ethernet port was not connected.
M2X1-264 / OEM00068693	After disconnecting and reconnecting the Ethernet cable, some Ethernet services did not restart correctly (for example, could not ping an IP address).
M2X1-269 / OEM00072286	When the mappings were deleted from the output variables mapping, the default values remained enabled (Transition Run>Stop).
M2X1-285 / OEM00060503	The M241 controller forwarded packets to its gateway.
M2X1-300 / OEM00077688	The user connections to the controller could be blocked.
M2X1-354 / OEM00066223	Logged data entries were missing.
M2X1-357 / OEM00075550	Even if function code 5 was configured, the Modbus serial IOScanner sent function code 15.
M2X1-413	ASCII Manager: The last byte was lost when an odd number of bytes was available.
M2X1-444	M251/M241 received the incorrect frame when Frame Received Timeout value was minimum.

PacDrive LMC Control

ID	Description
CVE-2019-9008	Specific cybersecurity vulnerabilities are mitigated.
CVE-2019-9009	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-10245	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-7052	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-10664	Specific cybersecurity vulnerabilities are mitigated.
LMCFW-1389	An OPC UA server error with <i>TskOpcUaAsyn</i> / <i>TskOpcUaJob</i> was detected when the IEC code was modified.
LMCFW-1395	An IO Link error was detected at the incorrect event channel.

ID	Description
LMCFW-1402 / LMCFW-2047	A software error (PageFault) <i>8902 TskOpcUaAsyn / TskOpcUaJob</i> was detected after IEC program modification.
LMCFW-1962	State of the touch probe input was only refreshed for the first 16 touch probe inputs.
LMCFW-2010	A Real-Time Process (RTP) exception was detected with hardware watchdog after calling <i>FC_TPEdge</i> .
LMCFW-2048	Specific cybersecurity vulnerabilities are mitigated.
LMCFW-2370	Unusual drive velocity peaks were detected in the Sercos line topology.
LMCFW-2379	The message <i>8191: Mechanical overload protection without power on the axis</i> was triggered when switching the <i>TorqueLimiton</i> mode to <i>Mechanical Overload Protection</i> even if the axis was not powered.
LMCFW-2528	The function <i>FC_ControllerStopSet</i> was not working depending on the parameter <i>i_rDeceleration</i> .
LMCFW-2819	OPC UA time stamp could not be adjusted to UTC time.
LMCFW-2823	The parameter <i>VendorCode</i> in a Sercos drive was not verified.
LMCFW-2824	The <i>SercosDrive</i> parameter was not updated.
LMCFW-2906	The OPC UA server replied an incorrect <i>ArrayDimensions</i> value for scalar.
LMCFW-3101	The unresponsive behavior with the bit 'Valid' of <i>FC_GetParameter</i> no longer applies.
LMCFW-3230	The firmware update did not work in some cases.
LMCFW-3334	Unexpected build errors were triggered.
LMCFW-3825	The FDR state 1 was skipped during the FDR procedure.
LMCFW-3878	An OPC UA exception was raised during an online change.
LMCFW-4028	The Profinet hardware watchdog was exceeded repeatedly.
LMCFW-4038	The <i>FC_DiagConfigSet2</i> did not operate as intended.
SI-3444 / OEM00076369	Modifications were detected for persistent variables, although the persistent variables were not modified. This occurred if a 128 MB Compact Flash (CF) memory card was used.

TM3 Bus Coupler

ID	Description
TM3BC-1313	Analog input values were not updated correctly when the diagnostic parameter of the analog module was disabled.

Known Operational Anomalies

Lexium 62

ID	Description
SERVOD-520	Overcurrent can occur if the following conditions apply: - A LXM62 StandardPlus or LXM62 AdvancedPlus drive is used with Plus firmware (non-compatibility mode). - AND - The LXM62 drive is decelerated with a high current (> 50 A). - AND - A motor is operated with high velocity (> 60% of nominal speed). - AND - The current is changing forcefully (> 20 A/ms). This can lead to the diagnostic messages <i>8107: Overcurrent</i> or <i>8119: Power stage short-circuit / ground fault</i>, and the power stage is switched off (free-wheeling mode). If the message 8119 is displayed, you must reset the drive. This issue can also occur when switching off <i>ControllerEnable</i> or when the drive triggers a reaction (to stop the motor) from another diagnostic message. Workaround: - Reduce the velocity. - Reduce the deceleration. - Reduce the jerk. - Reduce the peak current (<i>UserDrivePeakCurrent</i>). - Reduce the current limitation (<i>UserCurrentLimit</i> or <i>DriveStopCurrentLimit</i>). - Reduce the control loop gain of the velocity and position control loop. You can combine the measures freely.

M262

ID	Description
M262-5063	When the object <i>UserIdentityToken.UserIdentityTokenType</i> is used in an OPC UA visualization, the WebVisualization screen may close. Workaround: Restart the WebVisualization screen.
M262-5870	The axis error ID 108 read with <i>FBReadAxis</i> error can be detected if more than six parameters are exchanged with an ATV320.
M262-5913	After several consecutive power cycles, the controller infrequently stops operating and the log message <i>BlkDrvUdp</i> is indicated.
M262-5948	With large applications using Input Run / Stop the controller is starting slower than if the RUN/STOP input is not configured.
M262-6032	Starting the WebVisualization immediately after the controller is running takes longer with EcoStruxure Machine Expert V2.0 (average time 1 s).
M262-6077	After an update from V1.2.4 to V2, the login via Nodename may not be possible. Workaround: Change the Connection Mode to Fast TCP.
M262-6098	If the controller is restarted after an online change, infrequently the IP address can be lost.
M262-6100	The M262 controller can start in exception state after downloading the WebVisualization via FTP. Workaround: Restart the controller after download.
M262-6151	Infrequently, if the number of TM3BCEIP bus coupler exceeds 15, and one of those bus couplers is power cycled, it is no longer seen on the network.

M262 Motion

ID	Description
MK-1088	General Motion Control - <i>CamIn</i> : The slave is not moving in the first cycle if started while the master axis is moving (<i>MasterStartMode</i> absolute).
MK-1168	General Motion Control: An unexpected movement of <i>PLCO.MC_MoveAbsolute</i> with Jerk = 1E+16 occurs.
MK-1213	When you disable the axis while running in CSV mode, the axis can freeze for a few cycles (~5 cycles), this freeze can be heard on the motor shaft. If this axis is master of another axis (for example, <i>MC_GearIn</i>), this freeze can be visible on the slave axis.
MK-1281	An exception can occur in the controller (seen as System watchdog) if the execution time exceeds 700 µs (code executed in the <i>AFTER_RTP</i> task) during the Sercos PhaseUp. Workaround: Add a condition (wait phase 4) before executing the IEC code of the <i>AFTER_RTP</i> task.

M241/M251

ID	Description
M2X1-690	The EcoStruxure Operator Terminal Expert cannot establish a connection to the M241/M251 controller when the connection mode IP address is selected. Workaround: It is working well if the connection mode Node name is selected.
M2X1-526 / PEP0626052R	Application loaded into controller using mass storage feature does not always start in run. Workaround: Perform a Clean all action before building the application to resolve the issue (requires EcoStruxure Machine Expert V2.0).
M2X1-590	Status of IP Master communication is not refreshed after an application update. Workaround: Perform a power cycle to resolve the issue.
M2X1-634	After an online change, open editors may display online value of variables incorrectly. Workaround: Close opened tabs and re-open again to resolve the issue.
M2X1-650	Webvisualisation may not respond after an online change command. Workaround: Perform a Clean all command to resolve the issue.
M2X1-654	After upgrading a SoMachine V4.3 project, going to the Users and Groups tab may lead to a message about existing device user data even if the initial application did not contain user rights definition. Workaround: Ignore and close the popup message.

PacDrive LMC Control

ID	Description
LMCFW-2023 / OEM00076650	Too many fieldbus participants with too much data can lead to the following error message: <i>EtherCAT Master: Download bus configuration to NetX</i> .
LMCFW-2820	An incorrect status is returned by the system when the TM5 module is in error state.
LMCFW-2910	<i>PositionBehaviorOfMasterAndSlave</i> may have different behaviour in C2C.
LMCFW-2911	Name and IP address may not be displayed in the hardware after downloading the Profinet configuration.
LMCFW-3137	<i>IO-Channel Optimization</i> leads to an incorrect transfer of input/output data.
LMCFW-3490	A Sercos message may be displayed when displaying SLC variables
LMCFW-3988	The Profinet Scan For Devices displays a controller IP address conflict.
LMCFW-3991	The Profinet diagnostics functions return the message 'Not Supported'.
LMCFW-4129	A hardware watchdog occurs while a break point is active and a download is executed.
LMCFW-4132	A disabled Profinet device may update the input values.
LMCFW-4230	An error is detected during firmware change of the LXM62DC13 using FDR (Fast Device Replacement).
LMCFW-4512	For a large system setup (more than 119 axis) a watchdog error may be detected on the LMC controller during the Sercos PhaseUp.

ID	Description
LMCFW-4549	The LMC Pro controller may not boot when a USB key is plugged into the port CN7 .
LMCFW-4565	A cycle time overrun (> 8 ms) may occur after downloading the project for the first time.
LMCFW-4575	A Sercos error can be detected after reconnecting a device that uses the Sercos Robustness feature, page 170.
LMCFW-4606	A connection to a PC-based OPC UA server (using the name instead of the IP address) with PacDrive LMC controller as client cannot be established.
LMCFW-4684	An exception <i>Cycletime overrun</i> may occur with a ProfiNetIO controller. Workaround: Temporarily update the Watchdog sensitivity and / or the Overrun factor by using the <i>SystemInterface</i> function <i>FC_CycleTimeSet()</i> .
LMCFW-4695	A PacDrive LMC controller as OPC UA client does not support the login only with credentials but without certificates.
LMCFW-4725	<i>SysTimeRtcSetTimezone</i> may not set the time as expected.
OEM00054944	It is not possible to establish an EtherNet/IP connection when the EtherNet/IP device (ATV32/IL•) is connected directly to the controller. Workaround: Add a switch between the controller and the EtherNet/IP device.

Library Information

Version Identification

Description	Version
ApplicationLogger	1.1.4.0
CNCExtension	1.0.4.0
CommonMotionInterface	1.4.3.0
CommonMotionTypes	1.0.2.0
CommonToolbox	1.0.2.0
EMailHandling	2.1.0.0
EtherNetIP Explicit Messaging	1.1.9.0
EtherNetIP Remote Adapter	1.1.2.0
FastSampling	1.0.1.0
FileFormatUtility	1.5.5.0
FtpRemoteFileHandling	1.3.8.0
GMC Independent Altivar	1.3.2.0
GMC Independent Lexium	1.2.3.0
GMC Independent PLCopen MC	1.3.3.0
HttpHandling	1.2.0.0
M262Diagnostics	V1.0.7.0
MachineAssistantServices	1.0.2.0
Mathematics	1.0.2.0
ModbusHandling	1.0.5.0
MotionInterface	2.0.108.9437
MqttHandling	2.1.0.0
OpcUaHandling	2.0.14.0
PD_AxisModule	1.6.4.0
PD_ETest	1.5.1.0
PD_MultiBelt	1.4.7.0

Description	Version
PD_PacDriveLib	1.9.6.0
PD_SmartInfeed	1.4.5.0
PD_SoMotionGenerator	1.6.2.0
PD_Template	1.6.4.0
PLCopen MC part 1	2.0.108.9437
PreventaSupport	1.1.7.0
Robotic	3.1.2.0
RoboticModule	2.12.0.0
RoboticsAutoTune	2.0.0.0
SchneiderElectricRobotics	2.10.0.0
SchneiderElectricRobotics Parameters	2.13.0.0
SchneiderElectricRobotics Toolbox	1.5.0.0
Sercos Device Modules	1.0.0.0
SercosMaster	2.0.108.9437
SlcRemoteController	1.3.8.0
SqlRemoteAccess	2.0.3.0
TcpUdpCommunication	2.1.4.0
TeSys island	2.0.4.0
TwidoEmulationsupport	1.2.3.0
Unwinder	1.3.0.0
XpsuSupport	1.0.4.0

New Features

CNCExtension

The new library offers tools to use the G-Code functionalities with M262 controllers.

EMailHandling, HttpHandling, MqttHandling, TcpUdpCommunication

- New parameter in connection settings to specify a host name for the TLS feature Server Name Indication (SNI).
- TLS protocol version 1.3 is supported.
- Improved diagnostics about the result of the certificate verification.
- Improved certificate verification. That allows to simplify the management of certificate by taking into account only root certificate from the chain of trust from the server certificate.
- Secured communication using TLS encryption is supported by PacDrive LMC motion controllers.

FastSampling

The new library provides functionalities to sample the drive position, current and velocity faster than in a Sercos cycle.

FileFormatUtility

The library is available to parse a JSON-formatted file, to modify parsed strings and write them back to an application buffer or file.

The updated function block *FB_JasonUtilities* allows to parse an application buffer out of a JSON-formatted string or a file.

GMC Independent PLCopen MC

Support of Lexium MDrive on EtherNet/IP for Modicon M2xx and Modicon M262 Motion Controllers.

MachineAssistantServices

The new library offers functionalities to discover Ethernet devices and to perform a basic configuration of these devices.

Mathematics

The library has new mathematical structures and global constants.

ModbusHandling

The new library provides function blocks to implement Modbus client and server functionality in the application.

OpcUaHandling

The complete features of the library are now also supported by PacDrive LMC controllers.

New function blocks available:

- *UA_Browse*
- *UA_MonitoredItemAddList*
- *UA_MonitoredItemOperateList*
- *UA_MonitoredItemRemoveList*
- *UA_SubscriptionCreate*
- *UA_SubscriptionDelete*
- *UA_SubscriptionProcessed*
- *UA_TranslatePathList*

PD_PacDriveLib

The library replaces all STRUCTS of the folder Mathematics with the alias of SE_Math (Mathematics library).

The following data types are changed to the ALIAS type which reference to the corresponding data types of the CommonMotionTypes library:

- *ET_CamType*
- *ET_MultiCamWsMode*
- *ST_CamPoint*
- *ST_MultiCam*
- *ST_Vector3D*

PD_SoMotionGenerator

ET_DiagExt.NoJobWhileAxisMoving is not triggered anymore.

The reference to the PD_PacDriveLib library is changed to CommonMotionTypes library directly.

PreventaSupport

Function blocks with obsolete attributes are marked and refer to the new library XpsuSupport which includes several improvements.

Sercos Device Modules

A new function template is available: Lexium 32S_Sercos

XpsuSupport

The new library provides the *FB_XpsuDiag* and *FB_XpsuMain* function blocks to be used for diagnostic and maintenance purposes with XPSU safety modules.

NOTE: The XpsuSupport Library Guide is not available and will be submitted shortly on the Help Server.

Examples

Machine Advisor Communication example:

- Extended diagnostic feature to retrieve the result of an unsuccessful certificate verification.

OpcUaHandling example:

- New example implementing the OPC UA client feature on a PacDrive LMC controller.

CNCExtension example:

- New example implementing an application which indicates the general way of working in an M262 controller application using the CNCExtension library. Real axes (drives) are not required as the motion is running in **Simulated** working mode.

Updated example projects:

- OpcUaClient example

Mitigated Anomalies

ID	Description
BOC-486 / SI-1711	PD_ETest: Allow the recording of measurands from TestCases / TestResources located in a library.
BOC-577 / IECLIB-2231	PD_MultiBelt: Prevention of watchdog exceptions during startup of <i>AutomaticMode</i> with warm start on MultiBelt applications with 8 belts.
BOC-579 / IECLIB-1232 / OEM00070287 / IECLIB-2447 / OEM00076384	PD_AxisModule V1.6.4.0: <i>SetPos</i> homing modes are now possible with disabled axis power by use of switch <i>i_xKeepPowerDisabled</i> in <i>ST_HomeSetPos</i> of <i>PD_AxisModule</i> . ApplicationLogger entries to detect <i>SetPosHoming</i> with enabled axis power. New <i>FC_InitHomeSetPos2</i> and <i>FC_InitHomeRestorePos2</i> for compatible offer of <i>i_xKeepPowerDisabled</i> in <i>TemplatePilotProgrammingFramework</i> .
BOC-701 / IECLIB-2601	PD_MultiBelt: StationOffset (<i>alrStationOffset</i>) was incorrect for a train.
BOC-710 / IECLIB-2595	GMC Independent libraries: <i>MC_Stop</i> with ILX was blocking the state machine when an error occurred during stop.
BOC-815 / IECLIB-2688	PD_SmartInFeed: In case of generating targets by use of <i>IF_TargetGenerator.etMode</i> -> <i>ET_TargetGeneratorMode.TouchProbe</i> , the user must configure <i>TouchProbeTargetType</i> . If the user neglects this step, it led to a spurious PageFault if the <i>VelocityRatio</i> function block is used at the same time. Therefore, the parameter <i>etTargetTpType</i> was set to the default value <i>Sl_ET_SimTypeTp.VirtualTp</i> .
BOC-816 / IECLIB-2689	PD_SmartInFeed: Added new <i>ET_DiagExt.NoTargetFound</i> to help avoid a PageFault in case of missing target.
BOC-836 / IECLIB-2709	MqttHandling: Assigned comments to correct function block inputs.
BOC-844 / IECLIB-2761	PD_SmartInFeed: Call of <i>Init</i> Method of <i>RandomGenerator</i> for simulation of different product length (<i>xProductLenghtVariance</i>) was missing.
BOC-982 / IECLIB-2873	Exception 8105 - <i>Encoder Signal out of Range</i> did not reset the flag <i>HomeOk</i> for an axis in the template.
BOC-1012 / IECLIB-2888	ApplicationLogger: The resolution of the timestamp of a log entry created with EcoStruxure Machine Expert V1.2.3.0 was not provided in milliseconds.
BOC-1027 / IECLIB-2907	GMC Independent PLCopen MC: <i>MC_Jog</i> - Added resetting the trigger to detect, if the velocity changed. The function block will process now the target velocity every controller cycle, if the value of the input <i>Velocity</i> changed.
BOC-1028 / IECLIB-2904	In the present CrankModuleExample project in EcoStruxure Machine Expert an old <i>VIS_AxisModule</i> was used.
BOC-1107 / IECLIB-3420	GMC Independent PLCopen MC: <i>MC_Power</i> - Improved timeout error. Added new diagnostic code (<i>PowerTimeout</i>) and moved providing the diagnostic code from the function block <i>MC_Power</i> to the function block <i>MC_ReadAxisError</i> .
BOC-1117 / IECLIB-3437	GMC Independent libraries: The function block <i>MC_Power</i> did not enable the power stage in combination with Lexium_IL*2 drives.
BOC-1118 / IECLIB-3438	GMC Independent Lexium: <i>SetStopRamp_ILX</i> (ILA2, ILE2) - Implemented reading the configured ramp type (profile or torque) and write the dedicated ramp parameter depending on this ramp type.
BOC-1119 / IECLIB-3440	CrankModule library: The crank module warm start could be executed before the transformation was active.
BOC-1120 / IECLIB-3439	GMC Independent libraries: <i>MC_ReadAxisInfo</i> - The outputs <i>LimitSwitchPos</i> and <i>LimitSwitchNeg</i> were not correct when Safe Torque Off (STO) inputs were FALSE.
BOC-1123 / ROB-124	In case of an emergency stop (E-Stop) the use of the variable <i>rstRefOrientationTCP</i> inside of <i>FB_AdditionalTransformationTCP</i> triggered a watchdog.
BOC-1134 / IECLIB-3450	GMC Independent PLCopen MC: <i>MC_ReadStatus</i> - Fixed bugs and modified the function blocks <i>MC_Reset</i> and <i>MC_ReadStatus</i> and the internal function <i>FC_DeviceStateToPlcOpenState</i> to fulfill the PLCopen state diagram.
BOC-1176 / IECLIB-3504	CommonToolbox: The output of the <i>FB_HeatingControl</i> kept the output <i>q_xPwmOutput</i> at TRUE during Autotune and an error appeared, or after an setpoint changes from a higher value to a very low value.
IECLIB-1833 / OEM00075244	PD_AxisModule V1.6.4.0: The <i>FC_InitDriveParameter</i> no longer performs automatic settings for <i>SlaveAxis.Delay</i> if the master signal is transferred via the C2C- or encoder network. An example code is available as a comment in <i>Init_XXXX</i> instead.
IECLIB-1883	Unwinder: The parameter <i>i_lrJLoadGain</i> only affect the additional load from the foil.
IECLIB-2442	PD_SoMotionGenerator: Stop profile is now correct for <i>etJobType = ET_MotionJobType.PosStop</i> .
IECLIB-2534	M262Diagnostics: Incorrect reading of online parameters from Sercos slave devices is corrected.
IECLIB-2609	GMC Independent PLCopen MC: In case the function block <i>MC_Stop</i> was interrupted by an error, a newly executed motion function block (after disabling and enabling the power stage) was aborted, when the input <i>MC_Stop.Execute</i> was set to FALSE.

ID	Description
IECLIB-2737	TcpUdpCommunication: The property <i>FB_TcpServer2.Socket.ReceiveBufferSize</i> is fixed for M262 controllers.
IECLIB-2807	SlcRemoteController: <i>FB_RemoteController</i> indicates status is correctly after formatting or changing Safe Key.
IECLIB-2909	FtpRemoteFileHandling: On LMC058 and M258 the LIST command for servers which send the data in several frames sometimes did not work correctly if the <i>FB_FtbClient</i> was previously connected to another FTP server.
IECLIB-3458	FileFormatUtility: The methods <i>Select</i> and <i>SelectElementOfArrayByIndex</i> now operates properly with nested arrays and complex types.
IECLIB-3486	FileFormatUtility: The method <i>Select</i> is now compatible with Json formatted string whose root element is a type <i>TypeArray</i> .
IECLIB-3535	GMC Independent PLCopen MC: Executing the function block <i>MC_Stop</i> , while <i>MC_Power</i> was disabling the power, created an error.
IECLIB-3576	FileFormatUtility: String length to determinate cut of truncated string no longer considers whitespace in front of value.
IECLIB-3577	FileFormatUtility: <i>SelectNext</i> returns the correct diagnostic message in case the root item was selected.
IECLIB-16844	TcpUdpCommunication: - The default socket option <i>GVL.G_stDefaultSocketOptionsTcpClient.timTimeoutConnectTlsValue</i> was not taken into account as timeout for establishing a connection using the method <i>ConnectTls()</i>. - The default socket option <i>GVL.G_stDefaultSocketOptionsTcpServer.timTimeoutAcceptTlsValue</i> was not taken into account as timeout for accepting a new connection on a secured server socket.
M262-5106	Changing the cycle time of a task caused an exception during download of the application using OPC UA.
M262-5092	Downloading large and complex applications caused an exception during download of the application.
M262-5072	Using multiple OPC UA clients and a large number of nodes resulted in a long execution time and consequently in a watchdog exception.
M262-4248	OPC UA client: <i>UA_ReadList</i> using a pointer in persistent variables led to an exception error. An advisory was already present during the build: "Do not use POINTER in persistent variables, since addresses will change at download."

Known Operational Anomalies

ID	Description
BOC-529 / IECLIB-2141	Moving the homed MultiBelt-Trains far in one direction by hand causes exception after Automatic Start.
BOC-531 / IECLIB-2498	Multibelt homing operates incorrectly after changing Belt-Length.
BOC-578 / IECLIB-2451	PacDriveLib motion function blocks report "Axis not ready" in combination with <i>FC_OverloadDetection</i> .
BOC-671 / IECLIB-2577	SmartInfeed: Filter setting causes error "unknown feedback" when <i>IrIdDistanceAfterPosEdge</i> = <i>G_IrProductLength</i> .
BOC-742 / IECLIB-2613	<i>FC_ControllerStopSet</i> operates incorrectly depending on the value of parameter <i>i_rDeceleration</i> .
BOC-1083 / IECLIB-3444	Multibelt feedback variable <i>xReadyForStep</i> is infrequently FALSE for one Sercos cycle.
BOC-1139 / IECLIB-3445	AxisModule: If the module is already stopped and you send a CMD <i>DriveEnableOff</i> in this situation, the CMD is not acknowledged.
BOC-1162 / IECLIB-3462	The simulation of a SmartInfeed is still active, even when setting the corresponding variable to FALSE.
BOC-1201 / IECLIB-3553	FtpRemoteFileHandling: No error is detected for the LIST command when the buffer size is too small.
IECLIB-16830	ModbusHandling: The connection management behavior of <i>FB_ModbusTcpServer</i> described in the ModbusHandling Library Guide is not supported. If the maximum number of 16 client connections from <i>FB_ModbusTcpServer</i> is reached, new connection requests are not processed.

Software Information

Version Identification

Description	Version
Schneider Electric Software Installer	20.21.09802
Diagnostics	20.0.21.0
Controller Assistant	20.0.21.0
Device Assistant	20.0.21.0
DiffViewer	20.0.21.0
Gateway	20.0.21.0
Launcher	20.0.21.0
OPCServer	3.5.16.30
SVN	4.2.7.0
Logic Builder ⁽¹⁾	2.0
Vijeo-Designer	6.2.11.1012
CoDeSys	V3.5 SP16 Patch4 HF2
SQL Gateway	2.0.0.0
Motion Sizer	4.2.0.0
(1) If using a virtual machine, the download of the online help operates correctly only if the option Accelerate 3D graphics is deactivated in the VM settings.	

New Features Schneider Electric Software Installer

Schneider Electric Software Installer

- A remaining time is shown for download and installation.
- The installation configuration (components) can be exported and imported.
- It is possible to check for updates for the installer.
- A repair of the installation is introduced.

New Features EcoStruxure Machine Expert

New Compiler Version

EcoStruxure Machine Expert V2.0 uses CoDeSys service pack 16: compiler version 3.5.16.84.

Cam Editor Online View

The use of the feature Cam Editor has been extended with an online view.

The benefits of the Cam Editor online view are:

- See the values in the controller
- Get motion feedback from your application

NOTE: The profiles InclSin, User profile (spline) , HarmoComb, ModAccTrCom, and ModiSinCom are not supported.

User Documentation

- A seamless integration of customer's libraries and help files in parallel to the official Online Help has been introduced. Supported formats are CHM and HTML.
- The Offline Help is available in standalone mode.

Script Hooks

The **Script Hook Manager** has been introduced to execute Python scripts triggered on events like ProjectSave, ProjectClosed, several SVN events, etc.

The benefits of the Script Hooks are:

- Automatic backups with different names of a project
- Get a reminder to save the project archive
- Automate additional work to any menu command

Sercos Diagnostic

A new page "Bus View" has been introduced inside Sercos editor for PacDrive.

The benefits of the new page are:

- Compare configuration with connected devices
- New graphic support to identify Sercos problems
- Filter possibilities: Filter to hide / show missing or "too many" devices
- Real-time online values to detect Sercos problems
- Direct jump to the device editors
- See a detected cable issue direct in the view

New Project Format

- A new project setting for security improvement has been introduced.
- You can now choose between the three options **No protection**, **Integrity check** and **Encryption**.
- **Integrity check** is the default project type for new projects/libraries. This setting means that a manipulation outside of EcoStruxure Machine Expert is detected and the project cannot be opened any more.

Device Assistant

Application Type and **Sercos Address** are now supported and are shown in two new columns.

The benefits of the revised version of the Device Assistant are:

- Quick read-only information of existing command **Edit parameters....**
- Double drives are displayed with literal prefix like "A:" or "B:".

Machine Expert Code Analysis - Rule Set

Three predefined rules sets (All Rules, Basic Rules and Standard Rules) have been introduced which can be selected before adding conventions or metric tables.

The benefits of the rule set are:

- Easy start up target to smooth start and focus on most relevant finding at the beginning.
- Avoid getting big list of findings when start cleaning up the project with code analysis.

Machine Expert Code Analysis - New Metric Query's for Comments

New queries are available to check the comments for code, declaration and description.

Machine Expert Code Analysis - New Convention Query

A new convention query has been introduced which allows to detect if a function block or structure is used as input parameter type (Copy-per-Value). Same is true for device representing function blocks.

Machine Expert Code Analysis - New Metric Application Size

There are three new metrics available:

- Application Size (Code)
- Application Size (Data)
- Application Size (Data+Code)

Machine Expert Code Analysis - New Convention: Persistent and Retain Usage Check

- When retain or persistent variables are used in function block declarations, the complete memory location of the function block is in the **Retain** area of the controller.
- The memory performance of **Retain** is slower than normal memory and causes performance issues executing the code in time-critical situations.

Machine Advisor Code Analysis

- It has been introduced that the convention trend can be displayed and exported.
- Rule sets and new queries are available from Machine Expert.

SQL Gateway

The SQL Gateway supports an Oracle database.

Axis Editor - Online / Offline Behavior

- Opening of the online dialog by double-clicking in the **Edit** field has been introduced.
- **Write Online** changes axis configuration online.
- **Write Offline** changes axis configuration in the project.

NOTE: The feature requires an update of the AxisUiInterface library.

Application Logger

The functions of the Application Logger have been revised and now offer the following benefits:

- The Logger Point ID can be filtered now.
- Logger entries can be colored via context menu as already known from the Diagnostics tool.
- Each entry in each column can be used as color identified.

Other Modifications

- Usability of Smart coding has been improved.
- Extensive improvements of the ST editor.
- CFC: Update of the editor.

General Improvement

- General
 - Improved scaling with high DPI monitors (as of Windows 10)
- **Applications tree**
 - Display of access modifiers (PROTECTED, PRIVATE, INTERNAL)
- Bookmarks
 - Global and persistent bookmarks (**Bookmarks** view)
- Compiler
 - Memory reduction
- Continuous Function Chart (CFC) Editor
 - Support of qualified values
 - Code generation for automatic assignment and monitoring
 - Multiple insertion of elements from **Toolbox** via Ctrl + left mouse click
 - Auto Data Flow mode (automatic execution order based on element positions and linking), adaptable in CFC POU properties
 - Command **Set Start of Feedback loops**
 - Drag and drop of variables from declaration to block inputs/outputs
 - Improved Auto routing of connections
- Controller - **Log** tab
 - Sorting of table columns
- Controller - **PLC Settings** tab
 - Enabling of CAA Device Diagnosis
- Cross Reference
 - Filtering of found symbols
 - New column **Usage context**
- Device Editors
 - New **Log** tab shows log messages related to the device
 - Expandable messages
- **Devices tree**
 - Errors of (collapsed) child devices visible on parent devices
 - Notification about errors / acknowledgement of errors via contextual menu

- Device User Management
 - Secured, encrypted transmission of user name and passwords - now only possible online
 - Export/import via password-secured file
- Fieldbus
 - Support of function block for I/O channels
- IEC Languages
 - Task local variables
 - *ABSTRACT* as new keyword
 - New data type `__VECTOR`
 - 64-bit data types: *LDATE*, *LDATE_AND_TIME*, *LTIME_OF_DAY*
- Library Manager
 - Better navigation through linked identifiers, forward and backward buttons
- Cybersecurity
 - Encrypted communication (no / optional / enforced encryption) via **Communication Settings**
 - Optional / enforced Device User Management via **Communication Settings**
 - Signing of compiler libraries
- SmartCoding
 - Switch scopes (all, keywords, global, local) with arrow left / right
 - Highlighting searched strings in results.
- ST Editor
 - Highlighting of all occurrences of the selected symbol
 - Search symbol via Ctrl+Shift+I
 - Declaring variables via SmartTag
 - Auto declaring variables via SmartTag
- Status bar
 - Offline status field for “Up To Date” application
- SVN
 - Improved performance for comparing working project with base project
- Symbol Configuration
 - Configurable set of different symbols for separate clients
- Task Configuration
 - Display of variable usage in different tasks
- Toolbar
 - Selection of active application in drop-down box
- Visualization
 - Stabilization of XY chart
 - Trace (filling curves, curls as markings)
 - Trend (graphs with fill color)
 - Rectangle (radius setting)
 - Combo box (value range, supports dynamically selected text list)
 - Frame shifting (via input configuration - switch frame visualization)
 - Trace and Trend (additional color configuration)
 - Integrated visualization shows the online WebVisualization functions
 - Configurable tab order

- Watch List
 - Monitoring of instances via interfaces or pointers
- WebVisualization
 - Overlays (dynamic movement for the elements, inner rotation)
 - Time-controlled animations (smooth moving of menus, smooth showing/hiding dialogs, animated images - GIF, SVG -, less load on controller)

New Features EcoStruxure Machine Expert - Safety

New Features

- Integration of SAFEPROG V3.7
- External compare interface for non-graphical objects (e.g. structured text, project info)
- Extended ST language features enabled (FOR, CASE, IF, EXIT, RETURN)
- Search function is available in worksheets with structured text (ST)
- Italian language support on the GUI elements and user documentation (online/offline help)
- Quality improvements on software and user documentation
- Cybersecurity improvements
- New TM5/TM7 IO FW seco component added to Schneider Electric Software Installer. Delivers now version consistent qualified safety IO slice FW also directly to customer installation. Update as described via Device Assistant tool.
- Updated TM5CSLCx00FS FW (SWC enhancement)
- Updated TM5SPS10FS FW enabling higher switching cycle frequency up to 2 Hz.
- Support of TM262M05 for functional safety
- Support of LXM62DC13E safety drive

Compatibility EcoStruxure Machine Expert

Overview

EcoStruxure Machine Expert V2.0 can be installed in parallel to EcoStruxure Machine Expert V1.1 or V1.1SP1 or V1.2.x.

EcoStruxure Machine Expert can be installed in parallel to other Schneider Electric software products, such as SoMachine and SoMachine Motion.

Compatibility of Device User Management

The user rights storage format is updated with EcoStruxure Machine Expert V2.0.

User rights included in controllers programmed with EcoStruxure Machine Expert versions earlier than V2.0 must be recreated after updating their firmware version to EcoStruxure Machine Expert V2.0.

For general information on compatibility of EcoStruxure Machine Expert, refer to the [Compatibility and Migration Guide](#).

Compatibility of Python Function `change_device_user_password`

The Python function `change_device_user_password` from `usermgt.py` was replaced by `create_live_user_management()` and `change_user_password(user, oldPassword, newPassword)` from `ScriptOnlineDevice`.

`change_device_user_password` can be used for controllers with a firmware version prior to EcoStruxure Machine Expert V2.0.

Compatibility EcoStruxure Machine Expert - Safety

Project Updates

- No incompatibility for re-use of safety projects generated with former versions.

NOTE: Updated projects from former versions opened in EcoStruxure Machine Expert - Safety V2.0 do not show project CRC. A re-compile of the project is needed once to update to new internal safety project structure. After this step the project CRC is re-calculated and will be shown now and will be the same as former project. No change of any functional safety related function by this process.

- Safety release is updated to Machine Expert V2.0.
- No re-certification needed related to new TM5CSLCx00FS and TM5SPS10FS delivered FW versions and unchanged updated projects to this version.
- However in case of updating systems with new TM5SPS10FS V332 FW the related safety function has to be tested and the updated technical characteristics in the user guide have to be considered.

NOTE: In general, after a safety system update the safety related functions have to be re-tested as usual.

Overview of the validated EcoStruxure Machine Expert - Safety version with the appropriate safety-related firmware.

Device	Safety-related firmware version for EcoStruxure Machine Expert - Safety version			
	1.1	1.2	1.2.2	2.0
TM5CSLC100FS	2.52	2.52	2.53	2.56
TM5CSLC200FS	2.52	2.52	2.53	2.56
TM5SAI4AFS	322	322	322	322
TM5SDC1FS	302	302	302	302
TM5SDI20DFS	305	305	305	305
TM5SDI2DFS	305	305	305	305
TM5SDI4DFS	305	305	305	305
TM5SDM4DTRFS	305	305	305	305
TM5SDM8TBFS	305	305	305	305
TM5SDO2DTRFS	300	300	300	300
TM5SDO2TAFS	280	280	280	280
TM5SDO2TFS	280	280	280	280
TM5SDO4TAFS	280	280	280	280
TM5SDO4TFS	280	280	280	280
TM5SDO6TBFS	295	295	295	295
TM5SPS10FS	320	320	320	332
TM5STI4ATCFS	322	322	322	322

Device	Safety-related firmware version for EcoStruxure Machine Expert - Safety version			
	1.1	1.2	1.2.2	2.0
TM7SDI8DFS	305	305	305	305
TM7SDM12DTFS	305	305	305	305

Mitigated Anomalies

EcoStruxure Machine Expert

ID	Description
OEM00074431 / CDSYS-139	Auto-Declare Using a statement like <code>ptVar := ADR(var)</code> ; where <i>ptVar</i> is declared a <i>POINTER TO INT</i> had led to an auto-declaration proposal of <i>POINTER TO INT</i> for <i>var</i> instead of <i>INT</i> .
OEM00074574 / CDSYS-141	Auto-Declare: Using a statement like <code>GVL.toto := bool_1</code> ; where <i>bool_1</i> is declared as <i>BOOL</i> and <i>GVL</i> is the name of a <i>GVL</i> caused an autodeclaration proposal of <i>INT</i> for <i>toto</i> instead of <i>BOOL</i> .
OEM00074647 / CDSYS-143	Auto-Declare: Using Auto-Declare from a POU did not offer an already existing PersistentVars as object, except if selecting in the following order: <i>PERSISTENT</i> and <i>RETAIN</i> followed by <i>VAR_GLOBAL</i> as scope.
OEM00076869 / CDSYS-197	Project Export/Import: After exporting modules, when importing, the modules were reordered alphabetically by module name.
OEM00071094 / CDSYS-72	Trace: Multi-selection of variables in the Trace Record part of the Trace Configuration dialog box was not supported.
OEM00071445 / CDSYS-76	ProfiNetIO-Controller (Master): New parameters on the General tab: I/O provider/ consumer status. Parameter Application stop > Substitute values: When the user stops the application, the provider state was set to BAD. The slaves then had set the inputs and outputs to predefined substitute values.
OEM00071929 / CDSYS-83	Online Change: Adding a library opened the Online Change dialog box, even if nothing was used out of this library.
OEM00072060 / CDSYS-84	Auto-Declare: Using a statement like <code>IF Var_0 OR Var_1 THEN</code> had triggered an auto-declaration proposal of <i>INT</i> instead of <i>BOOL</i> .
SI-3971 / DTM-68	When you converted a controller, for example, an M262L20 to an M262M35, the module configuration of the TM5/TM7 interface was not converted and was no longer available after conversion.
BOC-45 / CDSYS-1	A double-click on an error message did not open the Trace Configuration with additional information about an incorrect variable.
BOC-54 / CDSYS-376	There was a performance impact from EcoStruxure Machine Expert on LMC controller when an ALIAS was used.
BOC-67 / SI-5594	Automatic I/O mapping was not available via Python.
BOC-412 / PLAT- 612	LogRecord Dateloggung added an incorrect time stamp to each record.
BOC-423 / CDSYS-373	Online change was prohibited after minor changes with an error C0367: <i>"Internal Error 3 prohibiting Online Change! Clean Application and download necessary"</i> .
BOC-469 / SI- 6563	The multiple download did not work with DTM of ATV320.
BOC-471 / SI- 5601	The Configuration tab of TM5 CANopen bus coupler was hidden after export device.
BOC-481 / SI- 3793	In some projects, the drive parameter was changed after a project update.
BOC-485 / SI- 4549	It was not possible to add a user documentation to EcoStruxure Machine Expert.
BOC-486 / SI- 1711	It was not possible to use a test resource from a library in ETest.
BOC-500 / CDSYS-271	Replace function caused an error <i>"Value cannot be null"</i> when a visualization was used.
BOC-501 / CDSYS-246	After contacts in LD network were added the network was not displayed correctly.
BOC-502 / CDSYS-243	If the attribute <code>'to_string'</code> in an enumeration of a library was used, a compiler error was triggered on the project which used the library functionality.
BOC-503 / CDSYS-240	The percentage (%) value information of Memory area 4 for controller was incorrect in German language.
BOC-504 / CDSYS-237	When getting an error message with additional related code position information for the occurrence in the different task the positions were missing or incorrect.
BOC-505 / CDSYS-210	In some projects an <i>"Internal system error"</i> was triggered during code generation.

ID	Description
BOC-506 / CDSYS-193	A replacement of multiple items with auto-complete (IntelliSense) in some projects created an assertion.
BOC-508 / CDSYS-158	Under certain circumstances, the values of global variable list <i>Global_SWC_Variable</i> were not visible after login ("???" appeared in place of the values). If you executed a mouse-click into the variable list, the current values appeared.
BOC-509 / CDSYS-157	Hiding a graph in the visualization operated incorrectly.
BOC-511 / CDSYS-59	It was not possible to get the information about the number of selected variables in the Symbol Configuration .
BOC-522 / CDSYS-249	It was not possible to change the sort sequence of files on a flash card.
BOC-523 / CDSYS-233	Empty rungs (LD) were generated after a PLCopen XML export/import.
BOC-524 / CDSYS-167	When the IEC trace was used, a software error (<i>PageFault</i>) was triggered while reading the config file.
BOC-525 / CDSYS-133	A compiler error was triggered when multiple assignment on an output were used.
BOC-526 / SI- 6288	Default value of <i>TraceBufferSize</i> in EcoStruxure Machine Expert was too small.
BOC-527 / CDSYS-88	If the pragma <i>If defined</i> was used, EcoStruxure Machine Expert automatically modified the <i>type</i> to capital letters <i>TYPE</i> , if the cursor was leaving the line of code.
BOC-536 / CDSYS-327	Project Compare did not operate in some projects, terminating with a "Cannot compare" error.
BOC-539 / CDSYS-273	When modifications were reverted in an SVN project, the project was synchronized with SVN and a notification was displayed: <i>"An inconsistency or unexpected error was detected and automatically repaired. Please check your project. If this problem is repeatable, please contact the support department with the steps to repeat."</i>
BOC-541 / CDSYS-245	The FBD output connection had an incorrect color.
BOC-543 / CDSYS-224	A trace parameter of type <i>AS</i> created an error "CycleTime overrun".
BOC-544 / CDSYS-155 / OEM00075351	You log in to a project (FBD code) and put the focus on a network (which is not the last one) in an action/program. If you log out and log in again, the focus will be on the last network in the action/program. The same behavior is shown up, if you switch between actions.
BOC-547 / CDSYS-134 / OEM00073945	Accessing a variable name of the TM5 module, I/O mapping was not possible with Python scripting using an <i>ARRAY</i> .
BOC-548 / CDSYS-124	Find and replace: Regular expression was operating correctly for find, but if you try to replace a string the control characters (e.g. \t for tab) were not filtered, means the control character is part of the replacing string after replacing.
BOC-549 / CDSYS-120	A reset of the flag "Connect boxes with straight lines" in Tools > Options > FBD . EcoStruxure Machine Expert created junctions in the signal path.
BOC-550 / CDSYS-66 / OEM00069953	To display different comments for libraries you can enter the key <i>LibDocContent</i> . Using <i>LibDocContent</i> with <i>DocsOnly</i> of <i>CommentsAndDocs</i> , the same results were displayed.
BOC-551 / CDSYS-238	A rising edge contact was not working in parallel branch in LD.
BOC-552 / CDSYS-189	If a copy and paste of a part of a CFC code was executed and the copied part is near the position of the original part. Every further copy and paste attempt was result in a copied code far away from the position of the original code.
BOC-558 / M2X1- 183 / OEM00078429	Relocation Table : The Length of <i>ARRAY</i> variables containing structures with elements of type <i>DATE</i> , <i>TIME</i> , <i>DATE_AND_TIME</i> is now correctly displayed.
BOC-562 / CDSYS-270	Library Manager : No namespace of inherited function blocks was shown.
BOC-570 / CDSYS-81	The EtherNet/IP communication was not working, if the adapter connection was configured to predefined connection (EDS file).
BOC-581 / CDSYS-360	Direct call of the <i>PLC_R</i> (for example <i>_dwSerialNumber</i> etc.) variable(s) under the Vijeo Designer numeric display, caused a controller error.
BOC-636 / SI- 5609	It was not possible to stop the application before an application download.
BOC-645 / CDSYS-390	Bitmap was not displayed for all POUs in FBD.
BOC-659 / SI-5598	VisualizationManager: The Visual Style Editor was not operational.

ID	Description
BOC-666 / CDSYS-405	SVN compare function needed a lot of time in large projects.
BOC-673 / CDSYS-396	There was a precompiling error with the RTC Control example project regarding <i>iq_dwDate Time</i> .
BOC-685 / CDSYS-401	The state (TRUE/FALSE) of an input variable of a method was not monitored in Online view, if the variable was an element of an ARRAY and negated.
BOC-686 / SI- 5871	An error message was triggered when persistent variables were reset from EcoStruxure Machine Expert.
BOC-688 / CDSYS-400	An SVN update was possible while the application was online (project online).
BOC-713 / SI- 5676	There was no pop-up when and why a license was not accepted.
BOC-721 / CDSYS-426	It was not possible to precisely select the location of a comment in Chinese character with the mouse or keyboard in ST editor.
BOC-722 / CDSYS-425	The cursor position in LD function block was lost when you changed tabs.
BOC-731 / CDSYS-427	The <i>GetDayOfWeek</i> function from <i>CAA_DTUtil</i> library sent an incorrect return value on Saturday 2/29/2020 (Leap Year).
BOC-747 / SI-5746	There was no setting to prefer the Online help offline.
BOC-769 / IAT-78	Online Help: The modified installation path created unnecessary folders.
BOC-812 / CDSYS-442	Open an expression structure (e.g. <i>raifBelt-Array</i>) of the <i>SmartInfeed</i> closes automatically while scrolling (with scroll bar and/or mouse wheel), at some Arrays (e.g. <i>raifTargets-Array</i>) it was not possible to open the array because it closed immediately after opening.
BOC-813 / CDSYS-443	Refactoring, for example a function name "local", in the active editor the name was not changed in the project (e.g. Device tree).
BOC-846 / PLAT- 942	When using the BIT data type, the analysis of the relocation table was not able to calculate the size of the related structure variables.
BOC-850 / CDSYS-459	An external file in EcoStruxure Machine Expert that was only inserted as a link was not opened correctly. Instead of the original file, only a temporary one was opened that could not be edited.
BOC-861 / SI- 5984	<i>ApplicationLogger</i> : The text size of the <i>ApplicationLogger</i> filter was not sufficient to read the complete text.
BOC-866 / CDSYS-464	The precompile error for the attribute 'strict' (ENUM) was misleading.
BOC-870 / CDSYS-465	The precompile function has returned incorrect precompile error messages which was misleading.
BOC-874 / CDSYS-462	The I/O mapping as a result of the importation of some EtherNet/IP EDS files was incorrect if the length of a member in the Assembly Member List was different from the length of the parameter used.
BOC-878 / CDSYS-466	When you had loaded a trace data recorded with a runtime buffer size > 10001, only the last "part" of the full trace was visible.
BOC-879 / CDSYS-463	An ENUM with the attribute 'strict' in VAR_IN_OUT did not cause a compile error.
BOC-892 / CDSYS-467	Diagonal visualization element had moved unintentionally.
BOC-895 / CDSYS-468	After an import from code of an XML file (Import PLCopenXML), the code was modified (<i>Out1</i> added to several functions).
BOC-909 / CDSYS-486	The visualization had shown randomly one or more black squares on the screen after using the numpad window.
BOC-947 / CDSYS-388	The Trace stopped recording after 1h 11min.
BOC-949	It was not possible to precisely select the location of a variable in Chinese character with the mouse or keyboard in ST editor.
BOC-971 / SI- 6376	Smpb file is proposed as supported file, but when opening such a file an error occurred.
BOC-980 / CDSYS-529	Generate code leads no longer to an AssertionFailed exception in some projects using function blocks which use arrays with a variable size.
BOC-992 / CDSYS-527	Array online monitoring range works properly and allows more than 1000 REFERENCE TO ARRAY elements for online monitoring.
BOC-999 / CDSYS-532	Global search for cross reference is now possible.
BOC-1000 / SI- 6472	The communication parameters of a Profinet device are now displayed correct in the PDI file.

ID	Description
BOC-1002 / SI- 6473	Converted a PacDrive LMC Pro to a PacDrive LMC Eco project, the PLC Settings are no longer changed unintentionally.
BOC-1003 / SI- 6474	Now messages are shown about changed library version after converting a controller.
BOC-1004 / SI- 6475	The activation of a parameterized <i>TestCase</i> had led to compile errors, if the handover of the test parameters in an array was realized as follows: [2 (0), 5, 6].
BOC-1017 / SI- 6542	Device addressing in the popup menu points now to the correct PacDrive controller.
BOC-1022 / SI-6574	Opening a large project on SVN was time-consuming.
BOC-1046 / M2X1-142	The M241 controller was missing in the TM3HSC library version mapping list.
BOC-1068 / CDSYS-564	A user structure which "extends" from <i>PDL.ST_Vector3D</i> created the compiler error "Keyword EXTENDS not applicable to type <i>PDL.ST_Vector3D</i> ".
BOC-1072 / CDSYS-552	Smart coding did not work on alias from a library of type ARRAY OF STRUCTURE.
BOC-1086 / SI- 5669	The functionality of Add function from Template did not transfer the IP address used in the template to the device.
BOC-1089	The PreCompiler created an error if a project with M262M controller was used where the <code>ARRAY OF PLCO.MC_CAM_ID</code> was used in the code.
BOC-1100 / CDS-64615	In an application with two function blocks <i>FB_1</i> and <i>FB_2</i> where <i>FB_1</i> has two methods that it provides to <i>FB_2</i> . A call of <i>FB_2</i> generated the advisory message <i>C0298 "Calculation of stack usage incomplete because of recursive calls:</i> <code>SR_Main () -> FB_2 () -> FB_1.METH_1 () -> FB_1.METH_2 () -> FB_1.METH_2 ()</code> <i>".</i>
BOC-1103 / PLAT-1278	The Download App macro contains now the command to download the WebVisualization files.
BOC-1109 / SI- 4922	Activation of Code Analysis trial is now successful.
BOC-1112 / CDSYS-518	It was not possible to verify the state / modifications of <i>UserRightsManagement</i> via IEC (monitoring of a parameter).
BOC-1164	The refactoring of a global constant did not work correctly when the global constant was used for the declaration of an array in a structure.
BOC-1174 / SI- 8901	Save parameters of all devices has generated an error message, when a ProfNet device was used.
BOC-1177 / SI- 8952	Library namespace was not shown in the CAM Editor.
BOC-1207 / M2x1-512	OPC UA: Not all M241/M251 variables inside an array were visible for an OPC UA client.
BOC-1218 / CDSYS-717	Library installation was unsuccessful while antivirus software was running.
BOC-1272 / CDSYS-564	Using a Vector3D resulted in detected precompiler errors, redmarking from smart coding.
CVE-2020-12525	Specific cybersecurity vulnerabilities are mitigated.
CVE-2019-13538	Specific cybersecurity vulnerabilities are mitigated.
CVE-2019-9008	Specific cybersecurity vulnerabilities are mitigated.
CVE-2019-7052	Specific cybersecurity vulnerabilities are mitigated.

EcoStruxure Machine Expert - Safety

ID	Description
SSP50-6783 / OEM00060343	In the SafeLogger you can read that the status of an input/output of a safety-related module has changed. More detailed information on the reason can be now decoded out of the additional info0 and info1 information. (Refer to the SafeLogger User Guide for details).
SSP50-6800 / OEM00068735	If you set the <i>MaxDataTransportTime</i> and <i>CommunicationWatchdog</i> parameters to significantly greater values than proposed by the calculator (for example, 6500 ms), this can result in an unstable system because these parameters influence the timeouts and restart timing of the safety-related system. In this case, the ModuleOK status for some safety-related modules is not reached or is unstable. Workaround: Use the values calculated by the Response Time Calculator or do not increase the parameters by more than factor two.
SSP50-6805 / OEM00068980	If you set the value for <i>MinDataTransportTime</i> to a value less than the value calculated by the Response Time Calculator, a build error message may be displayed. Workaround: The <i>MinDataTransportTime</i> must be set to the calculated value.
OEM00052480	An error was detected if a special character (e.g., German umlauts) was entered as part of the naming of a variable (in ST) in EcoStruxure Machine Expert - Safety. It was not possible to ignore or cancel this exception. Workaround: Special character compatibility is improved. However, it is best if you do not use special characters in variable names.
SSP50-4523 / SSP50-6890 / OEM00078271	The TM5SPS10FS module did not differentiate if the user parameter <i>centralcontrol</i> was set to Central or Direct.

Schneider Electric Software Installer

ID	Description
SI-5642	It is now possible to add an HMI to the project after deinstallation of a legacy version.
SI-6757	The device cache was corrupted after installation of "LogicBuilder softmotion" while the Logic Builder was open.

Documentation

ID	Description
BOC-314 / SI- 5435	The attribute 'to_string' was missing in Online help.
BOC-426 / SI- 5425	The Online help for <i>RecipeManCommands</i> did not include the data types of the method parameters.
BOC-460 / SI- 5446	There was no explanation on how to select a general export/import or a fast export/import.

Known Operational Anomalies

Controller Assistant

ID	Description
SI-11876	If Controller Assistant is executed via command line, the commands <code>-savecontrol</code> and <code>-loadcontrol</code> require additional switches to read / write the device user rights management. Without the commands, the operation is unsuccessful and the message "Cannot save device user rights to current image without a password." or "Cannot import device user rights from current image without a password." is displayed. Workaround: - For <code>-savecontrol</code> use: <pre>ReadOnlineUserRightsManagement<Ignore Read> [-UserRightsManagementPassword<Password>]</pre> - For <code>-loadcontrol</code> use: <pre>WriteOnlineUserRightsManagement<Keep Overwrite Restore> [-UserRightsManagementPassword<Password>]</pre> The <code>UserRightsManagementPassword</code> is only required for the options read and overwrite.

EcoStruxure Machine Expert

ID	Description
BOC-34 / SI-5600	Link to DHCP server configuration does not work for Modbus TCP.
BOC-376 / MS- 2018	The combination of SH3055 motors with GBX080 gearboxes is shown, even though such a combination is not allowed by the technical data sheet of GBX gearboxes.
BOC-468 / CDSYS-291	No compiler error is displayed for duplicate IO mapping.
BOC-470 / CDSYS-290	An error message due to direct addressing indicates incorrect spot.
BOC-513 / CDSYS-54	In the CAM editor the tappet values can be modified in the table. Using this method the value is limited to the <i>SlaveEndPosition</i> which is incorrect.
BOC-545 / CDSYS-152	If variables from a library are declared inside the global variable list, errors can occur while compiling the project.
BOC-554 / CDSYS-31	GIPLC1.1.0.0 order of variables declaration in function blocks is incorrect.
BOC-605 / MS-1960	No negative parameter is possible for Crank.
BOC-617 / MS-1946	Not possible to select minimal supply voltage for ILM.
BOC-619 / MS-1969	Motion Sizer: On a crank mechanic, the position curve is incorrect and also the label of the curve is incorrect.
BOC-620 / MS-1942	Motion Sizer: SH3 140 motors are missing in the motor database.
BOC-783 / MS-2062	Motion Sizer mains result not displayed due to load diagram and the cycle times set to an integer value.
BOC-794 / MS-2065	In some Motion Sizer projects there is an unexpected peak acceleration limitation in the results which does not match the motion profile.
BOC-847 / CDSYS-458	Missing documentation of CloseDialog2.
BOC-932 / CDSYS-500	The use of an AT declaration for a 32 bit variable (e.g. DWORD) inside a Struct, leads to an error from the equal check.
BOC-1061 / CDSYS-557	Replace all function only renames the first object found in the selection of an CFC (Continuous Function Chart).
BOC-1163 / CDSYS-563	Members of Structures extending Alias of Structure are not displayed in the Input Assistant .
BOC-1172 / IAT-97	SESU shows EcoStruxure Machine Expert V1.2.4.0 update even though EcoStruxure Machine Expert V1.2.5.0 is installed already.
BOC-1207 / M2X1-512	OPC UA issue on M241/M251: variables inside arrays are not all seen by an OPC UA client.
BOC-1238	The I/O mapping of some EDS files is incorrect in PacDrive projects.
BOC-1239	The compiler does not display the exception <i>C0224 Call Recursion: SR_Recursive -> SR_Recursive</i> if the program (which has the exception) is called inside the SFC-POU.
BOC-1285 / CDSYS-775	SFC action with qualifier <i>N</i> is not executed correctly.
BOC-1307 / CDSYS-800	The time base of Trace is set to hours if resolution μ s is selected.
CDSYS-765 / SI-9968	After updating a project created with EcoStruxure Machine Expert V1.1 (or SoMachine V4.3) compiler messages may be displayed regarding the library <i>IoDrvModbusSerial</i> that is required by the devices ZBRN2 Harmony XB4R/5R (on Modbus Serial IO Scanner) or ZBRN1 (on Industrial Ethernet Manager). Workaround: Delete the Modbus Serial IO Scanner and/or the ZBRN1 device from your application and restore them afterwards.

EcoStruxure Machine Expert - Safety

ID	Description
SSP50-9033	After a deinstallation of EcoStruxure Machine Expert V2.0 from a machine which had a parallel installation of EcoStruxure Machine Expert V1.2.x, the safety project import/export function of the remaining EcoStruxure Machine Expert V1.2.x installation is no longer available. Workarounds: - Execute the repair function of the Schneider Electric Software Installer on the EcoStruxure Machine Expert V1.2.x. - Or - Desinstall and reinstall the safety component for the V1.2.x version in the component view of the Schneider Electric Software Installer.

Schneider Electric Software Installer

ID	Description
SI-3860	If a Windows update is started during installation, a restart dialog box is displayed while the Harmony (DTM) is being installed.
SI-6370	Library documentation is missing in the Library Manager after deinstallation of a legacy version.

Additional Ethernet Port for PacDrive LMC Control

Overview

The additional Ethernet port provides the possibility to have an additional standard Ethernet interface on board for the following controllers:

- PacDrive LMC Pro/Pro2
- PacDrive LMC Eco (option module)

Ethernet Interface

The new Ethernet object provides for TCP/UDP communication.

- To establish a connection via the additional port with the Logic Builder in combination with the connection mode **Fast TCP**, enter the IP address of the additional port.
- To establish a connection via the additional port with the Logic Builder in combination with the connection mode **Nodename** (or **IP Address**), use the IP address of the default port.
- To establish a connection via the additional port with Vijeo-Designer in combination with the connection mode **Nodename**, use the node name of the default port but ensure that the IP addresses of the network cards of the PC and the HMIs are configured in accordance with the additional network.

Parameters

Overview

The **Ethernet** object uses the **UserFunctions** node of the EcoStruxure Machine Expert Logic Builder to implement the parameters.

- **Common** parameters, that are also provided by other user functions:
 - *LogAdr*
 - *ObjectType*
 - *stLogicalAddress*

- Specific parameters for **UserFunctions**:

- *Enable*, page 167
- *State*, page 167
- *IP Address*, page 168
- *Subnetmask*, page 168
- *NetX_Connector*, page 169
- *Valid*, page 169

Enable

General

Type	EF
Address	16#000B
Offline editable	Yes
Devices supporting the parameter	Ethernet
Traceable	Yes
Default value	on / 1

Functional Description

The parameter *Enable* determines the moment when the Ethernet object is activated.

- If the parameter *Enable* is set to *off / 0*, then the Ethernet object is not activated at the start of the controller.

The Ethernet object can later be activated by switching the value to *on / 1*.

- If the parameter *Enable* is set to *on / 1* at the start of the controller, then the Ethernet object is activated at the start of the controller.

The Ethernet object cannot be deactivated later. When setting from *on / 1* to *off / 0*, the value stays at *on / 1* and the diagnostic message 8740 *Device cannot be disabled* is added to the message logger.

- The parameter defines the moment, when the Ethernet firmware is loaded.

When the interface was activated, it cannot be deactivated because the Ethernet firmware cannot be unloaded.

Value	Data type	Meaning
off / 0	BOOL	Ethernet object is not activated at the start of the controller.
on / 1	BOOL	Ethernet object is activated at the start of the controller. When switching from <i>off / 0</i> to <i>on / 1</i> the Ethernet object is activated.

State

General

Type	AF
Address	16#000C
Offline editable	No
Devices supporting the parameter	Ethernet
Traceable	Yes
Default value	off / 0

Functional Description

The parameter indicates the status of the Ethernet object, and when the Ethernet object can be used for Ethernet communication.

Value	Data type	Meaning
off / 0	DINT	Ethernet object is not active. Ethernet firmware is not loaded.
loading / 1	DINT	Ethernet firmware is loading.
down / 2	DINT	Ethernet firmware is loaded. The Ethernet interface is down and cannot be used for Ethernet communication.
running / 3	DINT	Ethernet object is activated. Ethernet firmware is loaded. Ethernet interface is running and can be used for Ethernet communication.

IP Address

General

Type	EF
Address	16#000D
Offline editable	Yes
Devices supporting the parameter	Ethernet
Traceable	No
Default value	'192.168.1.100'

Functional Description

Defines the IP address of the additional standard Ethernet interface.

The parameter is checked for:

- Proper format [a1].[a2].[a3].[a4].
- The first position [a1] > 0 and ≠ 127 (127.x.x.x would be the local host)
- Overlapping with other network interfaces (standard Ethernet, Sercos UCC).
When overlapping is detected, the diagnostic message *8967 NRT IP parameter device different* is added to the message logger.

Value	Data type	Meaning
'192.168.1.100' (default)	STRING(15)	IP address of the additional standard Ethernet interface.

Subnetmask

General

Type	EF
Address	16#000E
Offline editable	Yes
Devices supporting the parameter	Ethernet

Traceable	No
Default value	'255.255.255.0'

Functional Description

The parameter defines the subnet mask of the additional standard Ethernet interface.

The parameter is checked for:

- Proper format [a1].[a2].[a3].[a4].
- The subnet mask consists of two parts from a binary point of view: [t1][t2], with [t1] consisting of binary 1 s and [t2] of binary 0 s (for example, 255.255.245.0 is not permitted since the third digit (245) is 1111 0101 in binary code, which means that the first 0 on the left is followed by more 1 s).
- The entered value is not 255.255.255.255.
- Overlapping with other network interfaces (standard Ethernet, Sercos UCC). When overlapping is detected, the diagnostic message 8967 *NRT IP parameter device different* is added to the message logger.

Value	Data type	Meaning
'255.255.255.0' (default)	STRING(15)	Subnet mask of the additional standard Ethernet interface.

NetX_Connector

General

Type	EF
Address	16#000F
Offline editable	Yes
Devices supporting the parameter	Ethernet
Traceable	Yes
Default value	Front / 1

Functional Description

The parameter *NetX_Connector* is set and can be set only to the value *Front / 1*.

Value	Data type	Meaning
Front / 1	DINT	Ethernet interface activated at connectors CN10 and CN11.

Valid

General

Type	EF
Address	16#00010
Offline editable	No
Devices supporting the parameter	Ethernet
Traceable	Yes
Default value	no / 1

Functional Description

The parameter allows to verify if the user function is activated. This is used for dynamic machine configuration.

At the Ethernet object the value is TRUE, because when the Ethernet object is added, the user function is always activated.

Value	Data type	Meaning
yes / 1	BOOL	User function is activated.

Sercos Improvements (Sercos Robustness) for PacDrive LMC Control

Overview

Sercos Robustness provides the possibility to keep the Sercos network operable even if a non-critical device is in an inoperable state or removed.

Sercos system reaction:

- Same default system behavior of the Sercos bus. A device error causes the Sercos bus to shut down and the Sercos master state change to error.
- The new system reaction of the Sercos master allows to continue operation in phase 4 even if a device goes in the Fail state (for example, broken device). The drives run in a virtual mode.
- Safety-related application allows to use the new system reaction.

Configuration of feature:

- Configuration on device level.
- Configuration is activated during Sercos phase up.

Supported Devices

The following devices support Sercos robustness:

- LXM62
- LXM62 PS
- LXM62ILM
- LXM52
- TM5NS31
- Sercos drives (third party drive)
- Sercos IO devices (third party IO devices)

Configuring Sercos Robustness System Reaction


The Sercos robustness function allows you to configure new system reaction using the application for each supported device:

- Activation via new user function **Sercos Robustness**. Refer to *Activating the Sercos Robustness Function*, page 171.
- New device parameter *ConfiguredSystemReaction* to set the system reaction *default* or *system reaction 1* (refer to *IEC Interfaces — Parameter Definition*, page 171).
- New device parameter *SystemReaction* displays the system reaction from the device.

- New device working state *error* – for example, inoperable devices switch into error state.
- New icon update when device is in an error situation.
- The parameters can be accessed via IEC application.

Activating the Sercos Robustness Function

To activate the **Sercos Robustness** and its new **UserFunctions**, click the tab **Feature Configuration** of your device. Then select **Enable Feature Configuration** and **Sercos Robustness**.



IEC Interfaces — Parameter Definition

Overview

Sercos robustness provides features for improved tolerance: *Sercos Master Object* and *Sercos Device Object*.

Sercos Master Object

- New global parameter to indicate the level of error behavior within the machine application.
- The parameter definition allows a quick overview in the diagnosis file:
 - *SystemReaction*: Enumeration
 - *Standard/Default* – 0;
 - *systemReaction1* – 1;

Sercos Device Object

New *WorkingState* of Sercos slaves.

- *real*, *virtual*, *deactivated*, *Error* (optional).
 - Sercos robustness:
 - If a device has a detected Sercos error and *SystemReaction* is set to *systemReaction1*, the *WorkingState* is transitioned to *Error*.
 - Changing the state of the device is handled within the real time process.
 - The device object icon changes from green to orange.

New parameters to select the Sercos system reaction, provided by the new user function Sercos robustness:

- *ConfiguredSystemReaction*: Enumeration
 - *Standard/Default* – 0;
 - *systemReaction1* – 1;

The value of this parameter is written to parameter *SystemReaction* in CP=0.

- *SystemReaction*: Enumeration
 - *Standard/Default* – 0;
 - *systemReaction1* – 1;

- *Valid*: Enumeration
 - *no* – 0;
 - *yes* – 1;

EcoStruxure Machine Expert V2.0.0.1

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M262	5.1.5.33

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

Mitigated Anomalies

ID	Description
PEP0651352R PEP0644016R	TCP Server and Client connections, disconnections led to a memory leak which could result into a crash with empty crash.txt file.
PEP0652453R	With Modicon M262 Motion Controllers, after several online changes, some crashes could occur.

Known Operational Anomalies

There are no additional known anomalies with this release.

Library Information

There is no additional library information for this release.

Software Information

There is no additional software information for this release.

EcoStruxure Machine Expert V2.0.1

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M241	5.1.9.21
M251	5.1.9.21

Description	Firmware Version
M262	5.1.5.35
TM5NEIP1/TM5NEIP1K	3.12
TM5NS31	2.79
TM5CSLC100FS	2.57
TM5CSLC200FS	2.57
LXM62....C.....	1.64.11.0 for hardware revision RS1•
LXM62....D.....	1.64.11.0 for hardware revision RS1•
LXM62....G.....	1.64.11.0
LMC Eco	1.66.5.1
LMC Pro	1.66.5.1
LMC Pro2	1.66.5.1

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

New Features

TM5CSLC•00FS/TM5NS31/TM5NEIP1/TM5NEIP1K

Cybersecurity improvements

Modicon M241/M251 Logic Controllers

- Possibility to disable the battery LED on the M241/M251 Logic Controllers.
- Extension of the SysSocket library to support the *SysSockPing* method.

Mitigated Anomalies

PacDrive LMC Controls & I/Os

ID	Description
CVE-2020-28895	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-35198	Specific cybersecurity vulnerabilities are mitigated.
CVE-2021-33485	Specific cybersecurity vulnerabilities are mitigated.
LMCFW-2016	A Cam switch task sporadically triggered the diagnostic message <i>8317 Cycle Time overrun</i> .
LMCFW-2877	LMC Pro 2 and LMC Eco were not starting up when a USB key was not formatted with FAT and connected.
LMCFW-2878	No communication error was displayed when the Profinet device was disconnected.
LMCFW-3869	The function block <i>FB_RobotP/S/TSeries</i> triggered the hardware watchdog in combination with C2C.
LMCFW-4261	The description of the runtime diagnostic message was not available.
LMCFW-4490	Output signals were not transmitted in time in a Profinet network.
LMCFW-4587	The <i>CamSwitchGroup</i> was not running with <i>Priority</i> and <i>Interval</i> configured.
LMCFW-4715	The message <i>Could not finish the configuration 16#C0CB006C</i> was displayed when many devices were connected.
LMCFW-4738	A missing CANbus device led to runtime errors that were not documented.
LMCFW-4777	The TM5NEIP1 module did not recover after it had lost communication.
LMCFW-4790	Simultaneous configuration and operation of the network protocols Profinet and Profibus was not possible when using the onboard interfaces.
LMCFW-4862	The <i>GetVersion()</i> function led to compile errors in combination with fieldbuses.
LMCFW-5029	The communication was interrupted without message when an endless loop was detected.
LMCFW-5164	The LMC controller permanently reported the diagnostic message <i>8710</i> .

TM5CSLC•00FS/TM5NS31/TM5NEIP1/TM5NEIP1K

ID	Description
CVE-2020-13987	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-17438	Specific cybersecurity vulnerabilities are mitigated.

M241/M251

ID	Description
M2X1-108	Modbus TCP data was not handled properly if had been mapped to an existing array.
M2X1-619	The <i>SetCurrentTaskCycle</i> function was not available and returned error 1.
M2X1-695	An unresolved reference was detected after download when using the Scanner Diagnostic library.
OEM00077573	An error message was displayed for the TM4PDPS1 library (Profibus) after opening a project archive generated with SoMachine V4.3.
PEP0560915R	It was not possible to join a multicast group using the TcpUdpCommunication library.
PEP0588930R	In the WebDataConfiguration editor of the Web server string variable types were limited to four characters.
PEP0596141R	The memory alignment in structures of the OPC UA Server Symbol Configuration was not correct.
PEP0621711R	The Modbus IOScanner Serial Line did not operate properly when set to ZERO.
PEP0643902R	The function block <i>MC_STOP_PTO</i> remained in <i>Busy</i> state.
PEP0646885R	The application call stack was not available.

M262

ID	Description
PEP0621713R	The Modbus IOScanner Serial Line did not operate properly when set to ZERO.
PEP0657534R	Modbus RTU: A timeout error is detected when the slave address is ≥ 128 for M262 Logic/Motion Controllers.

Known Operational Anomalies

PacDrive LMC Controls & I/Os

ID	Description
BTE-1091	Disabling the TM5NEIP1 module can lead to an unresponsive application. Workaround: Use the option Exclude from build instead of disabling.
BTE-1135	The LMC controller is not starting up when a TM5NEIP1 module is configured in the Devices tree but a physical device is not available.
BTE-1137	The status of the TM5NEIP1 SPS3 module can diverge between hardware and software.
LMCFW-4737	Delays can occur in ARTI3 communications.
LMCFW-5104	The Profinet startup is not completed when the data exchange exceeds the limit (5760 Bytes) and the message <i>16#C0CB0015 configuration of device failed</i> is displayed. Workaround: Use a second Profinet Controller via Ethernet Optional Module.
LMCFW-5244	A third-party client may not read elements of an array from an OPC UA Server.
LMCFW-5243	The Profibus configuration is sporadically unresponsive after executing a Reset warm command.
LMCFW-5477	Depending on the project the <i>AvailableLoad</i> may be impacted when device diagnostics is activated. Workaround: Set the Connection Mode to IP Address (Fast TCP) .
LMCFW-5571	The Profibus IO data exchange is incorrect.

Lexium 52

ID	Description
SERVOD-545 / PEP0628842R	When Lexium 52 is operated with V01.54.26.00 or earlier firmware versions, the power stage can be damaged when the diagnosis message <i>8107 Overcurrent</i> is triggered and is subsequently removed from the motor. NOTICE INOPERABLE EQUIPMENT - Adjust the motor peak current in the motor type plate at least to the locked rotor current provided by the manufacturer of the motor. - Ensure that the peak current of the drive supports at least this current. Failure to follow these instructions can result in equipment damage. When this is not possible, ensure that motion profiles are applied that use accelerations and decelerations that can be physically reached by the motor and the coupled mechanic. You can set the limit using the parameter <i>UserMaxAcc</i>. When motion profiles are used that work independently from the parameter <i>MaxAcc</i>, ensure that the physical limits are not exceeded.

TM5CSLC•00FS

ID	Description
SSP50-9638	The parameter <i>ApplicationType</i> of TM5CSLC•00FS is set to the default value <i>Modular Safety Device</i> after downloading a modified safety-related application. Workaround: If the <i>IdentificationMode</i> = <i>ApplicationType</i> is intended to be used for TM5CSLC•00FS devices the parameter <i>ApplicationType</i> must be re-written by the IEC application function or using the Device Assistant tool one time to the expected <i>ConfiguredApplicationType</i> to allow proper Sercos start up.

M241/M251

ID	Description
PEP0639064R	Incorrect handling of OPC UA Discovery URL.

Library Information

Version Identification

Description	Version
CertificateHandling	1.0.4.0
CollisionDetection	1.0.0.0
CommonToolbox	1.0.3.0
Communication Functions	1.3.2.0
EtherNetIP Explicit Messaging	1.1.11.0
FileFormatUtility	1.5.8.0
GeoMath	1.0.0.0
GMC Independent Base Deice	1.4.13.0
GMC Independent CANopen	1.2.6.0
GMC Independent EtherNetIp	1.4.5.0
GMC Independent Interface	1.3.9.0
GMC Independent Lexium	1.2.7.0
GMC Independent ModbusTCP	1.3.3.0
GMC Independent PLCopen MC	1.3.5.0
Lexium 28	1.6.2.0
ModbusHandling	1.0.7.0
MotionInterface	2.0.108.9458
OpcUaHandling	2.0.14.0
PD_ETest	1.5.1.0
PD_SoMotionGenerator	1.7.7.0
PLCopen MC part 1	2.0.108.9458
Robotic	3.2.0.0
RoboticModule	2.13.0.0
RoboticsAutoTune	2.0.0.0
SchneiderElectricRobotics	2.11.0.0
SchneiderElectricRobotics Parameters	2.14.0.0
SchneiderElectricRobotics Toolbox	1.5.0.0
SercosCommunication	1.2.1.0
SercosDriveUtility	1.2.1.0
SercosMaster	2.0.108.9458
SlcRemoteController	1.3.9.0
SMT_ESME_Axis	2.0.0.0
SMT_ESME_Camera	2.1.3.0
SMT_ESME_Conveyor	2.1.2.0
SMT_ESME_Robot_P-Series	2.2.0.0
SMT_ESME_Robot_S-Series	2.2.0.0
SMT_ESME_Robot_T-Series	2.1.1.0
SMT_ESME_Sensor	1.0.0.0
TcpUdpCommunication	2.2.8.0
XpsuSupport	1.0.5.0

New Features

CertificateHandling

This new library allows to create a customized self-signed certificate on the controller which can be used for the TCP communication function blocks. The new function blocks are available to create a CSR (Certificate Signing Request) and to install a certificate.

CollisionDetection

This new library offers a set of functions to perform a collision check between two or more objects and a distance calculation between two or more objects.

CommonToolbox

The attribute "`{attribute 'monitoring' := 'variable'}`" has been added to the properties of *FB_RunTimeMeasurements*.

EtherNetIP Explicit Messaging

Two new function blocks have been added to stop and start the connections of a device:

- *EIPStopDevice*
- *EIPStartDevice*

GeoMath

This new library offers a set of functions to deal with geometric and mathematical problems. It contains functions to manipulate vectors, matrices and Cartesian poses.

GMC Independent CANopen

Lexium MDrive CANopen has been implemented for GMC Independent libraries.

GMC Independent Lexium

The new function block *SpeedControl_ILX* and a dedicated visualization supporting Speed Control mode have been added.

GMC Independent ModbusTCP

Modbus FC6 (`SINGLE_WRITE`) is used instead of FC16 (`WRITE_VAR`) to communicate with ATVs.

OpcUaHandling

The requirements for certification have been fulfilled by implementing the substring feature.

SercosCommunication

- The new function block *FC_IdnStringToDword* has been added.
- New function blocks are available for reading and writing IDNs (IDentification Number) on the Sercos controller platforms (LMC and M262).

SercosDriveUtility

The function blocks of this library can also be used on M262 controllers.

TcpUdpCommunication

- The function to verify a Fully Qualified HostName (FQHN) has been implemented.
- A new function block *FB_Ping* to send a ping request to a communication partner has been implemented.
- The socket type STARTTLS for TCP client connection is supported.
- The default certificates for the TCP server and the TCP client out of the TcpUdpCommunication library are now created automatically if required and no other certificates are specified at the method inputs. The names of the certificates are *"*Controller reference* TCP server application"* and *"*Controller reference* TCP client application"*. The libraries deriving from the TcpUdpCommunication, such as EMailHandling, HttpHandling, MqttHandling, inherit this feature.

New Function Template

The template library *Communication Functions* provides the new template *PingClient*. This template provides a ready-to-use coding template for the *FB_Ping* of the TcpUdpCommunication library.

New Smart Template

The new smart template *SMT_ESME_Sensor* has been implemented.

Mitigated Anomalies

ID	Description
BOC-1312 / IECLIB-3890	Lexium 28: A new communication check (depending on the device settings for nodeguarding and/or heartbeat) has been implemented.
BOC-1407 / IECLIB-17091	GMC libraries: Moving away from <i>normally closed</i> limit switches for ILX1 drives is now possible.
BOC-1464 / IECLIB-17715	CommonToolbox Library Guide: For <i>FB_HeatingControl</i> the variables of the structure <i>ST_PID</i> have been corrected to <i>seconds</i> .
BOC-1475 / IECLIB-17740	Sercos Device Modules: The parameter <i>g_etSetDirection</i> is assigned to <i>fbMoveVelo.Direction</i> .
BOC-1501 / IECLIB-17781	Sercos Device Modules: The parameters at function call <i>SetAxisTypeLinearWithLimits</i> are assigned in correct order.
BOC-1594 / IECLIB-19848	OpCuaHandling Library Guide: The compatibility list has been updated.
IECLIB-3900	XpsuSupport: The comment on the input <i>i_xEnable</i> of <i>FB_XpsuMain</i> was improved.
IECLIB-16899	SlcRemoteController: Execute detection was improved for function blocks to allow to retrigger the function block directly after the <i>Done</i> output was set.
IECLIB-17095	FileFormatUtility: When the execution of method <i>Select</i> was not successful, the already selected item remained selected.
IECLIB-17702	ModbusHandling: The <i>FB_ModbusTcpServer</i> accepted requests addressed to unit IDs 0 to 255.
IECLIB-17717	TcpUdpCommunication: A timeout has been added to the <i>UpgradeToTls</i> method.
IECLIB-18871	ModbusHandling: The <i>FB_ModbusTcpServer</i> accepted requests with transaction ID = 0.

Known Operational Anomalies

ID	Description
BOC-1258 / IECLIB-3644	PD_MultiBelt: If the filter parameter <i>IrLockOutTime</i> is configured, the <i>TouchProbe</i> filter may detect signals which are shorter than configured by the parameter <i>IrMinProductTime</i> .
BOC-1372 / IECLIB-16860	PD_MultiBelt Library Guide: The description of <i>i_axWriteAxisEncoder</i> must be corrected.
BOC-1381 / IECLIB-16863	PD_MultiBelt: If a write to axis encoder is executed on a MultiBelt train in case an error has been detected, it can happen that the error message does not indicate the reason and displays a general <i>UnexpectedFeedback</i> message instead.
BOC-1408 / IECLIB-17092	PD_MultiBelt: The home flag of MultiBelt trains is reset on entering the service operation mode. The home flag has to be set inside the service operation mode again.
BOC-1492 / IECLIB-17743	PD_MultiBelt Library Guide: The variable <i>IrSmooth</i> must be replaced by <i>IrJerk</i> .
BOC-1505 / IECLIB-17817	FileFormatUtility Library Guide: The initialization of the XML write structure is not available and must be added.
BOC-1548 / IECLIB-18869	PD_PacDriveLib: The function block <i>FB_EndlessFeed</i> reports <i>VelRange</i> when connected to an axis.
BOC-1554 / IECLIB-18884	GMC libraries: The function block <i>MC_ReadStatus</i> could be randomly influenced by other axis.
BOC-1558 / IECLIB-18888	PD_MultiBelt: Multibelt collision prevention is not operating correctly due to long trains.
BOC-1562 / IECLIB-18902	PD_MultiBelt: If an indexed station is parameterized with <i>IrAdditionalStep</i> = -1 and <i>xWaitForTrainInQueue</i> = true the trains do not leave the station correctly with departure motion, but with step motion instead.
BOC-1576 / IECLIB-18927	PD_MultiBeltModule: If movement values are used to home the MultiBelt which exceed the maximum defined in <i>UserMaxVel</i> and <i>UserMaxAcc</i> an error is detected as designed. Nevertheless, the message does not indicate the reason and displays a general <i>UnexpectedFeedback</i> message instead.
BOC-1578 / IECLIB-18926	PD_MultiBeltModule: An incorrect Multibelt departure velocity is used due to a following pass-by station.
BOC-1580 / IECLIB-19846	PD_MultiBeltModule: An incorrect diagnostic message is displayed if the number of stations configured via <i>iq_stMultiBeltModuleIstf.astStation</i> is less than the number of stations specified by the parameter <i>iq_stMultiBeltModuleIstf.stMain.i_rstParameter.uiNumOfStations</i> .
BOC-1581 / IECLIB-19847	PD_MultiBeltModule: It can happen that Multibelt sporadically reports a collision with certain parameterizations.
BOC-1597 / IECLIB-19850	PD_MultiBeltModule: It can happen that a station does not move the trains after a warmstart if the station type was changed back and forth and a homing was executed while multibelt was not in automatic mode. Workaround: Execute a cold start when a homing was executed or a station is reconfigured.
BOC-1622 / IECLIB-19977	GMC libraries (CanOpen): Axis access management is not available for PacDrive.
IECLIB-3672	Unwinder: It is not possible to set the J-Load of the unwinder after a stop with the same radius.
IECLIB-18935	SqlRemoteAccess: Individual SQL requests longer than 195 characters are truncated even though the defined length (<i>GPL_Gc_uiRequestWstringLength</i>) is higher (for example, 200). Workaround: Divide the request into individual strings not longer than 195 characters each.
M262-7210/SI-13702	SM3_CNC and SM3_Basic: The library update is not performed correctly. Workaround: Update the SoftMotion version manually to 4.10.0.0 via the command Project > Project Settings > SoftMotion .
MK-350	SercosCommunication on M262: The function block <i>FB_ReadParameter</i> returns more than the number of bytes requested. To help prevent a potential memory leak take the length (number of bytes) for a readable IDN parameter into account.

Software Information

Version Identification

Description	Version
ATV320	1.3.3.0
ATV340	3.1.0.0
ATV6xx	2.6.5.0
ATV9xx	3.1.0.0
Lexium 32 A	1.20.03.05
Lexium 32 C	1.20.03.05
Lexium 32 I	1.20.03.05
Lexium 32 M-S	1.20.03.05
Motion Sizer	4.3.1.0
TeSysT	2.14.1.0

New Features EcoStruxure Machine Expert

Motion Sizer

The gear editor allows gear ratio values within the range of 0...999.

New Features EcoStruxure Machine Expert - Safety

New Features

Cybersecurity improvements for TM5CSLC•00FS and TM5NS31.

Compatibility EcoStruxure Machine Expert - Safety

Project Updates

No re-certification is needed related to the new TM5CSLC•00FS firmware version. Only cybersecurity enhancements have been performed in the non-safety related part of the firmware.

NOTE: In general, after a safety system update the safety related functions have to be re-tested as usual.

Overview of the validated EcoStruxure Machine Expert - Safety version with the appropriate safety-related firmware.

Device	Safety-related firmware version for EcoStruxure Machine Expert - Safety version				
	1.1	1.2	1.2.2	2.0	2.0.1
TM5CSLC100FS	2.52	2.52	2.53	2.56	2.57
TM5CSLC200FS	2.52	2.52	2.53	2.56	2.57
TM5SAI4AFS	322	322	322	322	322
TM5SDC1FS	302	302	302	302	302
TM5SDI20DFS	305	305	305	305	305
TM5SDI2DFS	305	305	305	305	305
TM5SDI4DFS	305	305	305	305	305
TM5SDM4DTRFS	305	305	305	305	305
TM5SDM8TBFS	305	305	305	305	305
TM5SDO2DTRFS	300	300	300	300	300
TM5SDO2TAFS	280	280	280	280	280
TM5SDO2TFS	280	280	280	280	280
TM5SDO4TAFS	280	280	280	280	280
TM5SDO4TFS	280	280	280	280	280
TM5SDO6TBFS	295	295	295	295	295
TM5SPS10FS	320	320	320	332	332
TM5STI4ATCFS	322	322	322	322	322
TM7SDI8DFS	305	305	305	305	305
TM7SDM12DTFS	305	305	305	305	305

Mitigated Anomalies

Motion Sizer

ID	Description
BOC-607 / MS-1950	The description for inertia of pinion was not clear in the Motion Sizer.
BOC-608 / MS-1947	There was a documentation issue for ILM140 drives in Motion Sizer, the length and the winding type of the motor and drive type did not match.
BOC-609 / MS-1944	The torque characteristic was not updated in the Motion Sizer after an update from the PWM frequency.
BOC-611 / MS-1937	The data export *.asc number of points was different to Ecam4 - 1 point less.
BOC-612 / MS-1943	Incorrect jerk was displayed for motion law 'mod sin' in the Motion Sizer.
BOC-613 / MS-1913	It was not possible to open some Motion Sizer projects (invalid object identifier).
BOC-618 / MS-1940	When a new gear box was manually added to the GearBox editor in Motion Sizer, an uneven gear factor was not displayed correctly.

EcoStruxure Machine Expert

ID	Description
BOC-1140 / CDSYS-634	Compiler: The message <i>Case label duplicate</i> was generated when using enumerations tagged with the attribute <code>to_string</code> and containing duplicate values inside of the switch case statement. No more error messages with EcoStruxure Machine Expert V2.0. <code>TO_STRING</code> returns the first symbol corresponding to the numeric input value if the numeric value is used more than once.
BOC-1163 / CDSYS-793	The Input Assistant did not operate correctly for recipes.
BOC-1295 / PLAT-1392	An error message was triggered if a located struct had been added to the OPC UA Symbol Configuration .
BOC-1322 / CDSYS-824	Online values were not displayed or were displayed incorrectly for flex arrays in a function block.
BOC-1418 / CDSYS-896	'Go to Definition' jumped to an incorrect 'Instance' of a global structure.
BOC-1451 / CDSYS-909	Compiler defines: <code>bit_word_addressing</code> became deactivated after reopening a project.
BOC-1493 / SI-13011	EcoStruxure Machine Expert V2.0 displayed the Machine Expert Integrity Check with every startup.
BOC-1511 / CDSYS-940	EcoStruxure Machine Expert V2.0 added configuration data to an EtherNet/IP device which did not have any target configuration data.
CDSYS-533	Trace: The Add Variable feature was inconsistent if multi channel had been activated.
CDSYS-682	A new variable in the Trace always had the color blue.
CDSYS-699	Trace: Values of variables in the diagram tree were displayed in separate columns.
CDSYS-700	Trace: The drag and drop function was not available for diagrams in the diagram tree view.
CDSYS-701	Trace: The trace diagram and the diagram tree view were not synchronized.
CDSYS-702	Trace: It was not possible to edit variable names directly in the diagram tree view.
CDSYS-710	Text information in the Trace Configuration were truncated.
CDSYS-758	Symbol Configuration: After an update of the project from V1.2.4 to V2.0 selected variables were lost.
CDSYS-759	Input Assistant: Members of Structures extending Lib Alias of Structure were not displayed (only compiled libraries).
CDSYS-778	Switching between Symbol Sets took a long time OR caused the software to terminate operation.
CDSYS-784	Multicore Operator <code>TEST_AND_SET</code> triggered an exception.
CDSYS-792	It took longer to start the WebVisualization immediately after starting the controller.
CDSYS-816	The Event task was displayed in RUN after log out log on to the M251 controller.
CDSYS-889	Opening a visualization took a long time.
CDSYS-916	Multidimensional flex arrays were not monitored in function blocks.

Known Operational Anomalies

EcoStruxure Machine Expert

ID	Description
BOC-945 / CDSYS-870	The trace editor buffer size for device trace cannot be modified. The trace recording time is limited to 01h 11min.
BOC-1343 / CDSYS-845	An incorrect property symbol is displayed for watch selection.
BOC-1350 / CDSYS-854	Incorrect behavior when extending a library function block method containing an input of type Array with maximum size defined by a library constant.
BOC-1364 / CDSYS-865	Constants are shifted when they are displayed online (FBD).
BOC-1367 / CDSYS-868	The Input Assistant starts with the focus on the register Categories .
BOC-1430 / SI-12737	There is a misspelling in SERCOS > Busview > Tooltip (German).
BOC-1433 / SI-12738 / SI-9136	The modification of the Effective Library Version in the Library Manager > Libraries > Properties > Specific Version is only updated after reopening of the editor.
BOC-1439 / SI-12739	Although the Software Catalog was removed in EcoStruxure Machine Expert V2.0 some menu items are still available in Tools > Customize .
BOC-1446 / CDSYS-674	Opening the library tree results in a complete resize of the EcoStruxure Machine Expert window when the DPI setting is not 100%.
BOC-1460 / SI-12819	<i>AddOnList missing</i> logs are generated during EcoStruxure Machine Expert V2.0 installation.
BOC-1473 / M262-6290	If the Sercos bus is configured incorrectly, a message is displayed indicating that the maximum number of devices is four, even though eight devices are supported.
BOC-1482 / IAT-115	The search in offline help does not return results in French language.
BOC-1520 / SI-13362	The status in the Gateway Management Console remains unknown. A connection with the default gateway configuration is still possible but it cannot be modified via the Gateway Management Console. The static remote connection configuration is not affected. Workaround: If the gateway configuration must be adjusted for a specific use case you can edit the Gateway.cfg file (requires a service restart). Location of the file: C:\Program Files (x86)\Schneider Electric\EcoStruxure Machine Expert\Tools\Gateway If the connection via the gateway is no longer possible try a different connection mode like Fast TCP.
BOC-1521 / CDSYS-943	If you use a generic EDS (Electronic Data Sheet) for an EtherNet/IP device the connection is changed to the default connection when you select another tab of the same device or you select another device.
BOC-1532 / CDSYS-948	Modifications on the property <i>Absolute Movement</i> have no effect on the visualization element Line .
BOC-1539 / SI-13406	The Diagnostics tool cannot read parameters of the PacDrive LMC controller when only Service Tools of V2.0 are installed.
BOC-1542 / CDSYS-951	Animations of expression results within a POU that implemented the LD or FBD language are unavailable.
BOC-1543 / SI-13414	The Diagnostics tool uses the fallback instead of the installed version when it is running standalone or together with just the service tools.
BOC-1547 / CDSYS-955	Path3D causes the visualization to stop operation after update to EcoStruxure Machine Expert V2.0.
BOC-1553 / PLAT-1564	Depending on the order of a call of a function block which has the same name as the POU in which the function block is called, invalid declarations in the code (real AT %MW) are not detected – no compile error messages are generated.
BOC-1569 / CDSYS-944	Performance issues occur when installing many libraries while the Library Manager editor is open.
BOC-1570 / CDSYS-945	The Auto Save operation interrupts the login command.
BOC-1571 / CDSYS-967	The EnumType leads to compilation errors being detected when using <code>Var PERSISTENT RETAIN</code> and executing the Add all Instance Paths command.
BOC-1579 / CDSYS-987	Unavailable error message results in unexpected state of outputs when located Boolean variables are mapped to these outputs.
BOC-1599 / PLAT-1590	An unexpected exclamation mark is displayed at the settings TAB of an EtherNet/IP device.
BOC-1626 / CDSYS-988	An SFC jump in a macro of an SFC POU causes an exception when opening the SFC editor for a special Sequential Function Chart.

ID	Description
BOC-1628 / SI-13906	When importing DTMs advisory messages are generated for already installed EDS files.
BOC-1630 / CDSYS-991	Cross reference list is incomplete after a build of the project.
BOC-1640 / SI-14017	<i>UserFunctions</i> parameters could not be saved with the Save parameters of active editor command.
HMI-778	Vijeo-Designer build time crash during programming / application creation, which results in a loss of data.
SI-10300	ETEST: Variables of all test cases (function block instances) are initialized on each test run.

EcoStruxure Machine Expert V2.0.2

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M241	5.1.9.34
M251	5.1.9.34
M262	5.1.6.1
TM5CSLC100FS	2.58
TM5CSLC200FS	2.58
LMC Eco	1.68.10.2
LMC Pro	1.68.10.2
LMC Pro2	1.68.10.2
LXM32S...M2 / LXM32S...N4	- Drive firmware: V1.12.02 - Sercos3 interface firmware: V1.12.02

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

New Features

Modicon M262 Logic/Motion Controllers

- Trend recording manager and alarm manager are now available.
- CPU load and time zone is now accessible from the webserver.
- TM5 IO-Link module is available through EtherNet/IP and Sercos TM5 bus couplers.
- SysLog enhancement with encrypted communication and documentation.
- New function blocks implemented to manage SD cards (*FB_GetFreeDiskSpace*, *FB_GetLabel*, *FB_GetTotalDiskSpace*).
- M262 as Modbus TCP Server can now manage up to 16 connections.
- The FTP client provides secured/encrypted connection (FTPs).
- A time stamp is available with an OPC UA variable using dedicated function blocks.
- A channel (IO Scanner line) can be disabled by the application (with function *IOS_CONTROLCHANNEL* and I/O mapping control bits).
- With firmware version V5.1.6.1, OPC UA is now certified by the OPC Foundation.

- The DHCP table has been extended from 128 to 192 devices.

Modicon M262 Motion Controllers

Online Help Improvements

Improved library description for MotionInterface and SercosMaster libraries in the online help.

Cyclic Synchronous Velocity (CSV) Improvements

- CSV support for *MC_CustomJob* has been added.
- CSV support for simulated drive has been added.

Product Measuring and Belt Tracking (Similar to Logical Encoder)

For synchronized movement with tracked products/material on material stream (belt, conveyor...) you can now measure the distance moved by an axis and synchronize with other axis/axis groups. This tracking function allows you to follow products. It is a partial equivalent to the logical encoder.

Switch Cam on Master Position

There is a new function to switch cams on a given position without reset or running the cam until the end position:

- Allows you to switch from one cam being executed to another cam.
- Switching cams is executed in smooth transition, it does not cause discontinuities, jumps, stops.

Control Drive with Cyclic Synchronous Torque (CST)

This new function is an alternative to Cyclic Synchronous Position (CSP) and is required for continuity with LMC078 / LMC058 functionality to address similar coverage of application needs.

A typical use case is, for example, capping or clamping applications where the target is to apply a defined pressure (force or torque) to the product.

TM5CSLC•00FS

Cybersecurity and quality improvements.

PacDrive LMC Control

IO-Link Integration for PacDrive

- IO-Link editor
- Libraries to handle process/parameters data
- Available for Sercos

Sercos Bus View

- SercosIpClient library available

Mitigated Anomalies

Lexium 52 / 62 / 62 ILM

ID	Description
LMCFW-1817	Lexium 62 Plus: Sercos phase up was not possible if devices were addressed with Identification mode = Application type .

M241/M251

ID	Description
CVE-2020-28895	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-35198	Specific cybersecurity vulnerabilities are mitigated.
CVE-2021-29241	Specific cybersecurity vulnerabilities are mitigated.
CVE-2021-33485	Specific cybersecurity vulnerabilities are mitigated.

M262

ID	Description
BOC-1473 / M262-6290	If the Sercos bus was configured incorrectly, a message was displayed indicating that the maximum number of devices was four, even though eight devices were supported.
CVE-2020-10245	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-28895	Specific cybersecurity vulnerabilities are mitigated.
CVE-2020-35198	Specific cybersecurity vulnerabilities are mitigated.
CVE-2021-3449	Specific cybersecurity vulnerabilities are mitigated.
CVE-2021-33485	Specific cybersecurity vulnerabilities are mitigated.
PEP0616129R	Improvement in the way to manage explicit messages in EtherNet/IP.
PEP0622369R	M262 was not able to manage more than 6 user parameters in some cases.
PEP0639053R	SysLog documentation has been improved.
PEP0645013R	Overall performance of the EtherNet/IP stack has been improved correcting some issues linked to the ARP (Address Resolution Protocol) table with very large architectures.
PEP1002000R	The OPC UA performance of large applications has been improved, reducing the sampling time.

M262 Motion

ID	Description
MK-666	In some situations there was no reaction of <i>MC_Power</i> if it had not been possible to power on the drive.
MK-1109	Inappropriate actions have been corrected when <i>MC_MoveAbsolute</i> is executed with small ramps and axis velocity in that point is "high".
MK-1121	In some cases <i>FC_ReadScaledPositionFeedback</i> did not return the correct position.
MK-1214	<i>MC_SetPosition</i> with <i>MC_CustomJob</i> could lead to an unintended operation.
MK-1289	In some cases <i>ErrorInEncoderCallbackResultDetected</i> on incremental encoder could not be cleared.
MK-1293	The M262 Motion controller stopped operation after several online changes and an empty <i>Crash.txt</i> file was created.
MK-1308	Online help: The <i>MC_GearIn</i> description has been improved.

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-1963	The C2C Encoder Input behavior on Sercos caused slave issues.
LMCFW-2004	SystemInterface: The <i>FC_AppendToWriteFile</i> connection to the controller was lost.
LMCFW-2019	Under certain circumstances, SoSafe login to the Safety Logic Controller (SLC) was not possible.
LMCFW-2052	A boot error was detected after a trace with the option Automatic restart was executed.
LMCFW-4394	TM5 EtherNet/IP caused slow loading times.
LMCFW-4684	An exception <i>Cycletime overrun</i> could occur with a ProfiNetIO controller.
LMCFW-4715	The CIFS Profinet V3 message "Could not finish the configuration 16#C0CB006C" was displayed when many devices were available in the network and the Profinet Stack was updated.
LMCFW-4737	Delays could occur in ARTI3 communications.
LMCFW-5534	Sercos DoubleLine-Topology: Sercos was in phase 4 although the devices on port two reported errors.
LMCFW-5255	Communication to the LMC was only possible after a restart.
LMCFW-5571	If the <i>enableAdditionalParameter</i> setting was selected, the Profibus IO data exchange was incorrect.
LMCFW-5866	The TM5SE4IOL module could not be disabled.

TM5CSLC•00FS

ID	Description
SSP50-9638	The parameter <i>ApplicationType</i> of TM5CSLC•00FS was set to the default value <i>Modular Safety Device</i> after downloading a modified safety-related application.

Known Operational Anomalies

M241/M251

ID	Description
M2x1-594	When the M241/M251 firmware is upgraded from 5.0.4.8 (EcoStruxure Machine Expert V1.2) to 5.1.9.14 (EcoStruxure Machine Expert V2.0), old user rights are not deleted and not reset. Workaround: Use an SD card to perform the upgrade or downgrade of the firmware.
M2x1-947	Specifically crafted HTTP packets, sent to WebVisualization, may provoke an unintended reboot of the controller. If you choose to activate the WebVisualization features, follow Schneider Electric Cybersecurity guidelines (https://www.se.com/ww/en/download/document/EIO0000004242/).

M262

ID	Description
CDSYS-929	In the <i>AlarmInfoGroup</i> , when adding a new alarm from the Observation Type column, sometimes a message is displayed. This does not affect the functionality.
CDSYS-1049	When alarm-related objects are imported, the alarm management task is not created automatically. Workaround: Delete the Alarm Manager object and add it manually. The task will be created with the next import.
M262-6577	When the time zone is defined in the webserver, Write as Local Time is not functional. Workaround: Use Write as UTC instead.
M262-8857	The export of a CSV file takes a long time (up to 10 minutes) when the IEC code is large or the WebVisualization is used.
M262-9412	In Trend Recording, the file size is always smaller than the configured maximum storage size.
M262-9422	After an error has been detected on the CANopen devices, the device remains red until it is explicitly acknowledged by the user by pressing the button even though the devices have already returned to operational state.
M262-11318	When the trend recording file is large, the message <i>Some kind of I/O disk error occurred. Check disk space.</i> may be displayed.
M262-11333	Upgrading a Modicon M262 Logic/Motion Controller from a V2.0.* firmware to a V2.0.2 firmware (V5.1.6.1) can have the effect that the applications can no longer be downloaded to the M262 (reboot required). Workaround: Perform the migration in the following order and in two separate steps: 1. Upgrade the Modicon M262 Logic/Motion Controller firmware. 2. Download the application.
M262-11336	Using the TM5 IO-Link module with some types of sensor, when <i>Invalid Process Data</i> is returned, events may not be detected.
M262-11359	Reset persistent is working only on variables used in the application code.
M262-11403	When <i>FC_GetFreeDiskSpace</i> is used in a task with a fast interval (less than 500 ms), the Modicon M262 Logic/Motion Controller may trigger the watchdog. Workaround: Use the function <i>FC_GetLabel</i> only in a task with an interval period greater than 500 ms because file system access is required.
M262-11445	The alarm history is not completely displayed when the file is large.
M262-11501	Some FTP servers may not operate properly with M262 FTP secure Client secure.
MK-1379	After about 300 cycles of phase 0-1-2 and call to <i>S3M.FC_SercosGetConfiguration()</i> , M262 no longer responds to a new call. Workaround: Do not call <i>S3M.FC_SercosGetConfiguration()</i> during the Sercos phase change of 1 to 2.
PEP1008491R	Specifically crafted HTTP packets, sent to WebVisualization, may provoke an unintended reboot of the controller. If you choose to activate the WebVisualization features, follow Schneider Electric Cybersecurity guidelines (https://www.se.com/ww/en/download/document/EIO0000004242/).

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-5705	The cycle time may increase after converting the project to EcoStruxure Machine Expert V2.0.
LMCFW-5706	The Profinet startup may not be performed and the message <i>16#C0CB0065 - Inconsistent topology configured</i> may be displayed.
LMCFW-5802	A download error (8903) may be displayed when EtherCat is configured for the optional module.
LMCFW-5855	When converting EcoStruxure Machine Expert V1.2 to V2.0, the EtherNet/IP Byte Order is inverted.
LMCFW-5864	The IO-Link master may detect an error if an IO-Link connector is 'inactive'.
LMCFW-5920	An FDR (Fast Device Replacement) timeout may occur for the firmware update of LXM62 Plus.
LMCFW-5923	Depending of the IO-Link sensor events may not be reported.

Library Information

Version Identification

Description	Version
CertificateHandling	1.1.2.0
FileFormatUtility	1.5.15.0
FtpRemoteFileHandling	1.4.3.0
GMC Independent Base	1.3.7.0
GMC Independent Interface	1.3.10.0
GMC Independent PLCopen MC	1.3.6.0
IecRtsServices	1.0.4.0
IoLinkHandling	1.0.2.0
M262Diagnostics	1.0.8.0
MachineAssistantServices	1.0.3.0
MqttHandling	2.2.1.0
OpcUaHandling	2.1.9.0
PD_GlobalDiagnostics	1.4.1.0
PD_Template	1.7.1.0
ProxyCommunicationSupport	1.0.5.0
Robotic	3.3.0.0
RoboticModule	2.14.0.0
SchneiderElectricRobotics	2.12.1.0
SchneiderElectricRobotics Parameters	2.15.0.0
SchneiderElectricRobotics Toolbox	1.6.0.0
SercosCommunication	1.2.3.0
SercosIpClient	1.0.2.0
SqlRemoteAccess	2.0.4.0
TcpUdpCommunication	2.2.10.0

Version Identification Safety Libraries

Description	Version
SF_EnableSwitch_SE	V1.00 from 11/19/15

Version Identification Examples

Description	Version
Machine Advisor Communication	1.3.2.0
MQTT Handling Example	1.3.2.0 (M262/LMC)
PackML Example for M262	1.0.0.0

Version Identification Smart Templates

Description	Version
Axis	2.1.0.0
Camera	2.2.0.0
Conveyor	2.2.0.0
Robot Cartesian	1.0.0.0
Robot P-Series	2.3.0.0
Robot S-Series	2.3.0.0
Robot T-Series	2.2.0.0
RobotCell	1.0.0.0
Sensor	1.1.1.0

New Features

CertificateHandling

A new function block *FB_CertificateHandling* has been added to retrieve attributes, delete and copy certificates.

FtpRemoteFileHandling

A new function block *FB_SecureFtpClient* has been added to support a secure FTP protocol via TLS.

IoLinkHandling

This new library allows to write user parameters of the IO-Link master, to read and write parameters of the IO-Link devices, and to handle events generated by the IO-Link devices.

MqttHandling

A new property has been added to the function block *FB_MqttClient* to support the usage of the interface *IF_ProxyHandler* which can be used to establish a connection to a remote server through a proxy server.

OpcUaHandling

- A new function block *FB_TimeStamper* has been added to time stamp value changes and to provide information through the OPC UA server of the M262 controller.
- The support of the SubString feature for the OPC UA client has been implemented to fulfill certification requirements.

PD_GlobalDiagnostics

The enumeration types *ET_Diag* and *ET_DiagExt* have been modified to provide textlist support.

PD_Template

The visualizations have been updated to make use of the enumeration types *ET_Diag* and *ET_DiagExt* with textlist support out of the PD_GlobalDiagnostics library.

ProxyCommunicationSupport

This new library provides the functionality to support the communication with a remote server through a proxy server.

SercosIpClient

This new library supports the implementation of the Sercos IP client functionalities provided by the runtime (PacDrive).

New Features for Safety Libraries

SF_EnableSwitch_SE

Editorial changes in the library without impact on functionality or safety behavior.

New Features for Examples

PackML Example

This new example application implements the PackML library on an M262 controller.

MQTT Handling Example

This example application implements the support of the connection to the remote server through a proxy server.

Machine Advisor Communication Example

This example application implements the support of the connection to the remote server (Machine Advisor) via HTTPS or MQTTS through a proxy server.

Mitigated Anomalies

ID	Description
BOC-1201 / IECLIB-3553	FtpRemoteFileHandling: No error was detected for the FTP command <i>List</i> when the buffer size was too small.
BOC-1554 / IECLIB-18884	GMC libraries: The function block <i>MC_ReadStatus</i> could be randomly influenced by other axis.
BOC-1622 / IECLIB-19977	GMC libraries (CanOpen): Axis access management was not available for PacDrive.
BOC-1641 / IECLIB-20216	FileFormatUtility: Parsing a Json string with control characters after a number is now supported.
IECLIB-16892	M262Diagnostics: The file was created over several cycles of the function block instead of within one cycle executed in a separate asynchronous task.
IECLIB-18935	SqlRemoteAccess: Individual SQL requests longer than 195 characters were truncated even though the defined length (<i>GPL_Gc_uiRequestWstringLength</i>) was higher (for example, 200).
IECLIB-19980	TcpUdpCommunication: In the case that a server refuses the client certificate, the client indicates that the server refuses the connection instead of returning an incorrect result.
IECLIB-20183	FileFormatUtility: Uniform handling of escape character for adding, retrieving and parsing Json elements.
IECLIB-20257	FileFormatUtility: Detected invalid escape characters while parsing a Json string.
IECLIB-21830	FileFormatUtility: <i>FB_JsonUtilities</i> is visible as object of the <i>FileFormatUtility</i> library.
IECLIB-21831 / M262-6283 / PEP0653633R	MachineAssistantServices: Add additional diagnostics information to <i>FC_GetPeerScanData</i> (based on M262 firmware extension).
IECLIB-21832	OpcUaHandling: <i>UA_ReadList</i> returns the complete data specified by the server in case of node data type <i>UATypeByte</i> and <i>IndexRangeCount 0</i> .

Known Operational Anomalies

ID	Description
BOC-1678 / IECLIB-20218	PD_MultiBelt: A departure velocity lower than step velocity is not applied for an indexed station.
BOC-1723 / IECLIB-20786	GMC Independent PLCopen MC: The <i>MC_Power</i> report <i>Device State Invalid</i> cannot be reset.
LMCFW-6032	For PacDrive controllers: If the value of <i>etNodeDataType</i> indicates <i>UATypeIECSymbol</i> , then <i>IndexRangeCount 0</i> defines the index ranges to address only the first element of the variable even if the variable is declared as an array.
LMCFW-6214	For PacDrive controllers: Only the value of <i>ContinuationPoint</i> with a size of 4 bytes is supported.
M262-11450	For Modicon M262 Logic/Motion Controllers: The value of <i>ContinuationPoint</i> is an opaque value that identifies the continuation point of type <i>ByteString</i> received by the OPC UA server. With each call of the function block <i>UA_Browse</i> with <i>ContinuationPointIn</i> is equal to 0, the OPC UA client stores internally the continuation point received by the OPC UA server if this value is not NULL. Up to 10 continuation points can be stored. The output <i>ContinuationPointOut</i> provides the index used by <i>UA_Browse</i> to store the continuation point received from the OPC UA server. This value can be used as <i>ContinuationPointIn</i> to get further results related to this browse operation. To clean the internal storage locations of continuation points, proceed as follows: 1. Call <i>UA_Browse</i> with <i>ContinuationPointIn</i> is equal to 16#FFFFFFFF. No browse request is sent to the OPC UA server. 2. Call <i>UA_Disconnect</i>. 3. Execute a Reset COLD, Reset WARM, DOWNLOAD and POWER CYCLE. To clean one storage location of continuation points, call <i>UA_Browse</i> with <i>ContinuationPointIn</i> between 1 and 10. A new browse request is sent. To handle the storage of continuation points, two new error codes have been created in <i>ET_Result</i>: • <i>InvalidContinuationPointIn</i> - 16#B0000114: An invalid <i>ContinuationPointIn</i> is detected. • <i>MaxContinuousPointStorageReached</i> - 16#B0000115: No resource is available to store a new continuation point from the server. Clean the internal storage locations of continuation points.

Software Information

Version Identification

Description	Version
OPCServer	3.5.16.60
Diagnostics	20.2.6.0
Controller Assistant	20.2.6.0
Device Assistant	20.2.7.0
Gateway	20.2.6.0
DiffViewer	20.2.7.0

DTMs

Description	Version
Lexium 28 A	1.6.0.8
Lexium 28 S	1.6.13.0
Lexium 32 A	1.20.04.02
Lexium 32 C	1.20.04.02
Lexium 32 I	1.20.04.02
Lexium 32 M-S	1.20.04.02

New Features EcoStruxure Machine Expert

Diagnostics Tool

User functions are part of the Diagnostics tool.

Diff Viewer

The Diff Viewer fully supports the compare options.

Digital Signature Verification

As a built-in security feature against cyberattacks and to increase the trust level, each loaded dynamic-link library (DLL) is scanned to verify whether or not it is trusted when a software (such as EcoStruxure Machine Expert) is started.

Project Archive

A new message is introduced if you open a project archive of a newer EcoStruxure Machine Expert version.

Project Information

The Windows file properties for .project and .projectarchive files are enhanced with project information. This includes information about the last online change / download and the project settings. This information is now available in the Windows explorer without opening EcoStruxure Machine Expert.

Python

- The Python help *Schneider Electric Script Engine User Guide* is created as HTML help and integrated in the EcoStruxure Machine Expert online help.
- New Python interfaces are added to determine the implementation language or to read the EcoStruxure Machine Expert version.

TestCase

It is possible to use a **TestCase** in a library from the library and/or from the project, that includes that library.

Trace

The **Trace** function has been improved by changing the order in the contextual menu and the color optimization.

User Documentation

The user documentation supports an HTML help file for user function blocks including **F1** contextual help.

Compatibility EcoStruxure Machine Expert - Safety

Project Updates

No re-certification is needed related to the new TM5CSLC•00FS firmware version. Only a quality enhancement has been performed in the non-safety related part of the firmware.

NOTE: In general, after a safety system update the safety related functions have to be re-tested as usual.

Overview of the validated EcoStruxure Machine Expert - Safety version with the appropriate safety-related firmware.

Device	Safety-related firmware version for EcoStruxure Machine Expert - Safety version					
	1.1	1.2	1.2.2	2.0	2.0.1	2.0.2
TM5CSLC100FS	2.52	2.52	2.53	2.56	2.57	2.58
TM5CSLC200FS	2.52	2.52	2.53	2.56	2.57	2.58
TM5SAI4AFS	322	322	322	322	322	322
TM5SDC1FS	302	302	302	302	302	302
TM5SDI20DFS	305	305	305	305	305	305
TM5SDI2DFS	305	305	305	305	305	305
TM5SDI4DFS	305	305	305	305	305	305
TM5SDM4DTRFS	305	305	305	305	305	305
TM5SDM8TBFS	305	305	305	305	305	305
TM5SDO2DTRFS	300	300	300	300	300	300
TM5SDO2TAFS	280	280	280	280	280	280
TM5SDO2TFS	280	280	280	280	280	280
TM5SDO4TAFS	280	280	280	280	280	280
TM5SDO4TFS	280	280	280	280	280	280
TM5SDO6TBFS	295	295	295	295	295	295
TM5SPS10FS	320	320	320	332	332	332
TM5STI4ATCFS	322	322	322	322	322	322
TM7SDI8DFS	305	305	305	305	305	305
TM7SDM12DTFS	305	305	305	305	305	305

Mitigated Anomalies

EcoStruxure Machine Expert

ID	Description
BOC-480 / SI-13188	In the Configuration tab of the CamDiagram editor, the input assistant was empty for the option Existing IEC Structure .
BOC-644 / PLAT-648	An incorrect compiler message was displayed because of the missing possibility to adjust individual current load on TM5 outputs.
BOC-646 / SI-5582	An option has been added to automatically reconnect the gateway remote connection.
BOC-779 / SI-5892 (Service Disk)	The installation file was too large for service use cases. A new service tool installation is now available.
BOC-1280 / SI-6488	When a TMSES4 was used to connect to the M262 controller, an invalid network route became active on connecting to Tesys Island via DTM on Connection 'Ethernet_2'. Therefore, a connection to Tesys Island could not be established.
BOC-1420 / SI-12681	By default, the Connection Mode: IP Address via Gateway was not operational as a firewall setting was not available.
BOC-1430 / SI-12737	There was a misspelling in SERCOS > Busview > Tooltip (German).
BOC-1431 / SI-12926	It was not possible to have a project-specific option for device status monitoring.
BOC-1433 / SI-12738 / SI-9136	The modification of the Effective Library Version in the Library Manager > Libraries > Properties > Specific Version was only updated after reopening of the editor.
BOC-1439 / SI-12739	Although the Software Catalog had been removed in EcoStruxure Machine Expert V2.0 some menu items were still available in Tools > Customize .
BOC-1460 / SI-12819	<i>AddOnList missing</i> logs were generated during EcoStruxure Machine Expert V2.0 installation.
BOC-1484	An unexpected message was displayed when a project was opened.
BOC-1520 / SI-13362	The status in the Gateway Management Console remained unknown. A connection with the default gateway configuration was still possible but it could not be modified via the Gateway Management Console . The static remote connection configuration was not affected.
BOC-1539 / SI-13406	The Diagnostics tool could not read parameters of the PacDrive LMC controller when only Service Tools of V2.0 were installed.
BOC-1543 / SI-13414	The Diagnostics tool used the fallback instead of the installed version when it was running standalone or together with just the service tools.
BOC-1547 / CDSYS-955	Path3D caused the visualization to stop operation after update to EcoStruxure Machine Expert V2.0.
BOC-1553 / PLAT-1564	Depending on the order of a call of a function block which had the same name as the POU in which the function block was called, invalid declarations in the code (real AT %MW) were not detected – no compile error messages were generated.
BOC-1569 / CDSYS-944	Performance issues occurred when installing many libraries while the Library Manager editor was open.
BOC-1570 / CDSYS-945	The Auto Save operation interrupted the login command.
BOC-1599 / PLAT-1590	An unexpected exclamation mark was displayed at the settings TAB of an EtherNet/IP device.
BOC-1628 / SI-13906	When importing DTMs advisory messages were generated for already installed EDS files.
BOC-1630 / CDSYS-991	The cross reference list was incomplete after a build of the project.
BOC-1640 / SI-14017	<i>UserFunctions</i> parameters could not be saved with the Save parameters of active editor command.
BOC-1656 / SI-14116	The new dynamic-link library (DLL) <i>Microsoft.VisualStudio.Diagnostics.ServiceModelSink.dll</i> has been added to the allowlist.
BOC-1658 / SI-14130	Names of types were not adapted if declared in the GVL (Global Variables List) of a function template when the function template was instantiated.
BOC-1661 / SI-14131	The Schneider Electric Software Installer deleted the registry folder during uninstallation of the gateway application.
BOC-1666 / SI-14175	There was an issue (missing variable) when adding a Lexium 32 device template.
BOC-1667 / SI-14179	There was a misspelling of DHCP in the Modbus TCP slave configuration tab (Spanish).

ID	Description
BOC-1712 / SI-14771	The online help description of the comparing structures feature of EcoStruxure Machine Expert has been updated.
BOC-1717 / SI-14734	Starting the SoMachine Motion or EcoStruxure Machine Expert Logic Builder suddenly took a long time (~15 hours) due to a special customer IT configuration.

Known Operational Anomalies

EcoStruxure Machine Expert

ID	Description
BOC-1650 / CDSYS-1011	The Input Assistant does not display an instance for the method call in the FBD editor.
BOC-1651 / CDSYS-1012	The behavior of the <i>Search</i> feature is different than the <i>Replace</i> feature in that the order of finding objects is not consistent between the two.
BOC-1659 / CDSYS-1022	The state variable <i>invisible</i> of visualization objects does not operate correctly for all objects.
BOC-1675 / CDSYS-1034	The conversion to EcoStruxure Machine Expert V2.0.0.1 results in an error being detected and EcoStruxure Machine Expert being closed.
BOC-1691 / SI-14713	The Controller Assistant does not allow to transfer the user rights management of a saved image.
BOC-1697 / CDSYS-1040	The Trace editor automatically adjusts the column width to the default when it is modified.
BOC-1713 / CDSYS-1046	Copy and paste operations in the LD editor damage the network logic.
BOC-1719 / CDSYS-1052	An error is detected while drawing an FBD/LD network that is part of a source library included in a project.
BOC-1730 / CDSYS-1057	When activating property handling in all element properties in the Visualization Manager and associating properties of the Text Editor visualization element to POU Properties this leads to an operational stop of the visualization.

Motion Sizer

ID	Description
- / MS-2193	The maximum torque is not correct for backwards motion, additional constant torque and inflexion point <> 0.5.

EcoStruxure Machine Expert V2.0.2.1

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M241	5.1.9.35
M251	5.1.9.35
M262	5.1.6.3: TM262***, except TM262L01MESE8T 5.1.7.1: TM262L01MESE8T (not available in the Controller Assistant, only available on the product)

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

Mitigated Anomalies

M241/M251

ID	Description
M2x1-936	Siemens Tecnomatix could not access the controllers via OPC UA.
M2x1-947	Specific cybersecurity vulnerabilities are mitigated.
M2x1-952	After building an M251 project, the error message <i>Failed to insert library EtherNet/IP Explicit Messaging</i> was displayed even though no error was detected.
PEP1002769R	The firmware update of M241 was unsuccessful with V5.0.8.4, and the LED Error was flashing.

M262

ID	Description
M262-11483	Specific cybersecurity vulnerabilities are mitigated.
M262-11545	Siemens Tecnomatix could not access the controllers via OPC UA.
M262-11554	Specific cybersecurity vulnerabilities are mitigated.
PEP1008491R	Specific cybersecurity vulnerabilities are mitigated.

There are no additional known anomalies with this release.

Library Information

Version Identification

Description	Version
Diagnostic Device Support	1.0.1.0
EtherNet/IP Explicit Messaging	1.1.12.0
EtherNet/IP Remote Adapter	1.1.3.0
FtpRemoteFileHandling	1.4.5.0
GMC Independent EtherNet/IP	1.4.6.0
M262Diagnostics	1.0.9.0
MachineAssistantServices	1.0.4.0
TeSys island	2.0.5.0
TwidoEmulationSupport	1.2.4.0

There is no additional library information for this release.

Software Information

Version Identification

Description	Version
Diagnostics	20.2.7.0
Controller Assistant	20.2.7.0
DiffViewer	20.2.8.0
NetManage Server	20.2.7.0

Mitigated Anomalies

ID	Description
BOC-621 / MS-1898	Motion Sizer: The performance of the Motion Sizer with large projects was slow while entering axis names and descriptions (slow refreshing). NOTE: It was already mitigated with V2.0.1.
BOC-919 / SI-6443	A generic EtherNet/IP object was available for PacDrive, but it did not work. NOTE: It was already mitigated with V2.0.
BOC-1396 / -	Scripting documentation: Some Python methods were added for code analysis. NOTE: It was already mitigated with V2.0.2.
BOC-1827 / SI-15567	Visualization Manager: The Visualization Style Editor was not operational.

Known Operational Anomalies

ID	Description
BOC-1744 / CDSYS-1069	If a connection between two blocks in CFC is linked to EN of the second block, you cannot delete the line by clicking on the line itself to select it. Workaround: To delete it, select the output of the first block.
BOC-1751 / SI-15006	Script hook events are not displayed when the project is opened by double-click.
BOC-1766 / CDSYS-1079	The description of <i>FB_RemoteAdapter</i> outputs is not available.
BOC-1775 / CDSYS-1085	The Auto Declare function reports a detected error when trying to initialize an array of more than 100 elements.
BOC-1786 / CDSYS-1089	The Qt WebBrowser is no longer displaying the WebVisualization.
BOC-1798 / PLAT-1889	M2•• controllers import incorrect default values of configuration data of an EtherNet/IP device.
BOC-1804 / CDSYS-1107	The compiler error <i>Identifier 'genvInput' not defined</i> is detected when a dialog box is opened from a table in the visualization.
BOC-1815 / SI-15520	Logic Builder: When a project archive is opened that has been created with the present version, a message is displayed as if it had been created with a previous version.
BOC-1818 / -	Logic Builder: The frame window is flickering if the Project Information dialog box is open.

EcoStruxure Machine Expert V2.0.3

Hardware/Firmware Information

Version Identification

Description	Firmware Version
LMC Eco	1.70.10.2
LMC Pro	1.70.10.2
LMC Pro2	1.70.10.2
M241	5.1.9.44
M251	5.1.9.44
M262	5.1.7.10
TM3BCEIP	2.4.0.3

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

New Features

Lexium™ MC12 multi carrier

The Lexium™ MC12 multi carrier is a transport system to be used in machines. It uses linear motion technology to move products individually through the machine. Carriers are moved on a configurable track consisting of arc and straight segments. Process steps can be decoupled and run at different velocities. Machines can be adapted to different products and product patterns on the fly.

For information about the C2C network concept (controller-to-controller coupling network concept) that is used in the Lexium™ MC12 multi carrier, refer to Additional Information - C2C for Lexium™ MC12 multi carrier, page 212.

M262

New Controller

The new controller reference TM262L01MESE8T is added. Modicon M262L01 is the new entry level for logic applications, with the same IIoT-Ready features as M262L10, with the only restriction that it is not possible to connect TMSES4 modules. For details, refer to the catalog.

TM262M05MESS8T Modification

TM262M05MESS8T maintains the features from the launch with the only restriction that it is not possible to connect TMSES4 modules. For details, refer to the catalog.

EcoStruxure Cybersecurity Admin Expert

As a new feature, M262 has been added to the standalone software EcoStruxure Cybersecurity Admin Expert.

To support this new feature, a model of M262 has been added to the EcoStruxure Cybersecurity Admin Expert 2.4. software. The model consists of two sections:

- Role-Based Access Control (RBAC)
- Device Specific Settings (DSS)

For details, refer to the Modicon M262 Logic/Motion Controller Programming Guide. For more information about EcoStruxure Cybersecurity Admin Expert, refer to the EcoStruxure Cybersecurity Admin Expert web site.

SCEP (Simple Certificate Enrollment Protocol)

An M262 allows communication with a SCEP server to request a certificate signing or certificate renewal from a Certification Authority (CA). The Simple Certificate Enrollment Protocol (SCEP) is a protocol for enrolling certificates in a controlled environment. The goal of SCEP is to support the secure issuance of certificates to network devices in a scalable manner using existing technology whenever possible. For details, refer to the Modicon M262 Logic/Motion Controller Programming Guide.

TM3 EtherNet/IP Bus Coupler

The latest firmware version V2.4.0.3 for the TM3 EtherNet/IP Bus Coupler (TM3BCEIP) supports the TM3DM16R and TM3DM32R.

Mitigated Anomalies

HMISCU

ID	Description
CVE-2020-28895 CVE-2020-35198 CVE-2016-20009	Specific cybersecurity vulnerabilities are mitigated.

M241/M251

ID	Description
M2X1-831	The error message <i>Map to existing variable with address not allowed</i> was not displayed.
M2X1-903	Login was not possible after performing several OPC UA connections / disconnections.
M2X1-926	Login was not possible after performing a Reset Origin Device .
M2X1-955 / CVE-2022-22519	Specific cybersecurity vulnerabilities are mitigated.
M2X1-957	On TM251MESC controllers, the FTP encryption remained active even after a restart with post configuration in disable state.
M2X1-962	<i>SetNodeName</i> could not be added on Clone script.

M262

ID	Description
M262-11401	Harmonization of the trusted certificate location between software access and firmware feature access.
M262-11403	When <i>FC_GetFreeDiskSpace</i> was used in a task with a fast interval (less than 500 ms), the Modicon M262 Logic/Motion Controller sometimes triggered the watchdog.
M262-11719	The memory was exhausted with the OPC UA server and a specific configuration.
MK-1379	After about 300 cycles of phase 0-1-2 and call to <i>S3M.FC_SercosGetConfiguration()</i> , the Modicon M262 Logic/Motion Controller no longer responded to a new call.
PEP1006717R / M262-11550	The Manage Images > Read From feature of the Controller Assistant did not operate as expected.
PEP1010607R / M262-11760	After updating EcoStruxure Machine Expert to V2.0.2, the projects could not be downloaded when using specific variable types.
PEP1013729R / M262-11773	A memory leak occurred when five OPC UA clients were executed in parallel. After some time, the message <i>NOT_ENOUGH_MEM</i> was displayed.

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-6651	The OPC UA server detected an error when the data type TIME was requested.

TM3 Bus Coupler

ID	Description
PEP1006120R	An incorrect parameter name was displayed in the compiler error message when using the TM3BCEIP with a monitoring timeout smaller than the channel repetition rate.

Known Operational Anomalies

M262

ID	Description
M262-6011	The multicore operator <code>TEST_AND_SET</code> causes an exception. Workaround: Remove the call for the operator <code>TEST_AND_SET</code> from the IEC program.
M262-11845	Controller user right files exported before the V2.0 official version are not compatible with the latest implementation. Workaround: When updating a device from V2.0 to the latest version, retrieve the old controller image containing user rights and update the firmware by using this image.
M262-11877	The <code>IOS_GETDIAGSTATUS</code> function is not updating values after reset if no communication is established with a device.
M262-11898	An SCEP (Simple Certificate Enrollment Protocol) page performance issue occurs if a response is not received.
M262-11902	A valid Certificate Revocation List (CRL) is required when signed certificates are used for OPC UA communication.
M262-11960	The IGMP (Internet Group Management Protocol) is not operating on the interfaces ETH2 and TMSES4. Protocols using multicast such as EcoStruxure Cybersecurity Admin Expert discovery or EtherNet/IP T->O connections may have unintended behavior if the Modicon M262 controller is connected through a smart switch with IGMP snooping enabled. Workaround: Three alternatives are available: • Disable IGMP snooping on the switch. • For EcoStruxure Cybersecurity Admin Expert: Declare the IP address of the Modicon M262 controller explicitly in the EcoStruxure Cybersecurity Admin Expert system editor using port 5357. • For EtherNet/IP: Change the T->O Connection Type value from Multicast to Point to Point.
M262-11977	A firewall may not apply one command from the file after a download via EcoStruxure Cybersecurity Admin Expert. Workaround: Restart the controller for the firewall to be fully applied.
PEP1009996R / M262-11761	If the <code>FB_ControlClone</code> is used without clone access rights, it will be required for future clone actions.

Lexium™ MC12 multi carrier

ID	Description
METWIN-599	While starting the emulation of the multi carrier, some carriers may not be displayed at the correct position on the track. Workaround: A change of the position of the carriers on the track solves this display issue.

Library Information

Version Identification

Description	Version
ApplicationLogger	V1.1.5.0
CertificateHandling	V1.1.4.0
CommonToolbox	V1.0.4.0
Diagnostic Device Support	V1.0.2.0
Diagnostic Interfaces	V1.0.2.0
DigitalTwinCommunication	V1.0.0.0
Explicit Messaging LMC	V1.0.0.0
Explicit Messaging M262	V1.0.0.0
GMC Independent Base Device	V1.4.15.0
GMC Independent PLCopen MC	V1.3.7.0
IoLinkHandling	V1.1.1.0
MachineAssistantServices	V1.0.5.0
Multicarrier	V1.0.3.0
MulticarrierStation	V1.0.0.0
PD_MultiBelt	V1.5.3.0
PD_MultiBeltModule	V1.5.1.0
PD_SoMotionGenerator	V1.7.9.0
PD_Template	1.7.2.0
Robotic	V3.4.2.0
RoboticModule	V2.15.0.0
SchneiderElectricRobotics	V2.12.4.0
SchneiderElectricRobotics Parameters	V2.16.1.0
SchneiderElectricRobotics Toolbox	V1.7.3.0
SqlRemoteAccess	V2.0.5.0
TcpUdpCommunication	V2.2.11.0
TimeSync	V1.1.3.0
Unwinder	V1.3.1.0

New Features

DigitalTwinCommunication

This new library provides OPC UA structures to automatically build and emulate a Schneider Electric object in EcoStruxure Machine Expert Twin.

IoLinkHandling

The library supports writing user parameters over EtherNet/IP for Modicon M262 Logic/Motion Controllers For the PacDrive LMC controllers no changes have been integrated.

Multicarrier

This new library contains core technology functionalities for the Lexium™ MC multi carrier.

MulticarrierStation

This new library contains station functionalities for the Lexium™ MC multi carrier.

PD_SoMotionGenerator

The library provides support for the Multicarrier library to use *C2CEncIn* as master for the carrier.

PD_Template

The new GPL (Global Parameter List) parameter *Gc_udiMaxStringSizeOfExceptionMsg* has been added. It is used for defining the string size of the variables *sMsg* in *ST_Exception* and *i_sMsg* in *FC_SetExceptionTpi*.

SqlRemoteAccess

The library now provides a (TCP/UDP) callback interface to verify the certificate received from the peer.

New Features for Examples

Multicarrier Example

This new example application indicates how to implement the Lexium™ MC multi carrier using the Multicarrier library.

Mitigated Anomalies

ID	Description
BOC-530 / IECLIB-2497	PD_Multibelt: Collision of two trains on Multibelt. This behavior is not reproducible anymore.
BOC-531 / IECLIB-2498	PD_Multibelt: Multibelt homing operated incorrectly after changing the Belt-Length.
BOC-1051 / IECLIB-2927	PD_Multibelt: Backward movement was performed after warmstart. This behavior is not reproducible anymore.
BOC-1083 / IECLIB-3444	PD_Multibelt: The Multibelt feedback variable <i>xReadyForStep</i> was infrequently FALSE for one Sercos cycle. This behavior is not reproducible anymore.
BOC-1258 / IECLIB-2415	PD_Multibelt: It could be that directly after a short peak in the touch probe signal, which is filtered out via the <i>IrMinProductTime</i> , a regular product was no longer detected.
BOC-1258 / IECLIB-3644	PD_Multibelt: If the filter parameter <i>IrLockOutTime</i> was configured, the TouchProbe filter sometimes detected signals which were shorter than configured by the parameter <i>IrMinProductTime</i> .
BOC-1372 / IECLIB-16860	PD_Multibelt Library Guide: The description of <i>i_axWriteAxisEncoder</i> has been corrected.
BOC-1492 / IECLIB-17743	PD_Multibelt Library Guide: The variable <i>IrSmooth</i> has been replaced by <i>IrJerk</i> .
BOC-1505 / IECLIB-17817	FileFormatUtility Library Guide: The initialization of the XML write structure has been added.
BOC-1558 / IECLIB-18888	PD_Multibelt: Multibelt collision prevention was not operating correctly due to long trains.
BOC-1558 / IECLIB-23203	PD_Multibelt: It was possible that a train was moving too slow in a PassBy station if the station position was blocked by a previous train. This could lead to a collision of a train behind with the train in the PassBy station. This collision situation is now avoided.
BOC-1583 / IECLIB-19852	PD_Multibelt: The parameter <i>stTrainFeedback.IrPosition</i> now displays the train position normalized in a period of zero to belt length.
BOC-1586 / IECLIB-19853	PD_Multibelt: With the new parameter <i>stGeneral.IrWarmStartMoveOutOfCrashDistance</i> it is now possible to execute a warmstart even after a collision has been detected. For this, multi belt is now allowed to move the trains at a distance of <i>IrWarmStartMoveOutOfCrashDistance</i> to achieve that there is a distance larger than the collision distance between the trains before the normal warmstart movement starts. The default value of the parameter is zero so that the default behavior is compatible to earlier versions.
BOC-1835 / IECLIB-23093	GMC libraries: <i>MC_Reset</i> for ATV drives takes into account the present drive state regarding STO (safe torque off).
BOC-1880 / IECLIB-23245	GMC libraries: Diagnostics outputs of <i>MC_Power</i> are synchronized with the other function blocks if a communication issue (disconnecting the device) is detected.
BOC-1893 / IECLIB-23417	ApplicationLogger: If the ApplicationLogger is used on PacDrive LMC controllers, the timestamp is converted to local time while adding the log entry.
IECLIB-2436	PD_Multibelt: Support of <i>IF_TouchProbe2</i> (for example, used by TM5 touch probe inputs) for all TouchProbe functionalities. When using TouchProbes where <i>CaptureEdgeSetDelayed</i> is TRUE, only the product edge defined with the parameter <i>xSensorEdge</i> is detected via TouchProbe. Thus, the opposite edge is only detected by sampling the digital signal of the TouchProbe input which results in reduced quality. When TouchProbes are used which were supported before, there is no change in behavior.
IECLIB-3672	Unwinder: It was not possible to set the J-Load of the unwinder after a stop with the same radius.
IECLIB-22772	CertificateHandling: Improved cleanup of certificates to release memory properly.
IECLIB-22772	TcpUdpCommunication: Improved cleanup of not-default certificates to release memory properly when closing the connection.
IECLIB-23210	CertificateHandling: When using a communication client function block like, for example, the <i>FB_HttpClient</i> or the <i>FB_MqttClient</i> and the sending of the client certificate was enabled, the consumed memory was increased with each connection. This issue is solved. The allocated memory is now released after the connection is closed.
IECLIB-23211	GMC libraries: The ATV STO (safe torque off) state is now verified during the start up phase.
OEM00073263 / IECLIB-2428	MultiBelt/MultiBeltModule: Under certain conditions, after stop and warmstart of a <i>MultiBelt</i> module, the <i>ET_DiagExt</i> message <i>TrainMovesBackward</i> was displayed.
OEM00075899 / IECLIB-2444	MultiBelt/MultiBeltModule: The <i>q_xHomeOk</i> bit of all trains was set to TRUE in homing mode <i>HomeOnTp</i> , even if the homing procedure had been stopped due to missing TouchProbe signals.

Known Operational Anomalies

ID	Description
BOC-1929 / IECLIB-23450	The parameter <i>RealTimeClock</i> of the PacDrive LMC controller is set to an incorrect time / timezone if the daylight saving time is active and the selected / used timezone is west of UTC (Universal Time Coordinated).
BOC-1947 / IECLIB-23472	CrankModule: If a command 620 (Manual) is sent to the CrankModule while the axis is disabled, the slide position drops to 0 for ~60 ms.
BOC-1950 / IECLIB-23499	SnmpManager: The <i>FB_SnmpManager</i> sends a public SET request by default instead of private. Workaround: Set <i>sCommunityName</i> to private.
BOC-2020 / IECLIB-23750	FtpRemoteFileHandling: When enabling the function block <i>SE_FTP.FB_FtpClient</i> while the FTP server is not present, the <i>q_etResult</i> is infinitely equal to <i>Initializing</i> .
BOC-2034 / IECLIB-23769	The tab Log in the device editor and the instance methods GetDeviceState and Enable are not supported by the preinstalled CANopen devices, such as Altivar and Lexium.
BOC-2035 / IECLIB-23768	IoLinkHandling: In the online help, section <i>FB_RegisterEvent</i> , the input <i>IF_IoLinkMaster</i> is described instead of <i>IF_IoLinkEvent</i> .
IECLIB-24338	Multicarrier: A carrier load with command <i>MoveGapControl</i> is not starting a new movement when the carrier in front or behind is loaded with command <i>MovePureSmg</i> and is in standstill.

Software Information

Version Identification

Description	Version
Diagnostics	20.3.3.0
Controller Assistant	20.3.1.0
Device Assistant	20.3.0.0
DiffViewer	20.3.3.0
Launcher	20.3.3.0
NetManage Server	20.3.0.0
EcoStruxure Machine Expert Twin	1.1.0.19321
Vijeo-Designer	6.2.12.1002

New Features EcoStruxure Machine Expert

Multicarrier Configuration Editor

The **Multicarrier Configuration** editor is used to configure a Lexium™ MC multi carrier from scratch or to modify an existing configuration. As a result, the **Multicarrier Configuration** editor adapts the device configuration in EcoStruxure Machine Expert and generates or modifies code in the application.

Emulation Settings

The **Emulation Settings** view of the device editor is available for PacDrive LMC Pro2 controllers. It is used to configure the emulation via EcoStruxure Machine Expert Twin and the communication between EcoStruxure Machine Expert Twin and the controller.

EcoStruxure Machine Expert Twin Visu for Lexium™ MC12 multi carrier

EcoStruxure Machine Expert Twin provides for emulation of mechatronic objects.

Trace Editor

The **Trace Editor** has been improved by cutting the name of variables from the left side.

User Documentation

An online help is available for network variable lists.

Mitigated Anomalies

EcoStruxure Machine Expert

ID	Description
CVE-2021-21863 CVE-2021-21864 CVE-2021-21866 CVE-2021-21867 CVE-2021-21868 CVE-2021-21869	Specific cybersecurity vulnerabilities are mitigated.
BOC-1285 / SI-16894	A NOTE has been added to the online help: NOTE: When associating a Boolean variable to an IEC step action, do not use this Boolean variable at another place throughout this SFC POU.
BOC-1579 / CDSYS-987	Unexpected state of outputs when located Boolean variables were mapped to these outputs.
BOC-1675 / CDSYS-1034	The conversion to EcoStruxure Machine Expert V2.0.0.1 resulted in an error being detected and EcoStruxure Machine Expert being closed.
BOC-1691 / SI-14713	The Controller Assistant did not allow to transfer the user rights management of a saved image.
BOC-1692 / CDSYS-1041	Trace editor: The variable name was cut from the incorrect side.
BOC-1697 / CDSYS-1040	Trace editor automatically adjusted the column width to the default when it was modified.
BOC-1719 / CDSYS-1052	An error was detected while drawing an FBD/LD network that was part of a source library included in a project.
BOC-1730 / CDSYS-1057	When activating property handling in all element properties in the Visualization Manager and associating properties of the Text Editor visualization element to POU Properties this led to an operational stop of the visualization.
BOC-1798 / DFPLAT-1889	M2• controllers imported incorrect default values of configuration data of an EtherNet/IP EDS (Electronic Data Sheet) device.
BOC-1815 / SI-15520	Logic Builder: When a project archive was opened that had been created with the present version, a message was displayed as if it had been created with a previous version.
BOC-1859 / SI-15726	A <i>NullReferenceException</i> was raised when attempting to mark entries in the Application Logger.
BOC-1923 / SI-16278	After installing only the component Machine commissioning and maintenance , Diagnostics was not starting.
BOC-1926 / SI-16279	A new version of the service tools is provided with EcoStruxure Machine Expert V2.0.3.
BOC-1954 / SI-16424	Download of the project was required even when the downloaded project had not been changed for the special case that a project was closed and reopened.
BOC-2019 / SI-17024	The online help described message logger functions that were not supported on M262 controllers.
BOC-2026 / SI-17032 / CVE-2013-2781	Specific cybersecurity vulnerabilities are mitigated.
BOC-2044 / SI-17051	Controller Assistant: The command <code>getFolder</code> did not copy the folder structure.

Known Operational Anomalies

EcoStruxure Machine Expert

ID	Description
BOC-1797 / SI-15849	Conversion of <i>smbp</i> files is not performed properly in EcoStruxure Machine Expert V2.0.1. Workaround: Convert the *. <i>smbp</i> project to EcoStruxure Machine Expert V1.1 SP1 and update it to EcoStruxure Machine Expert V2.0.*.
BOC-1830 / CDSYS-1114	When using a function block in a transition POU written in LD, the transition name cannot be assigned to a Boolean function block output.
BOC-1845 / CDSYS-1118	Using the same library in both Library Managers (global POU space and local below the Application node) has the effect that Parameter Lists cannot be configured for the global library and thus compiler errors are generated. Workaround: Do not use the same library in both Library Managers .
BOC-1848 / CDSYS-1121	A misleading precompile error C0201 is displayed when a project is opened in a new EcoStruxure Machine Expert instance. (Use case: An array is based on a GPL (Global Parameter List) constant and is connected to a VAR_IN_OUT of a function block.) The precompile error disappears after a Build .
BOC-1863 / CDSYS-1124	An issue occurs with SVN when using Save current values to recipe in the Persistent Variables editor. Workaround: Add a Recipe Manager before executing the (online) command.
BOC-1866 / CDSYS-1126	Parts (calculated time values) of the Advanced Trace Settings dialog box are not displayed when a system motion task was configured.
BOC-1894 / CDSYS-1140	An unexpected precompile error is detected while defining an array area with constants from an enumeration. Workaround: Initialize the enumeration values explicitly (or use CONSTANT variables instead).
BOC-1903 / CDSYS-1136	Incorrect address displayed for (a very special case of) arrays of structured variables in the declaration editor (in online mode).
BOC-1906 / CDSYS-1153	An error message is sporadically displayed when comparing projects and auto save is active.
BOC-1907 / CDSYS-1146	The cursor position is lost in the Project comparison view after committing accepted changes.
BOC-1919 / SI-16295	An invalid Guid (null object) is displayed in the device user management (in a very special case and after updating a controller image, adding a device user and disabling user management).
BOC-1937 / CDSYS-1151	Word wrap in combination with auto-complete does not operate correctly.
BOC-1946 / SI-16491	SDO (Service Data Objects) are modified when updating a project from SoMachine / SoMachine Motion to EcoStruxure Machine Expert (due to conversion of Lexium 32 A and Lexium 28 to other drive references).
BOC-1948 / SI-16422	Controller Assistant: An image read with a card reader cannot be transferred to the controller. Workaround: Delete potential pki folder from the image before transfer.
BOC-1949 / CDSYS-1154	With some projects, the flow control does not operate correctly.
BOC-1953 / CDSYS-1152	LibDoc: Malformed table errors (based on incorrect alignment of separator character " ") do not lead to a precise point in the source code comments.
BOC-1965 / CDSYS-1172	Refactoring modifies an internal variable name of a device when the name is already used by a global variable. Workaround: Do not rename a device if a global variable with the new name exists.
BOC-1977 / CDSYS-1157	The LD editor drawing is incomplete (incomplete horizontal link) due to the variable length.
BOC-1978 / CDSYS-1158	After a contact placed in a complex LD network after a closed parallel branch has been deleted, the network can no longer be displayed.
BOC-1979 / CDSYS-812	SmartCoding: The namespace of a variable is added in FBD/LD editors even so the corresponding option is deactivated.
BOC-1981 / CDSYS-1129	Trace editor: An incorrect diagram is selected in the Presentation (diagrams) tree view when selecting a diagram in the Trace view in case the Presentation (diagrams) tree contains variables or diagrams that are set to invisible.
BOC-1984 / SI-16782	The error message <i>Duplicate GUID</i> is displayed when copying a folder containing test cases and committing it to SVN.
BOC-1994 / CDSYS-1166	The visualization is set to offline mode if the cursor is moved to a specific button in the visualization.

ID	Description
BOC-1996 / SI-16785	A renamed user-defined motion profile is not available for smart coding. Workaround: Reopen the project after renaming.
BOC-2013 / SI-16923	Convert Device on a controller results in a corrupted internal state of a TM5 DTM used.
BOC-2022 / SI-17011	Executing the <code>savecontrol</code> command in the Controller Assistant leads to an error in the logfile.
BOC-2032 / SI-17055	EcoStruxure Machine Expert freezes when importing a motion profile into a specific project.
BOC-2033 / SI-17056	Deleting a user-defined motion profile leads to the fact that SVN also detects other motion profiles as changed, although they are not.

Motion Sizer

ID	Description
BOC-1896 / DFMS-2198	Result (Axis) view: Invalid gearbox values are not marked in red.
BOC-1991 / DFMS-2201	The Result (Axis) view is not updated after the motion profile has been changed.
BOC-2021 / DFMS-2202	In the load case Crank , a negative value is not possible for the parameters Minimum position of the slide and Maximum position of the slide .

Additional Information - C2C for Lexium™ MC12 multi carrier

General Information

For enabling a synchronized movement of carriers on different tracks in a Lexium™ MC12 multi carrier transport system, you can use the C2C network concept (controller-to-controller coupling network concept): two LMC controllers (LMC 1 and LMC 2) can be coupled via Sercos for enabling the synchronized movement of the carriers on the respective tracks.

- The SystemInterface function `FC_SetMasterEncoder()` is used to couple a **Lexium MC Carrier** object as a master encoder to a **C2C Encoder Output** in LMC 1.
- The order of calculations inside the real-time process (RTP) results in a delay of one Sercos cycle until the velocity is transferred from the carrier to the **C2C Encoder Output**.
- In LMC 2, a **C2C Encoder Input** can be used as a position source for the Multicarrier library method `IF_MoveSyncFromStandstill.StartSyncToExternalMaster()`.
- The parameter `DataDelay` of the **C2C Encoder Input** indicates the delay of the C2C network in milliseconds (ms). Additional delays can be input in the parameter `ApplicationDelay` of the **C2C Encoder Input**. For carrier synchronization, an additional delay of one Sercos cycle occurring on the **C2C Encoder Output** side of the C2C network must be input via the parameter `ApplicationDelay`. The method `IF_MoveSyncFromStandstill.StartSyncToExternalMaster()` uses both delay parameters `DataDelay` and `ApplicationDelay` to compensate for the delays.

Parameter *ApplicationDelay*

General

Type	ED
Devices supporting the parameter	C2C Encoder input
Offline editable	Yes
Traceable	Yes

Functional description

Input of additional delays on the **C2C Encoder Output** side of a C2C network.

Value range	Unit	Data type	Meaning
(-100...100)	ms	LREAL	The delay until the position value is transferred via C2C. The default value is 0.000 ms.

Interface *IF_C2CEncoderDelay* (SystemConfigurationLtf Library)

Overview

Type:	Interface
Available as of:	SystemConfigurationLtf_1.66.0.7
Inherits from:	–
Versions:	current version

Description

The interface provides the properties *DataDelay* and *ApplicationDelay*.

Name	Data type	Accessing	Description
<i>DataDelay</i>	LREAL	Read	Indicates the data delay to the original encoder signal in [ms]. The delay is identical for the C2C Encoder Input objects with the same ID in the entire C2C network (C2C Master and C2C Slaves).
<i>ApplicationDelay</i>	LREAL	Write	Input of additional delays on the C2C Encoder Output side of a C2C network in [ms]. The parameter can be set in offline mode.

Function *FC_SetMasterEncoder* (SystemInterface Library)

Overview

Type:	Function
Available as of:	SystemInterface_1.32.6.0
Versions:	Current version

Task

Pass the velocity signal of a master encoder to a Logical encoder or an encoder output (Incremental encoder output on the bus terminal **BT-4/ENC1** or synchronized encoder output on the encoder network).

Description

Master encoder
Lexium LXM62 Drive (LXM62DxS)
Lexium LXM52 Drive (LXM52)
Lexium ILM62 Drive Module (ILM62)
Virtual encoder (V_ENC)
Physical SinCos encoder (P_ENC)
Incremental encoder input (INC_IN) on PLC, on BT-4, on TM5
Sum master encoder (SMENC)
Sync. encoder input

Master encoder
C2C Encoder Input
Lexium MC Carrier
Slave encoder
Log. Encoder
Incremental Encoder Output on BT-4/ENC1
Incremental Encoder Output on TM5SE1MISC20005
Sync. encoder output
C2C Encoder Output

NOTE: Due to the order of calculations inside the real-time process (RTP), drives as, for example, Lexium LXM62 Drive, Lexium LXM52 Drive, Lexium ILM62 Drive Module and **Lexium MC Carrier** as a master encoder have an additional Sercos cycle delay until the velocity is transferred via the C2C network.

EcoStruxure Machine Expert V2.0.3.1

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M262	5.1.7.11

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

Mitigated Anomalies

M262

ID	Description
M262-12038	The Ethernet interface was not responding if no valid IP configuration was provided (Machine Expert application or/and post configuration).

M262 Motion

ID	Description
MSOLCTRL-1408	Repeatedly executed motion function blocks caused an M262 exception.

There are no additional known anomalies with this release.

Library Information

Version Identification

Description	Version
MotionApplicationFunctionBlocks	V1.0.4.0

New Features

MotionApplicationFunctionBlocks

This new library provides function blocks to control a machine that performs operations on a moving part. Typical operations are cutting, clamping, stamping, marking, sealing.

Known Operational Anomalies

ID	Description
MSOLSW-1490	When warm start mode (<i>ET_StartMode.MoveToCurvePosition</i>) is executed a second time, it can happen that the slave is not moving to the curve position. Workaround: Re-enable the <i>FlyingShear</i> function block (cold start) instead of executing the start mode <i>MoveToCurvePosition</i> a second time.
MSOLCTRL-1695	<i>FlyingShear</i>: In rare cases during warm start the incorrect curve is loaded and the message <i>InvalidCamTableId</i> is displayed at <i>q_sResultMsg</i> and the slaves do not start. Workaround: Re-enable the function block <i>FlyingShear</i> (cold start).

Software Information

There is no additional software information for this release.

EcoStruxure Machine Expert V2.1

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M241	5.1.10.10
M251	5.1.10.10
M262	5.1.7.23
TMSES4	1.0.0.8
TM3BCCO	2.1.50.2
TM3BCEIP	2.4.0.3
TM3BCSL	2.1.50.2
TM3•HSC202•	2.0
TM3DI8	2.0
TM3DI8G	2.0
TM3DI16	2.0
TM3DI16G	2.0
TM3DI16K	2.0
TM3DI32K	2.0
TM3DM8R	2.0
TM3DM8RG	2.0
TM3DM24R	2.0
TM3DM24RG	2.0
TM3DQ8••	2.0
TM3DQ16••	2.0
TM3DQ32••	2.0
TM5NEIP1 / TM5NEIP1K	3.12
TM5NS31	2.79
LXM32••••M2 / LXM32S•••N4	• Drive firmware: V1.12.2 • Sercos3 interface firmware: V1.12.02
LXM52••••C•••••	1.54.26.0
ILM••••••••••	1.54.26.0
LXM62••••C•••••	• 1.64.11.0 for hardware revision RS1• • 1.54.27.0 for hardware revision RS0•
LXM62••••D•••••	• 1.64.11.0 for hardware revision RS1• • 1.54.27.0 for hardware revision RS0•
LXM62••••E•••••	1.54.27.0
LXM62••••F•••••	1.54.27.0
LXM62••••G•••••	1.64.11.0
LMC Eco	1.72.19.1
LMC Pro	1.72.19.1
LMC Pro2	1.72.19.1
ATV340S	• Drive firmware: V1.4IE09_B06 • Sercos3 interface firmware: A1.2IE01_B00

Description	Safety-related Firmware Version
LXM62....E.....	1.2.5.0 SLCv1 1.3.3.0 SLCv2
LXM62....F.....	1.2.5.0 SLCv1 1.3.3.0 SLCv2
VW3E702200000 safety option module	1.2.5.0 SLCv1 1.3.3.0 SLCv2
TM5CSLC100FS	2.59
TM5CSLC200FS	2.59
TM5CSLC300FS	3.05
TM5CSLC400FS	3.05
BWU2984 SWID	134253
BWU2984 Safe CPU A	135115
BWU2984 Safe CPU B	135116
ASIMON360	3.2.6.7

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

New Features

TM5CSLC•00FS, TM5/TM7••FS, LXM62/ILM62 Safety

Two new Safety Logic Controller references have been added: TM5CSLC300FS and TM5CSLC400FS (SLCv2 system SLC, page 233)

TM5CSLC300FS and TM5CSLC400FS have a reduced device width (saving installation space) and a reduced power consumption. Compatible wiring interface allows for easy migration. The device marking has been improved (a QR code is provided that links to the product page, function switch).

The new safety-related timing management of the SLCv2 system provides conformity to the latest safety-related fieldbus standard evolutions (IEC61784-3) and improves system robustness.

The new setup mode function allows you to ignore the module replacement / firmware change acknowledgement requests during the commissioning phase.

For the SLCv2 system:

- The latest TM5/TM7••FS module firmware is provided incorporating the latest quality improvements and the new safety-related timing management.
- Updated LXM62/ILM62 Safety Drive Safety Module (DSM) firmware is provided incorporating the new safety-related timing management.

LMC• FDR (Fast Device Replacement) has been extended for easy safety-related TM5/TM7••FS and DSM firmware updates.

M241 / M251

Support of the fast TCP connection mode.

M262

New safety-related features:

- The SLCv2 system and the new devices TM5CSLC300FS and TM5CSLC400FS have been integrated.
- The firmware version verification feature has been implemented to help ensure consistency of the safety-related firmware used to the SLCv1 / SLCv2 system setup firmware definition. For further information, refer to the chapter *Compatibility EcoStruxure Machine Expert - Safety*, page 234.
- Quality improvements

OPC UA Method Call:

The OpcUaHandling library has been extended by new function blocks for method calls based on the PLCopen OPC UA Client for IEC 61131-3. With this new feature, Modicon M262 Logic/Motion Controllers can invoke methods implemented inside OPC UA servers. It enables Modicon M262 Logic/Motion Controllers to perform one more step in Machine to Machine (M2M) towards communication via OPC UA.

FB_Drive_PosControl:

The new library Extended Motion (EXM) provides the new function block *FB_Drive_PosControl* allowing position control loop inside the controller. *FB_Drive_PosControl* needs the target position, the position feedback from a variable and some configuration to tune the control loop and to provide an output variable with the speed setpoint to control a Variable Speed Drive in speed mode. It can be used for analog outputs and fieldbus communication managed by Modicon M262 Logic/Motion Controllers. This feature allows Modicon M262 Logic/Motion Controllers to manage position control for low performance position control with a speed drive.

MC_CamIn Enhancement:

New improvements involving *MC_CamIn*:

- Support of *MC_DigitalCamSwitch*: Allowing to activate up to 32 digital outputs based on the axis position.
- The new *FC_GetCamSlaveMovementFromGivenMasterForMultiCam* calculates the slave target position based on the master position coupled with cam profile.
- Two inputs have been added to *MC_CamIn* to scale the master or slave position.
- Support of cubic interpolation, improving profile quality, achieving smooth movement between the cam points.
- Support of linear interpolation for non-equidistant curve tables.

Motion Profile Generator:

- New improvement in the Motion Profile Generator helping to provide more control to the user in the deceleration of the motion profiles.
- CNC libraries are supporting modulo axis.

Diagnostics and Administrative Function Blocks from PLCOpen:

The following function blocks have been added to read axis parameters in accordance with the PLCOpen standard:

- *MC_ReadStatus*
- *MC_ReadMotionState*
- *MC_ReadAxisInfo*
- *MC_ReadAxisError*
- *MC_ReadActualPosition*
- *MC_ReadActualVelocity*
- *MC_ReadActualTorque* (for LXM32S)

PacDrive LMC Control

- Possibility to add additional symbol sets when exchanging data through OPC UA.
The additional symbol sets allow you to set different access levels for clients.
- Support of native OPC UA data exchange for arrays and structures.
 - In accordance with the OPC UA standard it is now possible to exchange the entire array/structure, not only element by element
 - The mechanism *IndexRange* is provided for element by element exchange.
- Boot encryption is now enabled.

New safety-related features:

- The SLCv2 system and the new devices TM5CSLC300FS and TM5CSLC400FS have been integrated.
- Extension of the FDR (Fast Device Replacement) to support automatic update of TM5/TM7•FS modules and DSM safety-related firmware.
- The firmware version verification feature has been implemented to help ensure consistency between the safety-related firmware and the SLCv1 / SLCv2 system setup firmware definition. For further information, refer to the chapter *Compatibility EcoStruxure Machine Expert - Safety*, page 234.
- Quality improvements

Mitigated Anomalies

HMISCU Controllers

ID	Description
CVE-2021-29241	Specific cybersecurity vulnerabilities were mitigated.

Lexium™ MC12 multi carrier

ID	Description
METWIN-599	While starting the emulation of the Lexium™ MC12 multi carrier, some carriers could not be displayed at the correct position on the track.

M241 / M251

ID	Description
M2X1-109	The new compiler definition ' <i>ETH2_NVL_Communication</i> ' has been added to control the NVL (Network Variables List) from Ethernet.
M2X1-836	The Acknowledge button no longer disappears when an error was detected in the CanOpen Manager .
M2X1-838	M241 / M251 logic controllers no longer become unresponsive if too many <code>READ_VAR</code> commands are received in parallel.
M2X1-967	The output <i>HSC_Err</i> is now reset after a new input pulse is received from <i>PeriodMeter</i> .

M262

ID	Description
M262-4344 / M262-4347 / M262-4350	The TMSES4 module was unable to recover from error states due to network storms while presenting a detected error in LED diagnostics.
M262-4345	Multiple TMSES4 modules were not separated when restarting the controller. This could lead to network storms.
M262-6087	With specific configurations, the MOD STS LED flashed red without a connection error detected.
M262-9486	An incorrect diagnostic message was displayed for TMSES4 modules in the System Diagnostic information.
M262-11877	The <i>IOS_GETDIAGSTATUS</i> function was not updating values after reset if no communication had been established with the device.
M262-11960	The IGMP (Internet Group Management Protocol) was not operating on the interfaces ETH2 and TMSES4. Protocols using multicast such as EcoStruxure Cybersecurity Admin Expert discovery or EtherNet/IP T->O connections sometimes had unintended behavior if the Modicon M262 controller was connected through a smart switch with IGMP snooping enabled.
PEP1009996R / M262-11761	If the <i>FB_ControlClone</i> had been used without clone access rights, it was required for future clone actions.
PEP1024146R	The alignment of OPC UA structure variables was incorrect in Modicon M262 controllers.
PEP1028888R	With a certain network configuration the TMSES4 module the firmware version 1.0.0.8 may be disrupted. Workaround: Updating to firmware version 1.0.1.2 will solve the issue.

M262 Motion

ID	Description
MK-974	While enabling a vertical axis, a small drop of the axis could be observed. This resulted from the gravity effect on the motor load for the time it took between requesting the enable and finalizing it.
MK-1048	The SLC remote controller displayed phase -1 when trying to set Sercos phase to 0 and it displayed phase 0 when trying to set Sercos phase to -1.
MK-1213	When you disabled the axis while running in CSV mode, the axis could freeze for a few cycles (~5 cycles). This freeze could be heard on the motor shaft. If this axis was master of another axis (for example, <i>MC_GearIn</i>), this freeze could be visible on the slave axis.

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-4750	Unavailable devices were sporadically creating not documented runtime errors.
LMCFW-5386	An invalid user account was detected after a cold reset of the controller.
LMCFW-5477	Depending on the project, the <i>AvailableLoad</i> could be impacted when device diagnostics was activated.
LMCFW-5920	An FDR (Fast Device Replacement) timeout could occur for the firmware update of LXM62 Plus.
LMCFW-6469	<i>FC_GetParLogAddrByName</i> did not work properly with <i>UserFunctions</i> .
LMCFW-6533	The Fast Device Replacement (FDR) was unresponsive in some applications when C2C and Safety Logic Controllers (SLC) were used.
LMCFW-6602	<i>SystemInterface.GetRefPositionLastCycle</i> did not handle <i>SetPos</i> correctly.
LMCFW-6960	The generic EtherNet/IP device description was not available for PacDrive.
LMCFW-7280	The function <i>GetMasterDiag</i> was not working for Profinet.
LMCFW-7285	The EtherNet/IP Adapter was not properly registering the data area for an explicit message.

Known Operational Anomalies

Safety System

ID	Description
SSP50-10052	The TM5CSLC300FS/400FS is going to the safe state when the memory key is removed during the SK-COPY function triggered by the <i>SLCRemoteController</i> interface. Workaround: Use the local HMI on the Safety Logic Controller (SLC) to execute the copy, continue copy function.
SSP50-10188	The Fast Device Replacement (FDR) firmware update for safety I/O modules is not possible for modules that are placed behind a missing or dummy module type in a bus coupler I/O island. Workaround: - Do not setup safety I/O modules behind a dummy module in a bus coupler island. - Ensure that the module electronics are plugged on the intended bus bases.
SSP50-10269	The <i>ConfigID</i> parameter for an AS-i gateway BWU 2984 is set to the default value during the project migration from the SLCv1 to the SLCv2 system. Workaround: Read the <i>ConfigID</i> from the BWU 2984, display and set the parameter back to the intended value.
SSP50-10489	The safety-related system firmware verification feature (<i>FWVersionCheck</i> = TRUE) blocks the Sercos phase-up in case a safety-related device is defined as optional and is not physically available in the machine setup. Workaround: - Disable the safety-related system firmware verification feature (<i>FWVersionCheck</i> = FALSE) and verify manually that the intended certified firmware versions are installed in your safety system depending on the SLCv1 or SLCv2 firmware table definition provided in the <i>Compatibility EcoStruxure Machine Expert - Safety</i>, page 234 chapter of this Release Notes document. - Do not use an optional feature for safety-related devices and ensure that the safety-related devices are physically available during the Sercos phase-up.

Lexium™ MC12 multi carrier

ID	Description
LMCFW-6626	Positions of carriers are not set to zero when <i>PhaseSet</i> of Sercos is set to 0.
LMCFW-7153	In some cases, not all error messages are displayed in the Message logger.
LMCFW-7331	Under certain conditions it is not possible to enable carriers by setting <i>EnableSet</i> to TRUE if safe drives and a high number of devices are used within the Sercos.
MLS-1898	Carriers which have been added to segments during active Safe Force Off (SFO) are not detected automatically after deactivation of SFO and normal operation of the track is reestablished. This can result in collisions with existing carriers. Workaround: Add carriers exclusively to disabled tracks. After you have changed the number of carriers attached to a track, cycle the Sercos phases (CP0 ->CP4). <i>NOTICE</i> INOPERABLE EQUIPMENT - Do not add carriers to enabled tracks (during Sercos phase other than CP0). - Be sure to reboot the Sercos communications after adding new carriers. Failure to follow these instructions can result in equipment damage.
MTLC-3648	During Sercos phase-up, the diagnostic message <i>8562: Carrier negotiation communication error detected</i> can be triggered.
MTLC-4031	During Sercos phase-up, the diagnostic message <i>8508 Sercos run-up not possible</i> can be triggered.
MTLC-4066	Under certain conditions, the diagnostic message <i>8551 Uncontrolled carrier received</i> is triggered although no segment is in error or disabled state.

ID	Description
MLTC-4095	The following diagnostic messages cannot be reset using <i>FC_Diagquit()</i>: 8125 - Motor load high 8568 - Segment coil load is high 8126 - Power stage temperature high 8127 - Motor temperature high 8161 - Control board temperature high 8132 - Tracking deviation limit exceeded 8169 - Sercos slave comm. disturbance detected 8186 - DC bus voltage high Workaround: Cycle the Sercos phases (CP0 ->CP4).
MLTC-4104	If a carrier is placed close to the transition between start and end segment of a closed track (± 1.7 mm), it is possible that the carrier will be incorrectly assigned to the adjacent segment. This leads to receiving either the last or the first logical ID incorrectly.

M241 / M251

ID	Description
M2X1-949	A File Transfer Protocol (FTP) with encryption enabled is not operational under WAN (Wide Area Network).
M2X1-1037	Long occurrences of OPC UA connection/disconnection lead to memory leak.

M262

ID	Description
M262-11937	OPC UA-signed certificates are modified by OPC UA when the IP address changes.
M262-12079	IO-Link: Some IODD1.1 files may not be supported.
M262-12196	The <i>ReadList</i> function block leads to incompatibilities when using EcoStruxure Machine Expert < V2.0 with EcoStruxure Machine Expert V2.1 firmware for Modicon M262 Logic/Motion Controllers.

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-6477	The IO-Link parameter cannot be written to the device during Sercos phase-up.
LMCFW-6480	A deactivated IO-Link channel/device may not provide the present state at module I/O mapping.
LMCFW-6777	The output frequency of the TM5SE1MISC20005 may not be stable for a constant velocity.
LMCFW-7171	After the diagnostic message <i>8902 Software error (page fault)</i> was triggered and a PacDrive LMC controller was restarted, the Application.app may no longer be present in the memory card of the controller.
LMCFW-7192	An <i>8902 Software error (page fault)</i> error can be detected with <code>t=TskSafetyLog</code> .
LMCFW-7274	The Profinet task cycle time may increase if the cable is disconnected.
LMCFW-7309	The PacDrive LMC controller as OPC UA client applying <i>SE_OPC.UA_Browse</i> can browse the application but not server items.
LMCFW-7316	A hardware watchdog may occur on a Profinet communication after running for 3...4 weeks.
LMCFW-7319	The number of Sercos devices may reduce the number of C2C slaves.
LMCFW-7320	An incompatible change is detected with <i>CmplecTask.lecTaskResetStatistics</i> .
LMCFW-7354	The boot phase of the IO-Link controller may be interrupted depending on the controller settings in the dialog box PLC Settings. Workaround: Configure the PLC Settings tab to update variables with one bus cycle task.

ID	Description
LMCFW-7362	An issue is detected when using the <i>FC_UserAdd</i> and the user rights management is disabled.
LMCFW-7363	The input data of the Profinet module may be moved after an online change.

Library Information

Version Identification

Description	Version
ApplicationLogger	1.1.7.0
AsyncManager	1.0.8.0
AutoTune	1.3.15.0
CNCExtension	1.0.5.0
CertificateHandling	1.1.5.0
CollisionDetection	1.0.1.0
CommonMotionInterface	1.4.4.0
CommonMotionTypes	1.0.3.0
CommonPouTypes	1.0.5.0
CommonToolbox	1.0.5.0
CrankModule	1.4.0.0
DigitalTwinCommunication	1.0.2.0
EMailHandling	2.1.3.0
EtherNet/IP Explicit Messaging	1.1.14.0
EtherNet/IP Remote Adapter	1.1.4.0
FastSampling	1.0.2.0
FeatureNotSupported	2.0.1.0
FileFormatUtility	1.5.17.0
FtpRemoteFileHandling	1.4.7.0
GMC Independent Altivar	1.3.3.0
GMC Independent Lexium	1.2.8.0
GMC Independent PLCopen MC	1.3.8.0
GeoMath	1.0.1.0
Hoisting	5.0.3.0
HttpHandling	1.3.6.0
IoLinkHandling	1.2.6.0
IoTCloudCommunication	1.0.9.0
Lexium 28	1.6.2.0
M262Diagnostics	1.0.10.0
MachineAssistantServices	1.0.6.0
Mathematics	1.0.3.0
ModbusHandling	1.0.8.0
MotionApplicationFunctionBlocks	1.0.11.0
MqttHandling	2.2.3.0
Multicarrier	1.0.18.0
MulticarrierStation	1.0.3.0
OpcUaHandling	2.2.6.0
PD_AxisModule	1.7.0.0
PD_ETest	1.6.0.0
PD_GlobalDiagnostics	1.5.0.0

Description	Version
PD_MultiBelt	1.6.0.0
PD_MultibeltModule	1.6.0.0
PD_PacDriveLib	1.10.1.0
PD_SmartInfeed	1.5.0.0
PD_SmartInfeedModule	1.5.0.0
PD_SoMotionGenerator	1.9.2.0
PD_Template	1.8.0.0
PLCCommunication	1.0.4.0
PLCopen MC part 1	2.13.3.0
PackML	1.2.4.0
PreventaSupport	1.1.8.0
ProxyCommunicationSupport	1.0.6.0
Robotic	3.6.5.0
RoboticModule	2.17.0.0
SchneiderElectricRobotics	2.14.0.0
SchneiderElectricRobotics Parameters	2.18.1.0
SchneiderElectricRobotics Toolbox	1.7.4.0
Sercos3PlcOpenMc	1.4.1.0
SercosCommunication	1.2.4.0
SercosDriveUtility	1.2.2.0
SercosIpClient	1.0.5.0
SlcRemoteController	1.4.4.0
SnmpManager	1.2.3.0
SqlRemoteAccess	2.0.8.0
TcpUdpCommunication	2.2.13.0
TeSys Library	3.0.1.0
TeSys_island	2.0.6.0
TimeSync	1.1.6.0
Toolbox	3.0.2.0
TransportSystemCommunication	1.1.1.0
TwidoEmulationSupport	1.2.6.0
Unwinder	1.4.0.0
UnwinderModule	1.3.0.0
UserMotorTypePlate	1.4.0.0
UserTorqueFeedForward	1.3.0.0
XpsuSupport	1.0.6.0

Version Identification Smart Templates

Description	Version
SMT_ESME_Axis	2.2.1.0
SMT_ESME_Camera	2.3.1.0
SMT_ESME_Conveyor	2.3.1.0
SMT_ESME_Robot Cartesian	1.1.3.0
SMT_ESME_Robot P-Series	2.4.2.0
SMT_ESME_Robot T-Series	2.3.1.0
SMT_ESME_RobotCell	1.1.0.0
SMT_ESME_Sensor	1.2.0.0

Version Identification Template Libraries

Description	Version
Altivar Device Templates	5.2.4.0
CANopen Device Modules	5.2.5.0
Communication Functions	1.3.8.0
EtherNet/IP Device Modules	5.2.16.0
Hardwired Device Modules	5.2.1.0
ModbusSL Device Modules	5.2.3.0
ModbusTCP Device Modules	5.2.3.0
Sercos Device Modules	1.1.5.0

New Features

Signed Libraries

All libraries are integrated as signed libraries (compiled-library-v3).

AsyncManager

The new interface *IF_AsyncManager2* provides additional information about the status of jobs and the number of tasks created.

EmailHandling

FB_SendEmail: The new parameter *etTlsMode* has been added which supports the STARTTLS mode.

EtherNet/IP Explicit Messaging

Timeout settings are taken into account after a **Reset Cold**.

GMC Independent Altivar

A new library diagnostic code *InvalidLengthOfData* has been added.

GMC Independent PLCopen MC

A new library diagnostic code *InvalidLengthOfData* has been added.

HttpHandling

Support of:

- OAuth protocol:
 - Resource Owner Password Flow
 - Client Credentials Flow
- Proxy handler provided by the ProxyCommunicationSupport library

IoLinkHandling

- A new function *FC_GetIoLinkMasterConnectionStatus* to retrieve the connection status of the IO-Link master is provided.
- A new function block *FB_EventLogger* to log the IO-Link events is provided.

IoTCloudCommunication

This new library provides functionalities to support the communication with IoT cloud services. It implements function blocks to connect and to transmit data to the monitoring Application Programming Interface (API) of the EcoStruxure Machine Advisor.

Multicarrier

- Interfaces to connect a robot to a carrier have been added.
- *MovePureSmg*: It is now possible to execute a *Setpos* on the three channels (new method *SetposRelativeChannelABC*).
- *MoveGapControl*: A constant gap in a group of carriers is preserved during movement.

MqttHandling

The function block *FB_MqttClient* supports the connection to an MQTT broker without specifying a client ID.

OpcUaHandling

- New function blocks implementing the method call functionality have been added.
- Support of node identifier type GUID.
- Support to read partial array in case the specified indexes on client side are out of range.

PD_PacDriveLib

The new interface *IF_AsyncManager2* provides additional properties for information about the status of jobs and the number of tasks created.

PD_SmartInfeed

No *UnknownFeedback* error is detected by the Touchprobe filter due to timing difference of the edge in the *Value* signal and the *CaptureOk* signal of the touch probe.

Robotic and RoboticModule

The feature tracking source has been integrated.

SchneiderElectricRobotics and SchneiderElectricRobotics Parameters

- Support of EcoStruxure Machine Expert Twin.
- New method *GetRobotData* has been added.

SlcRemoteController

- New features to clear data and to activate and deactivate the setup mode for the Safety Logic Controllers SLC300 and SLC400 have been integrated in the library.
- Provides extended status information at an output of the *FB_RemoteController* function block.

SnmpManager

FB_SnmpManager: The default value for the communication name for a SET request is *private*.

SqlRemoteAccess

- *FB_SqlDbRequest*: Improved diagnostic message at the output *q_sResultMessage* if the result *CertificateNotFound* is indicated at the output *q_etResult*.
- Empty data fields (NULL string) are now processed correctly.

New Features - Examples

OpcUaHandling Example

The example has been updated according to the modifications which were performed in the OPC UA server of the PacDrive LMC controller.

The access to an array of an OPC UA sever on a PacDrive LMC controller is implemented using a single node in conjunction with the indexes of the array.

RTC Control Example

Setting the timezone parameter has been modified to provide a proper conversion from UTC (Universal Time Coordinated) to Central Daylight Time (North America) using the function *SysTimeRtcConvertUtcToLocal*.

SlcRemoteController Example

- Handle new values of the enumeration *ET_State* inside the state machine.
- The SLC is configured to type SLC400.
- Extended status information is provided on the visualization and buttons have been added for the new setup mode and for clearing data.
- Buttons are now hidden on the visualization while the SLC is scanning and is unable to execute other commands.

Machine Advisor Communication Example

A new example is provided for the implementation of the communication with the EcoStruxure Machine Advisor service with the help of the IoTCloudCommunication library.

New Features - Function Templates

SntpClient

A new function template SntpClient is available which provides the implementation of the *FB_SntpClient* of the TimeSync library.

Lexium_32S_Sercos

The function template Lexium_32S_Sercos uses feedback values to update the variables for the actual velocity and the actual position of the axis.

Mitigated Anomalies

ID	Description
BOC-671 / IECLIB-2577	SmartInfeed: Filter setting caused error “unknown feedback” when <i>IdleDistanceAfterPosEdge</i> = <i>G_IrProductLength</i> .
BOC-1576 / IECLIB-18927	PD_MultiBeltModule: If movement values had been used to home the MultiBelt which exceeded the maximum defined in <i>UserMaxVel</i> and <i>UserMaxAcc</i> an error was detected as designed. Nevertheless, the message did not indicate the reason and displayed a general <i>UnexpectedFeedback</i> message instead.
BOC-1799 / IECLIB-22934	TwidoEmulationSupport: No more access violation when the amount of bits is lower than eight.
BOC-1891 / IECLIB-23416	GMC Independent Altivar: An additional output <i>q_wStatusword</i> has been added to get access to the current drive status.
BOC-1929 / IECLIB-23450	RTC Control Example: Setting the timezone parameter has been modified to provide a proper conversion from UTC (Universal Time Coordinated) to Central Daylight Time (North America) using the function <i>SysTimeRtcConvertUtcToLocal</i> .
BOC-1950 / IECLIB-23499	SnmpManager: The default value of the communication name for a SET request is <i>private</i> .
BOC-2009 / IECLIB-23699	SqlRemoteAccess: Empty data fields (NULL string) are now processed correctly.
BOC-2020 / IECLIB-23750	FtpRemoteFileHandling: When enabling the function block <i>SE_FTP.FB_FtpClient</i> while the FTP server is not reachable, the <i>q_etResult</i> indicates <i>UnableToEstablishConnection</i> after initializing.
BOC-2034 / IECLIB-23769	The tab Log in the device editor and the instance methods GetDeviceState and Enable were not supported by the preinstalled CANopen devices, such as Altivar and Lexium.
BOC-2035 / IECLIB-23768	IoLinkHandling: In the online help, section <i>FB_RegisterEvent</i> , the input <i>IF_IoLinkMaster</i> was described instead of <i>IF_IoLinkEvent</i> .
IECLIB-22687	FileFormatUtility: <i>FB_JsonUtilities</i> : The result message provides more details when parsing is unsuccessful.
IECLIB-23433	PD_SoMotionGenerator: A cam job is executed on the SoMotionGenerator which follows a master of type drive and on very specific timings during the acceleration phase of the master, a <i>setpos</i> is executed on the master drive. In this situation it could happen that the logical master position of the SoMotionGenerator channel displayed a small difference to the movement of the master drive. This difference could sum up over multiple occasions to result in a reasonable difference between the logical master and the master drive. Now the logical master position follows the master movement.
IECLIB-23494	TcpUdpCommunication: The start date of the default certificate is now set according to the Real Time Clock (RTC) of the controller.
IECLIB-23500	CNCExtension: <i>FB_ControlAxisByPosCNC</i> now supports modulo axes.
IECLIB-23703	TcpUdpCommunication: Improved clean-up of the Transport Layer Security (TLS) context in case of closing the TCP client/server while connecting/opening.
IECLIB-23742	TcpUdpCommunication: Corrected the clean-up of the default Transport Layer Security (TLS) context while resetting the application in case the corresponding client or server is already closed.
IECLIB-24337	PD_SoMotionGenerator: The logical master channels B and C are now disconnected correctly after the cam job has been completed.
IECLIB-24623	GMC Independent PLCopen MC: It is now verified whether the input <i>Length</i> of the <i>MC_WriteParameter</i> function block contains a valid value (1...4).
IECLIB-25248	Multicarrier: The carrier is loaded with the method <i>StartSyncToCarrierInFront</i> . During the movement it is now possible to overwrite the method with the move command <i>MoveGapControl</i> .
IECLIB-25257	Multicarrier: A configured velocity limitation is now considered when the input target is equal to the track length and the enumeration <i>ET_PosMode</i> is set to <i>RelativeForward/RelativeBackward</i> .
IECLIB-25264	Multicarrier: The move command <i>MoveGapControl</i> considers a minimum gap of the next carrier if the following conditions apply: - The carrier behind is loaded with <i>ET_PosMode</i> is set to <i>RelativeForward</i> and the target is equal to the track length. - Both carriers are started at the same time.
IECLIB-25593	Multicarrier: <i>StartSyncToCarrierInFront</i> : The curve compensation is now working with <i>ToolPivotPoint (0,0,0)</i> .
IECLIB-25614	MotionApplicationFunctionBlocks / <i>FlyingShear</i> : The slave axis was not moved to the curve position when the warm start mode <i>MoveToCurvePosition</i> was executed.

ID	Description
IECLIB-25615	MotionApplicationFunctionBlocks / <i>FlyingShear</i> : Executing a cold start of the <i>FlyingShear</i> function block could lead to a shift between master and slave when using different master velocities or different task cycle times. This shift could lead to an inaccurate length of the processed products. The cold start is now executed independent of the master velocity and the task cycle time.
MSOLCTRL-1695	MotionApplicationFunctionBlocks / <i>FlyingShear</i> : In rare cases during warm start the incorrect curve was loaded and the message <i>InvalidCamTableId</i> was displayed at <i>q_sResultMsg</i> and the slaves did not start.

Known Operational Anomalies

ID	Description
DFBOC-2211 / IECLIB-25962	CommonToolbox: The output <i>q_sResultMsg</i> of the methods <i>FB_RuntimeMeasurement.Start</i> and <i>FB_RuntimeMeasurement.End</i> indicate no message if the execution was successful.
DFBOC-2232	Multibelt: Different values for <i>lrTrainsDistance</i> in Station1 and Station2 lead to backward movement of the train in Station1.
DFBOC-2238 / IECLIB-26024	Lexium 28: The axis stops when executing <i>MC_MoveVelocity_LXM28</i> followed by <i>MC_MoveRelative_LXM28</i> .
SSP50-10163	SlcRemoteController: The memory key commands <i>CopySafeKeyStart</i> and <i>CopySafeKeyContinue</i> cannot be executed via the SlcRemoteController library if used with the TM5CSLC300FS/400FS. Workaround: Execute this function using the HMI on the front of the Safety Logic Controller (SLC) as described in the <i>Safety Logic Controller TM5CSLCx00FS Hardware Guide</i>.

Software Information

Version Identification

Description	Version
Schneider Electric Software Installer	21.22.33302
EcoStruxure Machine Expert Twin	1.2.0.0
Diagnostics	21.0.18.0
Controller Assistant	21.0.18.0
Device Assistant	21.0.14.0
DiffViewer	21.0.22.0
Gateway	21.0.12.0
Launcher	21.0.22.0
NetManage Server	21.0.11.0
OPCServer	3.5.16.60
SoftSPS	3.5.16.90
SVN	4.2.7.0
Logic Builder ⁽¹⁾	2.1.0.0
Vijeo-Designer	6.2.12.2054
Codesys	V3.5 SP16 Patch9 HF1
SQL Gateway	2.1.0.0
Motion Sizer	4.3.1.0
(1) If you are using a virtual machine, the download of the online help operates correctly only if the option Accelerate 3D graphics is deactivated in the VM settings.	

Version Identification of DTMs

Description	Version
Advantys OTB	11.1.0.0
ATV320	1.4.1.0
ATV340	3.2.3.0
ATV6xx	3.3.1.0
ATV9xx	3.3.3.0
Harmony XB5R	1.0.41
Lexium 28 A	1.6.0.08
Lexium 28 S	1.6.13.0
Lexium 32 A	1.20.04.2
Lexium 32 C	1.20.04.2
Lexium 32 i	1.20.04.2
Lexium 32 M-S	1.20.04.2
Modbus Serial Communication	2.6.12
Modbus TCP Communication	2.6.12
TeSys island	2.2.1.0
TeSysT	2.14.1.0
TeSysU	2.8.0.0
TM5-7 CANopen Interface	1.1.8
TM5-7 Expansion Module	1.1.8

New Features EcoStruxure Machine Expert

Editor History

Three buttons have been added to the toolbar. You can now see the last cursor position in different editors including device editors and code. This allows you to jump to the last cursor position to speed up the change on different code positions during commissioning.

IO-Link Editor

The column **Online value** and the two buttons **Save online values** and **Restore values...** have been added. The button **Read this Page** reads the IO-Link data into the new column (no longer into the **Value** column). This means that IO-Link data can be read without a new download request. In EcoStruxure Machine Expert V2.0.3.1 a download was required after reading parameter data of an IO-Link device via the IO-Link Editor.

SQL Gateway

In EcoStruxure Machine Expert V2.1, the database drivers for MySQL and SQLite were replaced. This has effects on the following functions:

- For MySQL the SharedMemory communication protocol is no longer supported.
- For SQLite password-protected database files are no longer supported.

- Various advanced properties are no longer supported. If you make use of advanced properties in your database connections, verify if these properties are still supported.

NOTE: Click **Advanced Properties** for the database connection. If properties are displayed with the suffix **[NOT SUPPORTED]**, verify that the database connection is still running as expected.

Miscellaneous

A new feature has been added when configuring a TM3 Bus Coupler on Modbus TCP. You can now enable or disable all channels defined on a scanner in relation to a bus coupler. A new method *ControlChannels(BOOL enable)* is available on TM3 Bus Coupler devices when connected behind Modbus TCP scanner. This method allows you to enable or disable all channels related to this bus coupler device and used by the Modbus TCP scanner.

Network variable exchange has been improved for Ethernet IP on Modicon M241 and M251 Logic Controllers. Previously, it was necessary to have an active connection on the Ethernet 1 port before NVL exchanges would initiate. A new compiler definition of *ETH_NVL_Communication* is now available to allow the start of NVL exchanges as soon as an ETH2 connection is active (and not necessarily restricted to ETH1).

New Features EcoStruxure Machine Expert - Safety

In EcoStruxure Machine Expert - Safety V2.1, the two new Safety Logic Controller references TM5CSLC300FS and TM5CSLC400FS are introduced and integrated.

The integrated safety solution now differentiates the two system setups:

- SLCv1: The legacy TM5CSLC100/200FS and corresponding safety-related device firmware and descriptions.
- SLCv2: The new TM5CSLC300/400FS and corresponding safety-related device firmware and descriptions.

For the SLCv1 system, existing applications can be used after project update without additional modifications.

The SLCv2 system offers many new features advantages over SLCv1 configurations. Consider using SLCv2 for all new machine designs predicated on EcoStruxure Machine Expert - Safety V2.1.

The SLCv2 safety system provides the following new features:

- TM5CSLC300FS and TM5CSLC400FS Safety Logic Controllers
 - Reduced width and power consumption
 - Improved marking (QR code, function switch)
- Latest TM5/TM7••FS module and Drive Safety Module (DSM) firmware versions delivered with Schneider Electric Software Installer.
- Update the system to be compatible to the latest safety fieldbus standard evolutions.
- New and more application-oriented, easy safety-related timing setup procedure resulting in enhanced robustness of the safety sub-system.
- Setup mode function added for Safety Logic Controller (SLC).
- Online/offline help and diagnostics adapted.

For LMC controller-based systems, the existing Fast Device Replacement (FDR) feature was extended to support, in addition to Sercos device update, automatic TM5/TM7••FS slices and DSM safety-related firmware updates.

The Fast Device Replacement (FDR) function extension for safety-related device firmware supports and simplifies the process for the system and maintenance engineer to help ensure correct and consistent machine safety-related device

setup with the intended and certified firmware versions of the defined safety-related application.

NOTE:

The Fast Device Replacement (FDR) update process duration can vary and depends on:

- The safety-related device type variants used in your system.
- The distribution of the safety-related device type variants in your system architecture. For example, if the same slice is used per I/O island, or if there are several different slices used per I/O island.
- The status of the safety-related firmware: Maintenance case (one device update only) or new machine setup from stock (update of n devices).

The new release contains updated safety-related offline/online documentation and updated diagnostic information.

Refer to the updated hardware and software documentation to become familiar with the new system features.

Compatibility EcoStruxure Machine Expert - Safety

Project Updates

SLCv1 System

With no new functional modifications introduced for existing projects, there is no re-certification needed related to the new TM5CSLC100FS / 200FS firmware version 2.59 delivered with this release.

Only a quality enhancement has been performed in the non-safety related part of the TM5CSLC100FS / 200FS firmware.

SLCv2 System

A new/adapted risk assessment following a safety function re-test and re-certification is needed related to the new TM5CSLC300FS / 400FS controllers for the new SLCv2 safety-related timing setup.

The application safety logic function is not changed by this migration which limits the re-test/re-certification scope to the validation of expected safety-related reaction times.

NOTE: In general, after a safety system update the safety-related functions must be re-tested as usual.

Overview of the validated EcoStruxure Machine Expert - Safety version with the appropriate safety-related firmware.

Device	Safety-related firmware version for EcoStruxure Machine Expert - Safety version						
	1.1 / 1.2	1.2.2	2.0	2.0.1	2.0.2 / 2.0.3	2.1	
						SLCv1	SLCv2
TM5CSLC100FS	2.52	2.53	2.56	2.57	2.58	2.59	-
TM5CSLC200FS	2.52	2.53	2.56	2.57	2.58	2.59	-
TM5CSLC300FS	-	-	-	-	-	-	3.05
TM5CSLC400FS	-	-	-	-	-	-	3.05
TM5SAI4AFS	322	322	322	322	322	322	334
TM5SDC1FS	302	302	302	302	302	302	335
TM5SDI20DFS	305	305	305	305	305	305	333
TM5SDI2DFS	305	305	305	305	305	305	333
TM5SDI4DFS	305	305	305	305	305	305	333
TM5SDM4DTRFS	305	305	305	305	305	305	333
TM5SDM8TBFS	305	305	305	305	305	305	333
TM5SDO2DTRFS	300	300	300	300	300	300	333
TM5SDO2TAFS	280	280	280	280	280	280	333
TM5SDO2TFS	280	280	280	280	280	280	333
TM5SDO4TAFS	280	280	280	280	280	280	333
TM5SDO4TFS	280	280	280	280	280	280	333
TM5SDO6TBFS	295	295	295	295	295	295	333
TM5SPS10FS	320	320	332	332	332	332	333
TM5STI4ATCFS	322	322	322	322	322	322	334
TM7SDI8DFS	305	305	305	305	305	305	333
TM7SDM12DTFS	305	305	305	305	305	305	333

Mitigated Anomalies

EcoStruxure Machine Expert

ID	Description
BOC-1482 / IAT-115	The search in offline help did not return results in the French language.
BOC-1751 / SI-15006	Script hook events were not displayed when the project was opened by double-click from the Windows Explorer.
BOC-1775 / CDSYS-1085	The Auto Declare function reported a detected error when trying to initialize an array of more than 100 elements.
BOC-1786 / CDSYS-1089	The Qt WebBrowser did not display the WebVisualization.
BOC-1797 / SI-15849	Conversion of <i>smbp</i> files was not performed properly in EcoStruxure Machine Expert V2.0.*.
BOC-1845 / CDSYS-1118	Using the same library in both Library Managers (global POU space and local below the Application node) had the effect that Parameter Lists were configured by the global library and thus compiler errors were generated. The values configured for the Parameter Lists in the local library were ignored.
BOC-1866 / CDSYS-1126	Parts of the Advanced Trace Settings dialog box (for example, calculated time values) were not displayed when a system motion task was configured.
BOC-1906 / CDSYS-1153	An error message was sporadically displayed when comparing projects and auto save was active. The message can now be disabled.
BOC-1919 / SI-16295	An invalid Guid (null object) was displayed in the device user management (in a very special case and after updating a controller image, adding a device user and disabling user management).
BOC-1946 / SI-16491	SDO (Service Data Objects) were modified when updating a project from SoMachine / SoMachine Motion to EcoStruxure Machine Expert (due to conversion of Lexium 32 A and Lexium 28 to other drive references). In these specific device conversion cases, the SDOs are no longer taken over but have to be re-configured.
BOC-1948 / SI-16422	Controller Assistant: An image read with a card reader could not be transferred to the controller.
BOC-1981 / CDSYS-1129	Trace editor: An incorrect diagram was selected in the Presentation (diagrams) tree view when selecting a diagram in the Trace view in case the Presentation (diagrams) tree contained variables or diagrams that were set to invisible.
BOC-1996 / SI-16785	A renamed user-defined motion profile was not available for smart coding.
BOC-2013 / SI-16923	Convert Device on a controller resulted in a corrupted internal state of a TM5 DTM used.
BOC-2032 / SI-17055	EcoStruxure Machine Expert froze when importing a motion profile into a specific project.
BOC-2033 / SI-17056	Deleting a user-defined motion profile led to the fact that SVN also detected other motion profiles as changed, although they were not.
DFBOC-1313 / DFSI-11153	The Schneider Electric Software Installer now displays partial installation.
DFBOC-1480 / DFSI-16696	The direct extension of function block (EN/ENO) in FBD (Function Block Diagram) is now enabled.
DFBOC-1494 / DFSI-17405	Export and import (into/from CSV files) of a TestSet did not include the header.
DFBOC-1561 / DFSI-13554	F1 contextual help on parameters was not supported.
DFBOC-1711 / DFSI-14715	A new Python interface provides the EcoStruxure Machine Expert version with which a project was created. NOTE: This is only available for projects saved with EcoStruxure Machine Expert V2.0 or later.
DFBOC-1864 / DFSI-15853	The SQL Gateway verifies the presence of the license now less strictly and less often.
DFBOC-1917 / DFSI-16421	Enable the menus Enable device user management on device and Disable device user management on device in online mode depending on the rights of the logged-in device user.
DFBOC-1952 / DFSI-16423	A script hook event for Save as was added.
DFBOC-1995 / DFSI-16784	The names of the user profiles are now preserved with the import.
DFBOC-2022 / SI-17011	Executing the <code>savecontrol</code> command in the Controller Assistant led to an error in the logfile.
DFBOC-2050 / DFSI-17074	The library <code>lecVarAccess</code> was removed when converting a drive.
DFBOC-2056 / DFSI-17102	No device addressing for 3rd party devices on Sercos was available.
DFBOC-2057 / DFSI-17207	Compile messages caused by PacDrive libraries used in a customer library were generated.

ID	Description
DFBOC-2058 / DFSI-17105	Online help: The description of the attribute pragma <code>symbol</code> has been detailed to explain it is ignored on usage of function block instances in arrays.
DFBOC-2059 / DFPLAT-1979	The build and generate code time was improved for projects containing many TM3BC.
DFBOC-2084 / DFSI-17233	A Python command to activate/deactivate the verification for updates on opening a project has been added.
DFBOC-2111 / DFSI-17324	Controller Assistant: Keep existing user management on device is now supported also for the case of a deactivated user management.
DFBOC-2113 / DFPLAT-2092	The Automatic I/O mapping project setting declared also variables for hidden inputs and outputs of TM5SE4IOL IO-Link Master which led to naming conflicts when renaming such a device.
DFBOC-2143 / DFPLAT-2170	Renaming of a device via Refactoring could lead to conflicting duplicate variable names for variables created by Automatic I/O mapping .
DFBOC-2151 / DFSI-17459	The pop-up dialog box providing information about newer available firmware versions on the PC did not appear during Login .
DFBOC-2174 / DFPLAT-2200	Mass Storage : It was not possible to add the SetNodeName command without parameter for resetting the node name.
DFBOC-2181 / DFSI-17630	Online help: Information about the All Variables view has been removed.
DFBOC-2237 / DFPLAT-2357	The Export as EDS command is displayed if an associated EDS template exists.

EcoStruxure Machine Expert - Safety

ID	Description
OEM00070466 / SSP50-4192	When the <i>MaxDataTransportTime</i> value was set to a value that was too small, the <i>TM5CSLCx00FS</i> did not change its status to RUN.
OEM00071897 / SSP50-6831	In the SafeLogger, some issues were displayed as non-safety-related messages, whereas they should have been safety-related messages. Known issues: • <i>0x9414 Cross communication error</i> • <i>0x960B Internal error cross communication</i> • <i>0xD126 Execution differences processes</i> • <i>0x8609 Supply voltage error</i>
OEM00077282 / SSP50-6867	In one special tested system configuration running with 1 ms Sercos cycle time, the state of <i>SafeModulOK</i> parameter of one safety-related module changed from TRUE to FALSE. This did not occur with 2 ms and 4 ms as Sercos cycle time in the same configuration.

Known Operational Anomalies

DTMs

ID	Description
DFSI-17384	ATV340S installed by EcoStruxure Machine Expert does not switch to connection mode with SoMove. Workaround: Update the DTM ATV340S to the latest version only via SESU (Schneider Electric Software Update).

EcoStruxure Machine Expert

ID	Description
DFBOC-2049 / CDSYS-1184	Visualizations referenced from a library are not found.
DFBOC-2080 / CDSYS-1187	Using an XYChart in a visualization leads to error messages. Workaround: Add a Web Visualization object.
DFBOC-2081 / CDSYS-1188	It is not possible to save recipes containing REAL, LREAL variables without having provided a value for the variables.
DFBOC-2094 / CDSYS-1191	Modified variable names (Chinese) of I/O Mapping become " _ ". Workaround: Delete the variable from the I/O Mapping , then add a new one.
DFBOC-2095 / CDSYS-1190	The function XSIZEOF cannot be used in FBD (Function Block Diagram). Workaround: Enter XSIZEOF as an ST expression inside an Execute box.
DFBOC-2106 / CDSYS-1195	Differences are displayed in the Project Compare tree for CFC POU's with Auto Data Flow Mode activated although no differences exist. Workaround: Open the corresponding objects to verify that there is no difference.
DFBOC-2136 / CDSYS-1015	Compile errors that are related to the usage of the library IoDrvModbusSerial are generated after a Convert device from TM241CEC24T to TM241CEC24R has been performed. Workaround: Remove the library and add it again as placeholder SE_ModbusIOScanner .
DFBOC-2142 / CDSYS-1211	Recipe Manager : An element of a STRUCT declared as an ENUM type that comes from a library cannot be added to a recipe definition.
DFBOC-2150 / DFSI-17458	Integrity verification is displayed when VisualStudio.Diagnostics.ServiceModelSink.dll is detected.
DFBOC-2153 / CDSYS-1212	The SVN command Commit can be executed while being online. This can lead to an update of the project in case the SVN repository was changed.
DFBOC-2163 / CDSYS-1225	Adding modules to a Profinet device takes a long time. Workaround: Close all device editors before adding modules.
DFBOC-2164 / CDSYS-1226	Changing the communication parameters of a Profinet device can take several seconds. Workaround: Close all other device editors before.
DFBOC-2170 / DFSI-17417	Adding a Profinet device for the first time can take several seconds in case of a large device repository after the installation of many third-party devices.
DFBOC-2185 / CDSYS-1232	It is not possible to add methods from several unit conversion function blocks to CFC or FBD/LD by using the Input Assistant . Workaround: Use the smart coding functionality instead.
DFBOC-2197 / CDSYS-1237	Differences are displayed in the Project Compare tree for CFC POU's and Visualization Manager although no differences exist. Workaround: Open the corresponding objects to verify that there is no difference.
DFBOC-2206 / CDSYS-1245	In the German user interface, some strings are truncated in the Search and Project Compare dialog boxes when specific DPI screen settings have been set. Workaround for the Search : Increase the size of the dialog box.
DFBOC-2210 / CDSYS-1246	No trace values are displayed after logout when the trace window was not docked to the frame.
DFBOC-2235	Compile errors are generated in case a cam diagram has the name MyCam and a program SR_MyCam already exists in the project. Workaround: Rename the cam diagram.
DFBOC-2239 / CDSYS-1259	The Import PLCopenXML... command allows importing a Sercos module from another parent device which should not be allowed.
DFBOC-2240 / DFSI-17844	Controller Assistant: Downgrading PacDrive LMC firmware from V2.0.* to V1.2 may lead to incorrect timing. Workaround: Download the firmware to the card reader.
DFBOC-2250	Using a CONSTANT as upper bound of arrays in NVL (Network Variable Lists) leads to the exception <i>Could not find any recognizable digits</i> .
DFBOC-2251	Modifying SDO parameters and switching to other editors may take several seconds.

EcoStruxure Machine Expert - Safety

ID	Description
DFBOC-2222 / SSP50-10529	EcoStruxure Machine Expert - Safety does not operate with offline licenses retrieved from the Floating License Server. Workaround: Remove the Floating License server configuration from the License Manager client. NOTE: As the first attempt will be unsuccessful, repeat the procedure.
SSP50-9810	The detailed description of the dialog box Confirmed changed SDIO Devices does not display the correct information. Related changes / updates are performed correctly and are not impacted. Workaround: To retrieve information about the safety-related device description version used in your project, verify the information in the <i>SAFEGRID</i> module information field. Also refer to the EcoStruxure Machine Expert - Safety User Guide for details.
SSP50-10098	The project comparison of a migrated SLCv1 project versus an updated SLCv2 project does not display details concerning differences in the safety-related parameters, such as new SDD, TPL. Workaround: Refer to the EcoStruxure Machine Expert - Safety User Guide for project migration suggestions. Manually compare the SLCv1 project <i>SAFEGRID</i> with the SLCv2 project <i>SAFEGRID</i> parameter information.

EcoStruxure Machine Expert Twin

ID	Description
METWIN-1013	When using EcoStruxure Machine Expert with automatic floating license retrieved from the floating license server configured, the embedded emulation view of the Lexium™ MC multi carrier or robot is not supported. Workaround: In the Schneider Electric License Manager, manually set the floating license offline for a certain duration and return it manually before the end of the duration.

Motion Sizer

ID	Description
DFBOC-2074 / DFMS-2185	Incorrect calculation of torque for Neugart PLN190 gearbox.
DFBOC-2083 / DFMS-2203	Small values are rounded in the Motion Sizer result page.
DFBOC-2092 / DFMS-2205	The LXM28-BCH2 torque-speed curve differs between Motion Sizer and the user guide.

EcoStruxure Machine Expert V2.1.1

Hardware/Firmware Information

Version Identification

Description	Firmware Version
M262	5.1.7.27
TMSES4	1.0.0.21
TM3BCCO	2.1.50.2
TM3BCEIP	2.4.0.3
TM3BCSL	2.1.50.2
TM3•HSC202•	2.0
TM3DI8	2.0
TM3DI8G	2.0
TM3DI16	2.0
TM3DI16G	2.0
TM3DI16K	2.0
TM3DI32K	2.0
TM3DM8R	2.0
TM3DM8RG	2.0
TM3DM24R	2.0
TM3DM24RG	2.0
TM3DQ8••	2.0
TM3DQ16••	2.0
TM3DQ32••	2.0
TM5NEIP1 / TM5NEIP1K	3.12
TM5NS31	2.79
LXM32••••M2 / LXM32S•••N4	- Drive firmware: V1.12.2 - Sercos3 interface firmware: V1.12.02
LXM52••••C••••	1.54.29.0
LMC Eco	1.74.5.1
LMC Pro	1.74.5.1
LMC Pro2	1.74.5.1
ATV340S	- Drive firmware: V1.4IE09_B06 - Sercos3 interface firmware: A1.2IE01_B00

Description	Safety-related Firmware Version
TM5CSLC100FS	2.59
TM5CSLC200FS	2.59
TM5CSLC300FS	3.05
TM5CSLC400FS	3.05
BWU2984 SWID	134253
BWU2984 Safe CPU A	135115
BWU2984 Safe CPU B	135116
ASIMON360	3.2.6.7

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

New Features

Lexium™ MC12 multi carrier

- It is no longer required that the Lexium™ MC12 multi carrier track is the first Sercos device connected to the controller.
- After the message *8562 Carrier negotiation communication error detected* has been displayed, a retry of Sercos phase-up is now possible without the need of segment power off/on.
- The segments are now configured in parallel, resulting in a much faster phase-up with large multi carrier systems.

Supervision of power consumption:

- New segment message: *8553 Segment power consumption near limit*

PacDrive LMC Controls & I/Os

The interrupt mode is implemented for Profinet IO controllers (see in the LMC Pro Device Objects and Parameters User Guide).

Mitigated Anomalies

Lexium 52

ID	Description
SERVOD-545 / PEP0628842R	When Lexium 52 was operated with V01.54.26.00 or earlier firmware versions, the power stage could be damaged when the diagnostic message <i>8107 Overcurrent</i> was triggered and was subsequently removed from the motor. This has been fixed by a correction of the switch-off sequence.

Lexium™ MC12 multi carrier

ID	Description
LMCFW-7422	Sometimes an error that had been detected in the segment was not reported by the PacDrive LMC controller.
LMCFW-7437	The reset of <i>RefPosition</i> values after <i>MoveDirectly Relative</i> with negative target was incorrect.
LMCFW-7458	Incorrect calculation of a reference acceleration of an inverted track is solved.
LMCFW-7490	The <i>EnableSet</i> parameter of the Lexium MC Carrier reflected the incorrect state.
MLTC-4066	When a multi carrier track was split into multiple SFO (Safe Force Off) sections, a segment could report the message <i>8551 Uncontrolled carrier received</i> even if all carriers were well controlled.
MLTC-4095	The following diagnostic messages issued by multi carrier segments can now be reset using <i>FC_Diagquit()</i> : • <i>8125 Motor load high</i> • <i>8126 Power stage temperature high</i> • <i>8127 Motor temperature high</i> • <i>8132 Tracking deviation limit exceeded</i> • <i>8161 Control board temperature high</i> • <i>8169 Sercos Slave comm. disturbance detected</i> • <i>8186 DC bus voltage high</i> • <i>8568 Segment coil load is high</i>
MLTC-4107	The Sercos phase-up was sporadically unsuccessful and the message <i>8552 Sercos cycle time too short</i> was displayed.
MLTC-4163	When the multi carrier track was enabled, sporadically a segment could report the message <i>8111 Shutdown due to tracking deviation</i> directly after enable, even if no tracking deviation existed.

M262

ID	Description
M262-16339	EtherNet/IP device disconnection due to firmware task priority inversion is fixed.
M262-14066	Disconnection of EtherNet/IP devices on one of the embedded switch ports led to disconnections of EtherNet/IP device(s) connected to the other port. The issue was detected using ATV340 and TM3BCEIP.
MSOLCTRL-3304	The <i>DirectionNegative</i> output value in <i>MC_ReadMotionState</i> was incorrect after an absolute movement had been executed.
MSOLCTRL-3335	When <i>MC_CamIn</i> was executed after recovering from a detected slave axis error, <i>RampIn</i> moved the slave axis to an incorrect position.
MSOLCTRL-3415	Incorrect behavior of <i>MC_PhasingAbsolute</i> after <i>MC_Stop</i> on the slave axis was detected in EcoStruxure Machine Expert V2.1.
MSOLCTRL-3486	A jump on <i>diSetPosition</i> using modulo slave axis could happen using <i>MC_CamIn</i> with slave scaling. The jump was not seen on the <i>IrPosition</i> of the axis.

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-5705	The cycle time could increase after converting the project to EcoStruxure Machine Expert V2.0.
LMCFW-7274	The Profinet task cycle time could increase if the cable was disconnected.
LMCFW-7316	A hardware watchdog could occur on a Profinet communication after running for 3...4 weeks.
LMCFW-7410	A task cycle time increase was detected on Profinet.
LMCFW-7438	The Ethernet connection was lost after losing the CANopen connection.
LMCFW-7425	For some applications the function <i>FC_OpcUaStart</i> was not working if instances of function blocks were used in the Symbol Configuration .
LMCFW-7445	An issue was detected when the EtherCAT master was configured on an optional module with a configuration file > 495 kB.
LMCFW-7469	The configuration was not updated correctly when switching the fieldbus on the same connector.

Known Operational Anomalies

M262

ID	Description
M262-14600	The RSTP (Rapid Spanning Tree Protocol) converge time is sometimes longer. Workaround: Use an RPI (Requested Packet Interval)/timeout combination greater than 100 ms which is the RSTP convergence time of the M262.

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-7400	The function <i>FC_SercosScanConfiguration</i> may increase the task cycle time.
LMCFW-7409	A difference in the Task deployment of the TM5 inputs (Sercos / EtherNet/IP) may be observed.
LMCFW-7427	After an application stop/start a hardware watchdog may occur when using a Profinet controller.
LMCFW-7443	The LMC PacDrive controller as a Profinet device may not be re-enabled with the function block <i>Reconfigure</i> .
LMCFW-7505	The connection might be lost after download of an application with OPC UA over the second Ethernet port.
LMCFW-7451	The functions <i>FC_OpenIncomingFirewallPort</i> and <i>FC_CloseIncomingFirewallPort</i> may not work as expected when the source is an IP address.
LMCFW-7453	No communication detected for a re-enabled PacDrive controller as EtherCAT slave below an EtherCAT master.
LMCFW-7454	A re-enabled PacDrive controller as EtherCAT slave may lead to a hardware watchdog.
LMCFW-7475	Unexpected behavior detected with Sercos robustness when using ATV340S.
LMCFW-7495	The PacDrive controller may not renew the Sercos address of a device if the address is used and configured by the Sercos addressing.
LMCFW-7496	The TM5 IO-Link master may not use the full bandwidth for the data transportation.
LMCFW-7536	The automatic update process of legacy SH3 servo motor type plates may lead to an exception.
LMCFW-7607	The data type <i>NamespaceIndexes</i> for structures may be incorrectly displayed when using OPC UA.
LMCFW-7615	The diagnosis message <i>The module was not found</i> might be displayed after calling the function block <i>Reconfigure</i>. Workaround: With CANbus and CANopen_Manager active per default in the project, call the function <i>FC_PrgResetAndStart</i> once after the LMC PacDrive controller boot to avoid the diagnosis message <i>The module was not found</i>.

Library Information

Version Identification

Description	Version
DigitalTwinCommunication	1.1.3.0
FeatureNotSupported	2.0.1.0
Multicarrier	1.1.11.0
MulticarrierStation	1.1.2.0

Version Identification Smart Templates

Description	Version
SMT_ESME_Axis	2.2.1.0
SMT_ESME_Camera	2.3.1.0
SMT_ESME_Conveyor	2.3.1.0
SMT_ESME_Robot Cartesian	1.1.3.0
SMT_ESME_Robot P-Series	2.4.2.0
SMT_ESME_Robot T-Series	2.3.1.0
SMT_ESME_RobotCell	1.1.0.0
SMT_ESME_Sensor	1.2.0.0

Version Identification Template Libraries

Description	Version
Altivar Device Templates	5.2.4.0
CANopen Device Modules	5.2.5.0
Communication Functions	1.3.8.0
EtherNet/IP Device Modules	5.2.16.0
Hardwired Device Modules	5.2.1.0
ModbusSL Device Modules	5.2.3.0
ModbusTCP Device Modules	5.2.3.0
Sercos Device Modules	1.1.5.0

New Features

Multicarrier

- Collision prevention: New parameter *ST_CrashPreventionParameter.xDisableCrashPreventionForMoveGapControl* to disable collision prevention for carriers which are moving with the move command *MoveGapControl*.
- A new superimpose move command (*.ifMoveSyncFromStandstill.ifSuperimposedChannelC.StartAbsolutePositioning*) for *MoveSync* is available.
- Possibility to disable single carriers and segments while the other carriers are moving.
- Possibility to explicitly define the jerk for a motion (method *SetExplicitlyLowerJerk*).

DigitalTwinCommunication

Supporting the SmartVisu (first step) feature on EcoStruxure Machine Expert Twin V1.3.

New Features - Examples

Multicarrier Example

An example station for superimposed movements has been added.

Mitigated Anomalies

ID	Description
IECLIB-27336	MulticarrierStation: The property <i>udiNumberOfCarriersInStationStanding</i> is now working as expected for <i>MoveCmd</i> , <i>MovePureSmg</i> and <i>MoveSync</i> .
IECLIB-27362	Multicarrier: <i>MoveGap</i> works now as expected in case the carrier is moved with the move command <i>MoveSync</i> and is connected to a carrier with <i>MoveSyncToExternalMaster</i> .
IECLIB-27608	Multicarrier: <i>MoveGap</i> is now working correctly if the carrier in front is moved with the move command <i>MoveSync</i> and connected to a carrier with <i>MovePure</i> command.
IECLIB-27642/DFBOC-2451	Multicarrier: <i>MoveGapControl</i> has been improved to avoid that acceleration is set to 0.
IECLIB-27666	Multicarrier: The function block <i>FB_CartesianCalculations</i> is now disabled properly.
IECLIB-27668	Multicarrier: <i>MoveGapControl</i> : Evaluation of a new lower jerk from a carrier in front works now as expected.
IECLIB-27959	Multicarrier: <i>MoveGapControl</i> now works as expected for <i>ET_PosMode: RelativeForward</i> .
IECLIB-28055	MulticarrierStation: In rare cases <i>MCRS.FB_ClampingStation</i> could trigger the diagnostic message <i>8902 Software error (page fault)</i> .
IECLIB-28121	MulticarrierStation: A <i>Stop</i> called for more than 100 carriers with <i>MoveSyncFromStandstill</i> no longer leads to an exception.
IECLIB-28149	MulticarrierStation: <i>MoveCmd MoveSuperimposed</i> works when a carrier has previously been loaded with <i>MoveCmd MoveSyncFromStandstill</i> .

Known Operational Anomalies

There are no additional known anomalies with this release.

Software Information

Version Identification

Description	Version
EcoStruxure Machine Expert Twin	1.2.1.0
Motion Sizer	4.3.1.0

Version Identification of SQL Server

Description	Version
MySQL	8.0.30 - Workbench 8.0
Oracle	- Oracle Database 18c Express Edition Release 18 – Version: 18.4.0.0.0 - SQL Plus – 18.4.0.0.0 - OracleXE213_Win64 (21c) sqldeveloper-22.2.0.173.2018-x64
MS SQL Server	- MS SQL Server 2019 Express/ 15.0.2101.7 (x64) - SQL Management Studio 18.12.1
SQLite	- Sqlite3 - 3.37.2 - sqlite-tools-win32-x86-3.39.02.00

Known Operational Anomalies

There are no additional known anomalies with this release.

EcoStruxure Machine Expert V2.1.2

Hardware/Firmware Information

Version Identification

Description	Firmware Version
LMC Eco	1.74.5.2
LMC Pro	1.74.5.2
LMC Pro2	1.74.5.2

Contact your local Schneider Electric representative in case you need specific information for your intended machine architecture.

Mitigated Anomalies

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-7643	The SystemUserFunctions and SystemUserFunctionsItf libraries were released in the EcoStruxure Machine Expert V2.1 and in the EcoStruxure Machine Expert V2.1.1 with the same version number but with different content.

Lexium™ MC12 multi carrier

ID	Description
MLTC-4246	The random message <i>8564 Carrier is lost</i> during Sercos phase-up no longer occurs.
MLTC-4247	Sercos is no longer blocked in phase 2 due to message <i>8564 Carrier is lost</i> during Sercos phase-up.

Known Operational Anomalies

PacDrive LMC Controls & I/Os

ID	Description
LMCFW-7636	Cyclic messages are displayed when a download with no real CANopen device is executed.
LMCFW-7647	In some cases, the <i>FC_OpcUaStart</i> may not return any value and stop the execution of the task.
LMCFW-7648	<i>IF_TouchProbe2.TPEdgeStart</i> may not work with more than 128 drive IO instances.

Library Information

Version Identification

Description	Version
Multicarrier	1.2.8.0
Robotic	3.6.6.0

Version Identification Examples

Description	Version
MulticarrierExample	1.1.10.0

New Features

Multicarrier

- New data and profile calculation of *MoveSync* commands are updated with a method call of the master carrier.
- *StartCurveCompensationToCarrierInFront*: It is now possible to start the curve compensation also in the curve segments.
- Track calibration: New calibration functionality for segment transitions of a Lexium™ MC multi carrier track. The track calibration modes *Forward*, *Backward* and *BothDirections* are supported (*ET_ModeTrackCalibration*).

Mitigated Anomalies

ID	Description
IECLIB-28185	Multicarrier: The method <i>MoveGap</i> functions as designed if the carrier gets the target which is the present position.
IECLIB-28197	Multicarrier: The addition of <i>SuperimposeProfile</i> and <i>MoveSyncProfile</i> functions as designed.
IECLIB-30355	Multicarrier: <i>StartVelocity</i> equal to zero is intercepted for all cases.
IECLIB-30444	Multicarrier: Target calculation of <i>MoveGapControl</i> functions as designed in combination of <i>MoveSyncToExternalMaster</i> .
ROB-313	Robotic: <i>FB_EllipticSpline.CalcSplineExtended</i> no longer reports the exception <i>IdenticalSplinePoints</i> with default parametrization.
ROB-421	Robotic: The exception <i>SwitchTimeInvalid</i> can no longer appear when <i>Execute()</i> is set to FALSE.
ROB-496	Robotic: <i>FastMoveSExtended</i> no longer reports that last spline point and target are not identical when you use it on targets outside the work envelope.
ROB-500	Robotic: <i>ExternalPositionSource</i> is no longer creating exception logger entries in the application logger for not configured robot components.

Known Operational Anomalies

There are no additional known anomalies with this release.

Software Information

There is no additional software information for this release.

Index

C

CodeMeter installation 15

D

DTM
 firmware version 126

F

firmware version
 DTMs 126

Schneider Electric
35 rue Joseph Monier
92500 Rueil Malmaison
France

+ 33 (0) 1 41 29 70 00

www.se.com

As standards, specifications, and design change from time to time,
please ask for confirmation of the information given in this publication.

© 2023 Schneider Electric. All rights reserved.

RN0000000035.19