

“X80 2ch Analog Output IO module” FIRMWARE HISTORY

Modules: BMXAMO0210, BMXAMO0210H

Version #	Date of Publication	Internal reference	Description
SV1.30	01/2021	PEP0590525R	Optimized the 4 status LEDs (RUN, ERR, I/O, DL) blinking fast mechanism. Under a rare condition , when the inconsistency of data in RAM occurs and could not be recovered autonomously, this issue will be indicated by module healthy bit and 4 status LEDs blinking fast.
		PEP0590524R	Fixed the issue that analog output module mounted in RIO drops can't boot up automatically after a firmware upgrade.

“X80 2ch Analog Output IO module” FIRMWARE HISTORY

Modules: BMXAMO0210, BMXAMO0210H

Version #	Date of Publication	Internal reference	Description
SV1.20	12/2016	PEP0348990R	Fixed the issue that output channels would be send out the value after the second cycle instead of first cycle.
		PEP0348699R	Fixed the issue that CH_ERROR=1 when below or above overflow is unchecked on BMX analog output module.