HOLDRITE®
CONVERTING MAKESHIFT METHODS INTO ENGINEERED SOLUTIONS℠

PEXRITE®

The Torchless Installation™

PEX STUB-OUT

PICK YOUR STUB-OUT METHOD



PEX TO COPPER STUB-OUT

Visit www.holdrite.com to view PEXRITE® installation videos, technical information, and list pricing.

Pick Your Stub-Out Method

PEX TUBING
PEXRITE® Turn-Out
#704



- Eliminates in-wall fittings and concealed joints
- Installs directly to the stud
- Provides 360° turning radius in PEXRITE brackets
- Reduces noise and vibration

COPPER OR RIGID TUBING
PEXRITE® Lock-n-Load™
#701



- Designed for PEX, copper and CPVC
- Tightens by hand - no tools or hardware required
- Eliminates soldering
- Secure fit prevents forward and backward movement

IMPORTANT:
Confirm compatibility of copper ells with PEX tubing manufacturer.

PEXRITE® Supports Integrate Directly with PEXRITE® Brackets Only



#103-18

PEXRITE® Turn-out #704 Installation Instructions

1 Install PEXRITE bracket to studs.



2 Insert #704 into bracket from the front.

3 Position #704 until bracket fits into groove, then rotate into place.

4 Insert PEX tube at 45° angle and set stub-out length.



5 Bend tube forward and snap into #704.

6 Complete! No concealed joint in the wall.

PEXRITE® Lock-n-L

1 Install PEXRITE bracket to studs.



4 Load tubing through #701 from back.

Additional Application Solutions

PEXRITE® #705
- 3/8" and 1/2" CTS PEX tubing Sink/lavatory and toilet stub-out
- Overhead 90° turn
- In-slab turn-out from decking into wall

PEXRITE® Pop-Up™ #707
- Single run pop-up for up to 7/8" O.D. PEX tubing, soft copper and flexible conduit
- In-slab installation at ground-work with rebar or wood decking
- Multi-run versatility for manifolds with interlocking feet

PEXRITE® #710, #711, #712
- Plastic nylon bend support
- Provides rigid 90° bend ideal for 1/2", 3/4" and 1" PEX tubing
- Compatible with all PEX tubing manufacturers

PEXRITE® Pop-Up™ #706
- Single run pop-up for 3/8" and 1/2" CTS PEX tubing
- Ideal for radiant heating applications
- Multi-run versatility for manifolds with interlocking feet



PEXRITE® Pop-Up™ #708 and #708-E
- Double run pop-up for in-slab flexible tubing support
- Multi-run versatility for manifolds with interlocking feet
- #708 design allows for side-entry of tubing
- #708-E design allows for easy zip tie installation of flexible or rigid tubing
- Mounts to wood form decking or slab-on-grade with rebar





n-Load #701 Installation Instructions

2 Insert #701 into bracket from the front.

3 Lock #701 into bracket with thumbs.

5 Push and twist back nut by hand, until tight.

6 Complete! Secures stub-out with no solder.



PEXRITE® Pop-Up™ Installation Instructions

1

2

3

4

HOLDRITE®
CONVERTING MAKESHIFT METHODS INTO ENGINEERED SOLUTIONS℠

PEXRITE®
THE TORCHLESS INSTALLATION™

PIPE SUPPORT BRACKETS AND STUB-OUT SUPPORTS

Model #	Description	Box Quantity
103-18	Galvanized bracket with 1 3/8" keyed holes, on 2" centers, 20" long.	50
103-26	Galvanized bracket with 1 3/8" keyed holes, on 2" centers, 26" long.	50
709	Galvanized bracket with 1 3/8" keyed holes, 7½" x 2".	50
709-L	Galvanized "L" bracket with 1 3/8" keyed holes, 4¼" x 3¼" x 2".	50
709-EXT	Galvanized bracket with 1 3/8" keyed holes and up to 8" center line off floor, 9"x 2 1/8" x 2".	50
721	Galvanized bracket 3 3/8" x 2¾" with 1 3/8" keyed hole. Integrates with the HOLDRITE STOUT BRACKET® or mounts directly to stud.	50
110-R	Galvanized bracket for island lavatory/sink, supports 4" and 8" centers, 2 1/8" x 1 7/8".	50
SB1S	Galvanized telescoping bracket, 10" - 18", supports PEX, Copper and CPVC.	50
SB2S	Galvanized telescoping bracket, 13" - 25", supports PEX, Copper and CPVC.	50

PEX STUB-OUTS

Model #	Description	Box Quantity
704	Turn-out supports 3/8" & ½" CTS PEX tubing. No tools required. Temp. range: -10° F to +180° F.	100
705	Turn-out supports 3/8" & ½" CTS PEX tubing. Mount to block of wood. Sink/lavatory and toilet stub-out support & overhead 90° turns. Temp. range: -10° F to +190° F.	50
710	90° overhead bend plastic nylon support for ½" CTS PEX tubing.	50
711	90° overhead bend plastic nylon support for ¾" CTS PEX tubing.	50
712	90° overhead bend plastic nylon support for 1" CTS PEX tubing.	25

PEX-TO-COPPER STUB-OUTS

Model #	Description	Box Quantity
701	Stub-out clamp supports ½" CTS PEX, Copper & CPVC tubing. No tools required. Temperature range: -10° F to +140° F	50
103-18-701	20" flat, galvanized bracket & ½" CTS #701 stub out clamps.	50 brackets/ 100 clamps
103-26-701	26" flat, galvanized bracket & ½" CTS #701 stub out clamps.	50 brackets/ 100 clamps

PEX POP-UP SUPPORTS

Model #	Description	Box Quantity
706	Single run 3/8" & ½" CTS Pop-up for PEX. Ideal for in-slab and radiant heating. Temp. range: -10° F to +190° F.	50
707	Single run Pop-up for PEX, soft copper and flexible conduit. Tube sizes up to 7/8" O.D. Temp. range: -10° F to +190° F.	25
708	Double run Pop-up for PEX, soft copper and flexible conduit. Tube sizes up to 1 1/8" O.D. Temp. range: -10° F to +190° F.	15
708-E	Double run Pop-up for PEX, flexible conduit (smurf tubing),& rigid conduit 90s. Tube sizes up to 2½" IPS. Temp. range: -10° F to +190° F.	15

INSERTS/CLAMPS

Model #	Description	Box Quantity
404-R, 405-R, 406-R	½", ¾" and 1" CTS Fire Retardant inserts. Meets UL94 V-2.	100

Visit www.holdrite.com to view PEXRITE® installation videos, technical information, and list pricing or call (800) 321-0316.

© 2015 HOLDRITE. All Rights Reserved. #LT29 4/15