


TPB Gasketed Box

INSTALLATION INSTRUCTIONS

All electrical products may represent a possible shock or fire hazard if improperly installed or used. Wiremold electrical products are UL listed, made for interior use in dry locations only and should be installed in conformance with current local and/or the National Electrical Code.

1. Remove cover to power compartment (optional).
2. Remove entrance end fitting by loosening two retaining screws (only if necessary).
3. Attach Gasket to bottom of box.
4. Insert power wires through Gasketed Box (small opening).
5. Install Gasketed Box and divider with two self-tapping screws to top of pole. Fasten Gasketed cover with four machine screws to top of box.
6. Replace power cover.
7. Install power pole per instructions (included with power pole).



USED WITH:

25DTP Series
AMDTP Series