


INSTALLATION INSTRUCTIONS

LX SERIES PENDANT MOUNTING KIT •PMLXW (White) •PMLXB (Black)



- 1. Connect building utility lead wires to pendant kit connection leads with wire nuts (provided).
 - Connect to black and white leads for 120VAC application.
 - Connect to red and white leads for 277VAC application.
- 2. Slip wires through crossbar provided. Mount crossbar to electrical box using mounting screws supplied with box.
- 3. Secure building ground wire to crossbar as shown.
- Install nut, lock washer, cover plate and canopy on long threaded end of stem (see illustration).
- 5. Feed wire through mounting stem and screw assembly into crossbar. Adjust canopy position and lock in place by tightening nut.
- 6. Install nut, lock washer and crossbar on short threaded end of stem as shown.
- Feed wire through universal mounting plate and canopy.
- 8. Install universal mounting plate to canopy and mount canopy to crossbar with screws provided (see illustration).
- Remove front stencil face from exit sign.
- Route wires through exit sign to quick connectors. Reference Liteforms LX Series installation instructions for details. Observe
 connection instructions from Step 1.
- Snap exit sign onto canopy.
- Snap front exit stencil face plate in place.

Warning: This product contains chemicals known to the state of California to cause cancer, birth defects, and/or other reproductive harm. Thoroughly wash hands after installing, handling, cleaning, or otherwise touching this product.

Copyright® Hubbell Lighting, Inc., All Rights Reserved • Specifications subject to change without notice. • Printed in U.S.A.

Lighting, Inc.

HUBBEL