




TO BE SOLD ONLY WITH
INSTALLATION INSTRUCTIONS

Push-In Wire Connectors

For MC-PCS Lighting Control/Signal Circuits

INSTRUCTIONS

- 1 Remove 1-1/8" (blue) outer jacket from each pair of control/signal wires per strip gauge.
- 2 Strip 3/8" insulation from individual control/signal wires (typically gray and purple) per strip gauge.
- 3 Fully insert stripped wires into ports, gray wires on gray side, purple wires on purple side. Connection ports are clear to confirm full wire insertion.
- 4 Group wire pairs together and snap close the shielding wings.



For permanent install only, not reusable. This product should be installed ONLY by an electrician or other qualified person in accordance with national and/or local code requirements.

**For 16 AWG Solid Copper Conductor ONLY
COPPER TO COPPER ONLY. Not for use with Aluminum wire
Non-grounding/Bonding Special-use Connector
Not for use with grounding/bonding purposes/conductors
600V max | 10A max | 105° C (221° F) rated**



HUBBELL COMMERCIAL CONSTRUCTION
A DIVISION OF HUBBELL INCORPORATED (DELAWARE)
www.hubbell.com/raco/en

How-To Videos





PARA SER VENDIDO SÓLO CON
INSTRUCCIONES DE INSTALACIÓN


Conectores de cable a presión

Para circuitos de control / señal de iluminación MC-PCS

INSTRUCCIONES

- 1 Retire 1-1/8" cubierta de alambre (azul) de cada par de alambres control / señal por calibre del cable.
- 2 Quite 3/8" de insulación de los cables control / señal individuales (típicamente gris y morado) por calibre del cable.
- 3 Inserte completamente los cables pelados en los puertos, los cables grises en el lado gris y los cables morados en el lado morado. Los puertos de conexión son claros para confirmar la inserción completa del cable.
- 4 Agrupe los pares de cables y cierre las alas de protección.

Medidor para remover insulación (escala 1: 1)



Solo para instalación permanente, no reutilizable. Este producto debe ser instalado ÚNICAMENTE por un electricista o por una persona calificada de acuerdo a las exigencias de los códigos nacionales y/o locales.

SOLAMENTE para conductor de cobre sólido de 16 AWG
COBRE A COBRE SOLAMENTE. No debe usarse con alambre de aluminio.
Conector de uso especial sin conexión a tierra
No debe utilizarse con fines de puesta a tierra / conexión / conductores
600V máx | 10A máx | 105° C (221° F) clasificado

Vídeo de instrucciones (Inglés)



www.hubbell.com/raco/en/Videos/MC-PCS_Connectors



HUBBELL COMMERCIAL CONSTRUCTION
A DIVISION OF HUBBELL INCORPORATED (DELAWARE)
www.hubbell.com/raco/en