

# CERTIFICATE OF COMPLIANCE

Certificate Number 20160112-E195978  
Report Reference E195798-19980114  
Issue Date 2016-JANUARY-12

Issued to: RACO  
3902 W SAMPLE ST  
PO BOX 4002  
SOUTH BEND, IN 46634-4002

This is to certify that  
representative samples of METALLIC OUTLET BOXES  
See addendum page for models

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 514A, Standard for Safety for Metallic Outlet Boxes  
CSA-C22.2 No. 18.1, Standard for Safety for Metallic Outlet  
Boxes  
UL 514D, Standard for Safety for Cover Plates for Flush  
Mounting Wiring Devices  
CSA C22.2 No. 42.1, Standard for Safety for Cover Plates  
for Flush Mounting Wiring Devices

Additional Information: See the UL Online Certifications Directory at  
[www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's  
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please  
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

Certificate Number 20160112-E195978  
Report Reference E195798-19980114  
Issue Date 2016-JANUARY-12

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

## These models are evaluated to UL 514A:

Conduit bodies for rigid or intermediate conduit: Models EALB-1, EALB-2, EALB-3, EALB-4, EALB-5, EALB-6, EALB-7, EALB-8, EALB-9, EALB-10, EAC-1, EAC-2, EAC-3, EAC-4, EAC-5, EAC-6, EAC-7, EAC-8, EAC-9, EAC-10, EALL-1, EALL-2, EALL-3, EALL-4, EALL-5, EALL-6, EALL-7, EALL-8, EALL-9, EALL-10, EALR-1, EALR-2, EALR-3, EALR-4, EALR-5, EALR-6, EALR-7, EALR-8, EALR-9, EALR-10, EAT-1, EAT-2, EAT-3, EAT-4, EAT-5, EAT-6, EAT-7, EAT-8, EAT-9, EAT-10, EASLB-1, EASLB-2, EASLB-3, EASLB-4, EASLB-5, EASLB-6, EALB-1CG, EALB-2CG, EALB-3CG, EALB-4CG, EALB-5CG, EALB-6CG, EAC-1CG, EAC-2CG, EAC-3CG, EALL-1CG, EALL-2CG, EALL-3CG, EALR-1CG, EALR-2CG, EALR-3CG, EAT-1CG, EAT-2CG, EAT-3CG

Conduit bodies for electrical metallic tubing: Models EBLB-1, EBLB-2, EBLB-3, EBLB-4, EBLB-5, EBLB-6, EBLB-7, EBLB-8, EBLB-9, EBLB-10, EBC-1, EBC-2, EBC-3, EBC-4, EBC-5, EBC-6, EBLL-1, EBLL-2, EBLL-3, EBLL-4, EBLL-5, EBLL-6, EBLR-1, EBLR-2, EBLR-3, EBLR-4, EBLR-5, EBLR-6, EBT-1, EBT-2, EBT-3, EBT-4, EBT-5, EBT-6, EBLB-1CG, EBLB-2CG, EBLB-3CG

Covers for conduit bodies: Models ESCV-1, ESCV-2, ESCV-3, ESCV-4, ESCV-5, ESCV-6, ESCV-7

## These models are evaluated to UL 514A, CSA-C22.2 No. 18.1:

Outlet boxes: Models 5333-0, 5334-0, 5335-0, 5337-0, 5337-5, 5338-0, 5340-0, 5341-0, 5342-0, 5343-0, 5345-0, 5346-0, 5348-0, 5390-0, 5919-1, 5937-0, 5937-1, 5937-2, 5938-0, 5361-0, 5361-1, 5361-2, 5361-5, 5361-6, 5361-7, 5372-0, 5912-1, 5912-4, 5912-6, 5981-0, 5981-1, 5981-2, 5320-9, 5321-6, 5387-0, 5910-1, 5910-4, 5910-6, 5911-1, 5921-0, 5922-0, 5958-0, 5958-1, 5958-2, 5388-0, 5389-0, 5337-1, 5320-2B, 5320-2, 5958-2, 5320-7, 5910-6, 5320-9, 5320-0B, 5320-0, 5958-0, 5320-5, 5910-1, 5320-1B, 5320-1, 5958-1, 5320-6, 5910-4, 5321-2, 5321-0B, 5321-0, 5921-0, 5321-5, 5321-1, 5322-0B, 5322-0, 5922-0, 5324-0B, 5324-0, 5324-5, 5911-1, 5324-1, 5330-0B, 5330-0, 5331-0B, 5331-0, 5333-0, 5333-0B, 5335-0, 5937-2, 5337-0, 5937-0, 5337-0B, 5337-5, 5919-1, 5337-1, 5937-1, 5340-0, 5340-0B, 5341-0, 5341-0B, 5343-0, 5345-0, 5345-0B, 5348-0, 5348-0B, 5390-0, 5385-0B, 5385-0, 5386-0B, 5386-0, 5387-0B, 5387-0, 5388-0, 5389-0B, 5389-0, 5323-0B, 5323-0, 5332-0, 5334-0, 5338-0, 5938-0, 5342-0, 5346-0, 5346-0B, 5361-2B, 5361-2, 5981-2, 5361-7, 5912-6, 5361-0B, 5361-0, 5981-0, 5361-5, 5912-1, 5361-1B, 5361-1, 5981-1, 5361-6, 5912-4, 5372-0B, 5372-0



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

Certificate Number 20160112-E195978  
Report Reference E195798-19980114  
Issue Date 2016-JANUARY-12

Outlet Box Covers: Models 5147-0, 5146-1, 5181-0, 5104-0, 5102-0, 5132-0, 5133-0, 5145-0, 5138-0,

Extension rings for boxes: Models 5363-0, 5399-0, 5399-0B, 5400-0, 5900-0, 5400-0B, 5400-5, 5406-0, 5407-0, 5407-0B, 5363-0, 5363-0B, 5403-0, 5405-0, 5405-0B

**These models are evaluated to UL 514D, CSA C22.2 No. 42.1:**

Outlet Boxes Covers: Models 5374-0, 5173-2B, 5173-2, 5973-2, 5173-7, 5173-0B, 5173-0, 5973-0, 5173-5, 5943-1, 5173-1B, 5173-1, 5973-1, 5173-6, 5174-0, 5175-2, 5975-2, 5175-0B, 5175-0, 5975-0, 5961-1, 5175-5, 5175-1, 5975-1, 5374-0B, 5374-0, 5974-0, 5177-0, 5158-9, 5146-0, 5146-5, 5906-1, 5095-0, 5180-2, 5980-2, 5180-7, 5942-6, 5180-0B, 5180-0, 5980-0, 5180-5, 5942-1, 5180-1, 5980-1, 5180-6, 5942-4, 5094-0, 5178, 5103-2, 5983-2, 5103-7, 5103-0, 5983-0, 5103-5, 5103-1, 5983-1, 5103-6, 5101-2, 5971-2, 5101-7, 5970-6, 5101-0, 5971-0, 5101-5, 5970-1, 5101-1, 5971-1, 5101-6, 5970-4, 5155-0, 5155-5, 5913-1, 5155-1, 5155-6, 5091-0, 5152-0, 5148-0, 5148-5, 5964-1, 5096-0, 5160-0, 5098-0, 5157-0, 5092-0, 5097-0, 5093-0

**These models are evaluated to UL 514D:**

Outlet Box Covers: Model 5125-0



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

