

Click!

GVAN●●3

ø 3 mm

2 Max.

Click!

OFF

Click!

GVAEB●●3

GVAE●●3

ø 3 mm

OFF

ø 4 mm

10°

⚠ DANGER / 危险

HAZARD OF ELECTRIC SHOCK, EXPLOSION, OR ARC FLASH
Disconnect all power before servicing equipment. Failure to follow these instructions will result in death or serious injury.

电击、爆炸或电弧闪光危险
在此电力设备上进行操作时，请先断开所有电源。不遵循上述规定将可能导致人员伤亡。

Click!

TEST

ø 3 mm

ø 5 mm

Ø4 mm			Ø3 mm		
GV2ME●●3 / GV2RT●●3			GVAN●●3		GVAE●●3
1...2,5 mm²	1...4 mm²	1...4 mm²	0,5...1,5 mm²	0,75...2,5 mm²	0,34...1 mm²
AWG 10 - 18 CU 75°C			AWG 14 - 18 CU 60 / 75°C		AWG 18 - 20 CU 60 / 75°C
STRIP = 3/8 " 剥线长度=3/8"			STRIP = 3/8 " 剥线长度=3/8"		STRIP = 3/8 " 剥线长度=3/8"

www.schneider-electric.com/site/home



1672546 (GV2ME●●3)

Schneider Electric Industries SAS

35, rue Joseph Monier
92506 Rueil Malmaison
France

GV2ME●●3, GV2RT●●3
W9 1645883 0211 A06
04 - 2016

