

Appendix

RATINGS	Relay	Rating (A)/No. and type of contact
	RXM 2AB	12 / 2 Open-Close
	RXM 3AB	10 / 3 Open-Close
	RXM 4AB	6 / 4 Open-Close
	RXM 4GB	3 / 4 Open-Close
	Socket	Rating (V/A)
	RXZ E2S108M	250 / 12
	RXZ E2M114	250 / 10
	RXZ E2M114M	250 / 10
	RXZ E2S114M	250 / 10
	RXZ E2S111M	250 / 10
	RXZ E2S114S	250 / 12A for 2C/O, 6A for 4C/O
	RXZ E14P	250 / 12A for 2C/O, 6A for 4C/O

Tan Hui Luan
 Electrical Surveyor
 Electrotechnical Systems
 South Asia Technical Support Office, Singapore
 Lloyd's Register Singapore Pte Ltd
 Phone +65 3163 0701
 Fax +65 6273 1662
 Email: hui-luan.tan@lr.org