

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20190212-E6294  
**Report Reference** E6294-20060811  
**Issue Date** 2019-FEBRUARY-12

**Issued to:** Schneider Electric USA, Inc.  
1010 Airpark Center Dr  
Nashville TN 37217

**This certificate confirms that representative samples of** PANELBOARDS  
See Addendum page

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL67 : Panelboards  
**Additional Information:** See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information.

This *Certificate of Compliance* does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20190212-E6294  
**Report Reference** E6294-20060811  
**Issue Date** 2019-FEBRUARY-12

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

Value Pack, Cat. Nos. HOMVP1, HOMVP14, HOMVP2, HOMVPL1, HOMVPL2, HOMVP4, HOMVP5, HOMVP9, HOMVP12, HOMVP16, HOMVP15, HOMVPRB1, QOVP1, QOVP2, QOVP10, HOM816M125RBVP, HOMVP12M100CBP4, CSEDVP1, SO1020VP, SO2040VP, HOM3040M200VP, HOM3040L200VP, HOM3040M200RBVP, HOM40M200VP, HOM2040M200VP, HOM24M100VP, HOM1224L125VP, HOM224M125RBVP, HOM3040M150VP, HOM3040M200EPVP, Q03040M200VP, QO32M100VP, QO140M200EPVP, HOM3040M200CAFIVP, HOM4060M200CAFIVP, QO132M100PCVP, QO124L125PGCVP, QO124M100PCVP, QO142L225PGCVP, QO142M200PCVP, HOM3040M200CAFIVP, HOM4060M200CAFIVP, HOM1224L125PGCVP, HOM1224M125PRBVP, HOM2040M100PC1AVP, HOM2040M100PCVP, HOM2040M200PCVP, HOM2448M100PCVP, HOM3060L225PCVP, HOM3060L225PGCVP, HOM3060M150PCVP, HOM3060M200PC1AVP, HOM3060M200PCAFVP, HOM3060M200PCVP, HOM3060M200PRBVP, HOM4080M200PC1AVP, HOM4080M200PCAFVP, HOM4080M200PCVP, QO124L125PQGCVP, QO142M200PQCVP, HOM4080M200PQCVP, HOM2040M100PQCVP, HOM3060M200PQCVP.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

